



1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

<https://maps.app.goo.gl/SymFtcFeou2tZpDi6>

Structural Photolog



Aerial View of Property



Aerial View of Property Line

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



Building Elevation (North)



Building Elevation (South)

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



Building Elevation (East)




Building Elevation (West)

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



5. Present Condition of Overall Structure



5.c. View of Surface Conditions

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



6. View of Masonry Bearing Wall




6.g. View of Exterior Masonry Finishes


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



6.h. View of Interior Masonry Finishes



6.h.4. Interior Paint Only

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.a.1. Type & Condition Roof System




7.a.3. View of Roof Drains


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.a.4. View of Parapet Wall



7.a.6. View of Roof Membrane/Covering

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.a.7. View of Roof Framing Members



7.a.7. View of Roof Framing Members

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.b.1. Type & Condition of Floor System(s)



7.b.1. Type & Condition of Floor System(s)

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.b.3. View of Stairs & Landings



7.b.5. View of Guardrails & Handrails

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.b.3. View of Stairs & Landings



7.b.5. View of Guardrails & Handrails

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



9.a. View of Concrete Framing System



10.a. View of Windows

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



10.c.1. View of Exterior Doors



10.c.1. View of Exterior Doors

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



11.a. View of Wood Framing



11.b.2. View of Wood Floors

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



11.b.3. View of Wood Roof Members




11.f. View of Ventilation

Property Consulting Group, Inc.


1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

<https://maps.app.goo.gl/SymFtcFeou2tZpDi6>

Electrical Photolog



Aerial View of Property



Aerial View of Property Line

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



3. View of Electrical Services



3. View of Electrical Services

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



4. View of Metering Equipment



4. View of Metering Equipment

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



6. View of Electrical Gutters, Wireways



6. View of Electrical Gutters, Wireways

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



7. View of Electrical Panels



7.1. View of Electrical Panel

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



7.2. View of Electrical Panel



7.3. View of Electrical Panel

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



7.4. View of Electrical Panel



7.5. View of Electrical Panel


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



8. View of Branch Circuits (Exiting panel enclosure)



9. View of Grounding of Service

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



10. View of Grounding of Branch Circuit Equipment



11. View of Service Conduit/Raceways

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



11. View of Service Conduit/Raceways




12. View of General Conduit/Raceways

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



13. View of Wires and Cables



13. View of Wires and Cables


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



18. View of Emergency Lighting



19. View of Building Egress Illumination

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



19. View of Building Egress Illumination



19. View of Building Egress Illumination

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



20. View of Fire Alarm System



20. View of Fire Alarm System

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



21. View of Smoke Detectors



22. View of Exit Lights

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



24. Wiring in Open or Under Cover Parking Garage Areas



25. Open or Under Cover Parking Garage Egress Illumination

Property Consulting Group, Inc.