


GIS -0 Limon Street



3/9/2022, 9:44:20 AM

| | | | | | |
|-----------------------|------------------------|----------------------------|------------------------|------------------------|------------------------|
| wServiceLine | 10" Polyvinyl Chloride | Concrete (Non-Reinforced), | Ductile Iron, SL2001 | Vitrified Clay, SL2003 | Vitrified Clay, SL2008 |
| WSERVICE | ssGravityMain | Ductile Iron | Ductile Iron, SL2004 | Vitrified Clay, SL2004 | Vitrified Clay, SL2009 |
| WHYDLIN | Polyvinyl Chloride | Reinforced Concrete | Vitrified Clay, SL2000 | Vitrified Clay, SL2005 | |
| wMain | Polyvinyl Chloride | Vitrified Clay | Vitrified Clay, SL2001 | Vitrified Clay, SL2006 | ssPressurizedMain |
| 2" Polyvinyl Chloride | Brick | Vitrified Clay | Vitrified Clay, SL2002 | Vitrified Clay, SL2007 | 64" ssPressurizedMain |
| 6" Polyvinyl Chloride | | | | | |



St Johns County, Maxar, Microsoft, Esri Community Maps Contributors, FDEP, © OpenStreetMap, Microsoft, Esri, HERE, Garmin, SafeGraph, GeoTechnologies, Inc., METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA