
ALTA/NSPS LAND TITLE SURVEY


SECTION 15-19-23

- SW CORNER, NW 1/4,

SECTION 15-19-23

FND. 5" X 5" CM NO #





LAND AREA:

219,250 SQUARE FEET

OR 5.0333 ACRES

ARC RADIUS LENGTH TANGENT

3°52'46" 5729.58' 391.33' --- N58°46'38"W 391.29' DESC 3*52'49" 5779.58' 391.40' 195.78' N58*46'38"W 391.33' CALC N58*46'57"W 390.91' MEAS

DESCRIPTION:

ZONING INFORMATION:

LIST OF POSSIBLE ENCROACHMENTS:

WITHOUT EXPRESSING A LEGAL OPINION AS TO OWNERSHIP OR NATURE. THE FOLLOWING POSSIBLE

ENCROACHMENTS ARE NOTED. ADDITIONAL ITEMS MAY BE DEPICTED HEREON THAT HAVE NOT BEEN INCLUDED

NOT PROVIDED AT TIME OF SURVEY

Commence at the Southwest corner of the NW 1/4 of the NW 1/4 of Section 15, Township 19 South, Range 23 East, thence run South a distance of 767.29 feet to the centerline of the Seaboard Coast Line Railroad, thence run South 52°08'08" East a distance of 551.53 feet along the centerline of said Seaboard Coast Line Railroad to the P.O.B. of this property, continue South 52°08'08" East a distance of 370.00 feet along said railroad centerline, thence run South 37°51'52" West a distance of 587.41 feet to the Northerly right of way of State Road 44, thence Northwesterly a distance of 391.33 feet along the arc of a curve concave to the North, being the North right of way of State Road 44, said arc having a chord distance of 391.33 feet, a chord bearing of North 58°46'38" West, a radius of 5729.5780 feet and a delta of 3°52'46", thence run North 39°33'06" East a distance of 632.69 feet back to the P.O.B. and to close. Less the North 30 feet for Railroad Right of Way purposes.

Contains 219,250 square feet or 5.0333 acres, more or less.



GENERAL SURVEY NOTES:

- 1. BEARING STRUCTURE BASED ON THE MONUMENTED SOUTHERLY LINE OF RAILROAD: BEING: \$52°08'08"E PER OFFICIAL RECORD BOOK 669 . PAGE 154. OF THE PUBLIC RECORDS FOR SUMTER
- 2. THIS SURVEY REFLECTS ONLY MATTERS OF RECORD AS PROVIDED BY THE CLIENT OR CLIENTS
- 3. THIS SURVEY WAS MADE ON THE GROUND. THE UNDERGROUND UTILITIES SHOWN HAVE BEEN LOCATED FROM FIELD SURVEY INFORMATION AND EXISTING DRAWINGS. THE SURVEYOR MAKES NO GUARANTEE THAT THE UNDERGROUND UTILITIES SHOWN COMPRISE ALL SUCH UTILITIES IN THE AREA, EITHER IN SERVICE OR ABANDONED. THE SURVEYOR FURTHER DOES NOT WARRANT THAT THE UNDERGROUND UTILITIES SHOWN ARE IN THE EXACT LOCATION INDICATED ALTHOUGH HE DOES CERTIFY THAT THEY ARE LOCATED AS ACCURATELY AS POSSIBLE FROM INFORMATION AVAILABLE. THE SURVEYOR HAS NOT PHYSICALLY LOCATED THE UNDERGROUND UTILITIES. ENGINEER AND CONTRACTOR SHALL VERIFY MEASUREMENTS OF CONNECTIONS TO EXISTING UTILITIES BEFORE ORDERING MATERIALS AND BEFORE COMMENCEMENT OF CONSTRUCTION. IF THERE IS A DISCREPANCY BETWEEN THE MEASUREMENTS SHOWN HEREON AND THE VERIFYING MEASUREMENTS, THIS SURVEYOR SHALL BE CONTACTED IMMEDIATELY TO FURTHER VERIFY THE DISCREPANCY.
- PERFORM OR WHICH IS BEYOND HIS PROFESSION OR SPECIALTY THEREIN. THEREFORE, WE ARE UNABLE
- 6. THIS SURVEY MADE WITH BENEFIT OF COMMITMENT FOR TITLE NO. 13-25308, EFFECTIVE: XXXXX, ISSUED BY WESTCOR LAND TITLE INSURANCE COMPANY.
- PRACTICE FOR THE STATE OF FLORIDA.
- 9. THE PROPERTY HAS INDIRECT ACCESS TO EAST STATE ROAD 44. A DEDICATED PUBLIC ROAD WITHIN
- 11. VISIBLE ABOVE GROUND EVIDENCE OF MUNICIPAL WATER, STORM SEWER FACILITIES AND TELEPHONE, GAS AND ELECTRIC SERVICES OF PUBLIC UTILITIES EXISTS IN THE LOCATIONS INDICATED
- 12. ALL PARCELS AND/OR LOTS SHOWN HEREON ARE CONTIGUOUS BETWEEN SAID PARCELS AND/OR
- 13. THERE IS NO OBSERVED EVIDENCE OF CURRENT EARTH MOVING WORK, BUILDING CONSTRUCTION
- 14. THERE ARE NO PROPOSED CHANGES IN STREET RIGHT OF WAY LINES, ACCORDING TO SUMTER
- 15. THERE IS NO OBSERVED EVIDENCE OF USE AS A CEMETERY OR REFUSE ON SITE.
- 9. Easement in favor of Sumter Electric Cooperative, Inc. as contained in instrument recorded in Official Records Book 133, Page 309, public records of Sumter County, Florida. (DOES NOT AFFECT SUBJECT PROPERTY)
- Right of Way Easement in Official Records Book 46, Page 733, public records of Sumter County, Florida. (AFFECTS SUBJECT PROPERTY, AS SHOWN HEREON)

This is to certify that this map or plat and the survey on which it is based were made in accordance with the 2016 Minimum Standard Detail Requirements for ALTA/NSPS Land Title Surveys, jointly established and adopted by ALTA and NSPS, and includes items 1, 2, 3, 4, 6, 7(a), 7(b1), 8, 9, 10, 11(a), 13, 14, 16, 17, 18 and 21 of Table A thereof. The field work was completed on 12-27-2019.

Date: 12-27-2019

Robert C. Johnson PSM 5551

This Survey is "Not Valid" without the signature and the original raised seal of this Florida licensed Surveyor and Mapper, unless provided with electronic signature with the ability to validate. (See: www.altamaxsurveying.com for instructions on signature validation). The seal appearing on this document was authorized by the signing Professional Surveyor and Mapper on the Date of the electronic signature.

- COUNTY, FLORIDA
- 4. THIS SITE LIES IN ZONE "X", BASED ON FLOOD INSURANCE RATE MAP NO. 12119C0134D, COMMUNITY NO. 120296, UN-INCORPORATED SUMTER COUNTY, FLORIDA AND HAVING AN EFFECTIVE DATE OF 09-27-2013.
- 5. ACCORDING TO FLORIDA STATUTES, CHAPTER 472.025, A LAND SURVEYOR SHALL NOT AFFIX HIS SEAL OR NAME TO ANY PLAN OR DRAWING WHICH DEPICTS WORK WHICH HE IS NOT LICENSED TO TO CERTIFY AS TO MUNICIPAL ZONING COMPLIANCE, INTERPRETATION OF ZONING CODES OR THE DETERMINATION OF VIOLATIONS THEREOF.
- 7. THERE ARE ZERO STRIPED PARKING SPACES INCLUDING ZERO HANDICAP SPACES.
- 8. THIS "BOUNDARY SURVEY" WAS MADE IN ACCORDANCE WITH LAWS AND/OR STANDARDS OF
- 10. THE PROPERTY DOES NOT LIE WITHIN ANY AREA SUBJECT TO REGULATION BY FEDERAL OR MUNICIPAL AUTHORITY AS INLAND COASTAL WETLANDS, BEACH, ESTUARY OR THE LIKE.
- LOTS AND DO NOT CREATE ANY GAPS, GORES OR HIATUSES.
- OR BUILDING ADDITIONS. COUNTY, FLORIDA. THERE IS NO OBSERVED EVIDENCE OF RECENT STREET OR SIDEWALK
- CONSTRUCTION OR REPAIRS.
- 16. LEGAL DESCRIPTION SHOWN HEREON IS THE SAME AS LEGAL DESCRIPTION SHOWN IN THE TITLE COMMITMENT REFERENCED HEREON.

SCHEDULE B-2 EXCEPTIONS NOTES:

ALTA/NSPS Land Title Survey Certification

To: CLH VENTURES, INC. AND TONY ABOUD





LEGEND

- BOTTOM OF BANK - BACK OF CURB - BACKFLOW PREVENTER - BACKFLOW PREVENTER - BUILDING HEIGHT MEASUREMENT

- BENCHMARK - BURIED ELECTRIC - CURB INLET

CONC - CONCRETE

- CONCRETE PAD

- DEED BOOK

- CONCRETE WALK

- DUMPSTER PAD

- ELECTRIC METER

- FLOOD INSURANCE RATE MAP

- GEOGRAPHIC INFORMATION SYSTEM

- FINISHED FLOOR ELEVATION

- FIBER OPTIC CABLE BOX

- FIBER OPTIC CABLE LINE

HDPE - HIGH-DENSITY POLYETHYLENE PIPE

- EASEMENT - EDGE OF PAVEMENT

- FOUND

- GAS LINE

- GAS METER

- GAS VALVE - GUY WIRE ANCHOR - HANDICAP PARKING

- HANDICAP RAMP

- IRON PIPE - IRON ROD - STORM JUNCTION BOX

MEAS - MEASURED

- ARC LENGTH - LANDSCAPED AREA

- METAL FENCE - METAL LID

- METAL SHED - MITERED END SECTION - MONITORING WELL

- NAIL AND DISK NAVD - NORTH AMERICAN VERTICAL DATUM

- NOT TO SCALE - ON LINE

POB - POINT OF BEGINNING

- CURVE RADIUS

- RECORD

POC - POINT OF COMMENCEMENT - PARKING SPACES

OW - OVERHEAD WIRE (M) - PLAT PB - PLAT BOOK

NGVD - NATIONAL GEODETIC VERTICAL DATUM

PDOT - PER DEPARTMENT OF TRANSPORTATION R/W MAP

- OFFICIAL RECORDS BOOK

- PER ENGINEERING PLANS - PAGE - POINT OF INTERSECTION

- PEDESTRIAN SIGNAL POLE - POINT OF TANGENCY

- REINFORCED CONCRETE PIPE - REUSE WATER METER

- REUSE WATER VALVE

SDO - SHOWN FOR DIRECTION ONLY

- STORM/DRAIN LINE - STORM INLET STORM MANHOLE

TELEPHONE LINE

- TELEPHONE RISE - TRAFFIC SIGNAL BOX - TRAFFIC SIGNAL WIRE - CABLE TV RISER

- VITRIFIED CLAY PIPE - VINYL FENCE

- EASEMENT NUMBER

ADDRESS:

6033 CR 44-A

WILDWOOD, FL 34785

Job Information

Revisions Description

02/11/20 | Corrected typo in description

- UTILITY POLE - UTILITY MARKER

 WOOD FENCE WLF - WETLAND FLAG - WOOD SHED

JOB NO. 903284

SCALE: 1" = 60' DRAWN BY: PJT

CF NO. SUM-15-19-23-UPDATE

FIELD DATE: 12-27-2019

- TRANSFORMER/JUNCTION BOX

- TOP OF BANK - TRAFFIC SIGN

- REUSE WATER LINE R/W - RIGHT OF WAY

- SANITARY LINE

SWF - STOCK WIRE FENCE

- POINT OF CURVATURE

- DRAINAGE EASEMENT - DOT INLET

CONCRETE BLOCK WALL

- COVERED CONCRETE CONCRETE FLUME

- CONCRETE HEADWALL - CHAIN LINK FENCE

- CONCRETE MONUMENT

CORRUGATED METAL PIPE



Altamax Surveying

SHEET 1 OF 1