

IMPROVEMENTS 510 MAIN

Replaced and Added HVAC (3 systems)
Replaced Plumbing Entire Building
Replaced Gas Lines and Meters Entire Building
Replaced Electrical Interior and Exterior Entire Building
Repaired and Replaced Brick (front exterior, south interior wall, interior areas upstairs)
New Facade, Windows, Siding/Trim
New Flooring throughout 1st floor
New Concrete Back room floor
Rockwool Insulation Ceiling
2 layer 5/8"Firewall Ceiling
New Drywall throughout 90% Building
New Exhaust/Ansul System Type 1
Sealed Brick Interior
New Exterior and Interior Doors
New Appliances Upstairs
New Bathroom Toilets, Sinks Entire Building
New Concrete Patio and Exterior Steps
New Fire Escape
Installed Mini Split Backroom
Gazebo
Fence
Built Walkway in Alley
5 New Windows Upstairs
27 Foot Laminate Service Counter
Tv Electrical Connections 1st and 2nd floor
Replaced 10ft Support Beam 2nd floor Study
220 Outlet Back Room
New Lighting Interior and Exterior 1st and 2nd floor