



1362 SW 2nd Street, Miami, FL 33135

20-Unit Multifamily Investment Opportunity

Asking Price: \$3,990,000



Executive Summary

1362 SW 2nd Street is a 20-unit multifamily property built in 1914 and situated on an 11,250 SF lot in the heart of Miami. The property generates a Net Operating Income of \$236,901.11 with a current cap rate of approximately 5.94% at the asking price of \$3,990,000.



Financial Overview

Gross Annual Income	\$356,580
Operating Expenses	\$119,678.89
Net Operating Income	\$236,901.11
Cap Rate (at Asking)	5.94%
Lot Size	11,250 SF

ACTUAL INCOME STATEMENT

1362 SW 2 St, Miami, FL 33135
20-Unit Multifamily Property

Prepared by: Oscar Arellano | The Oscar Arellano Team
Coldwell Banker Realty | RealEstateBulldog.com

Unit Mix & Current Rents

Unit	Beds	Baths	Monthly Rent
1	1	1	\$1,400
2	2	1	\$2,000
3	2	1	\$1,800
4	2	2	\$1,700
5	1	1	\$1,400
6	1	1	\$1,400
7	1	1	\$1,400
8	1	1	\$1,390
9	1	1	\$1,300
10	1	1	\$1,400
11	1	1	\$1,400
12	1	1	\$1,400
13	1	1	\$1,400
14	1	1	\$1,400
15	2	1	\$1,600
16	1	1	\$1,400
17	1	1	\$1,350
18	1	1	\$1,375
19	2	1	\$1,600
20	2	1	\$1,600

Total Monthly Rental Income: \$29,715

Total Annual Rental Income: \$356,580.00

Annual Operating Expenses

Expense	Annual Amount
Real Estate Taxes	\$47,949.00
Insurance	\$30,309.00
Local Business Tax / City Fees	\$1,600.50

FPL (Electric)	\$8,553.33
Water & Sewer	\$7,537.49
Maintenance	\$6,900.00
Repairs	\$7,658.44
Waste / Garbage	\$5,018.16
Fire & Safety	\$310.50
Landscaping	\$1,440.00
Pest Control	\$649.00
Gas	\$1,753.47
Total Operating Expenses	\$119,678.89

Net Operating Income (NOI): \$236,901.11

Cap Rate: 5.94%

Property Address
 Property Name
 Rent Roll As of Date

Trinity Affordable One, LLC
 1362 SW 2 ST, MIAMI, FL 33135
 January 17th, 2026


Occupancy Status (Vacant/Occupied)	Unit #s	# of Beds/Baths	Tenant Name	Sq. Ft.	Monthly Rent
1 Occupied	1	1 BD/ 1 BA	Ramon Cruz	600	\$1,400.00
2 Occupied	2	2 BD/ 1 BA	Ronaldo A. Rivera	600	\$2,000.00
3 Occupied	3	2 BD/ 1 BA	Carlos Tinoco	600	\$1,800.00
4 Occupied	4	2 BD/ 2 BA	Yanet Ramirez	675	\$1,700.00
5 Occupied	5	1 BD/ 1 BA	Castillo Mora		\$1,400.00
6 Occupied	6	1 BD/ 1 BA	Jayli Montero	400	\$1,400.00
7 Occupied	7	1 BD/ 1 BA	Yenier Eshevania Henao	400	\$1,400.00
8 Occupied	8	1 BD/ 1 BA	Cherlin amador	400	\$1,390.00
9 Occupied	9	1 BD/ 1 BA	Juan Carlos Sarmiento	400	\$1,300.00
10 Occupied	10	1 BD/ 1 BA	Roy Alexander	400	\$1,400.00
11 Occupied	11	1 BD/ 1 BA	Delinis Hernandez	400	\$1,400.00
12 Occupied	12	1 BD/ 1 BA	Juan Sevilla	400	\$1,400.00
13 Occupied	13	1 BD/ 1 BA	Laustace Fluckens	400	\$1,400.00
14 Occupied	14	1 BD/ 1 BA	Gloria Pacheco	400	\$1,400.00
15 Occupied	15	2 BD/ 1 BA	Armando Valdes	600	\$1,600.00
16 Occupied	16	1 BD/ 1 BA	Heidi Sevilla	600	\$1,400.00
17 Occupied	17	1 BD/ 1 BA	Sandra Chavez	400	\$1,350.00
18 Occupied	18	1 BD/ 1 BA	Nozipo Sutak	400	\$1,375.00
19 Occupied	19	2 BD/ 1 BA	Scarleth Cruz	600	\$1,600.00
20 Occupied	20	2 BD/ 1 BA	Alfonso Cruz	600	\$1,600.00
TOTALS					\$29,715.00

Interior Highlights





Aerial & Location Overview



Prepared By:

Oscar Arellano
The Oscar Arellano Team | Coldwell Banker Realty
RealEstateBulldog.com

James Hanskat, P.E.

Date: December 6, 2024

Attention: City of Miami Building Department
Attn: Luis Torres, Building Official
444 SW 2nd Avenue, 4th Floor
Miami, Florida 33130
(305) 416-1115

Case No.: Not Provided

Reference: 40 Year Re-Certification
Two-Story Residential Building
Folio No.: 01-4102-006-2220
1362 SW 2 ST, MIAMI, FL 33135
Bldg. No.: 1 / Sq. Ft.: 3,811

Owner: L B M INVESTMENTS LLC
PO BOX 521155 MIAMI, FL 33152

James Hanskat, P.E., has performed structural and electrical inspections of the above-referenced property located in Miami-Dade County, Florida.

Based upon our findings during the inspection of the building we recommend that the building be recertified for the next ten years. The building is structurally and electrically safe for continued use under present occupancy.


The intent of the report is to verify the structural and electrical integrity of the structure. This is not a code compliance inspection. In order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structural or electrical systems. To the best of my knowledge and ability, this report represents an accurate opinion of the present condition of the building based upon careful evaluation of observed conditions, to the extent reasonably possible.

I, James Hanskat, P.E.# 49801, certify that I currently hold an active license in the state of Florida and am competent through education and experience to provide the engineering services contained in this report. I hereby certify that Property Consulting Group, Inc., holds an active Certificate of Authorization # 8216 to provide the engineering services.

Should you have any questions concerning this report, please contact our office.

Signature: _____

James T Hanskat



Print Name:James Hanskat, P.E., # 49801 Date:December 6, 2024

CERTIFICATION OF COMPLIANCE WITH PARKING LOT ILLUMINATION STANDARDS IN CHAPTER 8C OF THE CODE OF MIAMI-DADE COUNTY

Date: 12/6/2024

RE: Case No.:

Not Provided

Property Address:

1362 SW 2 ST, BLDG.: 2, MIAMI, FL 33135

Building Description:


Two-Story Residential Building

1. I am a Florida registered professional engineer or architect with an active license.
2. On 11/8 2024, at 10:07 pm, I measured the level of illumination in the parking lot (s) serving the above referenced building.
3. Maximum 1.27 foot candle per SF, Minimum 1.08 foot candle per SF, Minimum to Maximum ratio 1 : 17, foot candle 1.17 average per SF.
4. The level of illumination provided in the parking lot (s) meets / does not meet the minimum standards for the occupancy classification of the building as established in Section 8C-3 of the Code of Miami-Dade County.

James T
Hanskat

Signature and Seal
of Architect or Engineer

Digitally signed by
James T Hanskat
Date: 2024.12.01
11:58:18 -05'00'




James Hanskat, P.E.
(Print Name)

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

<https://maps.app.goo.gl/SymFtcFeou2tZpDi6>

Structural Photolog



Aerial View of Property



Aerial View of Property Line

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



Building Elevation (North)



Building Elevation (South)

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



Building Elevation (East)



Building Elevation (West)

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



5. Present Condition of Overall Structure



5.c. View of Surface Conditions

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



6. View of Masonry Bearing Wall



6.g. View of Exterior Masonry Finishes


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



6.h. View of Interior Masonry Finishes



6.h.4. Interior Paint Only

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.a.1. Type & Condition Roof System



7.a.3. View of Roof Drains

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.a.4. View of Parapet Wall



7.a.6. View of Roof Membrane/Covering

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.a.7. View of Roof Framing Members



7.a.7. View of Roof Framing Members

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.b.1. Type & Condition of Floor System(s)



7.b.1. Type & Condition of Floor System(s)

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.b.3. View of Stairs & Landings



7.b.5. View of Guardrails & Handrails

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



7.b.3. View of Stairs & Landings



7.b.5. View of Guardrails & Handrails

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



9.a. View of Concrete Framing System



10.a. View of Windows

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



10.c.1. View of Exterior Doors



10.c.1. View of Exterior Doors

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



11.a. View of Wood Framing



11.b.2. View of Wood Floors

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Structural Photolog



11.b.3. View of Wood Roof Members




11.f. View of Ventilation

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

<https://maps.app.goo.gl/SymFtcFeou2tZpDi6>

Electrical Photolog



Aerial View of Property



Aerial View of Property Line

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



3. View of Electrical Services



3. View of Electrical Services


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



4. View of Metering Equipment



4. View of Metering Equipment

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



6. View of Electrical Gutters, Wireways



6. View of Electrical Gutters, Wireways

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



7. View of Electrical Panels



7.1. View of Electrical Panel

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



7.2. View of Electrical Panel



7.3. View of Electrical Panel

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



7.4. View of Electrical Panel




7.5. View of Electrical Panel

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



8. View of Branch Circuits (Exiting panel enclosure)



9. View of Grounding of Service

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



10. View of Grounding of Branch Circuit Equipment



11. View of Service Conduit/Raceways

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



11. View of Service Conduit/Raceways



12. View of General Conduit/Raceways


Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



13. View of Wires and Cables



13. View of Wires and Cables

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



18. View of Emergency Lighting



19. View of Building Egress Illumination

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



19. View of Building Egress Illumination



19. View of Building Egress Illumination

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



20. View of Fire Alarm System



20. View of Fire Alarm System

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



21. View of Smoke Detectors



22. View of Exit Lights

Property Consulting Group, Inc.

1362 SW 2nd St, Bldg. No.: 1, Miami, FL 33135

Electrical Photolog



24. Wiring in Open or Under Cover Parking Garage Areas



25. Open or Under Cover Parking Garage Egress Illumination

Property Consulting Group, Inc.