

1. Bldg 1 west elevation



2. Bldg 2 west elevation



3. Moisture damage bldg 2



4. Mold damage bldg 2





5. Poor drainage along southeast



6. Fair asphalt paving



7. Bldg 2 interior



8. Trash and debris to be removed



9. Damaged wood landscaping borders



10. Fair to poor finishes



11. Damaged soffits



12. Roof parapet wall





13. Soffits exposed



14. Roof surface rust bldg 1



15. Roof leak bldg 1



16. Roof coping poor





17. Damaged gutters



18. Interior overview bldg 1



19. Past roof leaks bldg2



20. Bldg 2 interior poor






21. ADA signage needed



22. Bldg 1 east elevation



23. Bldg 2 east ealevation



24. Bldg 2 restroom





25. Circuit breaker panel



26. Circuit breaker panels bldg 1



27. Concrete retaining wall along south



28. Concrete slab bldg 1






29. Copper plumbing



30. Corrugated metal roofing bldg 1



31. Corrugated metal roofing bldg 2



32. CPVC plumbing





33. Domestic water heater



34. Drive thru sign



35. Electrical meter



36. East paving





37. Electrical removed bldg 1



38. Entrance door and windows



39. Entrance doors bldg 1




40. Fire hydrant





41. Limited landsacping



42. Metal overhead door



43. Metal panel wall damages



44. Packaged HVAC





45. Plumbing removed bldg 1




46. Pole transformer



47. Poor water heater



48. Property east entrance



49. Property signage



50. Recent framing repairs



51. Recent roofing repairs bldg 2



52. Roof repairs bldg 1






53. Sidewalk along street



54. Split system HVAC



55. Steel framing



56. Walk in cooler roof





57. Windows bldg 1



58. Wood framing bldg 1



59. Wood framing



60. Rusting gutters




61. Minor brick crack at bldg 1



62. Pole signage

APPENDIX B Street Map and Aerial Photo









AERIAL PHOTO

1612 Frazier St, Conroe, Texas 77301 AEI Project Number: 458021



APPENDIX C Pre-Site Visit Questionnaire





PCA PRE-SURVEY QUESTIONNAIRE (ROI)

Environmental & Engineering Services

36 Parking

PROPERTY NAME:	razier			And the state of the	THE REAL PROPERTY OF	16
	012 Frazier		CITY (BUYO	~	STA	TE Y
Number of Buildings:	7	Date of Construction:	1972	Current Occupancy:	٥	%
Number of Stories:	1	Renovation Date(s):	N/A	Area of Current Vacant Space:		
Site Area in Acres:	344 acres	Gross Building Area:	1 (-1)	Rentable Building Area:	1,400	sq. ft.
Total Number of	25	Number of HC Parking Spaces:	1 -0 (Number of Van HC Spaces:	O	
GENERAL PROPERTY	INFORMAT	ION		an databanka selah s		
Please describe any origoing the Bly was wee	ing/current major l	building mainterian	seismic, and upgrade orders, receipts, etc.: Frame Bran elect pane nce, renovation, seismic	cine		_
Please describe any ongoing the Bly was were All interior Please describe any future I	ing/current major to the solution of the solut	building mainterian	corders, receipts, etc Corders, receipts, et	erius A Toleue C and upgrade work Vork:		_
Please describe any origoing the Big was were	g/current major l g/current major l y y building maintend	building mainterian work building mainterian ance, renovation, so	corders, receipts, etc Corders, receipts, et	and upgrade work:	reno	_
Please describe any origoin #1 Bls was 10 ee All interior Please describe any future I	ing/current major to the solution of the solut	building mainterian way (-euro) ance, renovation, s is a Tenant or Lan Landlord	ce, renovation, seismic seismic, and upgrade w	and upgrade work: REPLACEMENT:	reno	Zew ved.
Please describe any ongoing the Blanch was some please describe any future by Please indicate which of the Paving	g/current major l g/current major l y y building maintend	building mainterian way (-e ance, renovation, secondary) is a Tenant or Lan Landlord	seismic, and upgrade w	and upgrade work: REPLACEMENT:	renant	Zew ved.
Please describe any ongoing the Blanch was to see Please describe any future In Please indicate which of the Paving Pavement Seal-coating	ing/current major to the solution of the solut	building mainter and the second secon	renevation, seismic seismic, and upgrade worders responsibility for the total variety of the	crug change work change and upgrade work work: REPLACEMENT:	renant	Zew ved.
Please describe any origoin HI THE TO Please describe any future I Please indicate which of the Paving Pavement Seal-coating Pavement Striping	ing/current major to the solution of the solut	building mainter and the second secon	renovation, seismic seismic, and upgrade world responsibility for Window AC Units or Oth Comestic Water Heaters	crug change work change and upgrade work work: The second of the sec	renant	Zew ved.
Please describe any origoin Please describe any future I Please describe any future I Please indicate which of the Paving Pavement Seal-coating Pavement Striping Sidewalks	ing/current major to the solution of the solut	building mainterian way condition, see work building mainterian ance, renovation, see a Tenant or Lan Landlord H D F	seismic, and upgrade worden with the condensing units Vindow AC Units or Other Comestic Water Heaters ire Sprinkler in Tenant	replacement:	renant	Zew ved
Please describe any origoin Please describe any origoin Please describe any future I Please indicate which of the Paving Pavement Seal-coating Pavement Striping Sidewalks Exterior Paint	ing Still ig/current major to the still building maintenant following items Tenant	building mainterian building mainterian ance, renovation, services Landlord H D F F	renovation, seismic seismic, and upgrade world responsibility for Window AC Units or Oth Comestic Water Heaters	replacement:	renant	Zew ved.
Please describe any ongoin Please describe any ongoin Please describe any future is Please indicate which of the Paving Pavement Seal-coating Pavement Striping Sidewalks Exterior Paint Brick Pointing	ing Still ig/current major to the still building maintenant following items Tenant	building mainter and the second secon	receipts, etc Corders, receipts, etc Seismic, and upgrade was a sei	replacement:	renant	Zew ved
Please describe any origoin Please describe any origoin Please describe any future is Please indicate which of the Paving Pavement Seal-coating Pavement Striping Sidewalks Exterior Paint Brick Pointing Roofing	ag/current major land subject to the	building mainter and the second secon	seismic, and upgrade worden AC Condensing units Vindow AC Units or Other Comestic Water Heaters Fire Sprinkler in Tenant Fire Alarm in Tenant Sprinkler	crus crus crus crus crus crus crus crus	renant X	Zew ved.
Please describe any ongoing the Blanch of the Please indicate which of the Paving Pavement Seal-coating Pavement Striping Sidewalks Exterior Paint Brick Pointing	ag/current major land solution of the solution	building mainterian building mainterian ance, renovation, s Landlord H D F F E T	ACC Condensing units Vindow AC Units or Oth Comestic Water Heaters Fire Sprinkler in Tenant Fire Alarm in Tenant Species and Space Finishes	crus crus crus crus crus crus crus crus	renant	Zew ved.

Roofing
Elevator
Fire Protection
Electrician
Landscaping

Painting
HVAC
Plumbing
Trash Disposal
Security System



Environmental & Engineering Services

Please list all utility providers for the Property:

Domestic Water CT+ CONVOR Gas/ Oil/ Other Centerpoint

Sanitary Sewer III

Storm Drainage III

Steam N/A

QUESTIONNAIRE Stop interjor frame work-no	OVEC	"No	UNKNOWN		
		NO	- Children		
Are you aware of any violations the property has been cited for? (If Yes, attach citation)	×	×			
Is a tenant monthly fee charged for common area maintenance (CAM)?	×	K			
Does the Property experience any site drainage, ground water or flooding problems?		Diam'r.	some chest		
Is the amount of on-site parking provided adequate?	X				
Is the site lighting fully operational?	X		79732		
Are the utilities (water, sewer, gas, electric) adequate to meet needs of the tenants?	×	×			
Does the Property have any structural issues such as settlement, cracking or deflection?		Ž.	24 . 2 . 1919		
Has the Property experienced any fire related or seismic damage?	×		Maria III		
Does the Property exhibit any water/ moisture infiltration?	~		NAME AND TRACT		
Does the Property have any leakage or failures at the roof, walls or cellar?	~	∞	THE STATE OF		
Is fire retardant plywood (FRT) installed anywhere in the structure(s)?	1989	×			
Are any portions of the facades covered with EIFS (synthetic stucco or Dryvit)?	and delicated	×			
Any problems regarding synthetic stucco or EIFS?	~	~			
Is roof access available?	×				
Are the HVAC systems adequate and fully functional?	X	~	Section VIII		
Are there any plumbing leaks or prevalent past leaks?		X			
Is the water pressure sufficient at all times?	X	.0	STALL PARK.		
Is galvanized or polybutylene "gray" piping present anywhere in the Property?	1977-1-19	X			
Has any active or historical leaks related to galvanized or polybutylene piping occurred?	180/18	X	10.16		
Has retrofitting or replacement of galvanized or polybutylene piping taken place?					
Are there any electrical problems or inadequate electrical service?	北京市 、五	X			
Does each unit have a minimum of 60 amp electrical service?	×				
Is aluminum branch wiring present anywhere in the Property?	two miles	X			
If aluminum branch wiring is present, has retrofitting been performed?					
Are there any screw-in fuses present in the Property?		×			
Are there GFIs/ GFCIs located in kitchens and bathrooms?	X		X ST.		
Are there any elevator or escalator shutdowns or deemed out of service?					
Are the elevators regularly serviced under a full service maintenance contract?					
Are the fire sprinkler systems regularly serviced and tested?	VIII I				
Are the fire alarm and detection devices regularly serviced and tested?					
Is common area interior painting performed as part of routine maintenance?	X	3 1			
Was an "ADA Survey" ever conducted on the property? (If Yes, please attach a copy)	Hay 7	X	E al L.		
Has any ADA improvements been made to the Property or does a Barrier Removal Plan exist for the Property?		X	Lawrence La		
Is there any unresolved ADA related complaints or pending litigation?	The second	×			
Is there any mold or microbial growth at the Property? # 2 Bly Leav	X	160-74			
Have any tenants or occupants complained about mold or microbial growth at the Property?		1 4 1	CALSE ONLS		
Is there a current formal indoor air quality management plan at the Property?	110. La	X			
Please indicate when the following systems have been last inspected:					
Fire Sprinkler Elevators/ Escalators					
Fire Alarm Facades					



Environmental & Engineering Services

REPLACEMENT/ REPA		ingineering services		(100) T. Bath		
(Indicate "NA" if tenant-own	ed or not applicable:) of the following, as app indicate "ORIG", if from orig rs. in age, etc. – please attac	inal building cons	struction. If apes for comme	oplicable, give an onts/ clarifications.	estimated range,
Paving:	Yrs.	Sealant/Striping:	Yrs.	Exte	erior Lighting:	Yrs.
Landscaping:	Yrs.	Irrigation System:	Yrs.	Build	ing Signage:	Yrs.
Masonry Pointing:	Yrs.	Exterior Paint:	Yrs.		EIFS:	Yrs.
Windows:	Yrs.	Doors:	Yrs.	Building Sealants:		Yrs.
Roofing:	Yrs.	Other Roofing: _	Yrs.		Skylights:	Yrs.
HVAC():	Yrs.	HVAC():	Yrs.	HVAC(_):	Yrs.
Electric Service:	Yrs.	Emergency Generator:	Yrs.	Water Line:		Yrs.
Water Pumps:	Yrs.	Water Heaters:	Yrs.	Sewer Lines		Yrs.
Elevator Finishes:	Yrs.	Elevator Controller:	Yrs.	Elevator Machinery: Central Fire Alarm		Yrs.
Escalators:	Yrs.	Fire Pump:	Yrs.	Panel:		Yrs.
Lobby:	Yrs.	Common Flooring:	Yrs.	Common Restrooms:		Yrs.
DOCUMENT REVIEW						
Please provide us with documentation may be	the following doc included as an e	uments prior to our site v xhibit within the Property	visit, indicating Condition Ass	the availab	lity of each. Th	is
CONTRACT PARTY		ental will be seen		vailable On-site	Available	Not
Site Plan and ALTA Su	irvev	A STATE OF THE REAL PROPERTY.		OH-SILE	Attached	Available
Certificate of Occupand						×
Copy of Open Building		Violations	A			×
Copy of Zoning Variand			Taylor May 25			Contract of the second
		e, unit area and occupar	icv %)		1.4 (0.0)	We to be stored
Reduced Floor Plans		Marian Language	1015713			
Original construction d	ocuments (core a	nd shell)	The state of	C 14 - 12 - 1		The second second
List of Mechanical Equ	ipment	。[29] 中华巴斯特里里斯				10 mm 1 mm 1 mm
List of Capital expendit	tures for last 5 year	ars	经 类的表现	STAR STA	THE WAY	1
List of Planned Capital		THE ALTERNATION AND THE		A WIND	ARREST LESS	The State of the S
Local Law #11 Façade	Inspection Repo	rts (NYC)	THE STATE	T. C. A. A.		Page Parking
Roof survey and warra	nty		PRIME PLA		Maria de la Maria	For Francisco
Service reports and ins	spection certificate	es for (elevator, escalato	r, HVAC,			
electrical generator, fire ADA Survey or Barrier		kier)				
		Report or engineering st	udios			
r reviously prepared Fr	operty Condition	Report or engineering st	udies	CONTRACTOR IN THE REAL PROPERTY.		
Interviewee / Title:					一种,阿尔 克克克	