Tax key number: 106-1317-0821-023

Property address: 611 Main St

Traffic / water / sanitary: Heavy / City water / Sewer

Summary o	Summary of Assessment							
Land	\$17,800							
Improvements	\$77,900							
Total value	\$95.700							

	Land										
Qty	Qty Land Use Width Depth Square Feet Acres		Water Frontage	Tax Class	Tax Class Special Tax Program						
1	Commercial			10,280	0.236	None	Commercial		\$17,800		

Commercial Building (Service/Garage Building)

Assessed value: \$61,900

Section name: Section 1
Year built: 1900
% complete: 100%
Stories: 1.00
Perimeter: 134 LF


Total area: 1,080 SF (all stories)



	Designed Use	Actual Use	Units	Area per Unit	Construction Class	Avg Ht	Quality	CDU
Occupancies	Service repair garage		1	1,080	Wood or steel framed exterior w	10.00	E (PR)	Fair

Component Description	Count	Stops	Area (sf)	Area (%)	Quality
Stud-Vinyl Siding			1,080	100.0%	D (FR)
Forced air unit			1,080	100.0%	D (FR)

	Qty	Description	Units	Grade	Location	Yr Blt	Condition
Other features	1	Pavement - Asphalt	2,000	E		1900	Fa
Other features	1	Pavement - Concrete	2,200	E		1900	Fa
Other features	1	Rear Entry Porch	60	E		1900	Fa



Section 2 Section name: 1920 Year built: % complete: 100%

1.00

Stories: Perimeter: 126 LF


Total area: 920 SF (all stories) photograph not available

Occupancies

	Designed Use	Actual Use	Units	Area per Unit	Construction Class	Avg Ht	Quality	CDU
es	Service repair garage		1	920	Masonry bearing walls	9.00	E (PR)	Fair

Exterior walls

	Component Description	Count	Stops	Area (sf)	Area (%)	Quality
ior walls	Stud-Vinyl Siding			920	100.0%	D (FR)
HVAC	Forced air unit			920	100.0%	D (FR)



Section name: Section 3
Year built: 1920
% complete: 100%

Stories: 1.00 Perimeter: 116 LF


Total area: 400 SF (all stories)

photograph not available

Occupancies

	Designed Use	Actual Use	Units	Area per Unit	Construction Class	Avg Ht	Quality	CDU
es	Service repair garage		1	400	Wood or steel framed exterior w	9.00	E (PR)	Fair

	Component Description	Count	Stops	Area (sf)	Area (%)	Quality
ior walls	Stud-Vinyl Siding			400	100.0%	D (FR)
HVAC	Space heater			400	100.0%	D (FR)



Section name: Section 4
Year built: 1930
% complete: 100%
Stories: 1.00

Stories: 1.00 Perimeter: 76 LF


Total area: 312 SF (all stories)

photograph not available

Occupancies

	Designed Use	Actual Use	Units	Area per Unit	Construction Class	Avg Ht	Quality	CDU
es	Service repair garage		1	312	Wood or steel framed exterior w	10.00	E (PR)	Fair

	Component Description	Count	Stops	Area (sf)	Area (%)	Quality
ior walls	Stud-Vinyl Siding			312	100.0%	D (FR)
HVAC	Forced air unit			312	100.0%	D (FR)



Section name: Section 5
Year built: 1940
% complete: 100%
Stories: 1.00

Stories: 1.00 Perimeter: 88 LF


Total area: 448 SF (all stories)

photograph not available

Occupancies

	Designed Use	Actual Use	Units	Area per Unit	Construction Class	Avg Ht	Quality	CDU
es	Service repair garage		1	448	Masonry bearing walls	10.00	E (PR)	Fair

	Component Description	Count	Stops	Area (sf)	Area (%)	Quality
ior walls	Stud-Vinyl Siding			448	100.0%	D (FR)
HVAC	Space heater			448	100.0%	D (FR)



2024 Property Records for Village of Brownsville, Dodge Country

# of identical OBIs: 1 Other Building Improvement (OBI)					
M	ain Structure		Modifications (Type, Size)	Photograph	
OBI type: Garage Const type: Detached, frame or cb Year built: 1990	Width: 48 LF Depth: 30 LF Floor area: 1,440 SF	Grade: Condition: % complete: Assessed \$:	100%		

Building Permits				
Issued	Permit #	Purpose	\$ Amount	Completed

Sales History					
Date	Price	Туре			
1/13/2011	\$23,700	Not a market sale			