PROPERTY LOCATED AT: 394 Main St, Westbrook, ME 04092

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

SECTION I – WATER SUPPLY

TYPE OF SYSTE	EM: Public Private Seasonal Unknown Drilled Dug Other
MALFUNCTION	S: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?
	Pump (if any): N/A Yes X No Unknown
	Quantity:
	Quality: \Box Yes \bigvee No \Box Unknown
	If Yes to any question, please explain in the comment section below or with attachment.
WATER TEST:	Have you had the water tested? Yes Ir No
	If Yes, Date of most recent test: Are test results available? Yes No
	To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?
	If Yes, are test results available? Yes No
	What steps were taken to remedy the problem?
IF PRIVATE: (Str	rike Section if Not Applicable):
INSTALLAT	ON: Location:
	Installed by:
	Date of Installation:
USE:	Number of persons currently using system:
	Does system supply water for more than one household? Ves No Unknown
Comments:	Public Water
Source of Section	I information: <u>Sellers</u>
Buyer Initials	Page 1 of 7 Seller Initials $M R M$
EXP Realty, 533 Congress St Port John Krouse	land ME 04101 Phone: 2079290956 Fax: Morse Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

PROPERTY LOCATED A	AT: 394 Main St, Y	Westbrook, MI	E 04092
--------------------	--------------------	---------------	---------

SECTI	ON II —	WASTE WAT	ER DISPOSAL		
TYPE OF SYSTEM: 🔀 Public] Private	Quasi-Pu	blic		Unknown
IF PUBLIC OR QUASI-PUBLIC (Stril Have you had the sewer line inspect	ted?	n if Not Applicat	ole):		🗌 Yes 📈 No
If Yes, what results:					
Have you experienced any problem	s such as	line or other mal	functions?		Yes No
Have you experienced any problem What steps were taken to remedy th	e problen	n? Vent piped h	locked in Snowst	torim. Remo	und Snow. No iss
IF PRIVATE (Strike Section if Not App					
Tank: Septic Tank			Other:		
	00 Gallor		n 🗍 Other:		
Tank Type: Concrete N	Aetal	Unknown			
Location:			<u> </u>	OR	
Date installed: Date la	st pumped	d: 1	Name of pumping	g company:	
Have you experienced any malfunct	tions?				Yes No
If Yes, give the date and describe th	e problen	n:			
Date of last servicing of tank:	N	Name of company	y servicing tank:		
Leach Field:				Yes	No 🗌 Unknown
If Yes, Location:					
Date of installation of leach field:		Installed by:			
Date of last servicing of leach field:					
Have you experienced any malfunct					
If Yes, give the date and describe th	e problem	n and what steps	were taken to ren	nedy:	
Do you have records of the design in	dicating t	the # of bedroom	s the system was	designed for	? Yes No
If Yes, are they available?					Language Languag
Is System located in a Shoreland Zo	ne?			Yes N	lo 🗌 Unknown
Comments:					
Source of Section II information:	S	cller			

Buyer Initials _____ ____

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

PROPERTY LOCATED AT: 394 Main St, Westbrook, ME 04092

SEC	CTION III – HEATI	NG SYSTEM(S)/H	EATING SOURCE(S	
Heating System(s) or Source(s)	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
TYPE(S) of System	FHW		51512115	5151LM +
Age of system(s) or source(s)	7 Vears old			
TYPE(S) of Fuel	Oil			
Annual consumption per system				
or source (i.e., gallons, kilowatt	Top II.			
hours, cords)	500 gallons			
Name of company that services system(s) or source(s)	Private Servicer			
Date of most recent service call	October 2023			
Malfunctions per system(s) or	None			
source(s) within past 2 years	loone			
Other pertinent information	None			
	10 0000			
Are there fuel supply line	×s?		Vec	🕈 No 🗌 Unknown
Are any buried?				
				No Unknown
Are all sleeved?				_ No _ Unknown
Chimney(s):				No
				No 🔀 Unknown
Is more than one heat	source vented through	one flue?	Yes	🖌 No 🔄 Unknown
Had a chimney fire:			Yes	No 🗌 Unknown
Has chimney(s) been	inspected?		X Yes	No Unknown
If Yes, date:	5 years +- ago			
Date chimney(s) last	cleaned:	None		
Direct/Power Vent(s):			Yes	No 🗌 Unknown
	ected?			No Unknown
If Yes, date:				
Source of Section III info	rmation	C. //		
Source of Section III IIIIo		Jeller		
		– HAZARDOUS N		
The licensee is disclosing	, that the Seller is maki	ng representations of	contained herein.	
A. UNDERGROUND	STORAGE TANKS	- Are there now,	or have there ever be	en, any underground
storage tanks on the prop	erty?		Yes	🖌 No 📋 Unknown
If Yes, are tanks in currer	1t use?		Yes	No Unknown
If no longer in use, how long have they been out of service?				
If tanks are no longer in u			to DEP? Yes	No Unknown
				No Unknown
Age of tank(s):	Siz	te of tank(s):		
Are tanks registered with Age of tank(s): Location:				
			(N)	PAN
Buyer Initials	h Lone Wolf Transactions (zipForm Editi	Page 3 of 7	Seller Initials	

What materials are, or were, stored in the tank(s)?		
Have you experienced any problems such as leakage:	Yes	🗌 No 🗌 Unknown
Comments:		
Source of information: Seller is unaware of any tank	5	
B. ASBESTOS – Is there now or has there been asbestos:		
As insulation on the heating system pipes or duct work?	Yes	🕅 No 🗌 Unknown
In the ceilings?	Yes	🗌 No 🔀 Unknown
In the siding?	Yes	🔀 No 🗌 Unknown
In the roofing shingles?	Yes	No 🗌 Unknown
In flooring tiles?	Yes	🗙 No 🗌 Unknown
Other:	Yes	📈 No 🗌 Unknown
Comments: No known as best os in puilding		
Source of information: $\underline{\bigcup e(ler)}$		
C. RADON/AIR - Current or previously existing:	<u> </u>	
Has the property been tested?	Yes	No Unknown
If Yes: Date: By:		
Results:		
If applicable, what remedial steps were taken?		
Has the property been tested since remedial steps?	Yes	No Unknown
Are test results available?	Yes	No
Results/Comments:		
Source of information:		
D. RADON/WATER - Current or previously existing:		
Has the property been tested?	Yes	🔀 No 🗌 Unknown
If Yes: Date: By:		
Results:		
If applicable, what remedial steps were taken?	3	
Has the property been tested since remedial steps?	Yes	No Unknown
Are test results available?	Yes	No No
Results/Comments:		
Source of information:		
E. METHAMPHETAMINE - Current or previously existing:	Yes	No 🗌 Unknown
Comments:		
Source of information:		
	(MIL	1 BAM
Buyer Initials Page 4 of 7 Seller Initials	itials V	(
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 7520	www.lwolf.com	Morse

F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in homes constructed prior to 1978)
Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property?
If Yes, describe location and basis for determination:
Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes H No
If Yes, describe:
Are you aware of any cracking, peeling or flaking paint?
Comments:
Source of information:
G. OTHER HAZARDOUS MATERIALS - Current or previously existing:
TOXIC MATERIAL:
LAND FILL:
RADIOACTIVE MATERIAL:
Other:
Source of information:
Buyers are encouraged to seek information from professionals regarding any specific issue or concern.

SECTION V - GENERAL INFORMATION

Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of
first refusal, life estates, private ways, trails, homeowner associations (including condominiums
and PUD's) or restrictive covenants? Unknown
If Yes, explain: <u>Ntighbor in back of property claiming eminent domain up to covront fonce</u> . Source of information: <u>Sellers</u>
Source of information: Sellers
Is access by means of a way owned and maintained by the State, a county, or a municipality
over which the public has a right to pass?
If No, who is responsible for maintenance?
Road Association Name (if known):

Buyer Initials _____ Page 5 of 7

RAM Seller Initials Morse

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.wolf.com

Are there any tax exemptions or reductions for this property for any reason in	ncluding b	ut not limited to	0:
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Bli			
	Yes		Unknown
If Yes, explain:		()	
Is a Forest Management and Harvest Plan available?	Yes	No 🗌	Unknown
Is house now covered by flood insurance policy (not a determination of flood zone	e) Ves	No	Unknown
Equipment leased or not owned (including but not limited to, propane tax	nk, hot wa	ater heater, sate	ellite dish,
water filtration system, photovoltaics, wind turbines): Type:			
Year Principal Structure Built: 1930 Seller believes			
What year did Seller acquire property?			
Roof: Year Shingles/Other Installed:			
Water, moisture or leakage:			
Comments: Heart als and water table Atortati	- Ors		
Foundation/Basement:			
Is there a Sump Pump?	X Yes	No 🗌	Unknown
Water, moisture or leakage since you owned the property:	🗶 Yes	No 🗌	Unknown
Prior water, moisture or leakage?	X Yes	No	Unknown
Comments: Heavy rais and water table fluct	vations		
Mold: Has the property ever been tested for mold?	Yes	No 🗌	Unknown
If Yes, are test results available?	Yes	No No	
Comments:			
Electrical: 🗌 Fuses 🔀 Circuit Breaker 🗌 Other:			Unknown
Comments:			
Has all or a portion of the property been surveyed?	Yes	No 🗌	Unknown
If Yes, is the survey available?	Yes	No 🗍	Unknown
Manufactured Housing – Is the residence a:			
Mobile Home	Yes	No 🗌	Unknown
Modular	Yes		Unknown
Known defects or hazardous materials caused by insect or animal infestation	inside or o		
-	Yes		Unknown
Comments:		4 -	
KNOWN MATERIAL DEFECTS about Physical Condition and/or value of	Property,	including those	e that may
Comments:			
Source of Section V information:			
	Non	MRAM	
Buyer Initials Page 6 of 7 Seller Initials	511		
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 7520	1 <u>www.lwolf.com</u>	Μ	lorse

SECTION VI - ADDITIONAL INFORMATION

Set additional information a Hached

ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL

Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer.

Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building, electrical or plumbing.

As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition.

SELLER	E 26/20Z4	SELLER	5-26-2024
Roger A. Morse	DATE	Carol Jo Morse	DATE
SELLER	DATE	SELLER	DATE

I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns.

BUYER	DATE	BUYER	DATE
BUYER	DATE	BUYER	DATE
REALTOR® Maine Association of REAL All Rights Reserved. Revised	EQUAL HOUSING DPPORTUNTY		
Produced with Lone Wolf	Transactions (zipForm Edition) 717 N Harwo	od St. Suite 2200. Dallas, TX, 75201 www.lwolf.com	Morse

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

SCOPE OF WORK: 394 MAIN STREET, WESTBROOK, ME

Existing mid to early twentieth century single story retail building with full basement needs structural repairs. The following is a preliminary plan of the necessary improvements.

<u>INTERIOR</u> structural repair on south wall: Two thirds of the south wall has a sloped top of foundation wall. The floor joists are notched, sit directly on the concrete and are below grade resulting in rotted joist ends. See photo of current condition showing the notched joists sitting directly on foundation wall.

- Install 2x6 pressure treated ledger on the full length of the existing concrete basement wall with expansion bolt anchors.
- Sister pressure treated 2x8's to each of the floor joists (that are notched and or rotted) and bear on the ledger. All existing joists that are solid should be shimmed to also bear on the ledger. Secure each joist to ledger with galvanized metal tie down. Plan on reinforcing (20) 2x10 floor joists. See photo of current condition showing the notched joists sitting directly on foundation wall

<u>EXTERIOR</u> repairs to wall sheathing where below grade: Approximately 24 linear feet on the east wall and approximately 24 linear feet on the south wall are 12 inch (+/-) below grade and assumed to be rotted. It does not appear to have a perimeter rim joist. See photo of current exterior condition.

- Pull crushed stone drip edge and filter fabric back to expose sub-grade conditions.
- Remove vinyl siding below grade to expose original siding and sheathing. Where siding and sheathing is below grade, replace with pressure treated lumber so that vinyl siding will be continuous with other vinyl siding when replaced.
- · Replace/reinstall vinyl siding to match existing.
- Reinstall filter fabric and stone drip edge. Maintain existing stone drip edge slope to drain.



Existing joist seat at basement wall



South wall prior to installed stone drip edge