

AVAILABLE - ±16,274 to 22,308 SF FLEX/INDUSTRIAL

18475 BANDILIER CIRCLE | FOUNTAIN VALLEY, CA



PROPERTY FEATURES:

- » ±22,308 SF Flex/Industrial Building with ±9,881 SF of Single-Story Office (Can be Reduced)
- » Divisible to 16,274 SF with ±7,851 SF of Office (Can be Reduced)
- » High-Image Building with Extensive Glass-line
- » High Identity, Located on the Corner of Ellis Avenue and Bandilier Circle
- » Two (2) Ground Level Loading Doors
- » Immediate Access to San Diego (405) Freeway
- » 400 Amps of Power (Verify)
- » Near Coastal Communities and Irvine Business Complex
- » 2:1 Car Parking Ratio
- » 18' Warehouse Clearance
- » Fire Sprinklers



CONTACT US: -

PAT LACEY Executive Director (714) 875-4134 pat@tidemarkrealestate.com

DRE 00988663

TAYLOR SNYDER, MBA **Senior Vice President** (949) 533-1321 taylor@tidemarkrealestate.com DRE Lic. 02092420


WILL GREUBEL Senior Vice President (714) 614-7623 will@tidemarkrealestate.com DRE Lic. 02039807

JIM SNYDER, CCIM, CPM® **Chief Executive Officer** (949) 533-1190 jim@tidemarkrealestate.com DRE 00872220



DISCLAIMER: The information contained herein has been obtained from the property owner or other third party and is provided to you without verification as to accuracy. We (Tidemark Real Estate Services, Inc., its brokers, employees, agents, principals, officers, directors and affiliates) make no warranty or representation regarding the information, property, or transaction. You and your attorneys, advisors and consultants should conduct your own investigation of the property and transaction.





ELLIS AVENUE

CONTACT US:

PAT LACEY Executive Director (714) 875-4134

pat@tidemarkrealestate.com DRE 00988663

Real Estate Services

TAYLOR SNYDER, MBA Senior Vice President

(949) 533-1321 taylor@tidemarkrealestate.com DRE Lic. 02092420

WILL GREUBEL Senior Vice President

(714) 614-7623 will@tidemarkrealestate.com DRE Lic. 02039807

JIM SNYDER, CCIM, CPM® **Chief Executive Officer**

(949) 533-1190 jim@tidemarkrealestate.com DRE 00872220

DISCLAIMER: The information contained herein has been obtained from the property owner or other third party and is provided to you without verification as to accuracy. We (Tidemark Real Estate Services, Inc., its brokers, employees, agents, principals, officers, directors and affiliates) make no warranty or representation regarding the information, property, or transaction. You and your attorneys, advisors and consultants should conduct your own investigation of the property and transaction.