



REMOVE SILL BEAM & FLOOR,
REMOVE ALL WOOD BLOCKING IN WALL.
REPLACE & REPAIR 4" BRICK WITH 4" ALONG ENTIRE WALL.

OPEN EXIST'G BLOCKED UP M.D.
RELOCATE WOOD WINDOW

REMOVE WINDOW CLOSE OPEN'G
W/ MASONRY & METAL STUD

NEW SOUTH STAIR (1 HOUR RATED)
SEE PLAN BLOW-UP SHEET A-14

SEE SHEET A-11 REGARDING BRIDGING
ALTERNATES FOR EXIST'G WOOD WINDOWS

NEW WOOD HANDRAIL @ 24" ABV.
NOSHING EDGE OF EACH SIDE OF EXIST'G
STAIR, PROVIDE TYP. EXTENSIONS.
NEW 42" AFF GUARD @ EXIST'G LANDING

REWORK & REGLAZE EXIST'G ALUM & GLASS
WINDOWS W/ NEW 1" INSULATING GLASS
& ALUM STOPS SEE SHEET A-11

RELOCATE INTERIOR BRICK SILL
REPAIR & TUCK-POINT LOOSE BRICK
WHERE WALL MEETS FLOOR

SECOND FLOOR
1/8" = 1'-0"

SELF FUNDED PLANTS INC.	
1432 HAMILTON AVE. CLEVELAND	
HENRY PIPER, ARCHITECT	
2ND FLOOR	A-5