

said Herrick tract, in all, 1141-29/100 feet to a 5/8 inch iron rebar found with an aluminum disk stamped Texas Department of Transportation Mon. No." found for the northeast corner of said State of Texas Parcel 24, and being in the south line of a tract described in the deed to the State of Texas. Parcel 25. recorded in Document Number 2011-20238 of said Official Public Records, and being the northwest corner of said Herrick tract.

Thence south 73 degrees-09 minutes-35 seconds east (deed call is south 73 degrees-10 minutes-21 seconds east) along the south line of said State of Texas Parcel 25, for the north line of said Herrick tract, at 34-90/100 feet pass a 5/8 inch iron rebar found with an aluminum disk stamped Texas Department Transportation Mon. No." found for the southeast corner of said State of Texas Parcel 25, from said 5/8 inch iron rebar found, another 5/8 inch iron rebar found bears north 28 degrees-40 minutes east 1-8/10 feet, and then continue along the north line of said Herrick tract, for the south line of said Standard tract, (deed call is south 73 degrees-09 minutes-45 seconds east), in all, 719-30/100 feet to the place of BEGINNING and containing 19-46/100 acres, as surveyed

NOTES :

The following easements do not appear to affect this lot: Volume 760, Page 377 and Volume 2022, Page 79 Bell County Deed Records.

The research for the land boundary property line of this tract has been provided by this surveyor or his associates. That research includes the names and references to the adjoining property owners. Those adjoining referenced are for compliance to the Texas Board of Professional Land Surveyors regulations, and are shown for information purposes only. All other research for documents such as, but not limited to, easements, deed restrictions, restrictive covenants, leases, etc. are the responsibility of the client's Title Company or other third parties other than this surveyor or company

Basis of Bearing: The survey work for this project is on Grid Bearings and Coordinates, based upon the Texas State Plane Coordinate System, Central Zone, NAD83 datum obtained from GPS observations and referenced to the SMARTNET NETWORK OF NORTH AMERICA, Base Station "TXTC" at Temple College in Temple, Texas whose published coordinate value: N=10,366,800.432 E=3,229,831.029. The distances shown are surface distances. The Combined Correction Factor (CCF) for this project is 0.9998585.

Copyright © 2023, Ronald Carroll Surveyors, Inc., All Rights Reserved. This survey was provided solely for the use of Herrick Properties, LLC.

Title Commitment by Heritage Title Co. and First American Title Insurance Co. GF No. 202301307 Effective Date May 1, 2023.

ALTA TABLE "A"

- 1. Monuments are noted and shown.
- Site address per Lamar Sign lease (Document Number 2015-00041408) is 5633 South IH 35, Belton, Texas 76513.

3. This Property is located in Flood Zone "X" (Areas determined to be outside the 0.2% annual chance Floodplain). Number 48027C0340E Panel No. 340, Community No. 480028. City of Belton, Tx. Having an effective date of September 26, 2008. This statement does not imply this lot will never flood nor does it create liability on the part of this surveyor or company in such an event.

4. 19.46 Acres

6(a). No zoning report provided.

7(a, b1 & c). No buildings were observed on subject site.

8. Billboard shown on survey.

9. No parking lots on site.

11(a). Texas 811 Ticket # 2258914408 / Dated March 30, 2022 / Members contacted:

CTL Century link: Phone, cable & fiber; Located off site BET City of Belton: Water line; Located

BET City of Belton: Sewer; located offsite

TM2 Oncor Electric Distribution: Electric; Located The underground utilities shown have been located from a field survey of above ground markings placed by the above mentioned Texas 811 members. This surveyor or company makes no guarantees that the underground utilities shown comprise all such utilities in the area, either in service or abandoned. The surveyor further does not warrant that the underground utilities shown are in the exact location indicated although the surveyor does state that

they are located as accurately as possible from the information available. The surveyor has not physically located the underground utilities. Before any digging call 1-800-DIG-TESS.

13. Adjoiners names are shown on survey.

14. Distance to nearest street provided on survey.

CERTIFICATE OF SURVEYOR

To Herrick Properties, LLC.; Heritage Title Co. and First American Title Insurance Co.

This is to certify that this map or plat and the survey on which it is based were made in accordance with the "Minimum Standard Detail Requirements for ALTA/ACSM Land Title Surveys," jointly established and adopted by ALTA and NSPS in 2021, and includes Items, 1-4, 6(a), 7(a), 7(b1), 7(c), 8-9, 1 (a), 13-14 of Table A thereof. Pursuant to the Accuracy Standards as adopted by ALTA and NSPS and in effect on the date of this certification, undersigned further certifies that in my professional opinion, as a Land Surveyor registered in the State of Texas, the Relative Positional Accuracy of this survey does not exceed that which is specified therein.

*Note: The word "certify" or "certificate" used hereon constitutes an expression of professional opinion regarding the facts of findings, which are the subject of their certification and does not constitute a warranty or guarantee either expressed or implied.

IONALD CARR 2025 onald Carro RPLS No. 2025 -tune 29,202=

ALTA-ACSM LAND TITLE SURVEY for HERRICK PROPERTIES, LLC FELIPE MADRIGAL SURVEY, ABSTRACT NUMBER 554 City of Belton, Bell County, Texas. RONALD CARROLL SURVEYORS, INC. Phone: (254) 773-1447 Fax: (254) 773-1728

TBPELS FIRM No. 10028400

