


- 101 RECEPTION ROOM**
- 102 BUSINESS OFFICE**
- 103 CONSULTATION ROOM #1**
- 104 CONSULTATION ROOM #2**
- 105 RESTROOM #1 (EXISTING)**
- 106 STERILIZATION/STORAGE (EXISTING)**
- 107 LAB (EXISTING)**
- 108 BREAK ROOM W/CLOSET (EXISTING)**
- 109 DOCTOR'S OFFICE (EXISTING)**
- 110 CLOSET (EXISTING)**
- 111 RESTROOM #2 (EXISTING)**
- 112 TREATMENT ROOM #1 (EXISTING)**
- 113 TREATMENT ROOM #2 (EXISTING)**
- 114 TREATMENT ROOM #3 (EXISTING)**
- 115 TREATMENT ROOM #4 (EXISTING)**
- 116 TREATMENT ROOM #5 (EXISTING)**
- 117 TREATMENT ROOM #6 (EXISTING)**
- 118 TREATMENT ROOM #7 (EXISTING)**
- 119 TREATMENT ROOM #8 (EXISTING)**
- 120 TREATMENT ROOM #9 (EXISTING)**
- 121 TREATMENT ROOM #10 (EXISTING)**
- 122 X-RAY ROOM (EXISTING)**
- 123 RESTROOM #3**
- 124 CONSULTATION ROOM #3**
- 125 SEATING AREA**

All Vacuum and Compressor units must be installed and operated in a thermostatically or otherwise stable ambient temperature environment. Forced air and HVAC input must be used in addition to an exhaust fan in order to regulate ambient temperatures of the room which houses these pieces of equipment.



A NEW DENTAL OFFICE FOR
DR. LATTA
GREENVILLE, SC
EQUIPMENT SPECIALIST: CLAY RICKMAN

001 010 0333
FAX 864-676-0041

—g Ben Hanby Drive
enville, SC 29615

103

EQUIPMENT SPECIALIST: CLAY RICKMAN

PREFACED BY A LICENSED ARCHITECT OR ENGINEER. CONCUL LOCAL AUTHORITIES
CONTRACTOR SHALL COMPLY WITH ALL STATE AND LOCAL CODES PERTAINING TO
THE CONSTRUCTION OF THIS PROJECT.

-DI

2011

RICK LF.

11

100

10

111

01

1

2

10

FP-001