

W/ WHITE COVER PLATES.

14) PATCH AND REPAIR ALL WINDOW SILLS TO REMAIN.

NOTES:

- DRAWINGS SHALL BE DONE IN
 ACCORDANCE TO APPLICABLE BUILDING
 CODES, LOCAL ORDINANCES AND
 THE STANDARDS OF OSHA AND THE
 NATIONAL BOARD OF HE UNDERWRITERS,
 2) AT LOCATIONS OF MASONIRY
 OPENINGS, RAISE HEAD OF OPENING,
 TO 8'0" AFF, ADJUST, WIDTH OF
 OPENING AS NOTED.
- 3.) CODE ANALYSIS:

 THE SECOND PLOOR OF 50 FRANKLING
 STREET IS APPROX, [2,000 \$ GROSS
 AREA SERVED BY Z INDEPENDENT
 STAIRWELLS, THE BUILDING IS
 FULLY SPRINKLERED AND IS IN
 THE CATAGORY OF TYPE 3B
 CONSTRUCTION, THERE IS NO
 REQUIREMENT TO PROVIDE 1 HR
 SEPARATION BETWEEN TENANTS
 IN THIS BUILDING TYPE.
- THE USE OF THE SPACE BEING,
 RENOVATED IS BUSINESS (B)
 WITH A POPULATION NOT TO EXCEED
 120 PEOPLE, BASED ON TABLE
 1008.1.2 OF THE STATE BUILDING
 CODE.
- SANATARY FACILITIES SHOWN WILL PROVIDE FOR GO WOMEN AND 75 MEN AS WELL AS MEET ALL ACCESSIBILITY REQUIREMENTS
- 4.) THIS IS A DESIGN-BUILD PROJECT.
 ELECTRICAL & LIGHTING AS WELL
 AS PLUMBING, HEATING &
 MECHANICAL SYSTEMS SHALL BE
 DESIGNED AND INSTALLED THROUGH
 THE GENERAL CONTRACTOR WHO
 WILL BE RESPONSIBLE FOR
 SATISFACTORY PERFORMANCE AS
 PER CODE AND GOOD ACCEPTABLE
 INSTALLATION METHODS, ALL
 SYSTEMS ARE EXPECTED TO BE
 COMPLETE AND TOTALLY FUNCTIONAL
 AT THE COMPLETION OF WORK
 PREPARED BY ENERGY SYSTEMS
 DESIGN INC., DATED 21 SEPT, OS
 FOR SPECIFIC HVAC GUIDE LINES.
- 5.) REFURBISH ALL WINDOWS TO FULL WORKING ORDER, REPLACE PALANCES AND REPAIR DAMAGED SASH FRAMES AS REQ D,

NUMBER: DATE: DESCRIPTION

REVISIONS:

PAUL MAGGI ASSOCIATES

ARCHITECTURE D INTERIOR DESIGN

303 LANE ROAD HOLDERNESS, NH 03245 603.968.3242 Tel 603.968.7613 Fax

66 LONG WHARF BOSTON, MA 02110 617.723.3996 Tel 617.723.3709 Fax

SCALE 16" = 1-0"
DATE OCT 19 2005
DRAWN P.C.M.
CHECKED

PROJECT NO.

SECOND FLOOR REMOVATION 50 FRANKLIN STREET BOSTON, MA.

FLOOR PLAN

A.2