




FOR LEASE - ±10,224 SF INDUSTRIAL

11240 YOUNG RIVER AVENUE | FOUNTAIN VALLEY, CA



PROPERTY FEATURES:

- » ±10,224 SF Freestanding Industrial Building
- » ±2,525 SF of Office
- » Two (2) 12'x12' Ground Level Loading Doors
- » Secured Yard/Parking Area
- » ±14' Warehouse Clear Height
- » 2:1 Car Parking Ratio
- » Warehouse Skylights
- » 600 Amps 120/208 Volt Power with a 480 Volt Transformer (verify)
- » Corner Location with Monument Sign
- » Great South Coast Metro Location and Good Access to the San Diego (405) Freeway



CONTACT US:

PAT LACEY
Executive Director

(714) 875-4134
pat@tidemarkrealestate.com
DRE Lic. 00988663

TAYLOR SNYDER, MBA
Senior Vice President

(949) 533-1321
taylor@tidemarkrealestate.com
DRE Lic. 02092420

WILL GREUBEL
Senior Vice President


(714) 614-7623
will@tidemarkrealestate.com
DRE Lic. 02039807

STEPHEN MARGARETIS
Senior Associate


(949) 439-1988
stephen@tidemarkrealestate.com
DRE Lic. 02112014

TIDEMARK
Real Estate Services


DISCLAIMER: The information contained herein has been obtained from the property owner or other third party and is provided to you without verification as to accuracy. We (Tidemark Real Estate Services, Inc., its brokers, employees, agents, principals, officers, directors and affiliates) make no warranty or representation regarding the information, property, or transaction. You and your attorneys, advisors and consultants should conduct your own investigation of the property and transaction.



EXISTING FLOOR PLAN



HYPOTHETICAL FLOOR PLAN



CONTACT US:

PAT LACEY
Executive Director
(714) 875-4134
pat@tidemarkrealestate.com
DRE Lic. 00988663

TAYLOR SNYDER, MBA
Senior Vice President
(949) 533-1321
taylor@tidemarkrealestate.com
DRE Lic. 02092420

WILL GREUBEL
Senior Vice President
(714) 614-7623
will@tidemarkrealestate.com
DRE Lic. 02039807

STEPHEN MARGARETIS
Senior Associate
(949) 439-1988
stephen@tidemarkrealestate.com
DRE Lic. 02112014

TIDEMARK
Real Estate Services

DISCLAIMER: The information contained herein has been obtained from the property owner or other third party and is provided to you without verification as to accuracy. We (Tidemark Real Estate Services, Inc., its brokers, employees, agents, principals, officers, directors and affiliates) make no warranty or representation regarding the information, property, or transaction. You and your attorneys, advisors and consultants should conduct your own investigation of the property and transaction.