


THIS PROPERTY DOES NOT LIE WITHIN THE
100 YEAR FLOOD PLAIN AS ESTABLISHED
BY THE U.S. DEPT. OF HOUSING & URBAN
DEVELOPMENT.
COMMUNITY/PANEL NO. 48201C 0235 M
MAP REVISION: 10/16/2013
ZONE X

A SUBSURFACE INVESTIGATION WAS BEYOND THE SCOPE OF THIS SURVEY



JAMES E. MOSLEY
NO. 1912
DRAWMAN NO. 22-01330
JANUARY 21, 2022

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE
ON THE GROUND, THAT THIS PLAT CORRECTLY
SHOWS THE LOCATION OF THE SURVEYED
TIME OF SURVEY AND THAT THERE ARE NO
ENCUMBRANCES APPEARING ON THE GROUND
CERTIFIED FOR THIS TRANSACTION ONLY AND
ABSTRACTING PROVIDED IN THE ABOVE
DECLARATION. I HAVE NOT BEEN AWARE OF ANY
VIOLATION OF THE PROVISIONS OF THIS SURVEY.




PRECISION SURVEYORS

PROFESSIONAL LAND SURVEYORS

1-800-LANDSURVEY
www.precision-surveyors.com

281-496-1586
281-496-1588
800 INDEPENDENT STREET SUITE 100 HOUSTON, TEXAS 77059
210-828-6444 FAX 210-828-1505
1100 N. GARDNER STREET HOUSTON, TEXAS 77061
FILE CODE NO. 100637000



A.C.I. & ARCHITECTURAL COMPANY, L.P.
10000 WESTHEIMER ROAD HOUSTON, TEXAS 77060
DRAWING BY: JES