

RECENT IMPROVEMENTS:

New Gas Split Heat and Air Unit

New Roof

New Exterior Walls

New Insulated interior walls covered with wood instead of standard plastic covering for metal buildings.

All new wiring including new conduit and new lights, 110 plugs throughout.

2 New power panels and plumbed to run 3 phase power.

New office and ½ bathroom.

New sidewalk entrance.

New 8-inch interior support posts and new engineered beams for roof support.