Curve Table					
Curve #	Length	Radius	Chord		
C1	10.31	238.00'	N18*20'39"E 10.31'		
C2	13.90'	262.00'	N18'03'54"E 13.90'		
С3	310.19	761.50	N04°52'33"E 308.05'		

Line Table				
Line #	Direction	Length		
L1	S72°53'48"E	42.05		
L2	S16°41'54"W	150.00'		
L3	S72°53'48"E	150.00'		
L4	S16°41'54"W	98.93'		
L5	S73°17'59"E	22.00'		
L6	S16°43'25"W	112.71		
L7	N27°53'48"W	14.14		
L8	N19°35'05"E	138.76		
L9	N05°53'37"W	21.64		

1/2" IRON ROD WITH

— CAP STAMPED "RPLS
2475" FOUND UNLESS
OTHERWISE MENTIONED

0.912 ACRES 14.522 ACRES N72°53'48"W 580.75' 33

BEING a 14.522 acre tract of land more particularly described by separate field notes.

BEING a 14.522 acre tract of land situated in the BALDWIN ROBERTSON SURVEY, ABSTRACT No. 17, Bell County, Texas and being a part or portion of Lot 1, Block 1, First Baptist—Temple West Campus according to the map or plat of record in Cabinet D, Slide 354—B, Plat Records of Bell County, Texas and being a part or portion of that certain 74.067 acre tract of land (TRACT TWO) described in a Special Warranty Deed dated December 15, 2020 from First Baptist Church, Temple, Texas, a Texas non—profit corporation to FBC Sanders, LLC, a Texas limited liability company and being of record in Document No. 202000070140, Official Public Records of Bell County, Texas.

MICHAEL E. ALVIS D

5402

WO SURVESTION

STATE OF TEXAS \(\) KNOW ALL MEN BY THESE PRESENTS, that I Michael E. Alvis, a Registered Professional Land Surveyor in the State of Texas, do hereby certify to JJABC, LP that this survey was this day made on the ground of the property described herein and is correct and that there are no discrepancies, conflicts, shortages in the area, easements, and right—of—ways except as shown hereon, that this tract of land has access to and from a public road, and I have marked all corners with monuments. This Survey substantially complies with the current Texas Society of Professional Surveyors Manual of Practice requirements for a Category 1B, Condition 3, TSPS Land Title Survey.

This Property is not within the Special Flood Hazard Area as per the Federal Emergency Management Agency Federal Insurance Administration Map No. 48027C0335E, dated September 26, 2008.

IN WITNESS THEREOF, my hand and soal, this the 31st day of March 2022.

Michael E. Alvis, R.P.L.S., No. 5402

TURLEY ASSOCIATES, INC.

ENGINEERING. PLANNING. SURVEYING
254.773.240

TEMPLE, TEXAS 7650

TBPE No. F-1658 · TBPLS No. 10056000

© TURLEY ASSOCIATES, INC.
THIS DRAWING IS THE
PROPERTY OF TURLEY
ASSOCIATES INC. AND MUST
BE SURRENDERED UPON
REQUEST. THE INFORMATION
THEREON MAY NOT BE
REPRODUCED WITHOUT THE
WRITTEN PERMISSION OF
TURLEY ASSOCIATES INC.

SURVEY OF:
14.522 ACRES
BALDWIN ROBERTSON SURVEY
ABSTRACT NO. 17
BELL COUNTY, TEXAS
PREPARED FOR:
FBC SANDERS

REVISIONS					
	DESCRIPTION	DFTR			
4/11	ADD NOTES FOR TITLE	ZMN			
DRAFTSMAN:					
ZMN					
DATE:					
3/24/2022					
COMPUTER FILE NAME:					
20-3294					
REFERENCE DRAWING NUMBERS:					

JOB NUMBER: # 20—3294 C 203294—C 1

GF# 22-1382, PROPOSED INSURED: JJABC, LP.

The following documents affect this lot:
Doc.# 2019-00026035
Doc.# 2020070140

The following documents do not affect this lot: Doc.# 2012-00051906 Volume 3539, Pg. 81 Doc.# 2013-00016413 Doc.# 2015-00005619 Doc.# 2022009376

The following document is a blanket easement and are non-locatable by description.
Volume 1018, Pg. 495

NOTES CORRESPONDING TO SCHEDULE "B":

10(A). TRAIL EASEMENT 20 FEET IN WIDTH ALONG THE WEST PROPERTY LINE(S), AS REFLECTED BY THE RECORDED PLAT OF SAID SUBDIVISION. (TRACT 1) DOES NOT AFFECT THIS PROPERTY.

10(B). SIDEWALK EASEMENT 20 FEET IN WIDTH ALONG THE PROPERTY LINE(S), AS REFLECTED BY THE RECORDED PLAT OF SAID SUBDIVISION. (TRACT 1) DOES NOT AFFECT THIS PROPERTY.