

## Other Options

[Go to GWIC website](#)  
[Plot this site in State Library Digital Atlas](#)  
[Plot this site in Google Maps](#)  
[View scanned well log \(9/3/2009 1:30:47 PM\)](#)

## Section 7: Well Test Data

Total Depth: 38  
Static Water Level: 21.05  
Water Temperature:

## Section 1: Well Owner(s)

1) MANN, WILLIAM (MAIL)  
79 SWEEBEE LANE  
COLUMBIA FALLS MT 59912 [01/21/2001]

## Section 2: Location

Township	Range	Section	Quarter Sections
30N	21W	24	NW¼ NE¼ SE¼ SW¼
County			Geocode

Depth pump set for test    feet.  
40 gpm pump rate with    feet of drawdown after 1 hours of pumping.  
 Time of recovery 0.08 hours.  
 Recovery water level 21.05 feet.  
 Pumping water level 21.2 feet.

## FLATHEAD

<b>Latitude</b>	<b>Longitude</b>	<b>Geomethod</b>	<b>Datum</b>
48.344993	-114.232511	TRS-SEC	NAD83
<b>Ground Surface Altitude</b>	<b>Ground Surface Method</b>	<b>Datum</b>	<b>Date</b>

Addition	Block	Lot
BRUNER TRACTS	9	

### Section 3: Proposed Use of Water

DOMESTIC (1)

## Section 4: Type of Work

Drilling Method: CABLE  
Status: NEW WELL

### Section 5: Well Completion Date

Date well completed: Sunday, January 21, 2001

## Section 6: Well Construction Details

### Borehole dimensions

From	To	Diameter
0	38	6

## Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
-2	28	6	0.250			STEEL
25	38	5	0.250			STEEL

**Completion (Perf/Screen)**

From	To	Diameter	# of Openings	Size of Openings	Description
28	33	5			.014 STNLESS STL SCREENS

### Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	0	CONT FED BENTONITE	

### Section 8: Remarks

## Section 9: Well Log

### Geologic Source

Unassigned

[illegible]

### Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name:

**Company:** ERICKSON DRILLING & PUMP CO

**License No:** WWC-478

**Date Completed:** 1/21/2001