2000 Teall Ave Enhancements:

- * New Parking Lot- repaired and repaved
- * New Parking Lot- sealed and striped
- * Building Exterior Painted
- * Interior Lighting improved
- * Three New RTU Heating & Air Conditioning
- * Entire Roof & Flashing Replaced
- * Entire Property Landscaped
- * Lobby Remodeled
- * All Bathrooms Remodeled
- * Lobby Remodeled
- * Entire Property Landscaped
- Ninety Percent of Building has New Carpeting & Flooring
- * New Awning / Canopy Overhang
- * Remodeled Stairways and 2nd Floor Landing- Flooring / Paneled Walls
- * Majority of Building Repainted