ESTIMATE

Diamond Property Services Inc. Dpservices1911@gmail.com 131-55 224th st Springfield Gardens, NY 11413

+1 (917) 624-7873

Michelle Cooper-Jackson

Bill to

Michelle Cooper-Jackson 6 Dovecote Lane Commack, NY 11725

Ship to

Michelle Cooper-Jackson 6 Dovecote Lane Commack, NY 11725

Estimate details

Estimate no.: 1083 Estimate date: 02/28/2024

#	Date	Product or service	SKU	Qty	Rate	Amount
1.		Service		1	\$0.00	\$0.00
		Estimate for:				
		Miss Shelly's Upward Prep				
		82 Nassau Rd Roosevelt, Ny				
2.		Service		1	\$5,750.00	\$5,750.00
		-Replace pulled down ceiling tiles in classro class	ooms and office areas, as new installation	of tracks ar	nd ceiling tiles fo	r basement
3.		Service		1	\$8,750.00	\$8,750.00
		- Replace baseboard radiators that were c test	eut out of all classrooms, office spaces an	d hallways a	nd then perforn	n a pressure
4.		Service		1	\$6,750.00	\$6,750.00
		Reconnect all sprinkler pipes and perform (Price may change if there are faulty pipes	•			
5.		Service		1	\$3,200.00	\$3,200.00
		Deep Sales Clean of the entire building, inc mildew resistant	luding scrubbing down mold growth on th	e lower level	l and treating it v	with mold and
6.		Service		1	\$2,100.00	\$2,100.00
		Repair Chain link fencing up to 75ft				
7.		Service		1	\$15,500.00	\$15,500.00
		Renovate the bathroom on the lower level,	to include new stalls and go from previous	s layout unle	ss informed oth	erwise,
		Includes two smaller bathrooms on lower le	evel as well			
8.		Service		1	\$7,650.00	\$7,650.00
		Repair Hvac units that are currently pulled	down and replace the necessary wiring f	or the units		

9.	Service		1	\$8,500.00	\$8,500.00		
	Basic labor to install vinyl tile flooring with favorable site conditions. La subfloor. Cut, fit and attach vinyl tile. Includes planning, equipment and setup and cleanup. (Open area in lower level)	, ,					
10.	Service		1	\$750.00	\$750.00		
	Repair Damaged wall in lower level						
11.	Service		1	\$1,442.00	\$1,442.00		
	plumb placement. Set jamb edges flush to finished wall surface. Secure unit to rough opening framing. Insulate perimeter and secure house wrap at window as appropriate. Repair of exterior and interior surfaces is not included. Includes planning, equipment and material acquisition, area preparation and protection, setup and cleanup.						
				ided. Includes	planning,		
12.	equipment and material acquisition, area preparation and protection, s			1ded. Includes			
12.	equipment and material acquisition, area preparation and protection, s						
	equipment and material acquisition, area preparation and protection, s Service 10% Overhead \$5895				\$11,790.00		
	equipment and material acquisition, area preparation and protection, s Service 10% Overhead \$5895 10% Profit \$5895	setup and cleanup.	1	\$11,790.00 \$0.00	\$11,790.00 \$0.00		
	equipment and material acquisition, area preparation and protection, s Service 10% Overhead \$5895 10% Profit \$5895 Service	setup and cleanup.	1	\$11,790.00 \$0.00	\$11,790.00		
12.	equipment and material acquisition, area preparation and protection, s Service 10% Overhead \$5895 10% Profit \$5895 Service	setup and cleanup. includes all associa	1	\$11,790.00 \$0.00	\$11,790.00 \$0.00		