

1012 5th Avenue, Suite 1, Coraopolis, PA 15108 (412) 387-3330




Black Creek

Commons Apartments

Atlantic Funding & Real Estate, LLC

Front View & Side Elevations



A-201

EA JAIMESON ELLIS



Issued For Permit

Commons Apartments Black Creek

32 East Buffalo Street Churchville, NY 14626

PO Box 26350, Rochester NY, 14626


Garage & Side Elevations



SITE PLAN

JJP RJS

300 State Street | Engineering Suite 201 | Architecture Rochester, NY 14614 | Environmental P: (585) 454-6110 | Planning www.labellapc.com




1012 5th Avenue, Suite 1, Corappolis, PA 15108 (412) 387-3330


Apartments

Atlantic Funding & Real Estate, LLC

Architectural Layout
Plans - First, Second
and Third Floors

AL-101





1012 5th Avenue, Suite 1, Coraopolis, PA 15108 (412) 387-3330

reaned For Review

Black Creek Commons


Apartments
32 East Buffalo Street Church/ab, NY 14038

Atlantic Funding & Real Estate, LLC

**Building Section** 



# FIRST FLOOR - AREA PLAN



SECOND FLOOR - AREA PLAN



THIRD FLOOR - AREA PLAN

## Gross Area Schedules

1012 5th Avenue, Suite 1, Coraopolis, PA 15108 (412) 387-3330 EA JAIMESON ELLIS



TOTAL	ELECTRICAL	STORAGE	ELEV. MECH.	WATER	CHANCOCKI KOLA
6240 GSF	69 GSF	42 GSF	84 GSF	67 GSF	210 001

TYPE	UNIT COUNT	UNIT COUNT GROSS AREA FLR
UNIT 1A	1	1259 GSF
UNIT 18	_	1250 GSF
UNIT 2A	-	1204 GSF
BZ IINU	_	1319 GSF
CIRCULATION		420 GSF
TOTAL	4	5452 GSF

Issued For Permit

TOTAL	CHIHT	SECOND	FRST	FLOOR	TOTAL G
17,144 GSF	5452 GSF	5452 GSF	6240 GSF	GROSS AREA	SROSS AREA


Black Creek

Commons Apartments


Atlantic Funding & Real Estate, LLC

A-001

**Project Summary** 



Black Creek




A-101

EA JAIMESON ELLIS nue, Suite 1, Coraopcis, PA 15108 (412) 387-3330

Issued For Permit

Commons Apartments Black Creek

Atlantic Funding & Real Estate, LLC













wenue, Suite 1, Coraopolis, PA 15108 (412) 387-3330

Commons Apartments Black Creek

Atlantic Funding & Real Estate, LLC

Third Floor and Roof Plans





C-000

### Phase I Environmental Site Assessment

### Location:

Black Creek Commons 32 East Buffalo Road Tax ID 143.10-1-37.1 Churchville, New York 14428

### Prepared for:

Al Spaziano Alantic Funding Real Estate LLC PO Box 26350 Rochester, New York 14626

LaBella Project No. 2242441 Award/Client Project No. N/A

Report Date: June 11, 2024

Date of First Research: May 23, 2024





### 10.0 CONCLUSIONS

LaBella has performed a Phase I Environmental Site Assessment in conformance with the scope and limitations of ASTM Practice E 1527-21 for 32 East Buffalo Road, Churchville, New York, the Subject Property. Any exceptions to, or deletions from, this practice are described in <u>Section 1.4</u> of this report.

This assessment has revealed no recognized environmental conditions, controlled recognized environmental conditions, or significant data gaps in connection with the Subject Property.

This report constitutes the findings of LaBella's investigation conducted for the Subject Property as written and reviewed by the following personnel:

Annika Smith

**Environmental Analyst** 

Mary Beth Facklam

Phase I Technical Reviewer

Mary Beth Facklam



### 7.4 Neighbors

The Subject Property is not an abandoned property; therefore, interviews with the neighboring property owners were not conducted.

### 7.5 Local Government Official

A FOIL request was submitted to the Village of Churchville Clerk, Stacy Stanton on May 23, 2024, requesting copies of building department, assessment, and fire marshal records on file for the Subject Property. A complete response has not been received as of the date of this report. Copies of the FOIL request(s) and any obtained records are included in the Municipal Information Appendix.

### 7.6 Local Fire Department

In LaBella's experience, records from the fire department that serves the Subject Property would be included in FOIL records obtained from the local government official, as noted in <u>Section 7.5</u> above.

### 7.7 State Regulator

A FOIL request was submitted to the NYSDEC on May 23, 2024, for information regarding the Subject Property and adjacent and/or nearby properties suspected to pose a potential concern to the Subject Property based on a review of the database report and/or other regulatory records.

Records were obtained from the NYSDEC and are discussed in further detail in Sections  $\underline{6.1.1}$ ,  $\underline{6.1.2}$ , and/or  $\underline{6.1.3}$  above. Copies of the FOIL request and the documents obtained are included in the Regulatory Information Appendix.

### 7.8 State and/or County Health Department

A FOIL request was submitted to the MCHD on May 23, 2024 for information regarding the Subject Property.

As of the date of this report submission, a response has not been received. A copy of the FOIL request is included in the <u>Regulatory Information</u> Appendix.

### 7.9 Summary of Interviews

LaBella's interviews and/or review of provided records did not identify conditions indicative of the presence or likely presence of hazardous substances or petroleum products in, on, or at the Subject Property unless discussed elsewhere in this report.



### 8.0 ADDITIONAL SERVICES/ASTM NON-SCOPE CONSIDERATIONS

### 8.1 Emerging Contaminants

Hazardous substances are those defined as such pursuant to CERCLS 42 U.S.C. § 9601(14), as interpreted by USEPA regulations and the courts. There are some substances that others may assume to be classified as hazardous substances that are in fact not defined (or not yet defined) as hazardous substances under CERCLA through interpretation by USEPA regulations.

These and any other "emerging contaminants," where they are not identified as a hazardous substance by CERCLA, as interpreted by USEPA regulations and the courts, are not included in the scope of E1527-21. Some of these substances may be considered a "hazardous substance" (or equivalent) under applicable state laws. In those instances, where a Phase I ESA is performed to satisfy both federal and state requirements, or as directed by the user of the report, it is permissible to include analysis and/or discussion of these substances in the same manner as any other Non-Scope Consideration. If and when such emerging contaminants are defined as hazardous substances under CERCLA, as interpreted by USEPA regulations and the courts, such substances shall be evaluated within the scope of ASTM E1527-21.

No information was provided indicating emerging contaminant impacts to groundwater in the area of the Subject Property; however, LaBella notes that no laboratory results for emerging contaminant analysis were provided for review.



### 9.0 FINDINGS AND OPINIONS

LaBella has been contracted by Alantic Funding Real Estate LLC to perform a Phase I ESA report for the Black Creek Commons property, 32 East Buffalo Road, Churchville, Monroe County, New York.

This assessment was prepared according to the ASTM E1527-21 as a portion of the User's requirements in the All Appropriate Inquiries process and to satisfy the due diligence requirements set for Alantic Funding Real Estate LLC.

The Subject Property is further described in <u>Section 2.0</u> while the history of the Subject Property is summarized in <u>Section 5.9</u>.

Based on the results of this assessment, no RECs, HRECs, de mimimis conditions, or significant data gaps have been identified in connection with the Subject Property.

Based on the results of this assessment, the following CREC has been identified in connection with the Subject Property:

 The Subject Property was historically utilized as a parking lot for the north adjacent manufacturing/industrial facility between at least 1969 and 2019. The north adjacent property, Lustre Coate Metallizing (which historically included the Subject Property) was identified as a Brownfield/SHWS (ID#C828113/828113). This facility was used for metal film and paint coating of plastic materials. No structures remain on-site. Investigations identified elevated levels of chlorinated compounds in groundwater and PCBs in surface soils. Primary contaminants of concern include PCBs, polycyclic aromatic hydrocarbons (PAHs), 1.1.1-trichloroethane (TCA), trichloroethene (TCE), cis-1,2-dichloroethene (cis-1,2-DCE), and metals. The property is listed as an active BCP site. LaBella conducted a Remedial Investigation Supplemental Testing report dated May 11, 2021 which documented the additional testing completed on the southern (Subject Property) portion of the facility. Results of this supplemental investigation were consistent with prior investigations, supported removal of the Subject Property from the BCP, and supported a determination that conditions on-site supported restricted residential or commercial development. It was determined that based on the supplemental testing, the Subject Property did not have any consequential release of hazardous waste and thus would not be included as part of the Superfund Site. Some constituents at the Site (semi-volatile organic compounds, PCBs, metals, and per and polyfluoroalkyl substances) exceeded the Unrestricted Use soil cleanup objectives in some locations, and benzene in groundwater slightly exceeded the groundwater standard in one location. Although NYSDEC has indicated the Subject Property portion of the former Lustre Coate facility did not require further investigation or remediation at that time, it was noted that fill/soil and groundwater would require handling per applicable regulations during any future ground disturbances. Based on the investigation completed on the Subject Property



portion of this facility and the restrictions placed by the NYSDEC, this information is considered a CREC.

While not considered a REC, CREC, HREC, de minimis condition, or significant data gap at this time, LaBella also notes the following:

- One pad-mounted transformer was noted on the southeastern portion of the Subject Property at the time of the site reconnaissance. No evidence of release from this equipment was observed.
- The Subject Property, listed as Black Creek Commons, was identified as an AIR Permit site (#8264800009) related to an Air Title V permit that has expired. Due to the nature and status of the listing, there does not appear to be a REC in association with the regulatory record attached to the Subject Property.

### 9.1 Additional Investigation

Based on the findings of this assessment, no additional investigation is warranted at this time.