


(MR) MAP REFERENCE
(DR) DEED REFERENCE
(S) SURVEY
(BOS) BOTTOM OF STRUCTURE
(TOS) TOP OF STRUCTURE
(AKA) ALSO KNOWN AS
(FKA) FORMERLY KNOWN AS
(C/L) CENTERLINE
LSA LANDSCAPE AREA

× ADD SPOT FLEVATIONS CONC. MONUMENT FN CONC. MONUMENT SE I.P. / I.B. SET STAKE FND

× 0.00 SPOT ELEVATIONS imes G: 0.00 GUTTER ELEV. TC: 0.00 TOP OF CURB ELEV. FF: 0.00 FINISH FLOOR ELEV. GF: 0.00 GARAGE FLOOR ELEV.  $\times$ BW: 0.00 BOTTOM OF WALL ELEV.

DRILL HOLE FND DRILL HOLE SET SURVEY STONE FNI CROSS CUT FOUND CROSS CUT SET

STAKE SET PK NAIL FND



## DYNAMIC SURVEY, LLC

BOUNDARY & TOPOGRAPHIC SURVEY • FINAL SURVEYS HYDROGRAPHIC SURVEY • CONSTRUCTION STAKEOUT ALTA/NSPS LAND TITLE • FOUNDATION LOCATION

## 1904 Main Street, Lake Como, NJ 07719 T: 732.974.0198 | F: 732.974.3521

Offices conveniently located at: Lake Como, New Jersey • T: 732.974.0198 Chester, New Jersey • T: 732.749.8780 Newark, New Jersey • T: 732.749.8780 Toms River, New Jersey • T: 732.749.8780

Newtown, Pennsylvania • T: 267.685.0276 Priladelphia, Pennsylvania • T: 267.685.0276 Bethlehem, Pennsylvania • T: 267.685.0276 Allen, Texas • T: 972.534.2100 Houston, Texas • T: 281.789.6400 Austin, Texas • T: 512.646.2646 Delray Beach, Florida • T: 561.921.8570 Annapolis, Maryland • T: 410.567.5000

www.dynamicec.com

1923 LUMBERTON 3, LLC

BLOCK 193, LOTS 4 & 4.01 505 SHELL ROAD TOWNSHIP OF CARNEY'S POINT, SALEM COUNTY NEW JERSEY

**CRAIG BLACK** 

NEW JERSEY LICENSE No. 24GB04257400 Only copies of the original survey with an original land surveyor's embossed seal shall be considered to be valid copies. Signature and embossed seal signify that this certification was prepared in

accordance with the existing code of practice adopted by the NJ State Board of Professional Engineers and Land Surveyors.

Certifications indicated hereon shall run only to the person for whom the certification is prepared, and on his behalf to the title company, governmental agency and lending institution listed hereon.

Certifications are not transferable to additional institutions or subsequent experts. Insufficient of the control of subsequent owners. Unauthorized alteration or addition to a certification bearing a licensed land surveyor's seal is illegal and punishable by law. Property subject to documents of record.

**ROADWAY** SURVEY

1923 23-00350 | 1"=30' | 04/04/202 CHECKED BY: FIELD BY: STC JRC/CJH