New Hampshire Association of REALTORS® Standard Form



#### TO BE COMPLETED BY SELLER

The following answers and explanations are true and complete to the best of SELLER'S knowledge. This statement has been prepared to assist prospective BUYERS in evaluating SELLER'S property. This disclosure is not a warranty of any kind by the SELLER, or any real estate FIRM representing the SELLER, and is not a substitute for any inspection by the BUYER. SELLERS authorize FIRM in this transaction to disclose the information in this statement to other real estate agents and to prospective buyers of this property.

NOTICE TO SELLER(S): COMPLETE ALL INFORMATION AND STATE NOT APPLICABLE OR UNKNOWN AS

		PRIATE. IF ANY OF THE INFORMATION IN THIS PROPERTY DISCLOSURE FORM CHANGES FROM THE DATE OF LETION, YOU ARE TO NOTIFY THE LISTING FIRM PROMPTLY IN WRITING.				
1.	SEI	LLER: Broad Bay Properties LLC C/O Linda Kelley and Broad Bay Properties C/O Greg Roberts				
2.						
3.		NDOMINIUM, CO-OP, PUD DISCLOSURE RIDER OR MULTIFAMILY DISCLOSURE RIDER ATTACHED? Yes No				
4.	SEI	LLER: ☐ has ☑ has not occupied the property for 11 years.				
5.	WA	TER SUPPLY				
	Plea a.	ase answer all questions regardless of type of water supply.  TYPE OF SYSTEM: Public Private Seasonal Unknown  Drilled Dug Other				
	b.	INSTALLATION: Location: Left of unit 535 Installed By: Thomas Date of Installation: 7/28/2020				
		What is the source of your information?				
c. USE: Number of persons currently using the system: 18						
		Does system supply water for more than one household? ☑Yes ☐No				
	d.	MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water systems?				
		Pump:				
	e. WATER TEST: Have you had the water tested?  Yes No Date of most recent test 3/11/2025					
		IF YES to any question, please explain in Comments below or with attachment.  Are you aware of any test results reported as unsatisfactory or satisfactory with notations?   Yes  No What steps were taken to remedy the problem?  COMMENTS:				
		COMMITTER 15.				
6.		NAGE DISPOSAL SYSTEM  TYPE OF SYSTEM: Public: ☐ Yes ☐ No Community/Shared: ☐ Yes ☐ No Private: ☑ Yes ☐ No ☐ Unknown Septic Design Available: ☑ Yes ☐ No				
	b. IF PUBLIC OR COMMUNITY/SHARED Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No What steps were taken to remedy the problem?					
	C. IF PRIVATE:  TANK: Septic Tank Holding Tank Cesspool Unknown  Tank Size 2250 Gal. Unknown  Tank Type Concrete Metal Unknown Other  Location: 1- in Front oh 527/529 1- by unit 535 Location Unknown Date of Installation: Tanks 2003  Date of Last Servicing: Name of Company Servicing Tank: DJ'S  Have you experienced any malfunctions? Yes No  Comments:					
SE	LLER	R(S) INITIALS BUYER(S) INITIALS /				

New Hampshire Association of REALTORS® Standard Form



	PROPERTY LOCATION: 527 Tamworth Road, Tamworth, NH 03886								
	d.	IF YES, Location Date of installati Have you experi	Yes No not not of unit 5. ion of leach field: 2003 ienced any malfunction septic for units 527/529 in the septic for units 527	27/529 and one by 3+2025 ons?		Size: 12 Bedro Installed By: _		Unkn	
	e.	IF YES, has a set Date of Evaluati Comments:  FOR ADDITION	CATED ON "DEVELO eptic system evaluation:  NAL INFORMATION TAL SERVICES SUB	ion been done w	ithin 180 days	? Yes C	No <u>U</u> Unk	nown	
7.	INS	<u>SULATION</u>	LOCATION Attic or Cap Crawl Space Exterior Walls Floors	Yes №  □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	Unknown	Fiber	Amount		Unknown  D  D  D
8.	Are you aware of any past or present underground storage tanks on your property?								
	b.	As insulation on	the heating system p  ☐ Yes ☑ No ☐  ☐ Yes ☑ No ☐	oipes or ducts? Unknown In		No <u>□</u> Unknown	∐Yes [ Yes [		Unknown Unknown
	c. RADON/AIR - Current or previously existing:  Has the property been tested?								
SE	LLEF	R(S) INITIALS	S I CC			BUYE	R(S) INITIALS		

New Hampshire Association of REALTORS® Standard Form



	PR	PROPERTY LOCATION: 527 Tamworth Road, Tamworth, NH 03886				
	d. RADON/WATER - Current or previously existing:  Has the property been tested?					
	_	Are test results available?YesNo Comments:				
	e.	Are you aware of lead-based paint on this property?				
		Comments:				
	f.					
9.	GENERAL INFORMATION  a. Is this property subject to liens, encroachments, easements, rights-of-way, leases, restrictive covenants, attachments, life estates, or right of first refusal?  ☑ Yes ☐ No ☐ Unknown If YES, Explain: Driveway easement  What is your source of information?					
b. Is this property subject to special assessments, betterment fees, association fees, or any other transferable   ☐ Yes ☐ No ☐ Unknown If YES, Explain:  What is your source of information?						
	c.	Are you aware of any onsite landfills or any other factors, such as soil, flooding, drainage, etc?  Yes No If YES, Explain:				
	d.	d. Are you aware of any problems with other buildings on the property? ☐ Yes ☑No If YES, Explain:				
	e. Are you receiving a tax exemption or reduction for this property for any reason including but not limited to current use, land conservation, etc.?    TYES NO TUNKNOWN If YES, Explain:					
f. Is this property located in a Federally Designated Flood Hazard Zone? ☐Yes ☑ No ☐ Unknown Comments: Land by river is but not buildings						
	g.	Has the property been surveyed? Yes No Unknown If YES, By: 1978-S. Coville  If YES, is survey available? Yes No Unknown				
	h.	How is the property zoned? None Tamworth Has no zoning				
	i.	Heating System Age: 2004+2006 Type: Hot water Fuel: LP Gas Tank Location: By each building				
		Owner of Tank: Eastern				
		Annual Fuel Consumption: Price: Gallons:				
		Date system was last serviced and by whom? Dasilva Plumbing and Heating				
		Secondary Heat Systems: Baseboard electric on 2nd floor of each unit				
		Comments: Tenants Pay Their own heat and electric				
	j.	Roof Age: 2004/2006 Type of Roof Covering: Metal				
		Moisture or leakage: No				
		Comments:				

New Hampshire Association of REALTORS® Standard Form



	Comments:
	Chimney(s) How Many? N/A Lined? N/A Last Cleaned: N/A Problems?  Comments:
m.	Plumbing Type: Cooper and Pex Age: 2004 and 2006 Comments:
n.	Domestic Hot Water: Age: 2-10 Yrs 4 are Stainless Type: Off Boiler Gallons: 29-38
ο.	Electrical System: # of Amps 100 each unit
	Solar Panels: Leased Owned If leased, explain terms of agreement:  Comments:
p.	Modifications: Are you aware of any modifications or repairs made without the necessary permits?   Yes  No If Yes, please explain:
q.	Pest Infestation: Are you aware of any past or present pest infestations?  Yes No Type:
r.	Methamphetamine Production: Do you have knowledge of methamphetamine production ever occurring on the property? (Per RSA 477:4-g) ☐ Yes ☑ No If YES, please explain:
5.	Air Conditioning: Type: N/A Age: N/A Date Last Serviced and by whom: Comments:
t.	Pool: Age: N/A Heated: Yes No Type: Last Date of Service: By Whom:
J.	Generator: Portable:YesNo Whole House:YesNo Kw/Size:Last Date of Service: If Portable:IncludedNegotiable Comments:
<b>/</b> .	Internet: Type Currently Used at Property: Spectrum
N.	Other (e.g. Alarm System, Irrigation System, etc.)  Comments:
ES ON D	ETO PURCHASER(S): PRIOR TO SETTLEMENT YOU SHOULD EXERCISE WHATEVER DUE DILIGENCE YOU DEEM SARY WITH RESPECT TO ADJACENT PARCELS IN ACCORDANCE WITH THE TERMS AND CONDITIONS AS MAY NTAINED IN PURCHASE AND SALES AGREEMENT AND DEPOSIT RECEIPT. YOU SHOULD EXERCISE WHATEVER DILIGENCE YOU DEEM NECESSARY WITH RESPECT TO INFORMATION ON ANY SEXUAL OFFENDERS TERED UNDER NH RSA CHAPTER 651-B. SUCH INFORMATION MAY BE OBTAINED BY CONTACTING THE LOCAL EXERCISE DEPARTMENT.

New Hampshire Association of REALTORS® Standard Form



PROPERTY LOCATION: 527 Tamworth Road, Tamworth, NH 0388	36				
10. ADDITIONAL INFORMATION  a. ATTACHMENT EXPLAINING CURRENT PROBLEMS, P.  ☑ Yes ☐ No  b. ADDITIONAL COMMENTS:  See Attached (10) + 4537 - Had Five 1					
See Attached Unit #537 - Had Fire/Sonoke damage W/ FISH tank powerstrips, We filed insurance Claim, As result entire unit was gutted completely, and Fully re-sheet rocks and insulated, including new appliances, cubinets, and Carpeting to restore 100%.					
Carpeting to restore 100%.	in appliances, Cabinets, and				
ACKNOW! EDGEMENTS.					
ACKNOWLEDGEMENTS: SELLER ACKNOWLEDGES THAT HE/SHE HAS PROVIDED THE ABOVE INFORMATION AND THAT SUCH INFORMATION IS ACCURATE, TRUE AND COMPLETE TO THE BEST OF HIS/HER KNOWLEDGE. SELLER AUTHORIZES THE LISTING BROKER TO DISCLOSE THE INFORMATION CONTAINED HEREIN TO OTHER BROKERS AND PROSPECTIVE PURCHASERS.					
SELLER(S) MAY BE RESPONSIBLE AND LIABLE FOR ANY FA	AILURE TO PROVIDE <u>KNOWN</u> INFORMATION TO BUYER(S).				
SELLER HOLAGE 4/17/2025	SELLER DATE  SELLER DATE				
BUYER ACKNOWLEDGES RECEIPT OF THIS PROPERTY PRECEDING INFORMATION WAS PROVIDED BY SELLER DISCLOSURE STATEMENT IS NOT A REPRESENTATION, W PROPERTY BY EITHER SELLER OR BROKER. BUYER IS EN AND INVESTIGATIONS VIA LEGAL COUNSEL, HOME, STAND ADVISORS AND TO INDEPENDENTLY VERIFY INFORMATION	AND IS NOT GUARANTEED BY BROKER/AGENT. THIS ARRANTY OR GUARANTY AS TO THE CONDITION OF THE ICOURAGED TO UNDERTAKE HIS/HER OWN INSPECTIONS RUCTURAL OR OTHER PROFESSIONAL AND QUALIFIED				
BUYER DATE	BUYER DATE				
	[				
SELLER(S) INITIALS _ K / CC	BUYER(S) INITIALS/				