

Other Options

[Return to menu](#)
[Plot this site in State Library Digital Atlas](#)
[Plot this site in Google Maps](#)

Section 7: Well Test Data

Total Depth: 400
Static Water Level: 88
Water Temperature:

Section 1: Well Owner(s)

1) GAYNOR, DON, NANCY (WELL)
7000 BROWNS MEADOW RD
NIRADAMT 59845 [10/03/2023]

Section 2: Location

Township	Range	Section	Quarter Sections
25N	23W	26	SW¼ NW¼ SW¼
County	Geocode	Parcel	
FLATHEAD			
Latitude	Longitude	Geomethod	Datum
47.894012	-114.534304	NAV-GPS	WGS84
Ground Surface Altitude	Ground Surface Method	Datum	Date

Addition	Block	Lot
----------	-------	-----

Section 3: Proposed Use of Water

DOMESTIC (1)

Section 4: Type of Work

Drilling Method: DUAL ROTARY
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Tuesday, October 3, 2023

Section 6: Well Construction Details

Borehole dimensions

From	To	Diameter
0	400	6

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
0	60	6.6	0.25		WELDED	A53B STEEL
40	400	4			SPLINE	PVC

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
320	360	4	160	1/2"	DRILLED HOLES

Annular Space (Seal/Grout/Packer)

From	To	Description	Cont. Fed?
0	60	GRANULAR BENTONITE	Y

Air Test *

15 gpm with drill stem set at 400 feet for 3 hours.
Time of recovery _ hours.
Recovery water level _ feet.
Pumping water level _ feet.

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Section 8: Remarks

WATER STARTED AT 30 GPM THEN SETTLE AT LIKE 15GPM

Section 9: Well Log

Geologic Source

Unassigned

[illegible]

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name: MARTIN WILSON
Company: COLDWATER DRILLING AND PUMPS
License No: WWC-624
Date 10/3/2023
Completed: