

ATLEnviroScience, LLC

December 6, 2022

Environmental Services of America
Po. BOX 250
Watkinsville, GA 30677

Re: Leigh Limousin
27 W Doyle St
Toccoa, GA 30577


Clearance Visual Inspection

Upon notification of completion of the abatement activities by the abatement contractor Environmental Services of America at the property: **27 W Doyle St**
Toccoa, GA
30577

Our representative performed visual inspections of the work areas to verify that the abatement activities had been completed and that there were no remaining visible signs of contamination in **Floor 9x9, vinyl and mastic (Second Floor)**

Conclusion

ATLEnviroScience, LLC hereby certifies that the work area has been visually inspected and that no dust, debris, or residual has been found. Furthermore, all work was performed in substantial compliance with federal, state and local regulations.

James Guy	Building Inspector	
Name	Title	 Signature