

TOWNSHIP 43 SOUTH, RANGE 6 WEST, OF THE SALT LAKE BASE & MERIDIAN, UTAH
 DEPENDENT RESURVEY AND SUBDIVISION OF A PORTION OF SECTION 35 AND TOPOGRAPHIC SURVEY OF PARCELS A & B



Found 1988 Alum. Cap. G-5 1/16 Corner for Section 5, T43S, R6W, S35E

- LEGEND**
- SET 5/8" x 30" REBAR AND/OR 24" T-BAR WITH CAP AND RLS, 6943 OR RLS, 165634 CORNERS SHOWN IN KEY PLANS SET AS NOTED.
 - CORNER SET BY OTHERS
 - ◆ FOUND QLO/BLU B.C. RECTANGULAR SURVEY CORNER
 - ◆ RECTANGULAR SURVEY CORNER SET IN THIS SURVEY (5-1/4" ALUM. CAP ON 2"x30" ALUM. PIPE (S-1/4" TALBOT LAND SURVEYORS) RLS 165634)
 - S350 — CONTIGUOUS AT 1 FOOT INTERVALS

SURVEYOR'S CERTIFICATE

I, Lanny K. Talbot, do hereby certify that a portion of Registered Land, Surveyor and that I hold Certificate No. 165634, as prescribed under the laws of the State of Utah, I further certify that this plat correctly represents a survey made by me or under my direction in accordance with the laws and accepted methods and procedures of surveying of the State of Utah and that the same has been correctly surveyed and staked on the ground.

Lanny K. Talbot
 Lanny K. Talbot RLS No. 165634



THESE DRAWING(S) OR ANY PORTION THEREOF SHALL NOT BE USED ON ANY PROJECT OR EXTENSIONS OF THIS PROJECT EXCEPT BY AGREEMENT IN WRITING WITH LANNY K. TALBOT AND ROCK CANYON RESOURCES.

TOPOGRAPHIC SURVEY
CHURCH OF THE FIRSTBORN NATIVE
PROPERTY

LOCATED IN
 SOUTH 1/2 SEC. 5, NORTH 1/2 SEC. 8,
 T. 41 S., R. 7 W., S.L.B.M., UTAH

TALBOT LAND SURVEYORS
 & **ROCK CANYON RESOURCES**
 663 S. PINE ST./BOX 11901, PANDORA, UT 84759
 PHONE: (435) 626-8018
 FAX: (435) 626-8019

DATE	3/17/2020	TITLE	COND CONSULTING - UT
DRAWN	LT	CHECKED	LT
SCALE	1" = 100'	SHEET	1 of 1

DWG. No. K-TOPG FINAL