

Report

Site Details

6455 64th Street

6455 64 St, Delta, BC V4K 4E2, Canada


















Shift Details

Date: 18 Nov 2025

Time: 12:00 - 13:00

Assigned Staff

Mankhush Mankhush

Time	Type	Description
12:47	Check In	<p>Check In at 12:47</p> <p>Staff: Mankhush Mankhush</p> <p>Site: 6455 64th Street</p>
12:50	Activity	<p>Activity Report Created</p> <p>Created By: Mankhush Mankhush</p> <p>Staff: Mankhush Mankhush</p> <p>Site: 6455 64th Street</p> <p>Description: Security Report – 6471 64th St, Delta BC V4K 4E2 Date & Time of Inspection:** November 18, 2025 Upon arrival at the property, a complete exterior and interior inspection was conducted. No individuals were present on-site, and the surroundings remained quiet throughout the walkthrough. The exterior of the building appeared secure, with all entry points closed and no indications of forced access. Fire lane signage was properly displayed, and the surrounding pavement showed no recent vehicle activity or disturbances. Inside the structure, several areas displayed notable interior damage. In a narrow interior room, a large portion of the ceiling had collapsed, leaving insulation, wooden beams, and debris across the floor and workbench. There were no signs of movement or current activity in this section. Additional areas of the hallway showed exposed wiring and partially removed wall sections, consistent with incomplete construction or deterioration, though no hazards involving individuals were observed. The warehouse portion contained scattered foam materials and general debris, but no unauthorized persons or suspicious objects were identified. Windows and doors remained intact with no visible tampering. The exterior lot and covered structure were also clear, with no persons present. At this time, the property has no electricity, and the site remained unoccupied and stable during the inspection.</p> <p>Images:</p> <div></div>
12:50	Check out	<p>Check out at 12:50</p> <p>Time Spent: 3m</p> <p>Staff: Mankhush Mankhush</p> <p>Site: 6455 64th Street</p>