

## Division of Petroleum & Chemical Safety

### Facility Details

<b>Facility Number:</b>	5016674
<b>Status:</b>	Active
<b>Facility Name:</b>	Darr's Truck Stop
<b>Address:</b>	<a href="#">10974 Route 111 Medora, IL 62063</a>
<b>County:</b>	Macoupin
<b>Property Parcel:</b>	
<b>Facility Type:</b>	Attended Self-Service Station
<b>Owner Type:</b>	Private
<b>Green Tag Decal:</b>	Y00789
<b>Green Tag Issue Date:</b>	6/28/2023
<b>Green Tag Expiration Date:</b>	12/31/2025

### Owner Details

<b>Owner Name:</b>	Loren Darr, Sr.
<b>Owner Address:</b>	<a href="#">P.O. Box 54 Medora, IL 62063</a>
<b>Owner Status:</b>	Current Owner
<b>Purchase Date:</b>	9/3/1986
<b>Type of Financial Responsibility:</b>	Certificate of Deposit
<b>Financial Responsibility Reporting Due Date:</b>	8/1/2025

### Motor Fuel Dispensing Permits

MFD Permit Type	Issue Date	Expiration Date
Self Service	5/12/2023	12/31/2025

### Owner Summary

[Click for Facility/Tank Ownership history](#)

Owner Number	Owner Name	Owner Status	Purchase Date
U0023174	Darr, Sr., Loren	Current Owner	9/3/1986
U0034243	Medora Mini Mart, Inc.	Former Owner	5/1/2006
U0003054	C J Kountry Cafe	Former Owner	12/31/1967

### Permits (Unexpired)

[Click for permit history](#)

No Active Permits Found

### Notice of Violations (Current)

No Notice of Violations Found

### IEMA Numbers Associated with the Facility

No IEMA Numbers Found

### UST Fund Eligibility and Deductibility Determinations

No Applications Found

### Tank Information

[Pay Tank Fees Online](#)

#### Tank Number 1

Capacity:	0	Petroleum Use:	
Product:		CERCLA Substance:	
Status:	Removed	CAS Code:	

Regulated Status:	Exempt		Removed Date:	8/19/1986
OSFM First Notify Date:			Abandoned Material:	
Current Age:			Abandoned Date:	
Install Date:			Red Tag Issue Date:	
Last Used Date:			Fee Due:	
Product Date:				

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
----------------	-----------	-------------------	------------------

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 2**

Capacity:	0		Petroleum Use:	
Product:			CERCLA Substance:	
Status:	Removed		CAS Code:	
Regulated Status:	Exempt		Removed Date:	8/19/1986
OSFM First Notify Date:			Abandoned Material:	
Current Age:			Abandoned Date:	
Install Date:			Red Tag Issue Date:	
Last Used Date:			Fee Due:	
Product Date:				

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
----------------	-----------	-------------------	------------------

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 3**

Capacity:	0		Petroleum Use:	
Product:			CERCLA Substance:	
Status:	Removed		CAS Code:	
Regulated Status:	Exempt		Removed Date:	8/19/1986
OSFM First Notify Date:			Abandoned Material:	
Current Age:			Abandoned Date:	
Install Date:			Red Tag Issue Date:	
Last Used Date:			Fee Due:	
Product Date:				

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
----------------	-----------	-------------------	------------------

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 4**

Capacity:	0		Petroleum Use:	
Product:			CERCLA Substance:	
Status:	Removed		CAS Code:	
Regulated Status:	Exempt		Removed Date:	8/19/1986
OSFM First Notify Date:			Abandoned Material:	
Current Age:			Abandoned Date:	
Install Date:			Red Tag Issue Date:	
Last Used Date:			Fee Due:	
Product Date:				

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
----------------	-----------	-------------------	------------------

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 5**

Capacity:	0		Petroleum Use:	
Product:			CERCLA Substance:	
Status:	Removed		CAS Code:	
Regulated Status:	Exempt		Removed Date:	8/19/1986
OSFM First Notify Date:			Abandoned Material:	
Current Age:			Abandoned Date:	
Install Date:			Red Tag Issue Date:	
Last Used Date:			Fee Due:	
Product Date:				

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
----------------	-----------	-------------------	------------------

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 6**

Capacity:	0		Petroleum Use:	
Product:			CERCLA Substance:	
Status:	Removed		CAS Code:	
Regulated Status:	Exempt		Removed Date:	8/19/1986
OSFM First Notify Date:			Abandoned Material:	
Current Age:			Abandoned Date:	
Install Date:			Red Tag Issue Date:	
Last Used Date:			Fee Due:	
Product Date:				

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
----------------	-----------	-------------------	------------------

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 7**

Capacity:	8000	Petroleum Use:	
Product:	Gasoline - Mid-grade	CERCLA Substance:	
Status:	Currently in use	CAS Code:	
Regulated Status:	Federal	Removed Date:	
OSFM First Notify Date:	4/21/1994	Abandoned Material:	
Current Age:	37	Abandoned Date:	
Install Date:	1/1/1987	Red Tag Issue Date:	
Last Used Date:		Fee Due:	\$0.00
Product Date:	1/1/1987		

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Corrosion Prot - Piping	Isolation Boots Flex Connector	N/A	N/A
Corrosion Prot - Piping	Fiberglass Non-Corrosive	N/A	N/A
Corrosion Prot - Tank	Fiberglass Non-Corrosive	N/A	N/A
Leak Detect - Piping	European with No Test Req Suction	N/A	N/A
Leak Detect - Tank	Automatic Tank Gauging Pneumercator TMS 3000	8/4/2023	8/4/2024
Overfill Prev Device	Overfill Drop Tube Valve	8/15/2022	8/15/2025
Piping	Flex Connector Steel	N/A	N/A
Piping	Fiberglass Single Wall Piping	N/A	N/A
Piping	Not Installed STP/Tanktop Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A
Spill Contain Device	Single Wall Spill Bucket	8/15/2022	8/15/2025
Tank	Fiberglass Single Wall	N/A	N/A
Vent, Riser, Fill Piping	Steel risers	N/A	N/A

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 8**

Capacity:	8000	Petroleum Use:	
Product:	Gasoline - Regular	CERCLA Substance:	
Status:	Currently in use	CAS Code:	
Regulated Status:	Federal	Removed Date:	
OSFM First Notify Date:	4/21/1994	Abandoned Material:	
Current Age:	37	Abandoned Date:	
Install Date:	1/1/1987	Red Tag Issue Date:	
Last Used Date:		Fee Due:	\$0.00
Product Date:	1/1/1987		

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Corrosion Prot - Piping	Isolation Boots Flex Connector	N/A	N/A
Corrosion Prot - Piping	Fiberglass Non-Corrosive	N/A	N/A
Corrosion Prot - Tank	Fiberglass Non-Corrosive	N/A	N/A
Leak Detect - Piping	European with No Test Req Suction	N/A	N/A
Leak Detect - Tank	Automatic Tank Gauging Pneumercator TMS 3000	8/4/2023	8/4/2024
Overfill Prev Device	Overfill Drop Tube Valve	8/15/2022	8/15/2025
Piping	Flex Connector Steel	N/A	N/A
Piping	Fiberglass Single Wall Piping	N/A	N/A
Piping	Not Installed STP/Tanktop Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A
Spill Contain Device	Single Wall Spill Bucket	8/15/2022	8/15/2025
Tank	Fiberglass Single Wall	N/A	N/A
Vent, Riser, Fill Piping	Steel risers	N/A	N/A

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 9**

Capacity:	8000	Petroleum Use:	
Product:	Diesel Fuel	CERCLA Substance:	
Status:	Currently in use	CAS Code:	
Regulated Status:	Federal	Removed Date:	
OSFM First Notify Date:	4/21/1994	Abandoned Material:	
Current Age:	37	Abandoned Date:	
Install Date:	1/1/1987	Red Tag Issue Date:	
Last Used Date:		Fee Due:	\$0.00
Product Date:	1/1/1987		

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Corrosion Prot - Piping	Isolation Boots Flex Connector	N/A	N/A
Corrosion Prot - Piping	Fiberglass Non-Corrosive	N/A	N/A
Corrosion Prot - Tank	Fiberglass Non-Corrosive	N/A	N/A
Leak Detect - Piping	European with No Test Req Suction	N/A	N/A
Leak Detect - Tank	Automatic Tank Gauging Pneumercator TMS 3000	8/4/2023	8/4/2024
Overfill Prev Device	Overfill Drop Tube Valve	8/15/2022	8/15/2025
Piping	Flex Connector Steel	N/A	N/A
Piping	Fiberglass Single Wall Piping	N/A	N/A
Piping	Not Installed STP/Tanktop Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A
Spill Contain Device	Single Wall Spill Bucket	8/15/2022	8/15/2025
Tank	Fiberglass Single Wall	N/A	N/A
Vent, Riser, Fill Piping	Steel risers	N/A	N/A

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Tank Number 10**

Capacity:	2000	Petroleum Use:	
Product:	Gasoline - Premium	CERCLA Substance:	
Status:	Currently in use	CAS Code:	
Regulated Status:	Federal	Removed Date:	
OSFM First Notify Date:	4/21/1994	Abandoned Material:	
Current Age:	37	Abandoned Date:	
Install Date:	1/1/1987	Red Tag Issue Date:	
Last Used Date:		Fee Due:	\$0.00
Product Date:	1/1/1987		

**Equipment**

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Corrosion Prot - Piping	Isolation Boots Flex Connector	N/A	N/A
Corrosion Prot - Piping	Fiberglass Non-Corrosive	N/A	N/A
Corrosion Prot - Tank	STIP3 Cathodic Protection with Dielectric Coating	5/16/2023	5/16/2026
Leak Detect - Piping	European with No Test Req Suction	N/A	N/A
Leak Detect - Tank	Automatic Tank Gauging Pneumercator TMS 3000	8/4/2023	8/4/2024
Overfill Prev Device	Overfill Drop Tube Valve	8/15/2022	8/15/2025
Piping	Flex Connector Steel	N/A	N/A
Piping	Fiberglass Single Wall Piping	N/A	N/A
Piping	Not Installed STP/Tanktop Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A
Spill Contain Device	Single Wall Spill Bucket	8/15/2022	8/15/2025
Tank	STIP3 Single Wall	N/A	N/A
Vent, Riser, Fill Piping	Steel risers	N/A	N/A

**Additional Tests**

Equipment Type	Equipment	Test Type	Test Result	Test Date
----------------	-----------	-----------	-------------	-----------

**Dispenser Information**

---

**NameID 1/2**

Status: Active

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Dispenser	Not Installed UDC Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A

**NameID 10/11**

Status: Active

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Dispenser	Not Installed UDC Sump	N/A	N/A

Equipment Type	Equipment	Last Passing Date	Test Expire Date
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A

**NameID 3/4**

Status: Active

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Dispenser	Not Installed UDC Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A

**NameID 5**

Status: Active

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Dispenser	Not Installed UDC Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A

**NameID 6/7**

Status: Active

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Dispenser	Not Installed UDC Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A

**NameID 8/9**

Status: Active

Equipment Type	Equipment	Last Passing Date	Test Expire Date
Dispenser	Not Installed UDC Sump	N/A	N/A
↳ Leak Detect - Piping	Piping Sump Sensors Not Regulated Not Installed	N/A	N/A

**MFD Motorfuel Dispensing Forms**

**No Forms Found**