

826 1st St. W – 24 UNITS

List of items needing to be replaced in individual units.

Unit A

Damage ceiling
attic trap
bedroom door missing
floor in kitchen and bath

Unit B

No kitchen cabinets
waterline, damaged/gone
no sink or toilet and bath
floors need replacement

Unit A 109

Some holes in wall]
Needs a unit turn

Unit D 109

Needs all new flooring
Some lighting
Holes in ceiling (so sheetrock is probably damaged throughout)

Unit E 109

Filled with belongings
Needs a unit turn

Unit F 109

Ready for unit turn

Unit G

No water heater
kitchen is gone
no bedroom door
bathroom sink and toilet are gone

105 9th Av Apt G

Hot water tank missing
Backdoor missing
kitchen sink missing
Bathroom sink missing
Bedroom door missing
bathroom sink missing

818 1st St W:

Missing HVAC Unit
Missing hot water tank
Missing toilet
Missing bathroom door
Missing bedroom door

820 1st St W

Missing HVAC unit
Missing front door
Missing bedroom door
Missing bathroom mirror
Bathroom sink destroyed

816 1st St W

Missing HVAC Unit
Hot water tank missing
Front and back door missing
Bedroom door missing
Bathroom sink missing
Thermostat missing
Broken window

830 1st St W.

Missing HVAC unit
Kitchen sink missing
Wall busted out in kitchen
Hole cut in the ceiling in bedroom
Missing ductwork

826 1st St W

Missing HVAC unit

Missing thermostat

Missing flooring

Missing hot water tank

Missing bathroom door

Missing smoke alarm

Missing flooring (lvp)

822 1st St W

Missing HVAC unit

Missing duct work

Missing sink missing flooring

Missing hot water tank

Damaged door frame