



**Building Safety Inspection**  
**Acceptance Notice**

December 30<sup>th</sup> , 2025

**Property Address:** 1111 SW 4 STREET  
**RE:** 10-YEAR BUILDING SAFETY INSPECTION  
**Folio:** 504209090830

Broward County Administrative Provisions Section 110.15 of the Florida Building Code has established a Building Safety Inspection Program requirement for buildings and structures that have been in existence for a period of 25 years or longer.

The Building Safety Inspection shall be performed by an independent Architectural or Engineering firm that is licensed in the State of Florida.

Buildings or structures that must perform a phase one and/or phase two milestone inspection as defined under **F.S. 553.899**, this building safety inspection shall serve as compliance for both milestone inspection requirements.

A Building Safety Inspection Report was submitted to and accepted by the City of Fort Lauderdale December 22<sup>nd</sup> , 2025, for the address listed above. The structure was deemed to be safe, both structurally and electrically, based on the report completed by:

**ELECTRICAL: CARLOS M. RODRIGUEZ P.E 0055488**

**STRUCTURAL: GONZAL A. PAZ P.E 60734**

Warm Regards,

*Marie Arias*

**Administrative Assistant**  
Building & Construction Enforcement Division

