



PHASE I ENVIRONMENTAL SITE ASSESSMENT

Prepared for

**Rick Church
Houston, Texas**

And

**Prosperity Bank-Bellaire Center
Houston, Texas**

*For an historic building having been used as a
railroad maintenance facility located at*

100 S. Elm Street, Pecos, Texas

Date of Investigation: September 2, 2021

Prepared by

Ray L. McKim, III CPL/ESA

an EPA qualified Environmental Professional

offices: San Angelo/Midland • 432.296.0091 • www.telecom-esa.com

PO Box 2356
Midland, TX 79702

Ray L. McKim, III
Certified Professional Landman
Environmental Site Assessor
d/b/a Telecom Site Services

ray@telecom-esa.com
(432)296-0091

September 8, 2021

Rick Church & Prosperity Bank
Houston, Texas

ATTN: Rick Church

RE: 100 S. Elm Street, Pecos, Texas

Dear Mr. Church:

Pursuant to your authorization to conduct a Phase I Environmental Site Assessment of the above captioned property, the following report details my investigative methods and findings. I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in 312.10 of 40 CFR 312. I have the specific qualifications based on education, training and experience to assess a property of the nature, history and setting of the subject property.

Also, I declare that I have no undisclosed interest in the property or owner/borrower, present or future.

I appreciate the opportunity to be of service to you and your company, and if you have any questions whatsoever concerning this report, please do not hesitate to contact me.

Sincerely,



Ray L. McKim, III

On November 1, 2005, the EPA issued new rules and regulations defining the "environmental professional" conducting "all appropriate inquiries". To qualify without a Professional Engineer's License or Professional Geologist License, an individual must have ten years of relevant full-time work experience. For more work history, see my website www.telecom-esa.com

Certified in 1993 as a Professional Landman & Environmental Site Assessor under the requirements as a member of the American Association of Professional Landmen; Member No. 3231.

In 1994, successful completion of the University of Texas at Arlington's course "Inspecting Buildings for Asbestos Containing Materials" in compliance with asbestos accreditation requirements under TSCA Title II. Ray L. McKim, III is not licensed in the State of Texas to perform asbestos testing.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	4
NEW RULES FOR AAI.....	5
ASSESSMENT OBJECTIVES	7
PHASE I SCOPE OF WORK	8
ACRONYMS AND SYMBOLS	9
 PART I- The Phase I Environmental Site Assessment	
LOCATION/SITE DESCRIPTION	10
1.0 Site Overview	
1.1 Legal Description/Location/Government Jurisdiction	
1.2 Operator and Site Usage	
SITE HISTORY	11
2.0 Past/Past Ownership and Usage	
2.1 Aerial Photos and Sanborn Maps	
ENVIRONMENTAL SETTING	12
3.0 Topography and Vegetation	
3.1 Soil and Geology	
3.2 Drainage and Surface Water Characteristics	
3.3 Groundwater Characteristics/Issues	
SITE INSPECTION	13
4.0 Site Conditions	
4.1 Chemical Substance Inventory, Storage and Disposal	
4.2 Asbestos	
4.3 Generators-AST, UST, LUST	
4.4 Radon, VIC and Indoor Pollution	
4.5 Polychlorinated Biphenyls (PCBs)	
4.6 UREA Formaldehyde, Lead Paint, NORMs	
4.7 55 gallon Drums or containers	
4.8 Interviews	
AREA & ADJACENT PROPERTY REVIEW	14
GOVERNMENT DATABASE REVIEW	15
LIMITING CONDITIONS.....	16
VITAE.....	17
 PART II- APPENDIX	
Pictures	
Google Earth Aerial Photos	
Tax Plat	
Database Report	

EXECUTIVE SUMMARY & RECOMMENDATIONS

Ray L. McKim, III was authorized by Rick Church to perform a Phase I Environmental Site Assessment of an old historic brick building located at 100 S. Elm Street, Pecos, Reeves County, Texas. The subject site was inspected by Ray L. McKim, III CPL/ESA on September 2, 2021.

The subject .51 acre site is a 14,420 shop type brick building with a smaller detached brick building and small lawn area. The subject tract is in a level area situated on the north edge of downtown Pecos, Texas. The building has suffered damage to windows and mechanical, plus extreme trash/vagrant damage. There was observed no significant staining or distressed vegetation in and around the small building, lawn area or outer edges of the facility. There are no registered petroleum underground storage tanks located on the property or on adjacent tracts. The records research database indicates no environmental concerns at or near the facility.

The facility will have city water and sewer available. The aerial photographs showed no environmental concerns. Flooding and stormwater runoff should not be a concern.

COMMENT: The facility needs extensive cleaning and then further inspection of any damage to the ground floor areas. **Testing for lead paint and asbestos will be necessary if the facility will be used as a child day care center.**

To the best of my knowledge there

- are no previous uses of the site that may have posed a threat to its environmental integrity.
- have been no disposal of nor accidental release of any hazardous substances at this site in significant quantities.
- are no pollution clean-up actions that have ever been taken at this site.
- are no significant quantities of toxic chemicals stored or utilized at this site.
- are no hazardous waste generated at this site that may require an EPA identification number. **The site has never been used as a dry-cleaning plant.**
- are no registered underground storage tanks that are located on this site.
- are no violations of any federal, state, or local hazardous substance regulations on this site.

I do not recommend the need for any Phase II investigation **UNLESS** the site will be converted to a public use, such as residential homes, apartments, man camps, parks, night club, children entertainment center etc (after extensive cleanup).

AAI- The “All Appropriate Inquiry”: NEW RULES for ENVIRONMENT SITE ASSESSMENTS

The 2002 Brownfields Amendments to CERCLA required the EPA to develop regulations establishing and practices for conducting environmental due diligence or the “all appropriate inquiries” (AAI). The AAI is the process of evaluating a property’s environmental conditions and assessing potential liability for any contamination. On November 1, 2005, the EPA released 40 CFR Part 312 that defines the final rules for the AAI standards and practices. These rules and regulations will be effective November 1, 2006, and must be followed for an AAI qualified Phase I report for a 1) innocent landowner’s defense 2) contiguous property owner protection and 3) bona fide prospective purchaser protection. Here is a summary of some of the more prominent changes in the new rules regarding environmental assessments:

Who is Qualified ?

Probably the single most important issue regarding the new rules and regulations is the definition of the “environmental professional” (EP). The new rules defines the environmental professional as someone who possesses sufficient specific education, training and experience necessary to exercise professional judgment to develop opinions and conclusions regarding conditions indicative of releases or threatened releases of hazardous substances on, at, in, or to a property, sufficient to meet the objectives and performance factors of the rule. In addition, an environmental professional must have:

- A state or tribal issued certification or license and three years of relevant full-time work experience; or
- A professional engineering or geologist license and three years of relevant full-time work experience; or
- A Baccalaureate degree or higher in science or engineering and five years of relevant full-time work experience; or
- Ten years of relevant full-time work experience.

The final rules do not recognize, or reference, any private organization’s certification program (including the AAPL’s ESA certification program) within the context of the regulatory language. (The writer of this report qualifies as to the latter requirement listed- see my work experience that is available for review on my webpage- www.telecom-esa.com).

No more “Real Estate Transaction Screens”:

The Transaction Screen (for example, form ASTM E 1528), will no longer hope to qualify for CERCLA liability. Any such screening tool will be a low-risk tool for such properties with minimal potential for environmental concerns.

Activity and Use Limitations (AULs):

AULs include engineering controls and institutional controls (e.g. deed restrictions, restrictive covenants or easements) and the responsibility for identifying AUL is shared by the EP and user.

User Responsibilities:

EP are to make clients (users of the property) aware that the following obligations must be provided upfront in the information gathering process- and that failure to do so could jeopardize the client's ability to qualify for CERCLA liability protection down the road;

- a. environmental cleanup liens filed or recorded against the site;
- b. AULs in place on the site;
- c. specialized knowledge or experience related to the property or nearby property;
- d. relationship of the purchase price being paid for the property to its value if not contaminated;
- e. commonly known or reasonable ascertainable information about the property;
- f. any obvious indications pointing to the presence or likely presence of contamination at the property;
- g. a title report back 40 years or to when the subject site was first developed.

Unless expressly noted otherwise in this report, the above elements are the responsibility of the user/purchaser of the property.

Core Phase I Action Items:

There are revisions for government records research (database reports) and mandatory search of Indian tribal records (where available) and mandatory review of local records. Historical research is broadened and data failure must be documented.

Site reconnaissance- **the subject property and adjoining properties must be visually and physically observed by the AAI qualified EP.** Extensive interviews must be performed if past owners, operators and occupants are likely to have material information about the property and is not duplicative of information gleaned from other sources.

Data Gaps:

The Phase I report and the EP must identify data gaps and document any steps to fulfill them. Also, the EP must comment on the significance of the data gaps, and whether or not they affect the EP's ability to form an opinion about the environmental condition of the target property.

Phase I Shelf Life:

A Phase I report older than **one year** from the property's date of purchase may not be used in its entirety without being updated by a qualified EP.

New Definitions for a Recognized Environment Condition (REC)- ASTM E 1527-13, beginning Nov 2013:

There are now actually three new REC definitions that an EP and the clients must understand. The new REC definition is stated below and there are two more possible RECs- the Historic REC and the Controlled REC, which will be further defined and discussed upon such determination by the EP. The CREC is defined as a REC from a past release of hazardous substances or petroleum products that has been addressed to the satisfaction of the applicable regulatory authority, with hazardous substances or petroleum products allowed to remain in place to the implementation of required controls. The HREC is a past release of any hazardous substances or petroleum products that has occurred in connection with the property and has been addressed to the satisfaction of the applicable regulatory authority or meeting unrestricted use criteria established by a regulatory authority, without subjecting the property to any required controls. Before calling the past release an HREC, the EP must determine whether the past release is a REC at the time the Phase I is conducted (if there been a change in the regulatory criteria).

ASSESSMENT OBJECTIVES

The Phase I Environmental Site Assessment is designed to identify significant use of chemicals and environmental contamination, historically or currently, on or near the site, which could devalue the property, alter the land's usage, necessitate government reporting and remediation or pose a significant health or environmental risk. In defining a standard of good commercial and customary practice for conducting an environmental site assessment of a parcel of property, **the goal** of the processes established by this practice **is to identify a recognized environmental condition**. The *term recognized environmental condition* means the presence or likely presence of any hazardous substances or petroleum products in, on, or at a property: (1) due to any release to the environment; (2) under conditions indicative of a release to the environment; or (3) under conditions that pose a material threat of a future release to the environment. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term does not include *de minimis* conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies .

Provided the Phase I ESA does not reveal environmental impairment, the inference to be drawn by the client or decision maker would be that no further investigation would be required and the assessment process should terminate at that point. However, if potential problems are indicated, the investigation or assessment would proceed in an attempt to quantify the level of contamination. An often disputed point in the Phase I ESA is whether the investigation should be expanded to include invasive methodology. For example, the decision on whether the work scope should include soil and water samples or even possibly asbestos sampling must often be established in defining the scope of work under the initial investigation. This important decision should be referred to the client or the person who commissioned the work itself based on the potential risks involved and cost constraints. **In a typical Phase I ESA, sampling is not performed unless the potential buyer has a low level of risk propensity.** Those conservative- minded purchasers may wish to have the added assurance obtained through sampling and analytical techniques normally performed in a **Phase II ESA** in order to establish a more comfortable risk tolerance. **To insure an unbiased "all appropriate inquiries" and remove any possibility of conflicts of interest, Ray L. McKim, III CPL/ESA does not perform Phase II ESA investigations.**

A Phase I ESA will address non-invasive areas and may or may not address other concerns as follows:

1. Business and property information
2. Site history and improvements
3. Adjacent property uses and ownership
4. Raw material used or stored on site
5. Above ground storage tanks
6. Waste storage areas, including pits
7. Utilities, water wells and oil and/or gas wells
8. Flood plains and wetlands potential
9. Underground storage tanks and leaking underground storage tanks
10. Polychlorinated Biphenyls (PCBs)
11. Radon gas
12. Drinking water quality and potential for lead contamination; and
13. Naturally occurring radioactive materials (NORMs).

In a Phase I ESA, the environmental professional will review appropriate and relevant public records in an attempt to discover whether any of the following has occurred:

1. Operations that may have produced hazardous waste either on the site or nearby;
2. Whether underground storage tanks were located on the property and whether such tanks have been closed or registered with appropriate state authorities;

3. Whether any industrial processes subject to federal or state regulation are now present or have been present in the past;
4. Whether the owner/operator of the site has been subjected to an enforcement action at any time in the past;
5. Whether adjacent owners have been the subject of an enforcement action or an environmental lawsuit;
6. Whether asbestos-containing materials were used in construction and whether asbestos has been previously removed or if the site has had previous demolition or renovation; or
7. Whether PCB' s are on the property or in the vicinity of the site being assessed.

This report will follow ASTM E 1527-13 *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process*, and will address any data gaps and its significance. The report may or may not be AAI compliant.

PHASE I SCOPE OF WORK

In fulfillment of the above-stated objectives, the following tasks were performed:

- 1) Current and historical site and area data and usage was secured through courthouse records, interviews with current land tenants, if any, and/or well operators, if applicable, plus the review of aerial photographs, and other readily available public documents.
- 2) Public records or databases pertaining to the subject property and properties within a 1 mile radius of the site were reviewed in order to identify: local geological, hydrogeological, and soil characteristics; generators of hazardous waste, usage and storage of hazardous chemical, registered and leaking petroleum storage tanks, and past chemical spills; environmental permits, violations of environmental statutes, and the status of remediation efforts.
- 3) Visual inspection, review of aerial photographs and maps, and interviews with knowledgeable parties were performed in order to identify specific areas of environmental concern on-site or within close proximity of the site. Specific areas of concern assessed were: evidence of surface contamination, storage of and leakage of waste materials and raw process chemicals, abandoned drums, fuel and waste oil storage tanks, PCBs, and the potential migration of pollutants onto or off of the property.

ACRONYMS AND SYMBOLS

ACM:	Asbestos Containing Material
AST:	Above ground Storage Tank
AAPL:	American Association of Professional Landmen
bbf:	Unit of volume for petroleum equal to 42 gallons
BTEX:	Benzene, Toluene, Ethylbenzene, Xylene
CERCLIS:	Comprehensive Environmental Response, Compensation, and Liability Information System
CERCLA:	Comprehensive Environmental Response Compensation and Liability Act
CFR:	Code of Federal Regulations
EPA:	United State Environmental Protection Agency
EPCRA:	Emergency Planning and Community Right-to-Know Act (Title III of SARA)
LPST:	Leaking Petroleum Storage Tank
MCF:	Million Cubic Feet
NEPA:	National Environmental Policy Act of 1969
NIOSH:	National Institute for Occupational Safety and Health
NORM:	Naturally Occurring Radioactive Materials
NPDES:	National Pollutant Discharge Elimination System
NPL:	National Priorities List
OSHA:	Occupational Safety and Health Administration
PCBs:	Polychlorinated Biphenyls
pH:	Potential of Hydrogen (a measure of acidity or alkalinity)
PRPs:	Potentially Responsible Parties
PST:	Petroleum Storage Tank
RCRA:	Resource Conservation and Recovery Act
RRC:	Railroad Commission of Texas
Sf:	Square feet
SARA:	Superfund Amendment and Reauthorization Act
SCL:	State equivalent CERCLIS list
SHPO:	State Historical Preservation Officer
SPL:	State equivalent priority list
SWLF:	Solid waste land fills
TACB:	Texas Air Control Board
TNRCC:	Texas Natural Resource Conservation Commission
TDH:	Texas Department of Health
TSCA:	Toxic Substances Control Act
TSD:	Treatment, Storage and/or Disposal
TWDB:	Texas Water Development Board
UST:	Underground Storage Tank
VOC:	Volatile Organic Compounds
ppm(b):	parts per million (billion)
N/2:	North half
NW/4:	Northwest quarter

LOCATION & SITE DESCRIPTION

1.0 Site Overview

The subject .51 acre site is an old, somewhat historic, 14,420 sf brick building with a large, shop like, “cavernous” interior, plus catwalks and other large rooms. There is a smaller building and concrete tank in the small yard area on the south side. The building was built adjacent to the railroad tracks by the railroad for train repairs. The building is pretty much “trashed”. The subject tract is in a level area situated on the north edge of Pecos, Texas.

1.1 Legal Description of subject tract/Location/Government Jurisdictions

.51 acres, more or less, being Lots 17-24, Block 8, Original Town site of Pecos, Reeves County, Texas. See tax plat in the appendix.

Address: 100 S. Elm Street, Pecos, Texas 79772.

Latitude 31-25-34 North; Longitude 103-29-57 West.

The proposed site is inside the city limits of Pecos and is subject to city zoning ordinances.

1.2 Operator and Site Usage

The subject site is owned by Stephen A. Davis improved as a large brick building currently vacated with a small building and small yard area. There are no tenants/easements or surface leases. There does not appear to be any major pipeline easements across the tract. Pipelines, per se, are usually not cause for environmental concern, but all lines should be located, well marked and any surface use duly noted with respect to the easement. **The lands may also be subject to an oil and gas lease.**

SITE HISTORY

2.0 Past/Present ownership and Usage

The ASTM standard recommends that the user provide an abstracted title run sheet or similar (such as the 50 year chain of title as requested by many bank protocols) as may be researched by a professional landman using the county clerks’ direct/indirect indices.

The current owner of record is Stephen A. Davis, which acquired the facility and land from Davis and Yeshey Myles in 2016. They bought the land from Reeves County in 2003. The building was built in 1900 by the railroad as a maintenance shop and most recently was used as an ice plant. An abstracted 50-year chain of title was not ordered and should not be considered a significant data gap and will not affect my opinion.

Historical telephone directories (ie Polk City Directories) are sometimes used to determine the use by address when other ownership information is lacking or suspect of use. The directories were not researched for this site and would not present a significant data gap.

2.1 Aerial Photographs & Sanborn Maps

Aerial photos back to 1996 were reviewed and showed no other usage to the land as noted, and the site improved as stated in the site history overview. The historic aerial photos revealed no usage that would affect the environmental integrity of the tract or surrounding the tract. No other aerials were ordered and should not be considered a significant data gap and will not affect my opinion. Sanborn maps are generally hand-drafted maps that were prepared in previous years for various purposes, but basically utilized for fire related information. These maps, when available,

may show features of environmental concerns and equipment not apparent on the aerial photographs. These maps were not available for the subject site - not a significant data gap and will not affect my opinion.

ENVIRONMENTAL SETTING

3.0 Topography and Vegetation

The site is in the north side of Pecos, in an urban, arid environment. The subject is a level site with one main building, smaller building, small lawn and some parking. There was observed no distressed vegetation or significant stained areas in the yard area or in the front/sides parking areas.

3.1 Soil and Geology

The surficial soil in the Reeves County/ Midland-Odessa area is principally Amarillo loam. Generally, it is a fine sandy loam which ranges in depth from 8 to 10 inches. Below that, to depths from 18 to 24 inches, the subsoil is fine sandy loam to sandy clay. Pleistocene windblown sand, clay deposits, and alluvium deposits underlie the soil section. Beneath the Pleistocene are 25 to 35 feet of caliche deposits, which can be relatively impermeable in local areas. For further soil specifics, the US Department of Agriculture's National Resource Conservation Services database may be consulted.

3.2 Drainage and Surface Water Characteristics

The site is basically a level site with drainage off all sides and there is a bar ditch on the north county road and a collection pond on the south end. There are no recent FEMA flood maps for this area. There appears to be no issues with stormwater runoff onto the land from adjoining tracts.

3.3 Groundwater Characteristics/Issues

Shallow groundwater may become polluted from sources such as surface chemical spills and disposal activities, unlined impoundments, reservoir water-flood operations, leaking wellbore casing, unplugged wells, leaking above ground and underground storage tanks, leaking pipelines, valves and connections, contaminated surface water and contaminated groundwater upgradient of the site. *When contamination is suspected, actual subsurface data should be obtained to accurately determine groundwater gradient and condition.*

There was observed no abandoned, open water wellbores.

This report does not cover old or newly installed septic tanks, if any, on the subject lands.

4.0 Site Conditions

The subject property was inspected on September 2, 2021, by Ray L. McKim, III.

The subject .51 acre site is an old, somewhat historic, 14,420 sf brick building with a large, shop like, “cavernous” interior, plus catwalks and other large rooms. There is a smaller building and concrete tank in the small yard area on the south side. The building was built adjacent to the railroad tracks by the railroad for train repairs. The building is pretty much “trashed”. The subject tract is in a level area situated on the north edge of Pecos, Texas. There are no open pits, drainage ditches or dumpsites on or near the subject tract. The origination of any construction fill dirt, if any, is unknown.

4.1 Chemical Substance Inventory, Storage and Disposal

The moment a person (or acting as a business) opens and uses a can of solvent, they are a waste generator. A Texas state license is required for hauling wastes (and generator self-transport limits), for all generators less than 100 kg/mo to use a licensed commercial hazardous waste hauler or to obtain a license if they self- transport the waste.

There are no significant quantities of chemicals, hazardous materials, nor radioactive materials observed on site.

4.2 Asbestos

Asbestos spray-on insulation was banned in 1979, yet there is still a possibility that some of the construction materials in buildings prior to 1980 may contain more than 1% asbestos. EPA established the National Emission Standards for Hazardous Air Pollutants (NESHAP) to regulate asbestos and defines Asbestos Containing Materials (ACM) as follows;

- 1) Friable asbestos materials (any material containing more than 1% asbestos as determined using polarized light microscopy (PLM), that when dry, can be crumbled, pulverized or reduced to powder by hand pressure);
- 2) Non-friable ACM, Category I;
- 3) Category I non-friable ACM that has become friable,
- 4) Category I non-friable ACM that will be or has been subjected to sanding, grinding, cutting or abrading;
- 5) Category II non-friable ACM that has a high probability of becoming or has become crumbled, pulverized or reduced to powder by the forces expected to act on the material in the course of demolition or renovation operations.

NESHAP also defines a **Presumed Asbestos Containing Material** as being the thermal system insulation and surfacing material found in buildings constructed no later than 1980.

The two brick building improvements on the subject tract were built in 1900, so who knows if there has been any added improvements through the years where ACM might have been used. An asbestos survey was not provided for this report.

4.3 Above Ground Storage Tanks (AST's) & Petroleum Underground Storage Tanks (PUST's) and Leaking Underground Storage Tanks (LUST's)

There are no petroleum AST's and no UST's observed on site, and the database does not show any registered AST/UST on site and none on adjacent properties. There are three active USTs within .25 miles of the subject, closest being .13 miles SE. There are ten inactive USTs- the closest one being .06 miles East. There are ten LPST site being reported, the closest being .13 miles SE from the subject- all the sites being report are cases closed. The remainder of the sites are more than .25 miles from the subject- none of these sites listed should be an environmental concern to the subject.

4.4 Radon, Vapor Intrusion Conditions (VIC) and Indoor Pollution

Radon is a radioactive gas naturally produced by the decay of radium in the soil. Research suggests that exposure to high levels of radon can increase the risk of lung cancer. However, there has been continuing debate within the scientific community over just how much radon is required to pose a health risk. Where there is a raw land tract involved, soil testing for radon cannot be accurately measured and the EPA does not recommend soil testing for radon on raw land tracts.

Radon is measured in picocuries per liter of air. The EPA considers levels higher than 4 pCi/L unsafe (Zone 1). There are some areas of the Texas Panhandle and counties just east of El Paso County which may see levels of 2 – 4 pCi/L (Zone 2). Most of Texas is in Zone 3- Low Potential, testing less than 2 pCi/L. **Reeves County is in Zone 3.**

The subject site nor adjacent properties has presented any evidence or suspicion or concern as to any VIC. The Permian Basin is also an area with a soil condition consisting of thick, hard layers of caliche which would naturally impede a VIC from adjoining properties suspect of a release. There are no dry cleaners on or adjacent to the subject facility. One site listed in the database is a drop station and the other is being reported as "active" but does not detail as a drop station and/or if solvents are being used.

4.5 Polychlorinated Biphenyls (PCBs)

The Toxic Substance Control Act regulates any transformer(s) with mineral oil containing polychlorinated biphenyl's (PCB) in concentrations greater than 50 parts per million (ppm). Such transformers are considered PCB-contaminated and require appropriate remediation, should they be found to be stained or leaking. None of the transformers located on or near the property line of the subject property show any signs of leakage, the PCB content, if any, unknown.

4.6 UREA Formaldehyde, Lead Paint, NORMs

There is no knowledge of any sampling or other survey to determine the presence of UREA formaldehyde foam insulation, or lead paint. Any oilfield pipe stored onsite may have naturally occurring radioactive materials (NORMs) and should be tested for same if such usage will be other than oilfield application.

4.7 55 gallon Drums or containers

There was observed no 55-gallon drums nor plastic bulk totes on site, the contents unknown. In the future, all empty drums/totes that contained hazardous substances or petroleum products should be removed and properly disposed. Should any 55-gallon drums, empty or otherwise,

which may be used for trash or parts storage, they should be labeled for such use, and all other labels removed.

4.8 Interviews

Interviews are often conducted as part of the Phase I ESA process. Interviews include may include owners or other public and/or governmental authorities to gain further information concerning the subject site. The present owner of the building/land was not available for interview.

Local Agency Reviews: The local fire chief of the Reeves County Fire department was contacted but did not return my call for questioning as to any local spills in the area. In the event that my office receives information at a later date from the City of Pecos/Reeves County regarding this property and/or immediate surrounding areas, I will forward that information to the client as a supplemental to this report.

AREA & ADJACENT PROPERTIES

The subject property lies on the north edge of Pecos and the downtown area, and on the south side of the railroad tracks and on the east side of Elm Street. The area is mostly urban, commercial, light industry uses with some residential neighborhoods interspersed. There are oil and gas operations in the city/county, but none close for concern. Growth for the area is minimal.

None of the adjacent neighbors were observed to be engaged in any suspect environmental activities.

North adjacent: railroad tracks

West across Elm Street: oilfield pipe yard

East adjacent: PimmCo

South adjacent: a postal company

GOVERNMENT DATABASES

Databases and published reports created by federal, state, and local agencies were reviewed to determine if the site or properties in the site vicinity had been reported as having possible environmental concerns. The agencies and the information reviewed as discussed in the following paragraphs.

Federal and State Regulatory Agency Inquires

National Priorities List: The National Priorities List (NPL) is a list of sites identified by the EPA as having a priority for cleanup. Factors involved in determining the priority for cleanup include: the nature of contamination, the number of persons at risk, and the type, quantity, and toxicity of materials released.

This site is not listed on the NPL. No properties within a 1-mile radius of the site were listed on the NPL list.

CERCLIS List: This list is compiled by the EPA and includes properties which have the potential for releasing or are known to have released hazardous material into the environment, as well as mitigation remediation, and enforcement activities. This list is also known as the Federal Superfund Database. Many of the sites on this list have not been thoroughly investigated. All NPL sites are included on the CERCLIS list.

This site was not listed on the CERCLIS List. No properties within a 1/2-mile radius of the site were listed on the CERCLIS list.

RCRA Notifiers List: Facilities which generate hazardous waste are required to notify the EPA of their waste generation, storage, treatment, and disposal activities. The RCRA Notifies List includes all facilities which have met this requirement.

This site was not listed on the RCRA Notifiers List. No properties within a 1/4-mile radius of the site were listed on the RCRA Notifiers List..

RCRA Violators List: Facilities which have been inspected or evaluated for possible violation of regulations or provisions of the compliance orders, consent agreements, or permit conditions are included on the RCRA Violations/Corrective Actions List.

This site was not listed on the RCRA Violators List. No properties within a 1-mile radius of the site were listed on the RCRA Violators List.

ERNS List: The Emergency Response Notification System consists of release notifications submitted to the National Response Center of the U.S. Coast Guard, since 1987. The system contains preliminary information on specific releases, including the reported discharger, date, material releases, quantity, source, locations, and response actions taken.

This site was not listed on the ERNS List. No properties within a 1/4-mile radius of the site were listed on the ERNS List.

The non- geocoded are not close to the facility. There are no other sites noted in the database that pose any significant environmental concern to the subject facility.

LIMITING CONDITIONS

This report is based upon the application of scientific principles and professional opinions to certain facts with resultant subjective interpretations. Professional opinions expressed herein are based upon currently available information obtained within the limits of the existing data, scope of work, budget, and schedule. By their very nature, Phase I Environmental Site Assessments are often limited in the capacity to identify all significant environmental concerns which might affect the site, particularly with regard to subsurface contamination, flood issues and on-site historical and near vicinity chemical usage and releases. To the extent that more definitive conclusions are desired by the client than are warranted by the currently available facts, it is specifically stated here that Ray L. McKim, III intends that the conclusions and recommendations of this report will be used as guidance and not necessarily a firm course of action except where explicitly stated as such. Ray L. McKim, III makes no warranties, expressed or implied, as to the merchantability or fitness of the property for a particular purpose.

This report cannot and does not purport to give any definitive soil or groundwater contamination issues that may be present concerning AST/UST. Only a state licensed contractor for UST removal can determine the cost of any tank removal and also take soil samples to determine any needed remediation.

This report does not address RF exposure compliance issues, nor FAA or FCC issues other than those mentioned specifically within the assessment report.

This report also does not address the presence (or lack thereof) of black mold and other related bacteria or fungi. Also, the report does not address the very remote possibility of Vapor Intrusion Conditions.

Flood maps and /or topo maps, either of which may be used in this report, are at best an estimate of potential flood levels and drainage patterns and conditions. To assure against flooding conditions, an engineering survey showing flood elevations is strongly advised. This also applies to any NEPA report that may have been done in conjunction with this site.

The information provided in this report is not to be construed as legal advice. This report will follow ASTM E 1527-13 *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process*, and will address any data gaps and its significance. The report may or may not be AAI compliant, any data gaps notwithstanding.

There may be a reliance of information from client's database and the accuracy of such information is not warranted and subject to such risk if used.

This report is for the sole use of the client identified herein on the cover letter- any uses or reliance of this report for parties not specifically named herein are not permissible without the written permission of Ray L. McKim, III. This report is void if payment for services rendered is not timely paid.

Vitae- Ray L. McKim, III

Graduated Texas Tech University- Business. Certified in 1993 as a Professional Landman & Environmental Site Assessor under the requirements as a member of the American Association of Professional Landmen; Member No. 3231. In 1994, successful completion of the University of Texas at Arlington's course "Inspecting Buildings for Asbestos Containing Materials" in compliance with asbestos accreditation requirements under TSCA Title II. Ray L. McKim, III is not licensed in the State of Texas to perform asbestos testing. Recent Client/Projects.

Oil & Gas

- 1) Antelope Energy-Reagan County Assets
- 2) Knowles SWD
- 3) Andrews County SWD
- 4) Traditions Oil & Gas- Panhandle Assets
- 5) SAGA Petroleum

Telecom- Phase I & NEPA for telecommunication towers

- 1) InSite Wireless/Vanguard Towers
- 2) C. A. Bass/Verizon/Kinder Morgan/Skyways
- 3) WesTex Towers
- 4) Centerpoint/TCT/Enbridge
- 5) Sprint Wireless-outside DAS projects- Houston, El Paso, Corpus Christi
- 6) Titan Towers
- 7) Oxy pipeline-towers
- 8) Kay Radio towers- Louisiana/East Texas

Wind Projects & Solar

- 1) AES- Buffalo Gap Wind Farm
- 2) Hecate Energy- Crane County

Regional Commercial Clients - Banks & SBA loans on commercial properties

- 1) Prosperity Bank- state wide
- 2) Western National Bank (now Frost)
- 3) Commercial State Bank (now AMMO)
- 4) Community National Bank
- 5) SouthWest Bank
- 6) Security Bank (now AMMO)
- 7) FNB-Stanton
- 8) Bank of Ozarks
- 9) AIM Bank Lubbock
- 10) First Capital of Texas

Developers/Engineering Firms

- 1) Maverick Engineering
- 2) Kent Oil Co. and associated companies
- 3) Globe Energy
- 4) SMT Interests
- 5) KelTech properties
- 6) Dixie Electric
- 7) RRC Engineering
- 8) Parkhill, Smith & Cooper
- 9) Cities of Crane & Seminole
- 10) Weir Engineering

Site: 100 S. Elm Street, Pecos, Texas
View of south side of subject and small lawn/yard area



Old water tank in yard area?



Looking inside main shop room-west side



Looking at east shop area



Looking at floor damage in west room



Looking at east side of facility



Small building at southeast corner of main building



Looking at north side of building



Looking at north and west side of building



Google Earth aerial circa 2019



Google Earth aerial circa 2015



Google Earth aerial circa 2011



Google Earth aerial circa 2003



Google Earth aerial circa 1996



Reeves CAD Property Search

Property ID: R000011258 For Year 2021

Map



Property Details

Account	
Property ID:	R000011258
Legal Description:	Acres 0.510, N18 LT 17,18-24 BLK 8ORIG
Geographic ID:	00500-00515-00000-000000
Agent:	
Type:	Real
Location	
Address:	100 S ELM
Map ID:	
Neighborhood CD:	R11258
Owner	
Owner ID:	GMNI20170202150609797
Name:	DAVIS STEPHEN A
Mailing Address:	17 Camino San Cristobal Galisteo, NM 87540-9765
% Ownership:	100.0%
Exemptions:	For privacy reasons not all exemptions are shown online.

Property Values

Improvement Homesite Value:	\$0
Improvement Non-Homesite Value:	\$10,090
Land Homesite Value:	\$0
Land Non-Homesite Value:	\$12,550
Agricultural Market Valuation:	\$0
Market Value:	\$22,640
Ag Use Value:	\$0
Appraised Value:	\$22,640
Homestead Cap Loss: ⓘ	\$0
Assessed Value:	\$22,640

VALUES DISPLAYED ARE 2021 PRELIMINARY VALUES AND ARE SUBJECT TO CHANGE PRIOR TO CERTIFICATION.

Information provided for research purposes only. Legal descriptions and acreage amounts are for appraisal district use only and should be verified prior to using for legal purpose and or documents. Please contact the Appraisal District to verify all information for accuracy.

Property Taxing Jurisdiction

Entity	Description	Tax Rate	Market Value	Taxable Value	Estimated Tax	Freeze Ceiling
00	REEVES CO APPR DIST	0.000000	\$22,640	\$22,640	\$0.00	
01	REEVES COUNTY	0.525535	\$22,640	\$22,640	\$118.98	
10	TOWN OF PECOS CITY	0.600000	\$22,640	\$22,640	\$135.84	
15	RCGWCD	0.004000	\$22,640	\$22,640	\$0.91	
20	ESD #1	0.100000	\$22,640	\$22,640	\$22.64	
25	ESD #2	0.100000	\$22,640	\$22,640	\$22.64	
30	P-B-T I.S.D	1.125000	\$22,640	\$22,640	\$254.70	
65	REEVES CO HOSP DIST	0.240000	\$22,640	\$22,640	\$54.34	
T2	TRZ 2 - PROPERTY	0.000000	\$22,640	\$22,640	\$0.00	

Total Tax Rate: 2.694535 Estimated Taxes With Exemptions: \$610.04 Estimated Taxes Without Exemptions: \$610.04

Property Improvement - Building

Living Area: 14,420.00sqft Value: \$10,094

Type	Description	Class CD	Year Built	SQFT
FLV	REPAIR SHOP	FLAT		14,420.00
FVO	VAULT	FLAT		0.00

Property Land

Type	Description	Acreage	Sqft	Eff Front	Eff Depth	Market Value	Prod. Value
FF65		0.51	22,195.00	193.00	115.00	\$12,545	\$0

Property Roll Value History

Year	Improvements	Land Market	Ag Valuation	Appraised	HS Cap Loss	Assessed
2021	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2020	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2019	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2018	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2017	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2016	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2015	\$10,090	\$12,550	\$0	\$22,640	\$0	\$22,640
2014	\$14,420	\$5,790	\$0	\$20,210	\$0	\$20,210
2013	\$14,420	\$5,790	\$0	\$20,210	\$0	\$20,210
2012	\$14,420	\$5,790	\$0	\$20,210	\$0	\$20,210
2011	\$14,420	\$5,790	\$0	\$20,210	\$0	\$20,210

Property Deed History

Deed Date	Type	Description	Grantor	Grantee	Volume	Page	Number
10/18/2016			DAVIS STEPHEN ETUX YESHEY MYLES	DAVIS STEPHEN A	1327	62	16- 13599
6/18/2004	0		DAVIS STEPHEN & YESHEY MYLES	REEVES COUNTY TRUSTEE	680	401	
12/3/2003	0		REEVES COUNTY TRUSTEE	PERMIAN MECHANICAL SERV INC	672	339	

DISCLAIMER

VALUES DISPLAYED ARE 2021 PRELIMINARY VALUES AND ARE SUBJECT TO CHANGE PRIOR TO CERTIFICATION.

Information provided for research purposes only. Legal descriptions and acreage amounts are for appraisal district use only and should be verified prior to using for legal purpose and or documents. Please contact the Appraisal District to verify all information for accuracy.

100 S. Elm St
100 S. Elm St
Pecos, TX 79772

Inquiry Number: 6647322.2s
September 02, 2021

FirstSearch Report



6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Search Summary Report

**TARGET SITE 100 S. ELM ST
PECOS, TX 79772**

Category	Sel	Site	1/8	1/4	1/2	> 1/2	ZIP	TOTALS
<i>NPL</i>	Y	0	0	0	0	0	0	0
<i>NPL Delisted</i>	Y	0	0	0	0	0	0	0
<i>CERCLIS</i>	Y	0	0	0	1	-	0	1
<i>NFRAP</i>	Y	0	0	0	1	-	1	2
<i>RCRA COR ACT</i>	Y	0	0	0	0	0	0	0
<i>RCRA TSD</i>	Y	0	0	0	0	-	0	0
<i>RCRA GEN</i>	Y	0	0	0	-	-	0	0
<i>Federal IC / EC</i>	Y	0	0	0	0	-	0	0
<i>ERNS</i>	Y	0	-	-	-	-	0	0
<i>State/Tribal NPL</i>	Y	0	0	0	0	0	0	0
<i>State/Tribal SWL</i>	Y	0	0	0	0	-	0	0
<i>State/Tribal LTANKS</i>	Y	0	2	9	7	-	0	18
<i>State/Tribal Tanks</i>	Y	0	4	16	-	-	0	20
<i>State/Tribal IC / EC</i>	Y	0	0	0	0	-	0	0
<i>State/Tribal VCP</i>	Y	0	0	0	0	-	0	0
<i>ST/Tribal Brownfields</i>	Y	0	0	0	0	-	0	0
<i>US Brownfields</i>	Y	0	0	0	0	-	0	0
<i>Other Haz Sites</i>	Y	0	0	0	-	-	0	0
<i>Spills</i>	Y	0	-	-	-	-	0	0
<i>Other</i>	Y	0	0	5	-	-	0	5
- Totals --		0	6	30	9	0	1	46

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2020 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Search Summary Report

**TARGET SITE: 100 S. ELM ST
PECOS, TX 79772**

Category	Database	Update	Radius	Site	1/8	1/4	1/2	> 1/2	ZIP	TOTALS
NPL	NPL	07/29/2021	1.000	0	0	0	0	0	0	0
	Proposed NPL	07/29/2021	1.000	0	0	0	0	0	0	0
NPL Delisted	Delisted NPL	07/29/2021	1.000	0	0	0	0	0	0	0
CERCLIS	SEMS	07/29/2021	0.500	0	0	0	1	-	0	1
NFRAP	SEMS-ARCHIVE	07/29/2021	0.500	0	0	0	1	-	1	2
RCRA COR ACT	CORRACTS	03/22/2021	1.000	0	0	0	0	0	0	0
RCRA TSD	RCRA-TSDF	03/22/2021	0.500	0	0	0	0	-	0	0
RCRA GEN	RCRA-LQG	03/22/2021	0.250	0	0	0	-	-	0	0
	RCRA-SQG	03/22/2021	0.250	0	0	0	-	-	0	0
	RCRA-VSQG	03/22/2021	0.250	0	0	0	-	-	0	0
Federal IC / EC	US ENG CONTROLS	05/17/2021	0.500	0	0	0	0	-	0	0
	US INST CONTROLS	05/17/2021	0.500	0	0	0	0	-	0	0
ERNS	ERNS	06/14/2021	TP	0	-	-	-	-	0	0
State/Tribal NPL	SHWS	06/30/2020	1.000	0	0	0	0	0	0	0
State/Tribal SWL	SWF/LF	04/26/2021	0.500	0	0	0	0	-	0	0
State/Tribal LTANKS	INDIAN LUST	10/01/2020	0.500	0	0	0	0	-	0	0
	LPST	03/25/2021	0.500	0	2	9	7	-	0	18
State/Tribal Tanks	UST	06/07/2021	0.250	0	1	13	-	-	0	14
	AST	06/07/2021	0.250	0	3	3	-	-	0	6
	INDIAN UST	10/01/2020	0.250	0	0	0	-	-	0	0
State/Tribal IC / EC	AUL	06/24/2021	0.500	0	0	0	0	-	0	0
State/Tribal VCP	VCP	03/31/2021	0.500	0	0	0	0	-	0	0
ST/Tribal Brownfields	BROWNFIELDS	03/01/2021	0.500	0	0	0	0	-	0	0
US Brownfields	US BROWNFIELDS	06/10/2021	0.500	0	0	0	0	-	0	0

Search Summary Report

**TARGET SITE: 100 S. ELM ST
PECOS, TX 79772**

Category	Database	Update	Radius	Site	1/8	1/4	1/2	> 1/2	ZIP	TOTALS
Other Haz Sites	PRIORITYCLEANERS	03/01/2021	0.250	0	0	0	-	-	0	0
	US CDL	05/18/2021	TP	0	-	-	-	-	0	0
Spills	HMIRS	03/22/2021	TP	0	-	-	-	-	0	0
	SPILLS	07/27/2021	TP	0	-	-	-	-	0	0
	SPILLS 90	10/23/2012	TP	0	-	-	-	-	0	0
	SPILLS 80	05/15/2005	TP	0	-	-	-	-	0	0
Other	RCRA NonGen / NLR	03/22/2021	0.250	0	0	2	-	-	0	2
	TSCA	12/31/2016	TP	0	-	-	-	-	0	0
	TRIS	12/31/2018	TP	0	-	-	-	-	0	0
	SSTS	04/19/2021	TP	0	-	-	-	-	0	0
	RAATS	04/17/1995	TP	0	-	-	-	-	0	0
	PRP	12/30/2020	TP	0	-	-	-	-	0	0
	PADS	11/19/2020	TP	0	-	-	-	-	0	0
	ICIS	11/18/2016	TP	0	-	-	-	-	0	0
	FTTS	04/09/2009	TP	0	-	-	-	-	0	0
	MLTS	03/08/2021	TP	0	-	-	-	-	0	0
	RADINFO	07/01/2019	TP	0	-	-	-	-	0	0
	INDIAN RESERV	12/31/2014	1.000	0	0	0	0	0	0	0
	US AIRS	10/12/2016	TP	0	-	-	-	-	0	0
	FINDS	05/05/2021	TP	0	-	-	-	-	0	0
	DRYCLEANERS	05/24/2021	0.250	0	0	2	-	-	0	2
	Ind. Haz Waste	02/04/2021	0.250	0	0	1	-	-	0	1
	- Totals --				0	6	30	9	0	1

Site Information Report

Request Date: SEPTEMBER 2, 2021
Request Name: RAY MCKIM

Search Type: COORD
Job Number: NA

Target Site: 100 S. ELM ST
 PECOS, TX 79772

Site Location

	<u>Degrees (Decimal)</u>	<u>Degrees (Min/Sec)</u>	<u>UTMs</u>
Longitude:	103.497906	103.4979060 - 103° 29' 52.46"	Easting: 642767.2
Latitude:	31.426580	31.4265800 - 31° 25' 35.68"	Northing: 3477669.8
Elevation:	2583 ft. above sea level		Zone: Zone 13

Demographics

Sites: 45	Non-Geocoded: 1	Population: N/A		
RADON				
Federal EPA Radon Zone for REEVES County: 2				
Note: Zone 1 indoor average level > 4 pCi/L. : Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L. : Zone 3 indoor average level < 2 pCi/L.				

Federal Area Radon Information for Zip Code: 79772				
Number of sites tested: 6				
<u>Area</u>	<u>Average Activity</u>	<u>% <4 pCi/L</u>	<u>% 4-20 pCi/L</u>	<u>% >20 pCi/L</u>
Living Area - 1st Floor	0.983 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

Federal Area Radon Information for REEVES COUNTY, TX				
Number of sites tested: 6				
<u>Area</u>	<u>Average Activity</u>	<u>% <4 pCi/L</u>	<u>% 4-20 pCi/L</u>	<u>% >20 pCi/L</u>
Living Area - 1st Floor	0.983 pCi/L	100%	0%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	Not Reported	Not Reported	Not Reported	Not Reported

Site Information Report

RADON

State Database: TX Radon

Radon Test Results

County	Mean	Total Sites	%>4 pCi/L	%>20 pCi/L	Min pCi/L	Max pCi/L
REEVES	1.1	10	.0	.0	<.5	2.8

Target Site Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46

GEOCODED: 45

NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
--------	------------------------	-----------	---------	----------	----------	----------

No sites found for target address

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46 GEOCODED: 45 NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
1	UST --INACTIVE --17809 --75643 --637611482003202	TXDOT MAINTENANCE FACILITY	2ND PECOS, TX	0.06 East	+ 0	1
A2	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --111787 --6A - FINAL CONCURRENCE ISSUED --0051722	PECOS BULK PLANT	101 N CYPRESS PECOS, TX 79772	0.07 NNE	+ 0	10
A3	AST --47546 --722767482002156 --51722 --INACTIVE	RIO GRANDE DISTRIBUTORS	101 N CYPRESS PECOS, TX 79772	0.07 NNE	+ 0	11
A4	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --111500 --6A - FINAL CONCURRENCE ISSUED --0051820	NEWELL OIL PECOS WAREHOUSE	104 N CYPRESS PECOS, TX 79772	0.08 NNE	+ 0	15
A5	AST --61411 --253724962002086 --51820 --INACTIVE	NEWELL OILCO PECOS WHSE	104 N CYPRESS PECOS, TX 79772	0.08 NNE	+ 0	16
6	AST --37917 --732153482002139 --63130 --ACTIVE	TRANS PECOS DAIRY	7 M ON HWY 75 W 1 M PECOS, TX	0.11 ENE	- 1	20
B7	LPST --119747 --6X - CROSS REF TO ANOTHER LPST	FORMER GREYHOUND BUS STATION	202 W 3RD ST PECOS, TX	0.13 SE	+ 1	23
B8	UST --ACTIVE --46609 --78099 --564422592002086	GREYHOUND BUS STATION	202 W 3RD ST PECOS, TX 79772	0.13 SE	+ 1	24

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46 GEOCODED: 45 NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
B9	UST --INACTIVE --65495 --64957 --576686842002086	GTE PECOS 445 CENTRAL OFFICE	312 S CYPRESS ST PECOS, TX 79772	0.14 SE	+ 1	35
B10	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --100548 --6A - FINAL CONCURRENCE ISSUED --0030494	GTE PECOS CENTRAL OFFICE	312 S CYPRESS ST PECOS, TX 79772	0.14 SE	+ 1	42
C11	UST --INACTIVE --9618 --49196 --597094292002089	TUMBLEWEED NO 5	402 W 3RD ST PECOS, TX 79772	0.15 SSW	+ 2	43
C11	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --111548 --6A - FINAL CONCURRENCE ISSUED --0009618	TUMBLEWEED NO 5	402 W 3RD ST PECOS, TX 79772	0.15 SSW	+ 2	55
D12	UST --INACTIVE --47801 --53309 --477704322002087	TRANS-PECOS GAS	134 W 3RD ST PECOS, TX 79772	0.15 ESE	+ 1	56
D13	LPST --93354 --3 - MONITORING	TRANS PECOS GAS CO INC	134 W 3RD ST PECOS, TX	0.15 ESE	+ 1	70
C14	LPST --94063 --6A - FINAL CONCURRENCE ISSUED	HWY 80 EXXON	414 W 3RD ST PECOS, TX	0.15 SSW	+ 2	71
C15	UST --INACTIVE --2119 --95339 --684263722003095	TUMBLEWEED STATION 3	414 W 3RD ST PECOS, TX 79772	0.15 SSW	+ 2	72

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46 GEOCODED: 45 NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
E16	UST --INACTIVE --30132 --64671 --832717492002150	RIO PECOS SALES	HWY 80 PECOS, TX	0.17 ESE	+ 0	92
E17	UST --ACTIVE --79351 --122884 --984370922010320	WTGF PECOS GASCARD 170302	113 E 3RD ST PECOS, TX 79772	0.17 ESE	+ 0	100
E18	LPST --MONITORING --101611 --6A - FINAL CONCURRENCE ISSUED --0041720	CORNER CONOCO STATION	115 E 3RD ST PECOS, TX 79700	0.17 ESE	+ 0	123
E19	UST --INACTIVE --41720 --37783 --371793222002138	CORNER CONOCO	115 E 3RD ST PECOS, TX 79772	0.17 ESE	+ 0	124
F20	AST --135723 --942575922019149 --90617 --ACTIVE	TOPLINE FUELS	107 S CEDAR ST PECOS, TX 79772	0.17 ENE	- 1	133
G21	AST --49203 --556772162002088 --50347 --INACTIVE	ENMONS ROUSTABOUT & OILFIELD	103 N CEDAR ST PECOS, TX 79772	0.17 NE	- 1	136
G22	UST --INACTIVE --2609 --41097 --380411472002086	REEVES COUNTY PCT 4 YARD	113 N CEDAR ST PECOS, TX 79772	0.18 NE	- 1	138
F23	UST --INACTIVE --4217 --42911 --526037522002088	PECOS MOTORS	120 S CEDAR ST PECOS, TX 79772	0.18 ENE	- 1	145

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46 GEOCODED: 45 NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
24	AST --37847 --687300932007193 --50687 --ACTIVE	WEST TEXAS GAS WHSE 2	210 E A ST PECOS, TX 79772	0.20 NE	- 2	150
H25	UST --ACTIVE --3661 --37715 --808466782002138	UNCLES 170200	201 E 3RD ST PECOS, TX 79772	0.22 ESE	- 1	157
H25	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --112872 --6A - FINAL CONCURRENCE ISSUED --0003661	UNCLES 170200	201 E 3RD ST PECOS, TX 79772	0.22 ESE	- 1	188
H26	UST --INACTIVE --13308 --61400 --593221782002087	GOODYEAR TIRE STORE	308 S CEDAR ST PECOS, TX 79772	0.22 ESE	- 1	189
H27	Ind. Haz Waste --73058	GOODYEAR AUTO SERVICE CENTER	308 S CEDAR ST PECOS, TX 79772	0.22 ESE	- 1	194
H27	RCRA NonGen / NLR --TXD149982175	GOODYEAR AUTO SERVICE CENTER	308 S CEDAR ST PECOS, TX 79772	0.22 ESE	- 1	197
H28	DRYCLEANERS --24007568 --CN605311430 --RN109656215 --ACTIVE	TOP TIER CLEANERS	212 E 3RD ST PECOS, TX 79772	0.23 ESE	- 1	201
H29	DRYCLEANERS --24007912 --CN605684638 --RN109656215 --ACTIVE	COMET CLEANERS	212 E 3RD ST PECOS, TX 79772	0.23 ESE	- 1	202
30	RCRA NonGen / NLR --TXD988069951	GREASEWOOD TREATING PLANT	HWY 285 10 MI N OF PECOS PECOS, TX, TX 79772	0.23 NNE	- 2	203

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46 GEOCODED: 45 NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
I31	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --113736 --6A - FINAL CONCURRENCE ISSUED --0000143	ACOSTA CONOCO	602 W 3RD ST PECOS, TX 79772	0.24 SW	+ 3	208
I32	UST --INACTIVE --143 --38068 --943056182002139	ACOSTA CONOCO	602 W 3RD ST PECOS, TX 79772	0.24 SW	+ 3	209
I32	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --114733 --6A - FINAL CONCURRENCE ISSUED --0000143	ACOSTA CONOCO	602 W 3RD ST PECOS, TX 79772	0.24 SW	+ 3	220
I33	LPST --93591 --6X - CROSS REF TO ANOTHER LPST	RIO GRANDE DISTRIBUTORS INC	620 W 3RD ST PECOS, TX	0.25 SW	+ 3	221
J34	LPST --92765 --3 - MONITORING	WEST SIDE SERVICE	702 W 3RD ST PECOS, TX 79772	0.30 SW	+ 3	222
J35	LPST --94301 --6X - CROSS REF TO ANOTHER LPST	FINA STORE	714 W 3RD ST PECOS, TX 79772	0.30 SW	+ 3	223
36	LPST --FINAL CONCURRENCE ISSUED, CASE CLOSED --114624 --6A - FINAL CONCURRENCE ISSUED	OCTAVIO MUNEZS PRIVATE RESIDEN	421 N CEDAR PECOS, TX 79722	0.31 NNE	- 3	224
37	SEMS-ARCHIVE	WAYNE FEEDS	2ND AND OLEANDER STREET PECOS, TX 79772	0.33 WSW	+ 2	225
38	LPST --91597 --6A - FINAL CONCURRENCE ISSUED	TOWN COUNTRY 29	915 W 3RD ST PECOS, TX	0.42 SW	+ 5	228
39	SEMS --0607544 --TXN000607544	PECOS MERCURY SPILL	623 S. ASH STREETSEP2013 PECOS, TX 79772	0.43 SE	- 1	229

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46

GEOCODED: 45

NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
40	LPST --93432 --6A - FINAL CONCURRENCE ISSUED	MERCHANTS FAST MOTOR LINES	PECOS, TX	0.45 WSW	+ 5	230
41	LPST --91630 --6A - FINAL CONCURRENCE ISSUED	ALLSUPS 102266	708 S CEDAR ST PECOS, TX 79772	0.46 SE	+ 0	231

Sites Summary Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

TOTAL: 46

GEOCODED: 45

NON GEOCODED: 1

Map ID	DB Type --ID/Status	Site Name	Address	Dist/Dir	ElevDiff	Page No.
	SEMS-ARCHIVE --0603385 --TXD981600554	ACID DELINTING OF PECOS	0.8 MI N 2ND ST & ALAMO S PECOS, TX 79772	NON GC	N/A	N/A

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: TXDOT MAINTENANCE FACILITY
Address: 2ND
City,State,Zip: PECOS, TX
AI Number: 17809
Facility Type: FLEET REFUELING
Facility Begin Date: 08/28/1986
Facility Status: INACTIVE
Additional ID: 637611482003202
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: 2ND
Site Location (Nearest City Name): PECOS
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: T GALINDO,FORMAN
Contact Organization Name: TXDOT MAINTENANCE FACILITY
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9154454737
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 04/22/1986
Signature Name/Title On Earliest Reg Form: R S NEAL,DIST MAINT ENG.
Application Received Date On Earliest Reg Form: 05/08/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:

Owner CN: CN600803456
Owner Last Name: TEXAS DEPARTMENT OF TRANSPORTATION
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: SG
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 976653722002061
Additional ID: 637611482003202
AI Number: 17809
Owner Effective Begin Date: 08/28/1986
State Tax ID: Not reported
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1956
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 1000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 45957
Facility ID: 75643
Ai Number: 17809
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 12/31/1963
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): Y
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
 PECOS, TX

ID/Status: INACTIVE
 ID/Status: 17809
 ID/Status: 75643
 ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMethod (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N
 Piping Corr Prot Compliance Flag: N
 Tank Corrosion Prot Variance: N
 Piping Corrosion Prot Variance: N
 Temp Out Of Service Compliance: N
 Technical Compliance Flag: N
 Tank Tested Flag: N
 Installation Signature Date: 07/26/1993

Compartment Records:
 Tank ID: 1
 Tank Capacity: 1000
 UST Comprt ID: 118000
 UST ID: 45957
 AI Number: 17809
 Compartment ID: A
 Substance Stored1: EMPTY
 Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
 PECOS, TX

ID/Status: INACTIVE
 ID/Status: 17809
 ID/Status: 75643
 ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
 CompartmentReleaseDetectionMethod(Vapor): N
 CRDM(GW Monitoring): N
 CRDM(Monitoring Of Secondary Cont Barrier): N
 CRDM(Auto Tank Gauge Test/Inv Control): N
 CRDM(Interstitial Monitoring SecWall/Jacket): N
 CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
 CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
 CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
 PipingReleaseDetectionMethod(PRDM)(Vapor): N
 PRDM(Groundwater Monitoring): N
 PRDM(Monitoring Sec Containment Barrier): N
 PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
 PRDM(Mthly Piping Tightness Test)@.2Gph: N
 PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
 PRDM(TriennialTightTest(Suction/GravityPiping): N
 PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
 PRDM(Sir(StatInv Recon)/Inv Control)): N
 PRDM(Exempt System Suction: N
 Spill Overfill Prevention Equip(SOPE): N
 SOPE(Spill Cont/Bucket/Sump): N
 SOPE(DelShut-Off Valve): N
 SOPE(FlowRestrictorValue: N
 SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
 SOPE(N/A Deliveries To Tank<=25G): N
 Compartment Release Det Compliance Flag: N
 Piping Release Detection Compliance Flag): N
 Spill/OverfillPreventionCompliance Flag: N
 Compartment Release Detection Variance: N
 Piping Release Detection Variance: N
 Spill And Overfill Prevention Variance: N
 Stage I Vapor Recovery: Not reported
 Stage 1 Installation Date: Not reported

Install Date: 01/01/1956
 Tank Registration Date: 05/08/1986
 Number of Compartments: 1
 Tank Capacity: 1000
 Tank Singlewall: Y
 Tank Doublewall: N
 Pipe Type: Not reported
 UST ID: 45959
 Facility ID: 75643
 Ai Number: 17809

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Tank Id: 2
 Tank Status (Current): REMOVED FROM GROUND
 Tank Status Date: 12/31/1963
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): Y
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: 07/26/1993

Compartment Records:

Tank ID: 2
Tank Capacity: 1000
UST Comprt ID: 118002
UST ID: 45959
AI Number: 17809
Compartment ID: A
Substance Stored1: EMPTY
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b): N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1956
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 1000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 45958
Facility ID: 75643
Ai Number: 17809
Tank Id: 3
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 12/31/1963
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): Y
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: 07/26/1993

Compartment Records:

Tank ID: 3
Tank Capacity: 1000
UST Comprt ID: 118001
UST ID: 45958
AI Number: 17809
Compartment ID: A
Substance Stored1: EMPTY
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001252820 **DIST/DIR:** 0.063 East **ELEVATION:** 2583 **MAP ID:** 1

NAME: TXDOT MAINTENANCE FACILITY

Rev: 06/07/2021

ADDRESS: 2ND
PECOS, TX

ID/Status: INACTIVE
ID/Status: 17809
ID/Status: 75643
ID/Status: 637611482003202

SOURCE: TX Texas Commission on Environmental Quality

PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve)): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage 1 Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S103501599 **DIST/DIR:** 0.070 NNE **ELEVATION:** 2583 **MAP ID:** A2

NAME: PECOS BULK PLANT **Rev:** 03/25/2021
ADDRESS: 101 N CYPRESS ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
PECOS, TX 79772 ID/Status: 111787
REEVES ID/Status: 6A - FINAL CONCURRENCE ISSUED
SOURCE: TX Texas Commission on Environmental Quality ID/Status: 0051722

LPST:
Name: PECOS BULK PLANT
Address: 101 N CYPRESS
City,State,Zip: PECOS, TX 79772
Facility ID: 0051722
LPST Id: 111787
Facility Location: 101 N CYPRESS
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: ODESSA
Discovered Date: 10/09/1996
Entered Date: 10/17/1996
Reported Date: 10/10/1996
Closure Date: 02/09/2007
Priority: 3.5 - A DESIGNATED MAJOR OR MINOR AQUIFER IS IMPACTED
Program: 1P - PRIVATIZATION CONTRACTOR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: A designated major or minor groundwater aquifer is affected or immediately threatened.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 1P/1
Coordinators RPR: TH2
Responsible Party Name: Not reported
Responsible Party Contact: JERRY L SMITH
Responsible Party Address: PO BOX 1770
Responsible Party City,St,Zip: EL PASO, TX 79949 1770
Responsible Party Telephone: 432/336-7551
Reported Date: 10/10/1996
Case Start Date: 02/09/2007

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120475 **DIST/DIR:** 0.070 NNE **ELEVATION:** 2583 **MAP ID:** A3

NAME: RIO GRANDE DISTRIBUTORS **Rev:** 06/07/2021
ADDRESS: 101 N CYPRESS ID/Status: 47546
PECOS, TX 79772 ID/Status: 722767482002156
ID/Status: 51722
ID/Status: INACTIVE
SOURCE: TX Texas Commission on Environmental Quality

AST:
Name: RIO GRANDE DISTRIBUTORS
Address: 101 N CYPRESS
City,State,Zip: PECOS, TX 79772
Facility ID: 47546
Additional ID: 722767482002156
AI Number: 51722
Facility Type: WHOLESALE
Facility Begin Date: 03/27/1990
Facility Status: INACTIVE
Facility Exempt Status: N
Records Off-Site: N
UST Financial Assurance Required: N
Number of Active ASTs: 0
Site Location Description: Not reported
Site Location (nearest city name): Not reported
Site Location (county name): REEVES
Site Location (TCEQ region): 7
Site Location (location zip): 79772
Contact Name/Title: /
Contact Organization Name: RIO GRANDE DISTRIBUTORS INC
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact CityStateZip: Not reported
Contact Telephone: 9153367551
Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date on Earliest Reg Form: 02/21/1990
Signature First Name on Earliest Reg Form: JERRY L
Application Received Date on Earliest Reg Form: 02/26/1990
Signature Middle Name on Earliest Reg Form: Not reported
Signature Last Name on Earliest Reg Form: SMITH
Signature Title on Earliest Reg Form: PRES
Signature Role on Earliest Reg Form: Not reported
Signature Company on Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: N
Facility Not Inspectable Reason A: Not reported
Facility Not Inspectable Reason B: Not reported
Enforcement Action Date: Not reported
Facility:
Facility ID: 47546
Tank ID: 4

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120475 **DIST/DIR:** 0.070 NNE **ELEVATION:** 2583 **MAP ID:** A3

NAME: RIO GRANDE DISTRIBUTORS

Rev: 06/07/2021

ADDRESS: 101 N CYPRESS
PECOS, TX 79772

ID/Status: 47546
ID/Status: 722767482002156
ID/Status: 51722
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST ID: 157861
AI Number: 51722
Install Date: 08/31/1989
Tank Registration Date: 02/26/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 12000
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 47546
Tank ID: 3
AST ID: 157862
AI Number: 51722
Install Date: 08/31/1989
Tank Registration Date: 02/26/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 12000
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120475 **DIST/DIR:** 0.070 NNE **ELEVATION:** 2583 **MAP ID:** A3

NAME: RIO GRANDE DISTRIBUTORS

Rev: 06/07/2021

ADDRESS: 101 N CYPRESS
PECOS, TX 79772

ID/Status: 47546
ID/Status: 722767482002156
ID/Status: 51722
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 47546
Tank ID: 2
AST ID: 157863
AI Number: 51722
Install Date: 08/31/1989
Tank Registration Date: 02/26/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 17200
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 47546
Tank ID: 1
AST ID: 157864
AI Number: 51722
Install Date: 08/31/1989
Tank Registration Date: 02/26/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 17200
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120475 **DIST/DIR:** 0.070 NNE **ELEVATION:** 2583 **MAP ID:** A3

NAME: RIO GRANDE DISTRIBUTORS

Rev: 06/07/2021

ADDRESS: 101 N CYPRESS
PECOS, TX 79772

ID/Status: 47546
ID/Status: 722767482002156
ID/Status: 51722
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U003372801 **DIST/DIR:** 0.078 NNE **ELEVATION:** 2583 **MAP ID:** A4

NAME: NEWELL OIL PECOS WAREHOUSE **Rev:** 03/25/2021
ADDRESS: 104 N CYPRESS ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
PECOS, TX 79772 ID/Status: 111500
REEVES ID/Status: 6A - FINAL CONCURRENCE ISSUED
SOURCE: TX Texas Commission on Environmental Quality ID/Status: 0051820

LPST:
Name: NEWELL OIL PECOS WAREHOUSE
Address: 104 N CYPRESS
City,State,Zip: PECOS, TX 79772
Facility ID: 0051820
LPST Id: 111500
Facility Location: 104 N CYPRESS
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: ODESSA
Discovered Date: 08/09/1996
Entered Date: 08/21/1996
Reported Date: 08/09/1996
Closure Date: 02/09/2007
Priority: 4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program: 1P - PRIVATIZATION CONTRACTOR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Groundwater is affected.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 1P/1/1P/1/1P/1
Coordinators RPR: TH2
Responsible Party Name: Not reported
Responsible Party Contact: LEE COWELL
Responsible Party Address: PO BOX 390
Responsible Party City,St,Zip: ALPINE, TX 79831
Responsible Party Telephone: 972/401-6685
Reported Date: 08/09/1996
Case Start Date: 02/09/2007

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120476 **DIST/DIR:** 0.078 NNE **ELEVATION:** 2583 **MAP ID:** A5

NAME: NEWELL OILCO PECOS WHSE
ADDRESS: 104 N CYPRESS
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 61411
ID/Status: 253724962002086
ID/Status: 51820
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST:
Name: NEWELL OILCO PECOS WHSE
Address: 104 N CYPRESS
City,State,Zip: PECOS, TX 79772
Facility ID: 61411
Additional ID: 253724962002086
AI Number: 51820
Facility Type: WHOLESALE
Facility Begin Date: 03/26/1990
Facility Status: INACTIVE
Facility Exempt Status: N
Records Off-Site: N
UST Financial Assurance Required: N
Number of Active ASTs: 0
Site Location Description: Not reported
Site Location (nearest city name): Not reported
Site Location (county name): REEVES
Site Location (TCEQ region): 7
Site Location (location zip): 79772
Contact Name/Title: /
Contact Organization Name: NEWELL OIL CO-PECOS WHSE
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact CityStateZip: Not reported
Contact Telephone: 9158373322
Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date on Earliest Reg Form: 03/20/1990
Signature First Name on Earliest Reg Form: LEE
Application Received Date on Earliest Reg Form: 03/23/1990
Signature Middle Name on Earliest Reg Form: Not reported
Signature Last Name on Earliest Reg Form: COWELL
Signature Title on Earliest Reg Form: PRES
Signature Role on Earliest Reg Form: Not reported
Signature Company on Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: N
Facility Not Inspectable Reason A: Not reported
Facility Not Inspectable Reason B: Not reported
Enforcement Action Date: Not reported
Facility:
Facility ID: 61411
Tank ID: 5

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120476 **DIST/DIR:** 0.078 NNE **ELEVATION:** 2583 **MAP ID:** A5

NAME: NEWELL OILCO PECOS WHSE
ADDRESS: 104 N CYPRESS
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 61411
ID/Status: 253724962002086
ID/Status: 51820
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST ID: 158130
AI Number: 51820
Install Date: 08/31/1989
Tank Registration Date: 03/23/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 14634
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 61411
Tank ID: 2
AST ID: 158131
AI Number: 51820
Install Date: 08/31/1989
Tank Registration Date: 03/23/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 12/30/1991
Tank Reg Status: FULLY REGULATED
Tank Capacity: 14634
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120476 **DIST/DIR:** 0.078 NNE **ELEVATION:** 2583 **MAP ID:** A5

NAME: NEWELL OILCO PECOS WHSE
ADDRESS: 104 N CYPRESS
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 61411
ID/Status: 253724962002086
ID/Status: 51820
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 61411
Tank ID: 3
AST ID: 158132
AI Number: 51820
Install Date: 08/31/1989
Tank Registration Date: 03/23/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 12/30/1991
Tank Reg Status: FULLY REGULATED
Tank Capacity: 5000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 61411
Tank ID: 1
AST ID: 158133
AI Number: 51820
Install Date: 08/31/1989
Tank Registration Date: 03/23/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 12/30/1991
Tank Reg Status: FULLY REGULATED
Tank Capacity: 14634
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120476 **DIST/DIR:** 0.078 NNE **ELEVATION:** 2583 **MAP ID:** A5

NAME: NEWELL OILCO PECOS WHSE

Rev: 06/07/2021

ADDRESS: 104 N CYPRESS
PECOS, TX 79772

ID/Status: 61411
ID/Status: 253724962002086
ID/Status: 51820
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 61411
Tank ID: 4
AST ID: 158134
AI Number: 51820
Install Date: 08/31/1989
Tank Registration Date: 03/23/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 0
Substance: Not reported
Other Substance B: Not reported
Other Substance C: Not reported
Steel: N
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120489 **DIST/DIR:** 0.113 ENE **ELEVATION:** 2582 **MAP ID:** 6

NAME: TRANS PECOS DAIRY
ADDRESS: 7 M ON HWY 75 W 1 M
PECOS, TX

Rev: 06/07/2021
ID/Status: 37917
ID/Status: 732153482002139
ID/Status: 63130
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST:

Name: TRANS PECOS DAIRY
Address: 7 M ON HWY 75 W 1 M
City,State,Zip: PECOS, TX
Facility ID: 37917
Additional ID: 732153482002139
AI Number: 63130
Facility Type: FLEET REFUELING
Facility Begin Date: 07/15/1992
Facility Status: ACTIVE
Facility Exempt Status: N
Records Off-Site: N
UST Financial Assurance Required: N
Number of Active ASTs: 2
Site Location Description: 7 M ON HWY 75 W 1 M
Site Location (nearest city name): PECOS
Site Location (county name): REEVES
Site Location (TCEQ region): 7
Site Location (location zip): 79772
Contact Name/Title: TX SELLERS/
Contact Organization Name: TRANS PECOS DAIRY
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact CityStateZip: Not reported
Contact Telephone: 9154459811
Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date on Earliest Reg Form: 06/02/1992
Signature First Name on Earliest Reg Form: KEITH
Application Received Date on Earliest Reg Form: 06/08/1992
Signature Middle Name on Earliest Reg Form: Not reported
Signature Last Name on Earliest Reg Form: OLIVER
Signature Title on Earliest Reg Form: AUDITOR
Signature Role on Earliest Reg Form: Not reported
Signature Company on Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: N
Facility Not Inspectable Reason A: Not reported
Facility Not Inspectable Reason B: Not reported
Enforcement Action Date: Not reported

Facility:
Facility ID: 37917
Tank ID: 00015

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120489 **DIST/DIR:** 0.113 ENE **ELEVATION:** 2582 **MAP ID:** 6

NAME: TRANS PECOS DAIRY
ADDRESS: 7 M ON HWY 75 W 1 M
PECOS, TX

Rev: 06/07/2021
ID/Status: 37917
ID/Status: 732153482002139
ID/Status: 63130
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST ID: 166271
AI Number: 63130
Install Date: 01/01/1992
Tank Registration Date: 06/08/1992
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1992
Tank Reg Status: FULLY REGULATED
Tank Capacity: 2000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37917
Tank ID: 00015
AST ID: 166272
AI Number: 63130
Install Date: 01/01/1992
Tank Registration Date: 06/08/1992
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1992
Tank Reg Status: FULLY REGULATED
Tank Capacity: 2000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100120489 **DIST/DIR:** 0.113 ENE **ELEVATION:** 2582 **MAP ID:** 6

NAME: TRANS PECOS DAIRY
ADDRESS: 7 M ON HWY 75 W 1 M
PECOS, TX

Rev: 06/07/2021
ID/Status: 37917
ID/Status: 732153482002139
ID/Status: 63130
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S118368246 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B7

NAME: FORMER GREYHOUND BUS STATION

Rev: 03/25/2021

ADDRESS: 202 W 3RD ST
PECOS, TX
REEVES

ID/Status: 119747
ID/Status: 6X - CROSS REF TO ANOTHER LPST

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: FORMER GREYHOUND BUS STATION

Address: 202 W 3RD ST

City,State,Zip: PECOS, TX

Facility ID: Not reported

LPST Id: 119747

Facility Location: Not reported

TCEQ Region# and City: REGION 07 - MIDLAND

Region City: Not reported

Discovered Date: 06/01/2015

Entered Date: 09/28/2015

Reported Date: 06/01/2015

Closure Date: 12/31/3000

Priority: 3.3 - GW IMPACT NON-PUBLIC/NON-DOMESTIC H2O SUPPLY WELL W/IN.25MI

Program: 3 - STATE LEAD

CA Status: 6X - CROSS REF TO ANOTHER LPST

Priority Description: Not reported

Status: Not reported

Coordinators Primary: Not reported

Coordinators RPR: Not reported

Responsible Party Name: Not reported

Responsible Party Contact: Not reported

Responsible Party Address: Not reported

Responsible Party City,St,Zip: Not reported

Responsible Party Telephone: Not reported

Reported Date: 06/01/2015

Case Start Date: 12/31/3000

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: GREYHOUND BUS STATION
Address: 202 W 3RD ST
City,State,Zip: PECOS, TX 797723122
AI Number: 46609
Facility Type: Not reported
Facility Begin Date: 01/01/1963
Facility Status: ACTIVE
Additional ID: 564422592002086
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: Yes
Number Of Active UST: 3
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: FRED DOMINGUEZ,OWNER
Contact Organization Name: GREYHOUND BUS STATION
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9154455016
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 10/16/1988
Signature Name/Title On Earliest Reg Form: F DOMINGUEZ,OWNER
Application Received Date On Earliest Reg Form: 10/27/1988
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: No
Facility Not Inspectable: No

Owner:
Owner CN: CN600929855
Owner Last Name: DOMINGUEZ
Owner First Name: FRED
Owner Middle Name: Not reported
Owner Type: IN
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 555422582002086
Additional ID: 564422592002086
AI Number: 46609
Owner Effective Begin Date: 12/07/1988
State Tax ID: Not reported
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1963
Tank Registration Date: 10/27/1988
Number of Compartments: 1
Tank Capacity: Not reported
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 121955
Facility ID: 78099
Ai Number: 46609
Tank Id: 1
Tank Status (Current): TEMP OUT OF SERVICE
Tank Status Date: 08/31/1987
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:
Tank ID: 1
Tank Capacity: Not reported
UST Comprt ID: 121182
UST ID: 121955
AI Number: 46609
Compartment ID: A
Substance Stored1: EMPTY
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1963
Tank Registration Date: 10/27/1988
Number of Compartments: 1
Tank Capacity: Not reported
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 121956
Facility ID: 78099
Ai Number: 46609

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Tank Id: 3
 Tank Status (Current): TEMP OUT OF SERVICE
 Tank Status Date: 08/31/1987
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): N
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 3
Tank Capacity: Not reported
UST Comprt ID: 121183
UST ID: 121956
AI Number: 46609
Compartment ID: A
Substance Stored1: EMPTY
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION
ADDRESS: 202 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1963
Tank Registration Date: 10/27/1988
Number of Compartments: 1
Tank Capacity: Not reported
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 121957
Facility ID: 78099
Ai Number: 46609
Tank Id: 2
Tank Status (Current): TEMP OUT OF SERVICE
Tank Status Date: 08/31/1987
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 DIST/DIR: 0.131 SE ELEVATION: 2584 MAP ID: B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 2
Tank Capacity: Not reported
UST Comprt ID: 121184
UST ID: 121957
AI Number: 46609
Compartment ID: A
Substance Stored1: EMPTY
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage 1 Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Construction Notification:

NOC ID: 27304
Facility ID: 78099
AI Number: 46609
Application Received Date: 03/24/2015
Scheduled Construction Date: 03/24/2015
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: Not reported
Waiver Flag: Not reported
Late Filing Flag: Y
Form Received Date: 03/24/2015

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION

Rev: 06/07/2021

ADDRESS: 202 W 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Signature Date On Form: 03/23/2015
Signature Name On Form: ANGELA MILES
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: DOMINGUEZ, FRED
Owner CN At Time Of Construction: CN600929855
Owner AR At Time Of Construction: 23501
General Desc Of Prop Construct: THREE (3) UNDERGROUND STORAGE TANKS (YSTS) AND ASSOCIATED PIPING WILL BE REMOVED DURING THIS SITE ACTIVITY

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 64008
UST ID: Not reported
NOC ID: 27304
AI Number: 46609
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: Not reported
Company Name: TALON LPE
Representative Name: ANGELA MILES
Mailing Address (Delivery): 13111 LOOKOUT WAY
Mailing Address (Internal Delivery): Not reported
Mailing City: SAN ANTONIO
Mailing State: TX
Mailing Zip: 78233
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 210
Phone Number: 2658025
Phone Number Extension: Not reported
Fax Number Country Code: 1
Fax Number Area Code: 210
Fax Number: 5682191
Email Address: Not reported

Facility Billing Contacts:
Contact Organization Name: DOMINGUEZ FRED
Contact Mailing Address (Delivery): PO BOX 2085
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: PECOS, TX 79772 2085
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001278040 **DIST/DIR:** 0.131 SE **ELEVATION:** 2584 **MAP ID:** B8

NAME: GREYHOUND BUS STATION
ADDRESS: 202 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 46609
ID/Status: 78099
ID/Status: 564422592002086

SOURCE: TX Texas Commission on Environmental Quality

Contact Address Deliverable: Y
Facility ID: 78099
Additional ID: 564422592002086
Princ ID: 555422582002086
AI Number: 46609
Facility Name: GREYHOUND BUS STATION
AR Number: 23501
AR UST Number Suffix: Not reported
AR AST Number Suffix: U
Contact Name/Title: /

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: GTE PECOS 445 CENTRAL OFFICE

Address: 312 S CYPRESS ST

City,State,Zip: PECOS, TX 797723104

AI Number: 65495

Facility Type: Not reported

Facility Begin Date: 03/16/1994

Facility Status: INACTIVE

Additional ID: 576686842002086

Facility Exempt Status: N

Records Off-Site: No

UST Financial Assurance Required: No

Number Of Active UST: 0

Site Location Description: Not reported

Site Location (Nearest City Name): Not reported

Site Location (County Name): REEVES

Site Location (Tceq Region): 7

Site Location (Location Zip): 79772

Contact Name/Title: KEN BEARD,

Contact Organization Name: GTE PECOS 445 CENTRAL OFFICE

Contact Mailing Address1: Not reported

Contact Mailing Address2: Not reported

Contact Mailing City/State/Zip: Not reported

Contact Telephone: 2147177840

Facility Contact Address Deliverable: Not reported

Contact Fax Number: Not reported

Contact Email Address: Not reported

Signature Date On Earliest Reg Form: 03/07/1994

Signature Name/Title On Earliest Reg Form: KEN BEARD,ADMIN-ENVIRON COMP

Application Received Date On Earliest Reg Form: 03/14/1994

Signature Role On Earliest Reg Form: Not reported

Signature Company On Earliest Reg Form: Not reported

Enforcement Action: Not reported

Facility Not Inspectable: No

Owner:

Owner CN: CN600276158

Owner Last Name: FRONTIER SOUTHWEST INCORPORATED

Owner First Name: Not reported

Owner Middle Name: Not reported

Owner Type: CO

Contact Mailing Address (Delivery): Not reported

Contact Mailing Address (Internal Delivery): Not reported

Contact Mailing City: Not reported

Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 331328162001297
Additional ID: 576686842002086
AI Number: 65495
Owner Effective Begin Date: 02/22/1999
State Tax ID: 17505734446
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 08/31/1987
Tank Registration Date: 03/14/1994
Number of Compartments: 1
Tank Capacity: 285
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: S
UST ID: 149698
Facility ID: 64957
Ai Number: 65495
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 10/01/1991
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): Y
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 1
Tank Capacity: 285
UST Comprt ID: 75527
UST ID: 149698
AI Number: 65495
Compartment ID: A
Substance Stored1: DIESEL
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 25509
Cert ID: 69654
UST Comprt ID: 217006
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

Cert ID: 290564
UST Comprt ID: 838822
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 256033
UST Comprt ID: 736602
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 69653
UST Comprt ID: 217007
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 69649
UST Comprt ID: 217009
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 339970
UST Comprt ID: 987077
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 323468
UST Comprt ID: 937443
UST ID: 80333
AI Number: 65495
Tank ID: 2

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

Compartment ID: A

Self Cert ID: 25509
Cert ID: 69650
UST Comprt ID: 217010
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 305974
UST Comprt ID: 885300
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 239681
UST Comprt ID: 688421
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 69651
UST Comprt ID: 217011
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 273492
UST Comprt ID: 788277
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 69652
UST Comprt ID: 217008

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001829292 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B9

NAME: GTE PECOS 445 CENTRAL OFFICE

Rev: 06/07/2021

ADDRESS: 312 S CYPRESS ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 65495
ID/Status: 64957
ID/Status: 576686842002086

SOURCE: TX Texas Commission on Environmental Quality

UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Self Cert ID: 25509
Cert ID: 222467
UST Comprt ID: 638041
UST ID: 80333
AI Number: 65495
Tank ID: 2
Compartment ID: A

Facility Billing Contacts:
Contact Organization Name: GTE SOUTHWEST INCORPORATED
Contact Mailing Address (Delivery): 2400 N GLENVILLE DR
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: RICHARDSON, TX 75082 4331
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 64957
Additional ID: 576686842002086
Princ ID: 331328162001297
AI Number: 65495
Facility Name: GTE PECOS 445 CENTRAL OFFICE
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: /

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S116695205 **DIST/DIR:** 0.139 SE **ELEVATION:** 2584 **MAP ID:** B10

NAME: GTE PECOS CENTRAL OFFICE **Rev:** 03/25/2021
ADDRESS: 312 S CYPRESS ST ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
PECOS, TX 79772 ID/Status: 100548
REEVES ID/Status: 6A - FINAL CONCURRENCE ISSUED
SOURCE: TX Texas Commission on Environmental Quality ID/Status: 0030494

LPST:
Name: GTE PECOS CENTRAL OFFICE
Address: 312 S CYPRESS ST
City,State,Zip: PECOS, TX 79772
Facility ID: 0030494
LPST Id: 100548
Facility Location: 312 S CYPRESS
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: ODESSA
Discovered Date: 10/16/1991
Entered Date: 11/12/1991
Reported Date: 10/16/1991
Closure Date: 10/16/1995
Priority: 3.5 - A DESIGNATED MAJOR OR MINOR AQUIFER IS IMPACTED
Program: 1 - RPR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: A designated major or minor groundwater aquifer is affected or immediately threatened.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 1/2
Coordinators RPR: ARB
Responsible Party Name: Not reported
Responsible Party Contact: KEN BEARD
Responsible Party Address: PO BOX 152013
Responsible Party City,St,Zip: IRVING, TX 75015 2013
Responsible Party Telephone: 214/717-7840
Reported Date: 10/16/1991
Case Start Date: 10/16/1995

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: TUMBLEWEED NO 5
Address: 402 W 3RD ST
City,State,Zip: PECOS, TX 797723121
AI Number: 9618
Facility Type: RETAIL
Facility Begin Date: 07/17/1986
Facility Status: INACTIVE
Additional ID: 597094292002089
Facility Exempt Status: N
Records Off-Site: Yes
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: FRANK VAIRO,V.P.
Contact Organization Name: TUMBLEWEED NO 5
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 8178380330
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 04/10/1986
Signature Name/Title On Earliest Reg Form: EARL WAFER,PLANT MGR
Application Received Date On Earliest Reg Form: 05/08/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:
Owner CN: CN601018203
Owner Last Name: TUMBLEWEED PETROLEUM CORP
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 587094282002089
Additional ID: 597094292002089
AI Number: 9618
Owner Effective Begin Date: 04/02/1997
State Tax ID: 30115945641
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1974
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 8000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 25467
Facility ID: 49196
Ai Number: 9618
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 01/21/1999
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): Y
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): Y
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 04/25/1990

Compartment Records:
Tank ID: 1
Tank Capacity: 8000
UST Comprt ID: 28198
UST ID: 25467
AI Number: 9618
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 DIST/DIR: 0.150 SSW ELEVATION: 2585 MAP ID: C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: Y
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1974
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 8000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 25468
Facility ID: 49196
Ai Number: 9618

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5 **Rev:** 06/07/2021
ADDRESS: 402 W 3RD ST ID/Status: INACTIVE
 PECOS, TX 79772 ID/Status: 9618
 ID/Status: 49196
 ID/Status: 597094292002089
SOURCE: TX Texas Commission on Environmental Quality

Tank Id: 2
 Tank Status (Current): REMOVED FROM GROUND
 Tank Status Date: 01/21/1999
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): Y
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): Y
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): Y
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 04/25/1990

Compartment Records:

Tank ID: 2
Tank Capacity: 8000
UST Comprt ID: 28199
UST ID: 25468
AI Number: 9618
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): Y
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b): N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1986
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 1000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 25469
Facility ID: 49196
Ai Number: 9618
Tank Id: 3
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 01/21/1999
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): Y
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): Y
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): Y
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 04/25/1990

Compartment Records:

Tank ID: 3
Tank Capacity: 1000
UST Comprt ID: 28200
UST ID: 25469
AI Number: 9618
Compartment ID: A
Substance Stored1: LPG
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage 1 Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1981
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 500
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 25470
Facility ID: 49196
Ai Number: 9618
Tank Id: 4
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 01/21/1999
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
 PECOS, TX 79772

ID/Status: INACTIVE
 ID/Status: 9618
 ID/Status: 49196
 ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): N
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMethod (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N
 Piping Corr Prot Compliance Flag: N
 Tank Corrosion Prot Variance: N
 Piping Corrosion Prot Variance: N
 Temp Out Of Service Compliance: N
 Technical Compliance Flag: N
 Tank Tested Flag: Y
 Installation Signature Date: 04/25/1990

Compartment Records:

Tank ID: 4
 Tank Capacity: 500

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

UST Comprt ID: 28201
UST ID: 25470
AI Number: 9618
Compartment ID: A
Substance Stored1: USED OIL
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Facility Billing Contacts:
Contact Organization Name: TUMBLEWEED PETROLEUM CORP
Contact Mailing Address (Delivery): 7903 OLD SPRINGTOWN RD

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5

Rev: 06/07/2021

ADDRESS: 402 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 9618
ID/Status: 49196
ID/Status: 597094292002089

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: SPRINGTOWN, TX 76082 7143
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 49196
Additional ID: 597094292002089
Princ ID: 587094282002089
AI Number: 9618
Facility Name: TUMBLEWEED NO 5
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: FRANK VAIRO/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U003103628 **DIST/DIR:** 0.150 SSW **ELEVATION:** 2585 **MAP ID:** C11

NAME: TUMBLEWEED NO 5 **Rev:** 03/25/2021
ADDRESS: 402 W 3RD ST ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
PECOS, TX 79772 ID/Status: 111548
ID/Status: 6A - FINAL CONCURRENCE ISSUED
ID/Status: 0009618
SOURCE: TX Texas Commission on Environmental Quality

LPST:
Name: TUMBLEWEED PETROLEUM 5
Address: 402 W 3RD ST
City,State,Zip: PECOS, TX 79772
Facility ID: 0009618
LPST Id: 111548
Facility Location: 402 W 3RD ST
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: ODESSA
Discovered Date: 08/23/1996
Entered Date: 09/17/1996
Reported Date: 08/27/1996
Closure Date: 05/12/2009
Priority: 3.5 - A DESIGNATED MAJOR OR MINOR AQUIFER IS IMPACTED
Program: 1P - PRIVATIZATION CONTRACTOR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: A designated major or minor groundwater aquifer is affected or immediately threatened.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 1P/1/1P/1
Coordinators RPR: DB2
Responsible Party Name: Not reported
Responsible Party Contact: FRANK VAIRO
Responsible Party Address: 7903 OLD SPRINGTOWN RD
Responsible Party City,St,Zip: SPRINGTOWN, TX 76082
Responsible Party Telephone: 817/594-8022
Reported Date: 08/27/1996
Case Start Date: 05/12/2009

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

UST:
Name: TRANS-PECOS GAS
Address: 134 W 3RD ST
City,State,Zip: PECOS, TX 79772
AI Number: 47801
Facility Type: FLEET REFUELING
Facility Begin Date: 03/14/1989
Facility Status: INACTIVE
Additional ID: 477704322002087
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: MIKE A BURKHOLDER,MGR
Contact Organization Name: TRANS-PECOS GAS
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9154452035
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 10/10/1988
Signature Name/Title On Earliest Reg Form: SAME,
Application Received Date On Earliest Reg Form: 10/12/1989
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:
Owner CN: CN600988281
Owner Last Name: TRANS-PECOS GAS COMPANY INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 516704312002087
Additional ID: 477704322002087
AI Number: 47801
Owner Effective Begin Date: 03/14/1989
State Tax ID: 17418899757
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1968
Tank Registration Date: 10/12/1989
Number of Compartments: 1
Tank Capacity: 1000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 124553
Facility ID: 53309
Ai Number: 47801
Tank Id: 2
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 07/14/1989
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS

Rev: 06/07/2021

ADDRESS: 134 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: 08/03/1990

Compartment Records:
Tank ID: 2
Tank Capacity: 1000
UST Comprt ID: 42982
UST ID: 124553
AI Number: 47801
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 DIST/DIR: 0.153 ESE ELEVATION: 2584 MAP ID: D12

NAME: TRANS-PECOS GAS

Rev: 06/07/2021

ADDRESS: 134 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 18431
Cert ID: 305784
UST Comprt ID: 884745
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Cert ID: 95930
UST Comprt ID: 281020
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95929
UST Comprt ID: 281021
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 284400
UST Comprt ID: 820760
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95928
UST Comprt ID: 281022
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 321651
UST Comprt ID: 931984
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95927
UST Comprt ID: 281026
UST ID: 106555
AI Number: 47801
Tank ID: 2

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Compartment ID: A

Self Cert ID: 18431
Cert ID: 95926
UST Comprt ID: 281025
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 338956
UST Comprt ID: 984281
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95925
UST Comprt ID: 281024
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95924
UST Comprt ID: 281023
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 287533
UST Comprt ID: 829925
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95932
UST Comprt ID: 281018

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95933
UST Comprt ID: 281017
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95934
UST Comprt ID: 281016
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 238151
UST Comprt ID: 683891
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95935
UST Comprt ID: 281015
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95936
UST Comprt ID: 281014
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 18431
Cert ID: 95931
UST Comprt ID: 281019
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95937
UST Comprt ID: 281013
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Install Date: 01/01/1968
Tank Registration Date: 10/12/1989
Number of Compartments: 1
Tank Capacity: 1000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 124554
Facility ID: 53309
Ai Number: 47801
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 07/14/1989
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: 08/03/1990

Compartment Records:
Tank ID: 1
Tank Capacity: 1000
UST Comprt ID: 42983
UST ID: 124554
AI Number: 47801
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 18431
Cert ID: 305784
UST Comprt ID: 884745
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95930

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

UST Comprt ID: 281020
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95929
UST Comprt ID: 281021
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 284400
UST Comprt ID: 820760
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95928
UST Comprt ID: 281022
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 321651
UST Comprt ID: 931984
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95927
UST Comprt ID: 281026
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 18431
Cert ID: 95926
UST Comprt ID: 281025
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 338956
UST Comprt ID: 984281
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95925
UST Comprt ID: 281024
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95924
UST Comprt ID: 281023
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 287533
UST Comprt ID: 829925
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95932
UST Comprt ID: 281018
UST ID: 106555
AI Number: 47801

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95933
UST Comprt ID: 281017
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95934
UST Comprt ID: 281016
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 238151
UST Comprt ID: 683891
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95935
UST Comprt ID: 281015
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95936
UST Comprt ID: 281014
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95931

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001279044 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D12

NAME: TRANS-PECOS GAS
ADDRESS: 134 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 47801
ID/Status: 53309
ID/Status: 477704322002087

SOURCE: TX Texas Commission on Environmental Quality

UST Comprt ID: 281019
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Self Cert ID: 18431
Cert ID: 95937
UST Comprt ID: 281013
UST ID: 106555
AI Number: 47801
Tank ID: 2
Compartment ID: A

Facility Billing Contacts:

Contact Organization Name: TRANS-PECOS GAS CO INC
Contact Mailing Address (Delivery): PO BOX 1562
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: PECOS, TX 79772 1562
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 53309
Additional ID: 477704322002087
Princ ID: 516704312002087
AI Number: 47801
Facility Name: TRANS-PECOS GAS
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: /

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S111101255 **DIST/DIR:** 0.153 ESE **ELEVATION:** 2584 **MAP ID:** D13

NAME: TRANS PECOS GAS CO INC

Rev: 03/25/2021

ADDRESS: 134 W 3RD ST
PECOS, TX
REEVES

ID/Status: 93354
ID/Status: 3 - MONITORING

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: TRANS PECOS GAS CO INC

Address: 134 W 3RD ST

City,State,Zip: PECOS, TX

Facility ID: Not reported

LPST Id: 93354

Facility Location: Not reported

TCEQ Region# and City: REGION 07 - MIDLAND

Region City: Not reported

Discovered Date: 07/13/1989

Entered Date: 08/01/1989

Reported Date: 07/13/1989

Closure Date: 12/31/3000

Priority: 3.3 - GW IMPACT NON-PUBLIC/NON-DOMESTIC H2O SUPPLY WELL W/IN.25mi

Program: 3D - STATE LEAD DIRECT AWARD

CA Status: 3 - MONITORING

Priority Description: Not reported

Status: Not reported

Coordinators Primary: Not reported

Coordinators RPR: Not reported

Responsible Party Name: Not reported

Responsible Party Contact: Not reported

Responsible Party Address: Not reported

Responsible Party City,St,Zip: Not reported

Responsible Party Telephone: Not reported

Reported Date: 07/13/1989

Case Start Date: 12/31/3000

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S105049518 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C14

NAME: HWY 80 EXXON **Rev:** 03/25/2021
ADDRESS: 414 W 3RD ST ID/Status: 94063
PECOS, TX ID/Status: 6A - FINAL CONCURRENCE ISSUED
REEVES
SOURCE: TX Texas Commission on Environmental Quality

LPST:
Name: HWY 80 EXXON
Address: 414 W 3RD ST
City,State,Zip: PECOS, TX
Facility ID: Not reported
LPST Id: 94063
Facility Location: Not reported
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Not reported
Discovered Date: 11/15/1989
Entered Date: 12/08/1989
Reported Date: 11/15/1989
Closure Date: 01/10/2001
Priority: 2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi
Program: 1 - RPR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Not reported
Status: Not reported
Coordinators Primary: Not reported
Coordinators RPR: Not reported
Responsible Party Name: Not reported
Responsible Party Contact: Not reported
Responsible Party Address: Not reported
Responsible Party City,St,Zip: Not reported
Responsible Party Telephone: Not reported
Reported Date: 11/15/1989
Case Start Date: 01/10/2001

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: TUMBLEWEED STATION 3
Address: 414 W 3RD ST
City,State,Zip: PECOS, TX 797723121
AI Number: 2119
Facility Type: RETAIL
Facility Begin Date: 08/31/1989
Facility Status: INACTIVE
Additional ID: 684263722003095
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: ,
Contact Organization Name: TUMBLEWEED STATION 3
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 8178380330
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 03/03/1986
Signature Name/Title On Earliest Reg Form: DARRELL LOCKER,OWNER
Application Received Date On Earliest Reg Form: 05/08/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:
Owner CN: CN601018203
Owner Last Name: TUMBLEWEED PETROLEUM CORP
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 587094282002089
Additional ID: 684263722003095
AI Number: 2119
Owner Effective Begin Date: 09/01/1989
State Tax ID: 30115945641
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1966
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 5000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 5231
Facility ID: 95339
Ai Number: 2119
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 09/15/1989
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic)): Y
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:
Tank ID: 1
Tank Capacity: 5000
UST Comprt ID: 159697
UST ID: 5231
AI Number: 2119
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 DIST/DIR: 0.154 SSW ELEVATION: 2585 MAP ID: C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 860
Cert ID: 154264
UST Comprt ID: 437827
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Cert ID: 346928
UST Comprt ID: 1007999
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154266
UST Comprt ID: 437825
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154265
UST Comprt ID: 437826
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154256
UST Comprt ID: 437833
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154257
UST Comprt ID: 437834
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154258
UST Comprt ID: 437835
UST ID: 164023
AI Number: 2119
Tank ID: 3

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Compartment ID: A

Self Cert ID: 860
Cert ID: 154259
UST Comprt ID: 437832
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154260
UST Comprt ID: 437831
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154261
UST Comprt ID: 437830
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154262
UST Comprt ID: 437829
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154263
UST Comprt ID: 437828
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 247887
UST Comprt ID: 712653

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 230473
UST Comprt ID: 661592
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 263103
UST Comprt ID: 757725
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 279330
UST Comprt ID: 805301
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 296278
UST Comprt ID: 855668
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 312808
UST Comprt ID: 905266
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 860
Cert ID: 329871
UST Comprt ID: 956118
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Install Date: 01/01/1981
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 5000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 5232
Facility ID: 95339
Ai Number: 2119
Tank Id: 3
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 09/15/1989
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/Ext Polyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 3
Tank Capacity: 5000
UST Comprt ID: 159698
UST ID: 5232
AI Number: 2119
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 860
Cert ID: 154264
UST Comprt ID: 437827
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 346928
UST Comprt ID: 1007999
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154266

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

UST Compr ID: 437825
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154265
UST Compr ID: 437826
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154256
UST Compr ID: 437833
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154257
UST Compr ID: 437834
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154258
UST Compr ID: 437835
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154259
UST Compr ID: 437832
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 860
Cert ID: 154260
UST Comprt ID: 437831
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154261
UST Comprt ID: 437830
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154262
UST Comprt ID: 437829
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154263
UST Comprt ID: 437828
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 247887
UST Comprt ID: 712653
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 230473
UST Comprt ID: 661592
UST ID: 164023
AI Number: 2119

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 263103
UST Comprt ID: 757725
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 279330
UST Comprt ID: 805301
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 296278
UST Comprt ID: 855668
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 312808
UST Comprt ID: 905266
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 329871
UST Comprt ID: 956118
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Install Date: 01/01/1966

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Tank Registration Date: 05/08/1986
 Number of Compartments: 1
 Tank Capacity: 5000
 Tank Singlewall: N
 Tank Doublewall: N
 Pipe Type: Not reported
 UST ID: 5233
 Facility ID: 95339
 Ai Number: 2119
 Tank Id: 2
 Tank Status (Current): REMOVED FROM GROUND
 Tank Status Date: 09/15/1989
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): N
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): N
 Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMMethod (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 2
Tank Capacity: 5000
UST Comprt ID: 159699
UST ID: 5233
AI Number: 2119
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control): N
PRDM(Exempt System Suction): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b): N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 860
Cert ID: 154264
UST Comprt ID: 437827
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 346928
UST Comprt ID: 1007999
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154266
UST Comprt ID: 437825
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154265
UST Comprt ID: 437826
UST ID: 164023

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154256
UST Comprt ID: 437833
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154257
UST Comprt ID: 437834
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154258
UST Comprt ID: 437835
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154259
UST Comprt ID: 437832
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154260
UST Comprt ID: 437831
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Cert ID: 154261
UST Comprt ID: 437830
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154262
UST Comprt ID: 437829
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 154263
UST Comprt ID: 437828
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 247887
UST Comprt ID: 712653
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 230473
UST Comprt ID: 661592
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 263103
UST Comprt ID: 757725
UST ID: 164023
AI Number: 2119
Tank ID: 3

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3

Rev: 06/07/2021

ADDRESS: 414 W 3RD ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Compartment ID: A

Self Cert ID: 860
Cert ID: 279330
UST Comprt ID: 805301
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 296278
UST Comprt ID: 855668
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 312808
UST Comprt ID: 905266
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Self Cert ID: 860
Cert ID: 329871
UST Comprt ID: 956118
UST ID: 164023
AI Number: 2119
Tank ID: 3
Compartment ID: A

Facility Billing Contacts:

Contact Organization Name: TUMBLEWEED PETROLEUM CORP
Contact Mailing Address (Delivery): 1612 N SYLVANIA AVE
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: FORT WORTH, TX 76111 2733
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239191 **DIST/DIR:** 0.154 SSW **ELEVATION:** 2585 **MAP ID:** C15

NAME: TUMBLEWEED STATION 3
ADDRESS: 414 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 2119
ID/Status: 95339
ID/Status: 684263722003095

SOURCE: TX Texas Commission on Environmental Quality

Facility ID: 95339
Additional ID: 684263722003095
Princ ID: 587094282002089
AI Number: 2119
Facility Name: TUMBLEWEED STATION 3
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: MARK OWENS/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: RIO PECOS SALES
Address: HWY 80
City,State,Zip: PECOS, TX
AI Number: 30132
Facility Type: FLEET REFUELING
Facility Begin Date: 10/31/1986
Facility Status: INACTIVE
Additional ID: 832717492002150
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: HWY 80
Site Location (Nearest City Name): PECOS
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79735
Contact Name/Title: B BURKHOLDER,VP
Contact Organization Name: RIO PECOS SALES CO
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9154454200
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 06/24/1986
Signature Name/Title On Earliest Reg Form: R L DUNAGAN,MGR
Application Received Date On Earliest Reg Form: 06/26/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:

Owner CN: CN601246382
Owner Last Name: RIO PECOS SALES CO
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: OR
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 823717492002150
Additional ID: 832717492002150
AI Number: 30132
Owner Effective Begin Date: 10/31/1986
State Tax ID: Not reported
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1984
Tank Registration Date: 06/26/1986
Number of Compartments: 1
Tank Capacity: 2000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 79422
Facility ID: 64671
Ai Number: 30132
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 12/15/1988
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 1
Tank Capacity: 2000
UST Comprt ID: 72841
UST ID: 79422
AI Number: 30132
Compartment ID: A
Substance Stored1: DIESEL
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 DIST/DIR: 0.167 ESE ELEVATION: 2583 MAP ID: E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

More Self Certification:

Self Cert ID: 11458

Cert ID: 162342

UST Comprt ID: 471620

UST ID: 157193

AI Number: 30132

Tank ID: 5

Compartment ID: A

Self Cert ID: 11458

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

Cert ID: 162341
UST Comprt ID: 471621
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 223637
UST Comprt ID: 641428
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 241096
UST Comprt ID: 692613
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162344
UST Comprt ID: 471618
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162345
UST Comprt ID: 471617
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162335
UST Comprt ID: 471625
UST ID: 157193
AI Number: 30132
Tank ID: 5

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

Compartment ID: A

Self Cert ID: 11458
Cert ID: 162336
UST Comprt ID: 471626
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 297371
UST Comprt ID: 858823
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 290617
UST Comprt ID: 838970
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 313004
UST Comprt ID: 905889
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 329184
UST Comprt ID: 954157
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 346638
UST Comprt ID: 1007187

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 259606
UST Comprt ID: 747269
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 274132
UST Comprt ID: 790037
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162337
UST Comprt ID: 471627
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162338
UST Comprt ID: 471624
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162339
UST Comprt ID: 471623
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001263626 **DIST/DIR:** 0.167 ESE **ELEVATION:** 2583 **MAP ID:** E16

NAME: RIO PECOS SALES

Rev: 06/07/2021

ADDRESS: HWY 80
PECOS, TX

ID/Status: INACTIVE
ID/Status: 30132
ID/Status: 64671
ID/Status: 832717492002150

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 11458
Cert ID: 162346
UST Comprt ID: 471616
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162340
UST Comprt ID: 471622
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Self Cert ID: 11458
Cert ID: 162343
UST Comprt ID: 471619
UST ID: 157193
AI Number: 30132
Tank ID: 5
Compartment ID: A

Facility Billing Contacts:
Contact Organization Name: RIO PECOS SALES CO
Contact Mailing Address (Delivery): PO BOX 910
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: FORT STOCKTON, TX 79735 0910
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 64671
Additional ID: 832717492002150
Princ ID: 823717492002150
AI Number: 30132
Facility Name: RIO PECOS SALES
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: /

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: WTGF PECOS GASCARD 170302
Address: 113 E 3RD ST
City,State,Zip: PECOS, TX 79772
AI Number: 79351
Facility Type: FLEET REFUELING
Facility Begin Date: 05/02/2008
Facility Status: ACTIVE
Additional ID: 984370922010320
Facility Exempt Status: N
Records Off-Site: Yes
UST Financial Assurance Required: Yes
Number Of Active UST: 3
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: AL BARTZ,
Contact Organization Name: WTGF PECOS GASCARD 170302
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 4326824349
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 09/03/2015
Signature Name/Title On Earliest Reg Form: AL BARTZ,
Application Received Date On Earliest Reg Form: 09/03/2015
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: No
Facility Not Inspectable: No

Operator:
Princ ID: 108589422004169
Additional ID: 984370922010320
Ai Number: 79351
Operator CN: CN602647752
Operator Name: WTG FUELS INC
Operator Effective Begin Date: 05/02/2008
Operator Type: CO
Operator Role: OWNOPRCON
Contact Name: SHAWNETTE HALLFORD/SAFETY MANAGER

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Contact Organization Name: WTG FUELS INC
Contact Mailing Address (Delivery): 11501 W COUNTY ROAD 125
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: ODESSA TX 79765-9674
Contact Phone Country Code: 1
Contact Phone Area Code: 432
Contact Phone Number: 9677746
Contact Phone Extension: 0
Contact Fax Country Code: Not reported
Contact Fax Area Code: Not reported
Contact Fax Number: Not reported
Contact Fax Extension: Not reported
Contact Email Address: SHALLFORD@GASCARD.NET
Contact Address Deliverable: Not reported

Owner:
Owner CN: CN602647752
Owner Last Name: WTG FUELS INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): 11501 W COUNTY ROAD 125
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: ODESSA
Contact Mailing State: TX
Contact Mailing Zip: 79765
Contact Mailing Zip5: 9674
Contact Phone Number/Ext: 1 432 9677746/0
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: SHALLFORD@GASCARD.NET
Contact Address Deliverable: Not reported
Princ ID: 108589422004169
Additional ID: 984370922010320
AI Number: 79351
Owner Effective Begin Date: 05/02/2008
State Tax ID: 12006960657
Contact Role: OWNOPRCON
Contact Name/Title: SHAWNETTE HALLFORD/SAFETY MANAGER
Contact Organization Name: WTG FUELS INC

Self Certification:
Self Cert ID: 122884
Cert ID: 353479

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

AI Number: 79351
Self Certification Date: 04/28/2021
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2022
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 336481
AI Number: 79351
Self Certification Date: 05/06/2020
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2021
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 319935
AI Number: 79351
Self Certification Date: 04/30/2019
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2020
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 303172
AI Number: 79351
Self Certification Date: 04/30/2018
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2019
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 286022
AI Number: 79351
Self Certification Date: 05/02/2017
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2018
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 269797
AI Number: 79351
Self Certification Date: 05/19/2016
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2017
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 253111
AI Number: 79351
Self Certification Date: 05/14/2015
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2016
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 236917
AI Number: 79351
Self Certification Date: 05/28/2014

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2015
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 122884
Cert ID: 220149
AI Number: 79351
Self Certification Date: 05/24/2013
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2014
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: N
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: N

Self Cert ID: 122884
Cert ID: 217281
AI Number: 79351
Self Certification Date: 05/23/2012
Signature Name/Title: AL E BARTZ OPERATIONS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Delivery Certificate Expiration Date: 05/31/2013
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 122884
Cert ID: 217280
AI Number: 79351
Self Certification Date: 05/24/2011
Signature Name/Title: AL E BARTZ OPERATIONS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2012
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 122884
Cert ID: 217279
AI Number: 79351
Self Certification Date: 04/27/2010
Signature Name/Title: AL BARTZ OPS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2011
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 122884
Cert ID: 217278
AI Number: 79351
Self Certification Date: 05/20/2009
Signature Name/Title: AL BARTZ OPS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2010
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 122884
Cert ID: 217277
AI Number: 79351
Self Certification Date: 06/26/2008
Signature Name/Title: AL BARTZ OPER MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: INITIAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2009
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Tank:
Install Date: 05/02/2008
Tank Registration Date: 06/27/2008
Number of Compartments: 1
Tank Capacity: 15000
Tank Singlewall: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Tank Doublewall: Y
Pipe Type: P
UST ID: 210151
Facility ID: 122884
Ai Number: 79351
Tank Id: 1
Tank Status (Current): IN USE
Tank Status Date: 05/02/2008
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): Y
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMethod (FRP Tank Or Piping(Noncorrodible)): Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
PCPMeth(Isolated Open Area/2nd Containment): Y
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: Y
Piping Corr Prot Compliance Flag: Y
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: Y
Installation Signature Date: 06/06/2008

Compartment Records:

Tank ID: 1
Tank Capacity: 15000
UST Comprt ID: 183434
UST ID: 210151
AI Number: 79351
Compartment ID: A
Substance Stored1: DIESEL
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): Y
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

SOPE(Alarm (Set@<=90%) W/3a Or 3b): Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

Install Date: 05/02/2008
Tank Registration Date: 06/27/2008
Number of Compartments: 1
Tank Capacity: 12000
Tank Singlewall: N
Tank Doublewall: Y
Pipe Type: P
UST ID: 210152
Facility ID: 122884
Ai Number: 79351
Tank Id: 2
Tank Status (Current): IN USE
Tank Status Date: 05/02/2008
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): Y
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible)): Y
PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
PCPMeth(Isolated Open Area/2nd Containment): Y
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: Y
Piping Corr Prot Compliance Flag: Y
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: Y
Installation Signature Date: 06/06/2008

Compartment Records:

Tank ID: 2
Tank Capacity: 12000
UST Comprt ID: 183435
UST ID: 210152
AI Number: 79351
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): Y
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

Install Date: 05/02/2008
Tank Registration Date: 06/27/2008
Number of Compartments: 1
Tank Capacity: 10000
Tank Singlewall: N
Tank Doublewall: Y
Pipe Type: P
UST ID: 210153
Facility ID: 122884
Ai Number: 79351
Tank Id: 3
Tank Status (Current): IN USE
Tank Status Date: 05/02/2008
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): Y
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): Y
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
PCPMeth(Isolated Open Area/2nd Containment): Y
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: Y
Piping Corr Prot Compliance Flag: Y
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Installation Signature Date: 06/06/2008

Compartment Records:

Tank ID: 3
Tank Capacity: 10000
UST Comprt ID: 183436
UST ID: 210153
AI Number: 79351
Compartment ID: A
Substance Stored1: DIESEL
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): Y
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Construction Notification:

NOC ID: 34972

Facility ID: 122884

AI Number: 79351

Application Received Date: 07/10/2019

Scheduled Construction Date: 07/22/2019

UST Improvement: N

UST Installation: Y

UST Removal: N

UST Repair: N

UST Return To Service: N

UST Replacement: N

UST Abandonment: N

UST Stage I: N

AST Installation: N

AST Stage I: N

Historical Tracking Number: Not reported

Waiver Flag: Y

Late Filing Flag: N

Form Received Date: 07/10/2019

Signature Date On Form: 07/09/2019

Signature Name On Form: VICTOR JIMENEZ

Signature Company On Form: Not reported

Signature Title On Form: PM

Signature Role: Not reported

Owner Name At Time Of Construction: WTG FUELS INC;WTG FUELS INC

Owner CN At Time Of Construction: CN602647752,CN602647752

Owner AR At Time Of Construction: 62595A,62595U

General Desc Of Prop Construct: *30 DAY WAIVER REQUESTED* INSTALL OF (7) FUEL DISPENSERS, (3) NEW
SUBMERSIBLE TURBINE PUMPS, INSTALL OF NEW UNDERGROUND FUEL PIPE,
INSTALL OF (1) 6000 GALLON DW UST

NOC ID: 34702

Facility ID: 122884

AI Number: 79351

Application Received Date: 05/13/2019

Scheduled Construction Date: 05/13/2019

UST Improvement: N

UST Installation: N

UST Removal: N

UST Repair: Y

UST Return To Service: N

UST Replacement: N

UST Abandonment: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: Not reported
Waiver Flag: Y
Late Filing Flag: N
Form Received Date: 07/10/2019
Signature Date On Form: 07/09/2019
Signature Name On Form: VICTOR JIMENEZ
Signature Company On Form: Not reported
Signature Title On Form: PM
Signature Role: Not reported
Owner Name At Time Of Construction: WTG FUELS INC;WTG FUELS INC
Owner CN At Time Of Construction: CN602647752,CN602647752
Owner AR At Time Of Construction: 62595A,62595U
General Desc Of Prop Construct: REPLACE ENTRY BOOTS AT DISPENSER AND STP SUMPS.

NOC ID: 21211
Facility ID: 122884
AI Number: 79351
Application Received Date: 04/04/2008
Scheduled Construction Date: 05/01/2008
UST Improvement: N
UST Installation: Y
UST Removal: N
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M80404004
Waiver Flag: N
Late Filing Flag: Y
Form Received Date: 07/10/2019
Signature Date On Form: 07/09/2019
Signature Name On Form: VICTOR JIMENEZ
Signature Company On Form: Not reported
Signature Title On Form: PM
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 62595
General Desc Of Prop Construct: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 35079
UST ID: 210151
NOC ID: Not reported
AI Number: 79351
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000091
Company Name: D & H PUMP SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 35211
UST ID: 210153
NOC ID: Not reported
AI Number: 79351
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000091
Company Name: D & H PUMP SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 82984
UST ID: Not reported
NOC ID: 34972
AI Number: 79351
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: Not reported
Company Name: D&H UNITED FUELING SOLUTIONS INC
Representative Name: JACOB JOHNSON
Mailing Address (Delivery): 1221 TOWER TRAIL LN
Mailing Address (Internal Delivery): Not reported
Mailing City: EL PASO
Mailing State: TX
Mailing Zip: 79907
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 915
Phone Number: 8598150
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 82362
UST ID: Not reported
NOC ID: 34702
AI Number: 79351
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: Not reported
Company Name: D&H UNITED FUELING SOLUTIONS INC
Representative Name: JACOB JOHNSON
Mailing Address (Delivery): 1221 TOWER TRAIL LN
Mailing Address (Internal Delivery): Not reported
Mailing City: EL PASO
Mailing State: TX
Mailing Zip: 79907
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Phone Number Area Code: 915
Phone Number: 8598150
Phone Number Extension: Not reported
Fax Number Country Code: 1
Fax Number Area Code: 915
Fax Number: 8721370
Email Address: Not reported

Cont/Cons/Installer ID: 35080
UST ID: 210152
NOC ID: Not reported
AI Number: 79351
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000091
Company Name: D & H PUMP SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 22289
UST ID: Not reported
NOC ID: 21211
AI Number: 79351
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP000091
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 50236
UST ID: 210152
NOC ID: Not reported
AI Number: 79351
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP001232
Company Name: Not reported
Representative Name: STEVE SVOBODA
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 50368
UST ID: 210153
NOC ID: Not reported
AI Number: 79351
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP001232
Company Name: Not reported
Representative Name: STEVE SVOBODA
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 50235
UST ID: 210151
NOC ID: Not reported
AI Number: 79351
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP001232
Company Name: Not reported
Representative Name: STEVE SVOBODA
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Facility Billing Contacts:
Contact Organization Name: WTG FUELS INC
Contact Mailing Address (Delivery): 211 N COLORADO ST
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: MIDLAND, TX 79701 4607
Phone Number/Ext: /

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U004123731 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E17

NAME: WTGF PECOS GASCARD 170302

Rev: 06/07/2021

ADDRESS: 113 E 3RD ST
PECOS, TX 79772

ID/Status: ACTIVE
ID/Status: 79351
ID/Status: 122884
ID/Status: 984370922010320

SOURCE: TX Texas Commission on Environmental Quality

Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 122884
Additional ID: 984370922010320
Princ ID: 108589422004169
AI Number: 79351
Facility Name: WTGF PECOS GASCARD 170302
AR Number: 62595
AR UST Number Suffix: A
AR AST Number Suffix: U
Contact Name/Title: AL BARTZ/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S122367933 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E18

NAME: CORNER CONOCO STATION

Rev: 03/25/2021

ADDRESS: 115 E 3RD ST
PECOS, TX 79700
REEVES

ID/Status: MONITORING
ID/Status: 101611
ID/Status: 6A - FINAL CONCURRENCE ISSUED
ID/Status: 0041720

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: CORNER CONOCO STATION

Address: 115 E 3RD ST

City,State,Zip: PECOS, TX 79700

Facility ID: 0041720

LPST Id: 101611

Facility Location: 115 E 3RD ST

TCEQ Region# and City: REGION 07 - MIDLAND

Region City: ODESSA

Discovered Date: 01/17/1992

Entered Date: 02/06/1992

Reported Date: 01/17/1992

Closure Date: 06/11/2008

Priority: 4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS

Program: 1 - RPR

CA Status: 6A - FINAL CONCURRENCE ISSUED

Priority Description: A designated major or minor groundwater aquifer is affected or immediately threatened.

Status: MONITORING

Coordinators Primary: 1/1P/1/1P/1/1P/1

Coordinators RPR: MAO

Responsible Party Name: Not reported

Responsible Party Contact: AL BARTZ

Responsible Party Address: 211 N COLORADO

Responsible Party City,St,Zip: MIDLAND, TX 79701

Responsible Party Telephone: 432/655-3166

Reported Date: 01/17/1992

Case Start Date: 06/11/2008

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

UST:
Name: CORNER CONOCO
Address: 115 E 3RD ST
City,State,Zip: PECOS, TX 79772
AI Number: 41720
Facility Type: UNKNOWN
Facility Begin Date: 08/31/1987
Facility Status: INACTIVE
Additional ID: 371793222002138
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: Not reported
Site Location (Nearest City Name): PECOS
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: T X SELLERS,
Contact Organization Name: CORNER CONOCO
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9154459811
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 02/05/1986
Signature Name/Title On Earliest Reg Form: MONTE KESEY,MGR
Application Received Date On Earliest Reg Form: 05/08/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:
Owner CN: CN601509946
Owner Last Name: WEST TEXAS GAS INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 694349832002353
Additional ID: 371793222002138
AI Number: 41720
Owner Effective Begin Date: 09/01/1987
State Tax ID: 17514992639
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1978
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 4010
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 110499
Facility ID: 37783
Ai Number: 41720
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 01/17/1992
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 07/18/1990

Compartment Records:
Tank ID: 1
Tank Capacity: 4010
UST Comprt ID: 950
UST ID: 110499
AI Number: 41720
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1978
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 2005
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 110500
Facility ID: 37783
Ai Number: 41720

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Tank Id: 3
 Tank Status (Current): REMOVED FROM GROUND
 Tank Status Date: 01/17/1992
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): N
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): N
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 07/18/1990

Compartment Records:

Tank ID: 3
Tank Capacity: 2005
UST Comprt ID: 951
UST ID: 110500
AI Number: 41720
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b): N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1978
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 2961
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 110501
Facility ID: 37783
Ai Number: 41720
Tank Id: 2
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 01/17/1992
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 07/18/1990

Compartment Records:

Tank ID: 2
Tank Capacity: 2961
UST Comprt ID: 952
UST ID: 110501
AI Number: 41720
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001274061 **DIST/DIR:** 0.168 ESE **ELEVATION:** 2583 **MAP ID:** E19

NAME: CORNER CONOCO
ADDRESS: 115 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 41720
ID/Status: 37783
ID/Status: 371793222002138

SOURCE: TX Texas Commission on Environmental Quality

PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage 1 Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Facility Billing Contacts:

Contact Organization Name: WEST TEXAS GAS INC
Contact Mailing Address (Delivery): 211 N COLORADO ST
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: MIDLAND, TX 79701 4607
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 37783
Additional ID: 371793222002138
Princ ID: 694349832002353
AI Number: 41720
Facility Name: CORNER CONOCO
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: AL BARTZ/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: S125667865 **DIST/DIR:** 0.170 ENE **ELEVATION:** 2582 **MAP ID:** F20

NAME: TOPLINE FUELS
ADDRESS: 107 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 135723
ID/Status: 942575922019149
ID/Status: 90617
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST:
Name: TOPLINE FUELS
Address: 107 S CEDAR ST
City,State,Zip: PECOS, TX 797723206
Facility ID: 135723
Additional ID: 942575922019149
AI Number: 90617
Facility Type: RETAIL
Facility Begin Date: 06/28/2019
Facility Status: ACTIVE
Facility Exempt Status: N
Records Off-Site: Y
UST Financial Assurance Required: Not reported
Number of Active ASTs: 2
Site Location Description: Not reported
Site Location (nearest city name): Not reported
Site Location (county name): REEVES
Site Location (TCEQ region): 7
Site Location (location zip): 79772
Contact Name/Title: COURTNEY MCWILLIAMS/
Contact Organization Name: TOPLINE FUELS
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact CityStateZip: Not reported
Contact Telephone: 4326851402
Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date on Earliest Reg Form: Not reported
Signature First Name on Earliest Reg Form: Not reported
Application Received Date on Earliest Reg Form: Not reported
Signature Middle Name on Earliest Reg Form: Not reported
Signature Last Name on Earliest Reg Form: Not reported
Signature Title on Earliest Reg Form: Not reported
Signature Role on Earliest Reg Form: Not reported
Signature Company on Earliest Reg Form: Not reported
Enforcement Action: N
Facility Not Inspectable: N
Facility Not Inspectable Reason A: Not reported
Facility Not Inspectable Reason B: Not reported
Enforcement Action Date: Not reported
Facility:
Facility ID: 135723
Tank ID: 1

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: S125667865 **DIST/DIR:** 0.170 ENE **ELEVATION:** 2582 **MAP ID:** F20

NAME: TOPLINE FUELS
ADDRESS: 107 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 135723
ID/Status: 942575922019149
ID/Status: 90617
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST ID: 224745
AI Number: 90617
Install Date: 06/28/2019
Tank Registration Date: 08/29/2019
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 06/28/2019
Tank Reg Status: FULLY REGULATED
Tank Capacity: 12000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: N
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: EXEMPT BY TCEQ RULE
Inst Stage Date: Not reported

Facility ID: 135723
Tank ID: 2
AST ID: 224746
AI Number: 90617
Install Date: 06/28/2019
Tank Registration Date: 08/29/2019
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 06/28/2019
Tank Reg Status: FULLY REGULATED
Tank Capacity: 12000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: N
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: S125667865 **DIST/DIR:** 0.170 ENE **ELEVATION:** 2582 **MAP ID:** F20

NAME: TOPLINE FUELS
ADDRESS: 107 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 135723
ID/Status: 942575922019149
ID/Status: 90617
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Contains CO: N
Contains NO: N
Vapor Rec: EXEMPT BY TCEQ RULE
Inst Stage Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189562 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G21

NAME: ENMONS ROUSTABOUT & OILFIELD

Rev: 06/07/2021

ADDRESS: 103 N CEDAR ST
PECOS, TX 79772

ID/Status: 49203
ID/Status: 556772162002088
ID/Status: 50347
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST:

Name: ENMONS ROUSTABOUT & OILFIELD
Address: 103 N CEDAR ST
City,State,Zip: PECOS, TX 797722528
Facility ID: 49203
Additional ID: 556772162002088
AI Number: 50347
Facility Type: FLEET REFUELING
Facility Begin Date: 02/27/1990
Facility Status: INACTIVE
Facility Exempt Status: N
Records Off-Site: N
UST Financial Assurance Required: N
Number of Active ASTs: 0
Site Location Description: Not reported
Site Location (nearest city name): Not reported
Site Location (county name): REEVES
Site Location (TCEQ region): 7
Site Location (location zip): 79772
Contact Name/Title: /
Contact Organization Name: ENMONS ROUSTABOUT & OILFIELD
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact CityStateZip: Not reported
Contact Telephone: 9154459730
Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date on Earliest Reg Form: 02/21/1990
Signature First Name on Earliest Reg Form: JIM
Application Received Date on Earliest Reg Form: 02/23/1990
Signature Middle Name on Earliest Reg Form: Not reported
Signature Last Name on Earliest Reg Form: WAFER
Signature Title on Earliest Reg Form: OWNER
Signature Role on Earliest Reg Form: Not reported
Signature Company on Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: N
Facility Not Inspectable Reason A: Not reported
Facility Not Inspectable Reason B: Not reported
Enforcement Action Date: Not reported
Facility:
Facility ID: 49203
Tank ID: 2003

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189562 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G21

NAME: ENMONS ROUSTABOUT & OILFIELD

Rev: 06/07/2021

ADDRESS: 103 N CEDAR ST
PECOS, TX 79772

ID/Status: 49203
ID/Status: 556772162002088
ID/Status: 50347
ID/Status: INACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST ID: 155109
AI Number: 50347
Install Date: 01/01/1984
Tank Registration Date: 02/23/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 06/01/1993
Tank Reg Status: FULLY REGULATED
Tank Capacity: 2006
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: REEVES COUNTY PCT 4 YARD

Address: 113 N CEDAR ST

City,State,Zip: PECOS, TX 797722528

AI Number: 2609

Facility Type: UNKNOWN

Facility Begin Date: 06/10/1986

Facility Status: INACTIVE

Additional ID: 380411472002086

Facility Exempt Status: N

Records Off-Site: No

UST Financial Assurance Required: No

Number Of Active UST: 0

Site Location Description: Not reported

Site Location (Nearest City Name): Not reported

Site Location (County Name): REEVES

Site Location (Tceq Region): 7

Site Location (Location Zip): 79772

Contact Name/Title: RUSS SALCIDO,

Contact Organization Name: REEVES COUNTY PCT 4 YARD

Contact Mailing Address1: Not reported

Contact Mailing Address2: Not reported

Contact Mailing City/State/Zip: Not reported

Contact Telephone: 9154453075

Facility Contact Address Deliverable: Not reported

Contact Fax Number: Not reported

Contact Email Address: Not reported

Signature Date On Earliest Reg Form: 02/24/1986

Signature Name/Title On Earliest Reg Form: BILL PIGMAN,COUNTY JUDGE

Application Received Date On Earliest Reg Form: 05/08/1986

Signature Role On Earliest Reg Form: Not reported

Signature Company On Earliest Reg Form: Not reported

Enforcement Action: Not reported

Facility Not Inspectable: No

Owner:

Owner CN: CN600929251

Owner Last Name: REEVES COUNTY

Owner First Name: Not reported

Owner Middle Name: Not reported

Owner Type: CY

Contact Mailing Address (Delivery): Not reported

Contact Mailing Address (Internal Delivery): Not reported

Contact Mailing City: Not reported

Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 370411472002086
Additional ID: 380411472002086
AI Number: 2609
Owner Effective Begin Date: 06/10/1986
State Tax ID: Not reported
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1980
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 1500
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 6401
Facility ID: 41097
Ai Number: 2609
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 04/25/1997
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 06/24/1991

Compartment Records:

Tank ID: 1
Tank Capacity: 1500
UST Comprt ID: 10752
UST ID: 6401
AI Number: 2609
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1980
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 1500
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 6402
Facility ID: 41097
Ai Number: 2609

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

Tank Id: 2
 Tank Status (Current): REMOVED FROM GROUND
 Tank Status Date: 04/25/1997
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): N
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 06/24/1991

Compartment Records:

Tank ID: 2
Tank Capacity: 1500
UST Comprt ID: 10753
UST ID: 6402
AI Number: 2609
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b): N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001239589 **DIST/DIR:** 0.175 NE **ELEVATION:** 2582 **MAP ID:** G22

NAME: REEVES COUNTY PCT 4 YARD

Rev: 06/07/2021

ADDRESS: 113 N CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 2609
ID/Status: 41097
ID/Status: 380411472002086

SOURCE: TX Texas Commission on Environmental Quality

Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Facility Billing Contacts:

Contact Organization Name: REEVES COUNTY
Contact Mailing Address (Delivery): 100 E 4TH ST
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: PECOS, TX 79772 4024
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 41097
Additional ID: 380411472002086
Princ ID: 370411472002086
AI Number: 2609
Facility Name: REEVES COUNTY PCT 4 YARD
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: RUSS SALCIDO/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240960 **DIST/DIR:** 0.182 ENE **ELEVATION:** 2582 **MAP ID:** F23

NAME: PECOS MOTORS
ADDRESS: 120 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 4217
ID/Status: 42911
ID/Status: 526037522002088

SOURCE: TX Texas Commission on Environmental Quality

UST:
Name: PECOS MOTORS
Address: 120 S CEDAR ST
City,State,Zip: PECOS, TX 797723207
AI Number: 4217
Facility Type: FLEET REFUELING
Facility Begin Date: 06/18/1986
Facility Status: INACTIVE
Additional ID: 526037522002088
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: JACK CASIMIR,MGR.
Contact Organization Name: PECOS MOTORS INC
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9154476236
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 04/14/1986
Signature Name/Title On Earliest Reg Form: JACK CASIMIR,MANAGER
Application Received Date On Earliest Reg Form: 05/08/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:
Owner CN: CN600997662
Owner Last Name: PECOS MOTORS INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: OR
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240960 **DIST/DIR:** 0.182 ENE **ELEVATION:** 2582 **MAP ID:** F23

NAME: PECOS MOTORS
ADDRESS: 120 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 4217
ID/Status: 42911
ID/Status: 526037522002088

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 536037512002088
Additional ID: 526037522002088
AI Number: 4217
Owner Effective Begin Date: 06/18/1986
State Tax ID: 17412956157
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1982
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 1000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 10288
Facility ID: 42911
Ai Number: 4217
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 08/31/1995
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240960 **DIST/DIR:** 0.182 ENE **ELEVATION:** 2582 **MAP ID:** F23

NAME: PECOS MOTORS
ADDRESS: 120 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 4217
ID/Status: 42911
ID/Status: 526037522002088

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: Y
Installation Signature Date: 04/29/1994

Compartment Records:
Tank ID: 1
Tank Capacity: 1000
UST Comprt ID: 13977
UST ID: 10288
AI Number: 4217
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240960 DIST/DIR: 0.182 ENE ELEVATION: 2582 MAP ID: F23

NAME: PECOS MOTORS
ADDRESS: 120 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 4217
ID/Status: 42911
ID/Status: 526037522002088

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Facility Billing Contacts:

Contact Organization Name: PECOS MOTORS INC
Contact Mailing Address (Delivery): 1717 W JACKSON ST
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: PECOS, TX 79772 4702
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240960 **DIST/DIR:** 0.182 ENE **ELEVATION:** 2582 **MAP ID:** F23

NAME: PECOS MOTORS
ADDRESS: 120 S CEDAR ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 4217
ID/Status: 42911
ID/Status: 526037522002088

SOURCE: TX Texas Commission on Environmental Quality

Facility ID: 42911
Additional ID: 526037522002088
Princ ID: 536037512002088
AI Number: 4217
Facility Name: PECOS MOTORS
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: JACK CASIMIR/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2

Rev: 06/07/2021

ADDRESS: 210 E A ST
PECOS, TX 79772

ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST:

Name: WEST TEXAS GAS WHSE 2
Address: 210 E A ST
City,State,Zip: PECOS, TX 79772
Facility ID: 37847
Additional ID: 687300932007193
AI Number: 50687
Facility Type: RETAIL
Facility Begin Date: 03/08/1990
Facility Status: ACTIVE
Facility Exempt Status: N
Records Off-Site: N
UST Financial Assurance Required: N
Number of Active ASTs: 5
Site Location Description: Not reported
Site Location (nearest city name): Not reported
Site Location (county name): REEVES
Site Location (TCEQ region): 7
Site Location (location zip): 79772
Contact Name/Title: T X SELLERS/
Contact Organization Name: WEST TEXAS GAS INC WHSE 2
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact CityStateZip: Not reported
Contact Telephone: 9154459811
Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date on Earliest Reg Form: 02/14/1990
Signature First Name on Earliest Reg Form: LARRY
Application Received Date on Earliest Reg Form: 02/20/1990
Signature Middle Name on Earliest Reg Form: Not reported
Signature Last Name on Earliest Reg Form: MILLS
Signature Title on Earliest Reg Form: SPECIAL REP
Signature Role on Earliest Reg Form: Not reported
Signature Company on Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: N
Facility Not Inspectable Reason A: Not reported
Facility Not Inspectable Reason B: Not reported
Enforcement Action Date: Not reported

Facility:
Facility ID: 37847
Tank ID: 153

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2
ADDRESS: 210 E A ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

AST ID: 155783
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1991
Tank Reg Status: FULLY REGULATED
Tank Capacity: 2000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 152
AST ID: 155784
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1960
Tank Reg Status: FULLY REGULATED
Tank Capacity: 10000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2
ADDRESS: 210 E A ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 151
AST ID: 155785
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1960
Tank Reg Status: FULLY REGULATED
Tank Capacity: 8000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 150
AST ID: 155786
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1960
Tank Reg Status: FULLY REGULATED
Tank Capacity: 8000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2
ADDRESS: 210 E A ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 149
AST ID: 155787
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1960
Tank Reg Status: FULLY REGULATED
Tank Capacity: 3000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported

Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 42
AST ID: 155788
AI Number: 50687
Install Date: 08/31/1989
Tank Registration Date: 02/20/1990
Mult Comp: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2
ADDRESS: 210 E A ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Tank Status: OUT OF USE
Tank Status Date: 08/31/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 2000
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 156
AST ID: 155789
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: IN USE
Tank Status Date: 01/01/1960
Tank Reg Status: FULLY REGULATED
Tank Capacity: 16000
Substance: GASOLINE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2
ADDRESS: 210 E A ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Facility ID: 37847
Tank ID: 155
AST ID: 155790
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 09/30/1989
Tank Reg Status: FULLY REGULATED
Tank Capacity: 16000
Substance: EMPTY
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N
Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Facility ID: 37847
Tank ID: 154
AST ID: 155791
AI Number: 50687
Install Date: 01/01/1960
Tank Registration Date: 02/20/1990
Mult Comp: N
Tank Status: OUT OF USE
Tank Status Date: 08/31/1991
Tank Reg Status: FULLY REGULATED
Tank Capacity: 2000
Substance: KEROSENE
Other Substance B: Not reported
Other Substance C: Not reported
Steel: Y
Fiber: N
Aluminum: N
Metal: N
Concrete: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

AST

EDR ID: A100189564 **DIST/DIR:** 0.200 NE **ELEVATION:** 2581 **MAP ID:** 24

NAME: WEST TEXAS GAS WHSE 2
ADDRESS: 210 E A ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: 37847
ID/Status: 687300932007193
ID/Status: 50687
ID/Status: ACTIVE

SOURCE: TX Texas Commission on Environmental Quality

Dike: N
Liner: N
Contains CO: N
Contains NO: N
Vapor Rec: Not reported
Inst Stage Date: Not reported

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

UST:
Name: UNCLES 170200
Address: 201 E 3RD ST
City,State,Zip: PECOS, TX 797723217
AI Number: 3661
Facility Type: RETAIL
Facility Begin Date: 01/01/1985
Facility Status: ACTIVE
Additional ID: 808466782002138
Facility Exempt Status: N
Records Off-Site: Yes
UST Financial Assurance Required: Yes
Number Of Active UST: 4
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: AL BARTZ,OPS MANAGER
Contact Organization Name: UNCLES 170200
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 4326824349
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 11/20/2015
Signature Name/Title On Earliest Reg Form: AL BARTZ,OP MGR
Application Received Date On Earliest Reg Form: 11/23/2015
Signature Role On Earliest Reg Form: LEGAL AUTH REP OWNER
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: No
Facility Not Inspectable: No

Operator:
Princ ID: 108589422004169
Additional ID: 808466782002138
Ai Number: 3661
Operator CN: CN602647752
Operator Name: WTG FUELS INC
Operator Effective Begin Date: 04/01/2004
Operator Type: CO
Operator Role: OWNOPRCON
Contact Name: SHAWNETTE HALLFORD/SAFETY MANAGER

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Contact Organization Name: WTG FUELS INC
Contact Mailing Address (Delivery): 11501 W COUNTY ROAD 125
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: ODESSA TX 79765-9674
Contact Phone Country Code: 1
Contact Phone Area Code: 432
Contact Phone Number: 9677746
Contact Phone Extension: 0
Contact Fax Country Code: Not reported
Contact Fax Area Code: Not reported
Contact Fax Number: Not reported
Contact Fax Extension: Not reported
Contact Email Address: SHALLFORD@GASCARD.NET
Contact Address Deliverable: Not reported

Owner:
Owner CN: CN602647752
Owner Last Name: WTG FUELS INC
Owner First Name: Not reported
Owner Middle Name: Not reported
Owner Type: CO
Contact Mailing Address (Delivery): 11501 W COUNTY ROAD 125
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: ODESSA
Contact Mailing State: TX
Contact Mailing Zip: 79765
Contact Mailing Zip5: 9674
Contact Phone Number/Ext: 1 432 9677746/0
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: SHALLFORD@GASCARD.NET
Contact Address Deliverable: Not reported
Princ ID: 108589422004169
Additional ID: 808466782002138
AI Number: 3661
Owner Effective Begin Date: 04/01/2004
State Tax ID: 12006960657
Contact Role: OWNOPRCON
Contact Name/Title: SHAWNETTE HALLFORD/SAFETY MANAGER
Contact Organization Name: WTG FUELS INC

Self Certification:
Self Cert ID: 37715
Cert ID: 353416

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

AI Number: 3661
Self Certification Date: 04/28/2021
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2022
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 336417
AI Number: 3661
Self Certification Date: 05/06/2020
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2021
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 319943
AI Number: 3661
Self Certification Date: 04/30/2019
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2020
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 303104
AI Number: 3661
Self Certification Date: 04/30/2018
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2019
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 285949
AI Number: 3661
Self Certification Date: 05/02/2017
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2018
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 269807
AI Number: 3661
Self Certification Date: 05/19/2016
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2017
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 253028
AI Number: 3661
Self Certification Date: 05/14/2015
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2016
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 236791
AI Number: 3661
Self Certification Date: 05/28/2014

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2015
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: Y
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: Y

Self Cert ID: 37715
Cert ID: 220153
AI Number: 3661
Self Certification Date: 05/24/2013
Signature Name/Title: Al E Bartz Operations Manager
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2014
Reporting Method: S
Tank Corrosion Protection Compliance: Y
Piping Corrosion Protection Compliance: Y
Compartment Release Detection Compliance: N
Piping Release Detection Compliance: Y
Spill Prevention/Overfill Compliance: N

Self Cert ID: 37715
Cert ID: 630
AI Number: 3661
Self Certification Date: 05/23/2012
Signature Name/Title: AL E BARTZ OPERATIONS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Delivery Certificate Expiration Date: 05/31/2013
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 629
AI Number: 3661
Self Certification Date: 05/24/2011
Signature Name/Title: AL E BARTZ OPERATIONS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2012
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 628
AI Number: 3661
Self Certification Date: 04/27/2010
Signature Name/Title: AL BARTZ OPS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2011
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Self Cert ID: 37715
Cert ID: 627
AI Number: 3661
Self Certification Date: 05/20/2009
Signature Name/Title: AL BARTZ OPS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2010
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 626
AI Number: 3661
Self Certification Date: 05/06/2008
Signature Name/Title: AL BARTZ OPERATIONS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2009
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 625
AI Number: 3661
Self Certification Date: 05/14/2007
Signature Name/Title: AL BARTZ OPS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2008
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 624
AI Number: 3661
Self Certification Date: 05/05/2006
Signature Name/Title: AL BARTZ OPERATIONS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL

Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2007
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 623
AI Number: 3661
Self Certification Date: 05/13/2005
Signature Name/Title: AL BARTZ OPERATIONS MANAGER
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL

Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2006
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 622
AI Number: 3661
Self Certification Date: 04/26/2004
Signature Name/Title: AL BARTZ OPS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 05/31/2005
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 621
AI Number: 3661
Self Certification Date: 04/19/2004
Signature Name/Title: AL BARTZ OPS MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 04/30/2005
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 620

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

AI Number: 3661
Self Certification Date: 03/31/2003
Signature Name/Title: AL BARTZ OPER MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 04/30/2004
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 619
AI Number: 3661
Self Certification Date: 03/21/2002
Signature Name/Title: AL BARTZ
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: RENEWAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y
Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 04/30/2003
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Self Cert ID: 37715
Cert ID: 618
AI Number: 3661
Self Certification Date: 01/19/2001
Signature Name/Title: AL BARTZ OPER MGR
Signature Type Role: LEGAL AUTH REP OWNER
Filing Status: INITIAL
Registration Self Certification Flag: Y
Facility Fees Self Certification Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Financial Assurance Self Certification Flag: Y
Technical Standards Self Certification Flag: Y
Delivery Certificate Expiration Date: 04/30/2002
Reporting Method: Not reported
Tank Corrosion Protection Compliance: Not reported
Piping Corrosion Protection Compliance: Not reported
Compartment Release Detection Compliance: Not reported
Piping Release Detection Compliance: Not reported
Spill Prevention/Overfill Compliance: Not reported

Tank:
Install Date: 01/01/1985
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 8000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: P
UST ID: 9005
Facility ID: 37715
Ai Number: 3661
Tank Id: 1
Tank Status (Current): IN USE
Tank Status Date: 01/01/1985
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): Y
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): Y
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
PCPMeth(Isolated Open Area/2nd Containment): Y
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): Y
Tank Corr Prot Compliance Flag: Y
Piping Corr Prot Compliance Flag: Y
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: Y
Installation Signature Date: 11/23/2015

Compartment Records:

Tank ID: 1
Tank Capacity: 8000
UST Comprt ID: 681
UST ID: 9005
AI Number: 3661
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

Install Date: 01/01/1985
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 8000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: P
UST ID: 9007
Facility ID: 37715
Ai Number: 3661
Tank Id: 2
Tank Status (Current): IN USE
Tank Status Date: 01/01/1985
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): Y
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): Y
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): Y
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): Y
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
PCPMeth(Isolated Open Area/2nd Containment): Y
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): Y
Tank Corr Prot Compliance Flag: Y
Piping Corr Prot Compliance Flag: Y
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Installation Signature Date: 11/23/2015

Compartment Records:

Tank ID: 2
Tank Capacity: 8000
UST Comprt ID: 683
UST ID: 9007
AI Number: 3661
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Install Date: 11/01/1985
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 8000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: P
UST ID: 9008
Facility ID: 37715
Ai Number: 3661
Tank Id: 4
Tank Status (Current): IN USE
Tank Status Date: 11/01/1985
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): Y
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): N
Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): Y
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

TCPMeth(Unnecessary Per Corrosion Prot Spec): Y
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMMethod (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
PCPMeth(Isolated Open Area/2nd Containment): Y
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): Y
Tank Corr Prot Compliance Flag: Y
Piping Corr Prot Compliance Flag: Y
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: Y
Technical Compliance Flag: Y
Tank Tested Flag: Y
Installation Signature Date: 11/23/2015

Compartment Records:

Tank ID: 4
Tank Capacity: 8000
UST Comprt ID: 684
UST ID: 9008
AI Number: 3661
Compartment ID: A
Substance Stored1: DIESEL
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

Install Date: 01/01/1985
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 8000
Tank Singlewall: Y
Tank Doublewall: N
Pipe Type: P
UST ID: 9006
Facility ID: 37715
Ai Number: 3661
Tank Id: 3
Tank Status (Current): IN USE
Tank Status Date: 01/01/1985
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): Y
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): N
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): Y
Tank Mat(Concrete): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
 PECOS, TX 79772

Rev: 06/07/2021
 ID/Status: ACTIVE
 ID/Status: 3661
 ID/Status: 37715
 ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): N
 Piping Mat(Frp(Fiberglass Reinforced Plastic): Y
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): Y
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): Y
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): Y
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): Y
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): Y
 PCPMeth(Isolated Open Area/2nd Containment): Y
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): Y
 Tank Corr Prot Compliance Flag: Y
 Piping Corr Prot Compliance Flag: Y
 Tank Corrosion Prot Variance: N
 Piping Corrosion Prot Variance: N
 Temp Out Of Service Compliance: Y
 Technical Compliance Flag: Y
 Tank Tested Flag: Y
 Installation Signature Date: 11/23/2015

Compartment Records:
 Tank ID: 3
 Tank Capacity: 8000
 UST Comprt ID: 682
 UST ID: 9006
 AI Number: 3661
 Compartment ID: A
 Substance Stored1: GASOLINE
 Substance Stored2: Not reported
 Substance Stored3: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): Y
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: Y
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): Y
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction): N
Spill Overfill Prevention Equip(SOPE): Y
SOPE(Spill Cont/Bucket/Sump): Y
SOPE(DelShut-Off Valve): Y
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b): Y
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: Y
Piping Release Detection Compliance Flag): Y
Spill/OverfillPreventionCompliance Flag: Y
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: EXEMPT BY TCEQ RULE
Stage 1 Installation Date: Not reported

Construction Notification:
NOC ID: 27411
Facility ID: 37715
AI Number: 3661
Application Received Date: 04/09/2015
Scheduled Construction Date: 05/09/2015
UST Improvement: Y
UST Installation: N
UST Removal: N
UST Repair: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: Not reported
Waiver Flag: Not reported
Late Filing Flag: N
Form Received Date: 04/09/2015
Signature Date On Form: 04/09/2015
Signature Name On Form: FLOYD BOLER
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: WTG FUELS INC;WTG FUELS INC
Owner CN At Time Of Construction: CN602647752,CN602647752
Owner AR At Time Of Construction: 62595A,62595U
General Desc Of Prop Construct: ADDING FUEL ISLANDS & ADD'L DOUBLE WALL FIBERGLASS PIPING

NOC ID: 123
Facility ID: 37715
AI Number: 3661
Application Received Date: 09/27/2011
Scheduled Construction Date: 10/27/2011
UST Improvement: Y
UST Installation: N
UST Removal: N
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: NONE
Waiver Flag: N
Late Filing Flag: N
Form Received Date: 04/09/2015
Signature Date On Form: 04/09/2015
Signature Name On Form: FLOYD BOLER
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 62595
General Desc Of Prop Construct: REMOVE OLD DISPENSERS AND REPLACE DISPENSERS LIKE FOR LIKE.

NOC ID: 122
Facility ID: 37715
AI Number: 3661
Application Received Date: 12/21/2012
Scheduled Construction Date: 01/21/2013
UST Improvement: Y
UST Installation: N
UST Removal: N
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: NONE
Waiver Flag: N
Late Filing Flag: N
Form Received Date: 04/09/2015
Signature Date On Form: 04/09/2015
Signature Name On Form: FLOYD BOLER
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 62595
General Desc Of Prop Construct: MANIFOLD UNLEAD TANKS

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 67177
UST ID: 9008
NOC ID: Not reported
AI Number: 3661
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 0
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: 0
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 67173
UST ID: 9007
NOC ID: Not reported
AI Number: 3661
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 0
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: 0
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 67170
UST ID: 9005
NOC ID: Not reported
AI Number: 3661
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 0
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: 0
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 64269
UST ID: Not reported
NOC ID: 27411
AI Number: 3661
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 0
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: 0
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 142
UST ID: Not reported
NOC ID: 122
AI Number: 3661

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC
Representative Name: FLOYD BOLER
Mailing Address (Delivery): 4611 SINCLAIR AVE
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79707
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 144
UST ID: Not reported
NOC ID: 123
AI Number: 3661
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC
Representative Name: FLOYD BOLER
Mailing Address (Delivery): 4611 SINCLAIR AVE
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79707
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 67175

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

UST ID: 9006
NOC ID: Not reported
AI Number: 3661
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001070
Company Name: BOLER EQUIPMENT SERVICE INC
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 0
Phone Number Area Code: 432
Phone Number: 6940660
Phone Number Extension: 0
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 67171
UST ID: 9005
NOC ID: Not reported
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP000389
Company Name: BOLER B FLOYD
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6871634
Phone Number Extension: 0
Fax Number Country Code: 1
Fax Number Area Code: 432
Fax Number: 8942261

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Email Address: BOLER@BOLER.NET

Cont/Cons/Installer ID: 67176
UST ID: 9008
NOC ID: Not reported
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP000389
Company Name: BOLER B FLOYD
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6871634
Phone Number Extension: 0
Fax Number Country Code: 1
Fax Number Area Code: 432
Fax Number: 8942261
Email Address: BOLER@BOLER.NET

Cont/Cons/Installer ID: 143
UST ID: Not reported
NOC ID: 122
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP001070
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 64270
UST ID: Not reported
NOC ID: 27411
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP000389
Company Name: BOLER B FLOYD
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6871634
Phone Number Extension: 0
Fax Number Country Code: 1
Fax Number Area Code: 432
Fax Number: 8942261
Email Address: BOLER@BOLER.NET

Cont/Cons/Installer ID: 145
UST ID: Not reported
NOC ID: 123
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP001070
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Cont/Cons/Installer ID: 67172
UST ID: 9007
NOC ID: Not reported
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP000389
Company Name: BOLER B FLOYD
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6871634
Phone Number Extension: 0
Fax Number Country Code: 1
Fax Number Area Code: 432
Fax Number: 8942261
Email Address: BOLER@BOLER.NET

Cont/Cons/Installer ID: 67174
UST ID: 9006
NOC ID: Not reported
AI Number: 3661
Type Of Contact: INSTALLER
Contractor CRP Number Or Installer ILP Number: ILP000389
Company Name: BOLER B FLOYD
Representative Name: Not reported
Mailing Address (Delivery): PO BOX 80428
Mailing Address (Internal Delivery): Not reported
Mailing City: MIDLAND
Mailing State: TX
Mailing Zip: 79708

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: ACTIVE
ID/Status: 3661
ID/Status: 37715
ID/Status: 808466782002138

SOURCE: TX Texas Commission on Environmental Quality

Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: 432
Phone Number: 6871634
Phone Number Extension: 0
Fax Number Country Code: 1
Fax Number Area Code: 432
Fax Number: 8942261
Email Address: BOLER@BOLER.NET

Facility Billing Contacts:
Contact Organization Name: WTG FUELS INC
Contact Mailing Address (Delivery): 211 N COLORADO ST
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: MIDLAND, TX 79701 4607
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y
Facility ID: 37715
Additional ID: 808466782002138
Princ ID: 108589422004169
AI Number: 3661
Facility Name: UNCLES 170200
AR Number: 62595
AR UST Number Suffix: A
AR AST Number Suffix: U
Contact Name/Title: AL BARTZ/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U001240505 **DIST/DIR:** 0.216 ESE **ELEVATION:** 2582 **MAP ID:** H25

NAME: UNCLES 170200
ADDRESS: 201 E 3RD ST
PECOS, TX 79772

Rev: 03/25/2021
ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
ID/Status: 112872
ID/Status: 6A - FINAL CONCURRENCE ISSUED
ID/Status: 0003661

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: UNCLES 3661
Address: 201 E 3RD ST
City,State,Zip: PECOS, TX 79772
Facility ID: 0003661
LPST Id: 112872
Facility Location: 201 E 3RD ST
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: ODESSA
Discovered Date: 11/07/1997
Entered Date: 01/06/1998
Reported Date: 11/07/1997
Closure Date: 06/12/2008
Priority: 4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program: 1 - RPR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Groundwater is affected.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 1/1P/1
Coordinators RPR: DRR
Responsible Party Name: Not reported
Responsible Party Contact: AL BARTZ
Responsible Party Address: 211 N COLORADO
Responsible Party City,St,Zip: MIDLAND, TX 79701
Responsible Party Telephone: 432/682-4349
Reported Date: 11/07/1997
Case Start Date: 06/12/2008

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001248952 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H26

NAME: GOODYEAR TIRE STORE

Rev: 06/07/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 13308
ID/Status: 61400
ID/Status: 593221782002087

SOURCE: TX Texas Commission on Environmental Quality

UST:

Name: GOODYEAR TIRE STORE

Address: 308 S CEDAR ST

City,State,Zip: PECOS, TX 797723211

AI Number: 13308

Facility Type: RETAIL

Facility Begin Date: 08/31/1987

Facility Status: INACTIVE

Additional ID: 593221782002087

Facility Exempt Status: N

Records Off-Site: No

UST Financial Assurance Required: No

Number Of Active UST: 0

Site Location Description: Not reported

Site Location (Nearest City Name): Not reported

Site Location (County Name): REEVES

Site Location (Tceq Region): 7

Site Location (Location Zip): 79772

Contact Name/Title: ,

Contact Organization Name: GOODYEAR TIRE STORE

Contact Mailing Address1: Not reported

Contact Mailing Address2: Not reported

Contact Mailing City/State/Zip: Not reported

Contact Telephone: 9158373322

Facility Contact Address Deliverable: Not reported

Contact Fax Number: Not reported

Contact Email Address: Not reported

Signature Date On Earliest Reg Form: 04/30/1986

Signature Name/Title On Earliest Reg Form: R M HELDRIDGE,MGR CHEM & ENVIR

Application Received Date On Earliest Reg Form: 05/08/1986

Signature Role On Earliest Reg Form: Not reported

Signature Company On Earliest Reg Form: Not reported

Enforcement Action: Not reported

Facility Not Inspectable: No

Owner:

Owner CN: CN601070006

Owner Last Name: NEWELL OIL COMPANY INC

Owner First Name: Not reported

Owner Middle Name: Not reported

Owner Type: OR

Contact Mailing Address (Delivery): Not reported

Contact Mailing Address (Internal Delivery): Not reported

Contact Mailing City: Not reported

Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001248952 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H26

NAME: GOODYEAR TIRE STORE

Rev: 06/07/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 13308
ID/Status: 61400
ID/Status: 593221782002087

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 763831442002095
Additional ID: 593221782002087
AI Number: 13308
Owner Effective Begin Date: 09/01/1987
State Tax ID: 17413430046
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 08/31/1987
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 500
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 34304
Facility ID: 61400
Ai Number: 13308
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 12/27/1993
Empty: Y
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001248952 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H26

NAME: GOODYEAR TIRE STORE

Rev: 06/07/2021

ADDRESS: 308 S CEDAR ST
 PECOS, TX 79772

ID/Status: INACTIVE
 ID/Status: 13308
 ID/Status: 61400
 ID/Status: 593221782002087

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): N
 Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMethod (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N
 Piping Corr Prot Compliance Flag: N
 Tank Corrosion Prot Variance: N
 Piping Corrosion Prot Variance: N
 Temp Out Of Service Compliance: N
 Technical Compliance Flag: N
 Tank Tested Flag: Y
 Installation Signature Date: 06/05/1990

Compartment Records:
 Tank ID: 1
 Tank Capacity: 500
 UST Comprt ID: 60736
 UST ID: 34304
 AI Number: 13308
 Compartment ID: A
 Substance Stored1: USED OIL
 Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001248952 DIST/DIR: 0.224 ESE ELEVATION: 2582 MAP ID: H26

NAME: GOODYEAR TIRE STORE

Rev: 06/07/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 13308
ID/Status: 61400
ID/Status: 593221782002087

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N
PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control)): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Facility Billing Contacts:

Contact Organization Name: NEWELL OIL COMPANY INC
Contact Mailing Address (Delivery): PO BOX 390
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: ALPINE, TX 79831 0390
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001248952 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H26

NAME: GOODYEAR TIRE STORE

Rev: 06/07/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772

ID/Status: INACTIVE
ID/Status: 13308
ID/Status: 61400
ID/Status: 593221782002087

SOURCE: TX Texas Commission on Environmental Quality

Facility ID: 61400
Additional ID: 593221782002087
Princ ID: 763831442002095
AI Number: 13308
Facility Name: GOODYEAR TIRE STORE
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: LEE COWELL/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

Ind. Haz Waste

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER **Rev:** 02/04/2021
ADDRESS: 308 S CEDAR ST **ID/Status:** 73058
PECOS, TX 79772
REEVES
SOURCE: TX Texas Commission on Environmental Quality

Ind. Haz Waste:
Name: GOODYEAR AUTO SERVICE CENTER
Address: 308 S CEDAR ST
City,State,Zip: PECOS, TX 79772
Registration Number: 73058
Registration Initial Notification Date: 11/07/1986
Registration Last Amendment Date: 08/23/2001
EPA Identification: TXD149982175
Primary NAICS Code: Not reported
Status Change Date: 19861107
Land Type: PRIVATE
Description of Facility Site Location: 308 S Cedar St, Pecos, TX
Site Primary Standard Industrial Code: Not reported
Site Primary SIC Description: Not reported
Registration is Generator of Waste: Yes
Registration is Receivers of Waste: No
Registration is Transporter of Waste: No
Registration is Transfer Facility: No
Facility is STEERS Reporter: No
Required to Submit Annual Waste Summary: No
Facility Involved In Recycling: No
Revcr Has Monthly Reporting Requirement: 0
Mexican Facility: Not reported
Type of Generator: NON INDUS, CESQG
TNRCC Region: Not reported
Company Name: GOODYEAR AUTO SERVICE CENTER
Contact Name: J D BOWDEN
Contact Telephone Number: 915-7785421
Mailing Address: 6936 COMMERCE AVE
Mailing Address2: Not reported
Mailing City,St,Zip: EL PASO, TX 799151102
Mailing County: UNITED STATES
Facility Country: UNITED STATES
TNRCC Facility ID: 27491
Site Owner Tax ID: 0
Site Location Latitude: -00.000
Site Location Longitude: -000.000
Last Update to NOR Data: 20030506
Ind. waste permit Number: Not reported
Mun waste permit Number: Not reported
Non Notifier: No
Business Records Not Found for this RegNo/Year:
Owner:

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

Ind. Haz Waste

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER **Rev:** 02/04/2021
ADDRESS: 308 S CEDAR ST **ID/Status:** 73058
PECOS, TX 79772
REEVES
SOURCE: TX Texas Commission on Environmental Quality

Owner Mailing Address: Not reported
Owner Mailing Address2: Not reported
Owner Mailing Address3: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
Owner Phone Number: Not reported
Owner Fax Number: Not reported
Owner Email Address: Not reported
Owner Business Type: Unknown
Owner Tax Id: Not reported
Owner Bankruptcy Code: Not reported

Owner:
Owner Mailing Address: Not reported
Owner Mailing Address2: Not reported
Owner Mailing Address3: Not reported
Owner City,St,Zip: Not reported
Owner Country: Not reported
Owner Phone Number: Not reported
Owner Fax Number: Not reported
Owner Email Address: Not reported
Owner Business Type: Unknown
Owner Tax Id: 17413430046
Owner Bankruptcy Code: Not reported

Operator:
Operator Last Name: GOODYEAR AUTO SERVICE CENTER
Operator First Name: Not reported
Operator Name: GOODYEAR AUTO SERVICE CENTER
Operator Mailing Address: Not reported
Operator Mailing Address 2: Not reported
Operator Mailing City,St,Zip: Not reported
Operator Country: Not reported
Operator Phone: Not reported
Operator Fax: Not reported
Operator Email: Not reported
Operator Business Type: Unknown
Operator Tax Id: Not reported
Operator Bankruptcy Code: Not reported

Contact:
Contact Name: J BOWDEN
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 6936 COMMERCE AVE
Contact Address2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

Ind. Haz Waste

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER

Rev: 02/04/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772
REEVES

ID/Status: 73058

SOURCE: TX Texas Commission on Environmental Quality

Contact City,St,Zip: EL PASO, TX 79915 1102

Contact Phone: 1-915-7785421

Contact Fax: Not reported

Contact Email: Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:

Receiver Type: Not reported

Transporter for hire: 0

Transport own waste: 0

Eq 01, if transport waste type = 1: Not reported

Eq 02, if transport waste type = 2: Not reported

Eq 03, if transport waste type = 3: Not reported

Eq 04, if transport waste type = H: Not reported

Target TCEQ unique facid for discarded(merged) facility: Not reported

Waste Records Not Found for this RegNo/Year:

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER

Rev: 03/22/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772
REEVES

ID/Status: TXD149982175

SOURCE: US Environmental Protection Agency

RCRA NonGen / NLR:

Date Form Received by Agency: 2001-08-23 00:00:00.0

Handler Name: GOODYEAR AUTO SERVICE CENTER

Handler Address: 308 S CEDAR ST

Handler City,State,Zip: PECOS, TX 79772

EPA ID: TXD149982175

Contact Name: J D BOWDEN

Contact Address: COMMERCE AVE

Contact City,State,Zip: EL PASO, TX 79915

Contact Telephone: 915-778-5421

Contact Fax: Not reported

Contact Email: Not reported

Contact Title: Not reported

EPA Region: 06

Land Type: Private

Federal Waste Generator Description: Not a generator, verified

Non-Notifier: Not reported

Biennial Report Cycle: Not reported

Accessibility: Not reported

Active Site Indicator: Not reported

State District Owner: TX

State District: 07

Mailing Address: COMMERCE AVE

Mailing City,State,Zip: EL PASO, TX 79915

Owner Name: GOODYEAR AUTO SERVICE CENTER

Owner Type: Private

Operator Name: GOODYEAR AUTO SERVICE CENTER

Operator Type: Private

Short-Term Generator Activity: No

Importer Activity: No

Mixed Waste Generator: No

Transporter Activity: No

Transfer Facility Activity: No

Recycler Activity with Storage: No

Small Quantity On-Site Burner Exemption: No

Smelting Melting and Refining Furnace Exemption: No

Underground Injection Control: No

Off-Site Waste Receipt: No

Universal Waste Indicator: No

Universal Waste Destination Facility: No

Federal Universal Waste: No

Active Site Fed-Reg Treatment Storage and Disposal Facility: Not reported

Active Site Converter Treatment storage and Disposal Facility: Not reported

Active Site State-Reg Treatment Storage and Disposal Facility: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER

Rev: 03/22/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772
REEVES

ID/Status: TXD149982175

SOURCE: US Environmental Protection Agency

Active Site State-Reg Handler: ---
Federal Facility Indicator: Not reported
Hazardous Secondary Material Indicator: NN
Sub-Part K Indicator: Not reported
Commercial TSD Indicator: No
Treatment Storage and Disposal Type: Not reported
2018 GPRA Permit Baseline: Not on the Baseline
2018 GPRA Renewals Baseline: Not on the Baseline
Permit Renewals Workload Universe: Not reported
Permit Workload Universe: Not reported
Permit Progress Universe: Not reported
Post-Closure Workload Universe: Not reported
Closure Workload Universe: Not reported
202 GPRA Corrective Action Baseline: No
Corrective Action Workload Universe: No
Subject to Corrective Action Universe: No
Non-TSDFs Where RCRA CA has Been Imposed Universe: No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: No
TSDFs Only Subject to CA under Discretionary Auth Universe: No
Corrective Action Priority Ranking: No NCAPS ranking
Environmental Control Indicator: No
Institutional Control Indicator: No
Human Exposure Controls Indicator: N/A
Groundwater Controls Indicator: N/A
Operating TSDF Universe: Not reported
Full Enforcement Universe: Not reported
Significant Non-Complier Universe: No
Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 2004-03-25 00:00:00.0
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: Not reported
Manifest Broker: Not reported
Sub-Part P Indicator: No

Hazardous Waste Summary:

Waste Code: D001

Waste Description: IGNITABLE WASTE

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER
ADDRESS: 308 S CEDAR ST
PECOS, TX 79772
REEVES
SOURCE: US Environmental Protection Agency

Rev: 03/22/2021
ID/Status: TXD149982175

Handler - Owner Operator:

Owner/Operator Indicator: Owner
Owner/Operator Name: GOODYEAR T&R CO
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: UNKNOWN
Owner/Operator City,State,Zip: UNKNOWN, TX 00000-0000
Owner/Operator Telephone: 000-000-0000
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: GOODYEAR AUTO SERVICE CENTER
Legal Status: Private
Date Became Current: 2001-08-23 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 6936 COMMERCE AVE
Owner/Operator City,State,Zip: EL PASO, TX 79915
Owner/Operator Telephone: 915-778-5421
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: GOODYEAR AUTO SERVICE CENTER
Legal Status: Private
Date Became Current: 2001-08-23 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 6936 COMMERCE AVE
Owner/Operator City,State,Zip: EL PASO, TX 79915
Owner/Operator Telephone: 915-778-5421
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:

Receive Date: 1986-11-10 00:00:00.0
Handler Name: GOODYEAR AUTO SERVICE CENTER
Federal Waste Generator Description: Small Quantity Generator
State District Owner: TX
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000194781 **DIST/DIR:** 0.224 ESE **ELEVATION:** 2582 **MAP ID:** H27

NAME: GOODYEAR AUTO SERVICE CENTER

Rev: 03/22/2021

ADDRESS: 308 S CEDAR ST
PECOS, TX 79772
REEVES

ID/Status: TXD149982175

SOURCE: US Environmental Protection Agency

Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2001-08-23 00:00:00.0
Handler Name: GOODYEAR AUTO SERVICE CENTER
Federal Waste Generator Description: Not a generator, verified
State District Owner: TX
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Codes: No NAICS Codes Found

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

DRYCLEANERS

EDR ID: S120802991 **DIST/DIR:** 0.226 ESE **ELEVATION:** 2582 **MAP ID:** H28

NAME: TOP TIER CLEANERS **Rev:** 05/24/2021
ADDRESS: 212 E 3RD ST ID/Status: 24007568
PECOS, TX 79772 ID/Status: CN605311430
REEVES ID/Status: RN109656215
ID/Status: ACTIVE
SOURCE: TX Texas Commission on Environmental Quality

DRYCLEANERS:
Name: TOP TIER CLEANERS
Address: 212 E 3RD ST
City,State,Zip: PECOS, TX 79772
RN Number: RN109656215
Region: REGION 07 - MIDLAND
CN Number: CN605311430
DCR Number: DCR16045
AR Number: 24007568
Principal Name: ISABEL GALVAN AND MARCOS GALVAN
Bill Addr1: 406 MESQUITE ST
Bill Addr2: Not reported
Bill City/State/Zip: PECOS, TX 79772 4314
EMail: IGALVAN35@YAHOO.COM
Phone Number: 214 2066905
Site Name: Not reported
Site Type: DROP STATION REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2017
Solvent: Not reported
Gallons: Not reported
Part Stat: YES
Gross Receipts: \$150,000 OR LESS

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

DRYCLEANERS

EDR ID: S126914118 **DIST/DIR:** 0.226 ESE **ELEVATION:** 2582 **MAP ID:** H29

NAME: COMET CLEANERS **Rev:** 05/24/2021
ADDRESS: 212 E 3RD ST ID/Status: 24007912
PECOS, TX 79772 ID/Status: CN605684638
ID/Status: RN109656215
ID/Status: ACTIVE
SOURCE: TX Texas Commission on Environmental Quality

DRYCLEANERS:
Name: COMET CLEANERS
Address: 212 E 3RD ST
City,State,Zip: PECOS, TX 79772
RN Number: RN109656215
Region: REGION 07 - MIDLAND
CN Number: CN605684638
DCR Number: DCR16045
AR Number: 24007912
Principal Name: MGIM INTERPRISES LLC
Bill Addr1: PO BOX 1660
Bill Addr2: Not reported
Bill City/State/Zip: PECOS, TX 79772 1660
EMail: GALVAN.MARCOS32@YAHOO.COM
Phone Number: 432 4489218
Site Name: Not reported
Site Type: FACILITY REGISTRATION
Site Status: ACTIVE
Fiscal Year: FY2020
Solvent: Not reported
Gallons: Not reported
Part Stat: YES
Gross Receipts: \$150,000 OR LESS

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000696229 **DIST/DIR:** 0.233 NNE **ELEVATION:** 2581 **MAP ID:** 30

NAME: GREASEWOOD TREATING PLANT **Rev:** 03/22/2021
ADDRESS: HWY 285 10 MI N OF PECOS TX **ID/Status:** TXD988069951
PECOS, TX, TX 79772
REEVES
SOURCE: US Environmental Protection Agency

RCRA NonGen / NLR:
Date Form Received by Agency: 2018-02-07 00:00:00.0
Handler Name: GREASEWOOD TREATING PLANT
Handler Address: HWY 285 10 MI N OF PECOS TX
Handler City,State,Zip: PECOS, TX, TX 79772
EPA ID: TXD988069951
Contact Name: ENV MANAGER
Contact Address: 15211 FM 916
Contact City,State,Zip: MAYPEARL, TX 76064-1909
Contact Telephone: 972-435-3954
Contact Fax: Not reported
Contact Email: Not reported
Contact Title: ENVIRONMENTAL MANAGER
EPA Region: 06
Land Type: Private
Federal Waste Generator Description: Not a generator, verified
Non-Notifier: Not reported
Biennial Report Cycle: Not reported
Accessibility: Not reported
Active Site Indicator: Not reported
State District Owner: Not reported
State District: Not reported
Mailing Address: 15211 FM 916
Mailing City,State,Zip: MAYPEARL, TX 76064-1909
Owner Name: ENTERPRISE TEXAS PIPELINE LP
Owner Type: Private
Operator Name: ENTERPRISE TEXAS PIPELINE LP
Operator Type: Private
Short-Term Generator Activity: No
Importer Activity: No
Mixed Waste Generator: No
Transporter Activity: No
Transfer Facility Activity: No
Recycler Activity with Storage: No
Small Quantity On-Site Burner Exemption: No
Smelting Melting and Refining Furnace Exemption: No
Underground Injection Control: No
Off-Site Waste Receipt: No
Universal Waste Indicator: No
Universal Waste Destination Facility: No
Federal Universal Waste: No
Active Site Fed-Reg Treatment Storage and Disposal Facility: Not reported
Active Site Converter Treatment storage and Disposal Facility: Not reported
Active Site State-Reg Treatment Storage and Disposal Facility: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000696229 **DIST/DIR:** 0.233 NNE **ELEVATION:** 2581 **MAP ID:** 30

NAME: GREASEWOOD TREATING PLANT

Rev: 03/22/2021

ADDRESS: HWY 285 10 MI N OF PECOS TX
PECOS, TX, TX 79772
REEVES

ID/Status: TXD988069951

SOURCE: US Environmental Protection Agency

Active Site State-Reg Handler: ---
Federal Facility Indicator: Not reported
Hazardous Secondary Material Indicator: NN
Sub-Part K Indicator: Not reported
Commercial TSD Indicator: No
Treatment Storage and Disposal Type: Not reported
2018 GPRA Permit Baseline: Not on the Baseline
2018 GPRA Renewals Baseline: Not on the Baseline
Permit Renewals Workload Universe: Not reported
Permit Workload Universe: Not reported
Permit Progress Universe: Not reported
Post-Closure Workload Universe: Not reported
Closure Workload Universe: Not reported
202 GPRA Corrective Action Baseline: No
Corrective Action Workload Universe: No
Subject to Corrective Action Universe: No
Non-TSDFs Where RCRA CA has Been Imposed Universe: No
TSDFs Potentially Subject to CA Under 3004 (u)/(v) Universe: No
TSDFs Only Subject to CA under Discretionary Auth Universe: No
Corrective Action Priority Ranking: No NCAPS ranking
Environmental Control Indicator: No
Institutional Control Indicator: No
Human Exposure Controls Indicator: N/A
Groundwater Controls Indicator: N/A
Operating TSDF Universe: Not reported
Full Enforcement Universe: Not reported
Significant Non-Complier Universe: No
Unaddressed Significant Non-Complier Universe: No
Addressed Significant Non-Complier Universe: No
Significant Non-Complier With a Compliance Schedule Universe: No
Financial Assurance Required: Not reported
Handler Date of Last Change: 2018-03-07 11:55:20.0
Recognized Trader-Importer: No
Recognized Trader-Exporter: No
Importer of Spent Lead Acid Batteries: No
Exporter of Spent Lead Acid Batteries: No
Recycler Activity Without Storage: No
Manifest Broker: No
Sub-Part P Indicator: No

Hazardous Waste Summary:
Waste Code: D000
Waste Description: Not Defined

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000696229 **DIST/DIR:** 0.233 NNE **ELEVATION:** 2581 **MAP ID:** 30

NAME: GREASEWOOD TREATING PLANT

Rev: 03/22/2021

ADDRESS: HWY 285 10 MI N OF PECOS TX
PECOS, TX, TX 79772
REEVES

ID/Status: TXD988069951

SOURCE: US Environmental Protection Agency

Waste Code: D001
Waste Description: IGNITABLE WASTE

Waste Code: D004
Waste Description: ARSENIC

Waste Code: D005
Waste Description: BARIUM

Waste Code: D006
Waste Description: CADMIUM

Waste Code: D007
Waste Description: CHROMIUM

Waste Code: D008
Waste Description: LEAD

Waste Code: D009
Waste Description: MERCURY

Waste Code: D010
Waste Description: SELENIUM

Waste Code: D011
Waste Description: SILVER

Waste Code: D018
Waste Description: BENZENE

Waste Code: D035
Waste Description: METHYL ETHYL KETONE

Waste Code: D040
Waste Description: TRICHLORETHYLENE

Handler - Owner Operator:
Owner/Operator Indicator: Owner
Owner/Operator Name: VALERO TRANSMISSION LP
Legal Status: Private
Date Became Current: Not reported
Date Ended Current: Not reported
Owner/Operator Address: PO BOX 500
Owner/Operator City,State,Zip: SAN ANTONIO, TX 78292

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000696229 **DIST/DIR:** 0.233 NNE **ELEVATION:** 2581 **MAP ID:** 30

NAME: GREASEWOOD TREATING PLANT

Rev: 03/22/2021

ADDRESS: HWY 285 10 MI N OF PECOS TX
PECOS, TX, TX 79772
REEVES

ID/Status: TXD988069951

SOURCE: US Environmental Protection Agency

Owner/Operator Telephone: 512-246-2395
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Operator
Owner/Operator Name: ENTERPRISE TEXAS PIPELINE LP
Legal Status: Private
Date Became Current: 1800-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 15211 FM 916
Owner/Operator City,State,Zip: MAYPEARL, TX 76064-1909
Owner/Operator Telephone: 972-435-3954
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Owner/Operator Indicator: Owner
Owner/Operator Name: ENTERPRISE TEXAS PIPELINE LP
Legal Status: Private
Date Became Current: 1800-01-01 00:00:00.
Date Ended Current: Not reported
Owner/Operator Address: 15211 FM 916
Owner/Operator City,State,Zip: MAYPEARL, TX 76064-1909
Owner/Operator Telephone: 972-435-3954
Owner/Operator Telephone Ext: Not reported
Owner/Operator Fax: Not reported
Owner/Operator Email: Not reported

Historic Generators:
Receive Date: 1997-08-12 00:00:00.0
Handler Name: VALERO GREASEWOOD TREATING PLT
Federal Waste Generator Description: Not a generator, verified
State District Owner: TX
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2001-02-14 00:00:00.0

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

RCRA NonGen / NLR

EDR ID: 1000696229 **DIST/DIR:** 0.233 NNE **ELEVATION:** 2581 **MAP ID:** 30

NAME: GREASEWOOD TREATING PLANT

Rev: 03/22/2021

ADDRESS: HWY 285 10 MI N OF PECOS TX
PECOS, TX, TX 79772
REEVES

ID/Status: TXD988069951

SOURCE: US Environmental Protection Agency

Handler Name: VALERO TRANSMISSION LP
Federal Waste Generator Description: Not a generator, verified
State District Owner: TX
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: No
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

Receive Date: 2018-02-07 00:00:00.0
Handler Name: GREASEWOOD TREATING PLANT
Federal Waste Generator Description: Not a generator, verified
State District Owner: Not reported
Large Quantity Handler of Universal Waste: No
Recognized Trader Importer: No
Recognized Trader Exporter: No
Spent Lead Acid Battery Importer: No
Spent Lead Acid Battery Exporter: No
Current Record: Yes
Non Storage Recycler Activity: Not reported
Electronic Manifest Broker: Not reported

List of NAICS Codes and Descriptions:
NAICS Code: 48621
NAICS Description: PIPELINE TRANSPORTATION OF NATURAL GAS

Facility Has Received Notices of Violations:
Violations: No Violations Found

Evaluation Action Summary:
Evaluations: No Evaluations Found

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S116699818 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I31

NAME: ACOSTA CONOCO **Rev:** 03/25/2021
ADDRESS: 602 W 3RD ST ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
PECOS, TX 79772 ID/Status: 113736
REEVES ID/Status: 6A - FINAL CONCURRENCE ISSUED
SOURCE: TX Texas Commission on Environmental Quality ID/Status: 0000143

LPST:
Name: ACOSTA CONOCO
Address: 602 W 3RD ST
City,State,Zip: PECOS, TX 79772
Facility ID: 0000143
LPST Id: 113736
Facility Location: 602 W 3RD
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: ODESSA
Discovered Date: 12/31/3000
Entered Date: 12/08/1998
Reported Date: 12/31/3000
Closure Date: 10/25/2010
Priority: 3.3 - GW IMPACT NON-PUBLIC/NON-DOMESTIC H2O SUPPLY WELL W/IN.25mi
Program: 3 - STATE LEAD
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Groundwater is affected and a non-public or nondomestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 3/1
Coordinators RPR: KLM
Responsible Party Name: Not reported
Responsible Party Contact: KYLE WATTS
Responsible Party Address: 3009 WINDSOR
Responsible Party City,St,Zip: ODESSA, TX 79762
Responsible Party Telephone: 915/368-4627
Reported Date: 12/31/3000
Case Start Date: 10/25/2010

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

UST:
Name: ACOSTA CONOCO
Address: 602 W 3RD ST
City,State,Zip: PECOS, TX 797722900
AI Number: 143
Facility Type: RETAIL
Facility Begin Date: 05/27/1986
Facility Status: INACTIVE
Additional ID: 943056182002139
Facility Exempt Status: N
Records Off-Site: No
UST Financial Assurance Required: No
Number Of Active UST: 0
Site Location Description: Not reported
Site Location (Nearest City Name): Not reported
Site Location (County Name): REEVES
Site Location (Tceq Region): 7
Site Location (Location Zip): 79772
Contact Name/Title: KYLE D WATTS,
Contact Organization Name: ACOSTA CONOCO
Contact Mailing Address1: Not reported
Contact Mailing Address2: Not reported
Contact Mailing City/State/Zip: Not reported
Contact Telephone: 9153684627
Facility Contact Address Deliverable: Not reported
Contact Fax Number: Not reported
Contact Email Address: Not reported
Signature Date On Earliest Reg Form: 02/07/1986
Signature Name/Title On Earliest Reg Form: ACOSTA CONOCO,REP.
Application Received Date On Earliest Reg Form: 05/08/1986
Signature Role On Earliest Reg Form: Not reported
Signature Company On Earliest Reg Form: Not reported
Enforcement Action: Not reported
Facility Not Inspectable: No

Owner:
Owner CN: CN601201692
Owner Last Name: WATTS
Owner First Name: KYLE
Owner Middle Name: Not reported
Owner Type: IN
Contact Mailing Address (Delivery): Not reported
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City: Not reported
Contact Mailing State: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Contact Mailing Zip: Not reported
Contact Mailing Zip5: Not reported
Contact Phone Number/Ext: /
Contact Fax Country Code: Not reported
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Not reported
Princ ID: 933056182002139
Additional ID: 943056182002139
AI Number: 143
Owner Effective Begin Date: 05/27/1986
State Tax ID: Not reported
Contact Role: Not reported
Contact Name/Title: /
Contact Organization Name: Not reported

Tank:
Install Date: 01/01/1972
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: 4000
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 332
Facility ID: 38068
Ai Number: 143
Tank Id: 1
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 06/30/1999
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
 PECOS, TX 79772

Rev: 06/07/2021
 ID/Status: INACTIVE
 ID/Status: 143
 ID/Status: 38068
 ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic)): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMethod (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N
 Piping Corr Prot Compliance Flag: N
 Tank Corrosion Prot Variance: N
 Piping Corrosion Prot Variance: N
 Temp Out Of Service Compliance: N
 Technical Compliance Flag: N
 Tank Tested Flag: N
 Installation Signature Date: Not reported

Compartment Records:
 Tank ID: 1
 Tank Capacity: 4000
 UST Comprt ID: 1371
 UST ID: 332
 AI Number: 143
 Compartment ID: A
 Substance Stored1: DIESEL
 Substance Stored2: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
 PECOS, TX 79772

Rev: 06/07/2021
 ID/Status: INACTIVE
 ID/Status: 143
 ID/Status: 38068
 ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Substance Stored3: Not reported
 CompartmentReleaseDetectionMethod(Vapor): N
 CRDM(GW Monitoring): N
 CRDM(Monitoring Of Secondary Cont Barrier): N
 CRDM(Auto Tank Gauge Test/Inv Control): N
 CRDM(Interstitial Monitoring SecWall/Jacket): N
 CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
 CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
 CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
 PipingReleaseDetectionMethod(PRDM)(Vapor): N
 PRDM(Groundwater Monitoring): N
 PRDM(Monitoring Sec Containment Barrier): N
 PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
 PRDM(Mthly Piping Tightness Test)@.2Gph: N
 PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
 PRDM(TriennialTightTest(Suction/GravityPiping): N
 PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
 PRDM(Sir(StatInv Recon)/Inv Control)): N
 PRDM(Exempt System Suction: N
 Spill Overfill Prevention Equip(SOPE): N
 SOPE(Spill Cont/Bucket/Sump): N
 SOPE(DelShut-Off Valve): N
 SOPE(FlowRestrictorValue: N
 SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
 SOPE(N/A Deliveries To Tank<=25G): N
 Compartment Release Det Compliance Flag: N
 Piping Release Detection Compliance Flag): N
 Spill/OverfillPreventionCompliance Flag: N
 Compartment Release Detection Variance: N
 Piping Release Detection Variance: N
 Spill And Overfill Prevention Variance: N
 Stage I Vapor Recovery: Not reported
 Stage 1 Installation Date: Not reported

Install Date: 01/01/1972
 Tank Registration Date: 05/08/1986
 Number of Compartments: 1
 Tank Capacity: 5000
 Tank Singlewall: N
 Tank Doublewall: N
 Pipe Type: Not reported
 UST ID: 333
 Facility ID: 38068
 Ai Number: 143

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Tank Id: 3
 Tank Status (Current): REMOVED FROM GROUND
 Tank Status Date: 06/30/1999
 Empty: N
 Tank Regulatory Status: FULLY REGULATED
 Tank Int Prot (Internal Tank Lining Date): Not reported
 Piping Design (Single Wall): N
 Piping Design (Double Wall): N
 Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
 Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
 Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
 Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
 Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
 Tank Material (Steel): Y
 Tank Material(Frp(Fiberglass-Reinforced Plastic): N
 Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
 Tank Mat(Concrete): N
 Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
 Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
 Piping Material (Steel): Y
 Piping Mat(Frp(Fiberglass Reinforced Plastic): N
 Piping Mat(Concrete): N
 Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
 Piping Mat(Nonmetallic Flex Piping): N
 PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
 Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
 Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N
 Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
 TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
 TCPM(Cathodic Prot-FacInstallation): N
 TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
 TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
 TCPM(FRP Tank Or Piping(Noncorrodible)): N
 TCPM(Ext Nonmetallic Jacket): N
 TCPMeth(Unnecessary Per Corrosion Prot Spec): N
 Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
 Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
 PCPM(Cathodic Prot-Field Install): N
 PCPMeth (FRP Tank Or Piping(Noncorrodible): N
 PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
 PCPMeth(Isolated Open Area/2nd Containment): N
 PCPM (Dual Protected): N
 PCPM(Unnec Per Corrosion Prot Specialist): N
 Tank Corr Prot Compliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
 PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
 PECOS, TX 79772

Rev: 06/07/2021
 ID/Status: INACTIVE
 ID/Status: 143
 ID/Status: 38068
 ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Piping Corr Prot Compliance Flag: N
 Tank Corrosion Prot Variance: N
 Piping Corrosion Prot Variance: N
 Temp Out Of Service Compliance: N
 Technical Compliance Flag: N
 Tank Tested Flag: N
 Installation Signature Date: Not reported

Compartment Records:

Tank ID: 3
 Tank Capacity: 5000
 UST Comprt ID: 1372
 UST ID: 333
 AI Number: 143
 Compartment ID: A
 Substance Stored1: GASOLINE
 Substance Stored2: Not reported
 Substance Stored3: Not reported
 CompartmentReleaseDetectionMethod(Vapor): N
 CRDM(GW Monitoring): N
 CRDM(Monitoring Of Secondary Cont Barrier): N
 CRDM(Auto Tank Gauge Test/Inv Control): N
 CRDM(Interstitial Monitoring SecWall/Jacket): N
 CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
 CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
 CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
 PipingReleaseDetectionMethod(PRDM)(Vapor): N
 PRDM(Groundwater Monitoring): N
 PRDM(Monitoring Sec Containment Barrier): N
 PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
 PRDM(Mthly Piping Tightness Test)@.2Gph: N
 PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
 PRDM(TriennialTightTest(Suction/GravityPiping): N
 PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
 PRDM(Sir(StatInv Recon)/Inv Control)): N
 PRDM(Exempt System Suction): N
 Spill Overfill Prevention Equip(SOPE): N
 SOPE(Spill Cont/Bucket/Sump): N
 SOPE(DelShut-Off Valve): N
 SOPE(FlowRestrictorValue: N
 SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
 SOPE(N/A Deliveries To Tank<=25G): N
 Compartment Release Det Compliance Flag: N
 Piping Release Detection Compliance Flag): N
 Spill/OverfillPreventionCompliance Flag: N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage I Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Install Date: 01/01/1972
Tank Registration Date: 05/08/1986
Number of Compartments: 1
Tank Capacity: Not reported
Tank Singlewall: N
Tank Doublewall: N
Pipe Type: Not reported
UST ID: 334
Facility ID: 38068
Ai Number: 143
Tank Id: 2
Tank Status (Current): REMOVED FROM GROUND
Tank Status Date: 06/30/1999
Empty: N
Tank Regulatory Status: FULLY REGULATED
Tank Int Prot (Internal Tank Lining Date): Not reported
Piping Design (Single Wall): N
Piping Design (Double Wall): N
Tank Ext Cont(Fac-Built Nonmetallic Jacket): N
Tank Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Tank Ext Cont(Tank Vault/Rigid Trench Liner): N
Piping Ext Cont(Fac-Built Nonmetallic Jacket): N
Piping Ext Cont(Syn Tank-Pit/Piping-Trench Liner): N
Piping Ext Cont(Tank Vault/Rigid Trench Liner): N
Tank Material (Steel): Y
Tank Material(Frp(Fiberglass-Reinforced Plastic): N
Tank Mat(Composite (Steel W/Ext Frp Cladding)): N
Tank Mat(Concrete): N
Tank Mat(Jacketed (Steel W/Ext Nonmetallic Jck)): N
Tank Mat(Coated(Steel W/ExtPolyurethane Cladding)): N
Piping Material (Steel): Y
Piping Mat(Frp(Fiberglass Reinforced Plastic): N
Piping Mat(Concrete): N
Piping Mat(Jacketed(Steel W/Ext Nonmetallic Jacket)): N
Piping Mat(Nonmetallic Flex Piping): N
PipingConnect/Valves(Shear/Impact Valves(Under Disp)): N
Piping Connect/Valves(Steel Swing-Joints(End Of Piping)): N
Piping Connect/Valves (Flex Connectors(Ends Of Piping)): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Tank Corr Prot Meth(TCPM)(Cathodic-Field Installation): N
TCPM (ExtDielectricCoat/Laminate/Tape/Wrap): N
TCPM(Cathodic Prot-FacInstallation): N
TCPM(Composite Tank(Steel W/Frp Ext Laminate): N
TCPMeth(Coated Tank(Steel W/ExtPolyurethaneLaminate): N
TCPM(FRP Tank Or Piping(Noncorrodible)): N
TCPM(Ext Nonmetallic Jacket): N
TCPMeth(Unnecessary Per Corrosion Prot Spec): N
Piping Corr Prot Meth(Dielectric Coat/Laminate/Tape/Wrap): N
Piping Corr Prot Method(PCPM) (Cathodic Factory Install): N
PCPM(Cathodic Prot-Field Install): N
PCPMeth (FRP Tank Or Piping(Noncorrodible): N
PCPM(Nonmetallic FlexPiping (Noncorrodible)): N
PCPMeth(Isolated Open Area/2nd Containment): N
PCPM (Dual Protected): N
PCPM(Unnec Per Corrosion Prot Specialist): N
Tank Corr Prot Compliance Flag: N
Piping Corr Prot Compliance Flag: N
Tank Corrosion Prot Variance: N
Piping Corrosion Prot Variance: N
Temp Out Of Service Compliance: N
Technical Compliance Flag: N
Tank Tested Flag: N
Installation Signature Date: Not reported

Compartment Records:

Tank ID: 2
Tank Capacity: 0
UST Comprt ID: 1373
UST ID: 334
AI Number: 143
Compartment ID: A
Substance Stored1: GASOLINE
Substance Stored2: Not reported
Substance Stored3: Not reported
CompartmentReleaseDetectionMethod(Vapor): N
CRDM(GW Monitoring): N
CRDM(Monitoring Of Secondary Cont Barrier): N
CRDM(Auto Tank Gauge Test/Inv Control): N
CRDM(Interstitial Monitoring SecWall/Jacket): N
CRDM(Wkly Manual Gauging(Tanks<=1000 G): N
CRDM(Mthly Tank Gauging(Emer Gen Tanks): N
CRDM(Sir (Stat Inv Reconciliation)/Inv Control): N
PipingReleaseDetectionMethod(PRDM)(Vapor): N
PRDM(Groundwater Monitoring): N

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

PRDM(Monitoring Sec Containment Barrier): N
PRDM(InterstitialMonitoring w/in SecWall/Jacket): N
PRDM(Mthly Piping Tightness Test)@.2Gph: N
PRDM(AnnualPipingTightTest/ElecMon@.1Gph: N
PRDM(TriennialTightTest(Suction/GravityPiping): N
PRDM AutoLineLeakDet(3.0 Gph PressPiping): N
PRDM(Sir(StatInv Recon)/Inv Control): N
PRDM(Exempt System Suction: N
Spill Overfill Prevention Equip(SOPE): N
SOPE(Spill Cont/Bucket/Sump): N
SOPE(DelShut-Off Valve): N
SOPE(FlowRestrictorValue: N
SOPE(Alarm (Set@<=90%) W/3a Or 3b: N
SOPE(N/A Deliveries To Tank<=25G): N
Compartment Release Det Compliance Flag: N
Piping Release Detection Compliance Flag): N
Spill/OverfillPreventionCompliance Flag: N
Compartment Release Detection Variance: N
Piping Release Detection Variance: N
Spill And Overfill Prevention Variance: N
Stage 1 Vapor Recovery: Not reported
Stage 1 Installation Date: Not reported

Construction Notification:

NOC ID: 225
Facility ID: 38068
AI Number: 143
Application Received Date: 07/26/2007
Scheduled Construction Date: 08/25/2007
UST Improvement: N
UST Installation: N
UST Removal: Y
UST Repair: N
UST Return To Service: N
UST Replacement: N
UST Abandonment: N
UST Stage I: N
AST Installation: N
AST Stage I: N
Historical Tracking Number: M70726006
Waiver Flag: N
Late Filing Flag: N
Form Received Date: Not reported

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Signature Date On Form: Not reported
Signature Name On Form: Not reported
Signature Company On Form: Not reported
Signature Title On Form: Not reported
Signature Role: Not reported
Owner Name At Time Of Construction: Not reported
Owner CN At Time Of Construction: Not reported
Owner AR At Time Of Construction: 123
General Desc Of Prop Construct: Not reported

Contractor, Consultant and Installer:
Cont/Cons/Installer ID: 265
UST ID: Not reported
NOC ID: 225
AI Number: 143
Type Of Contact: CONTRACTOR
Contractor CRP Number Or Installer ILP Number: CRP001398
Company Name: Not reported
Representative Name: Not reported
Mailing Address (Delivery): Not reported
Mailing Address (Internal Delivery): Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Mailing Foreign Postal Code: Not reported
Mailing County Code: Not reported
Phone Number Country Code: 1
Phone Number Area Code: Not reported
Phone Number: Not reported
Phone Number Extension: Not reported
Fax Number Country Code: Not reported
Fax Number Area Code: Not reported
Fax Number: Not reported
Email Address: Not reported

Facility Billing Contacts:
Contact Organization Name: WATTS KYLE
Contact Mailing Address (Delivery): 3009 WINDSOR DR
Contact Mailing Address (Internal Delivery): Not reported
Contact Mailing City/State/Zip: ODESSA, TX 79762 7817
Phone Number/Ext: /
Contact Fax Number/Ext: /
Contact Email Address: Not reported
Contact Address Deliverable: Y

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

UST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 06/07/2021
ID/Status: INACTIVE
ID/Status: 143
ID/Status: 38068
ID/Status: 943056182002139

SOURCE: TX Texas Commission on Environmental Quality

Facility ID: 38068
Additional ID: 943056182002139
Princ ID: 933056182002139
AI Number: 143
Facility Name: ACOSTA CONOCO
AR Number: Not reported
AR UST Number Suffix: Not reported
AR AST Number Suffix: Not reported
Contact Name/Title: KYLE D WATTS/

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U001237549 **DIST/DIR:** 0.242 SW **ELEVATION:** 2586 **MAP ID:** I32

NAME: ACOSTA CONOCO
ADDRESS: 602 W 3RD ST
PECOS, TX 79772

Rev: 03/25/2021
ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
ID/Status: 114733
ID/Status: 6A - FINAL CONCURRENCE ISSUED
ID/Status: 0000143

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: HARPER OIL GAS
Address: 602 W 3RD ST
City,State,Zip: PECOS, TX 79772
Facility ID: 0000143
LPST Id: 114733
Facility Location: 602 W 3RD ST
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Odessa
Discovered Date: 12/31/3000
Entered Date: 08/27/1999
Reported Date: 12/31/3000
Closure Date: 10/25/2010
Priority: 3.3 - GW IMPACT NON-PUBLIC/NON-DOMESTIC H2O SUPPLY WELL W/IN.25mi
Program: 3 - STATE LEAD
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Groundwater is affected and a non-public or nondomestic water supply well is located within 0.25 miles of the UST/AST system or source area.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 3/1/3/1P/1
Coordinators RPR: KLM
Responsible Party Name: Not reported
Responsible Party Contact: KYLE WATTS
Responsible Party Address: 3009 WINDSOR
Responsible Party City,St,Zip: ODESSA, TX 79762
Responsible Party Telephone: 432/368-4627
Reported Date: 12/31/3000
Case Start Date: 10/25/2010

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S116702463 **DIST/DIR:** 0.252 SW **ELEVATION:** 2586 **MAP ID:** I33

NAME: RIO GRANDE DISTRIBUTORS INC

Rev: 03/25/2021

ADDRESS: 620 W 3RD ST
PECOS, TX
REEVES

ID/Status: 93591

ID/Status: 6X - CROSS REF TO ANOTHER LPST

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: RIO GRANDE DISTRIBUTORS INC

Address: 620 W 3RD ST

City,State,Zip: PECOS, TX

Facility ID: Not reported

LPST Id: 93591

Facility Location: Not reported

TCEQ Region# and City: REGION 07 - MIDLAND

Region City: Not reported

Discovered Date: 08/25/1989

Entered Date: 09/18/1989

Reported Date: 08/25/1989

Closure Date: 12/31/3000

Priority: 2.3 - DOM H2O SUPPLY WELL/LINE/SW INTAKE IMPACT ADDL H2O AVAILABLE

Program: 3 - STATE LEAD

CA Status: 6X - CROSS REF TO ANOTHER LPST

Priority Description: Not reported

Status: Not reported

Coordinators Primary: Not reported

Coordinators RPR: Not reported

Responsible Party Name: Not reported

Responsible Party Contact: Not reported

Responsible Party Address: Not reported

Responsible Party City,St,Zip: Not reported

Responsible Party Telephone: Not reported

Reported Date: 08/25/1989

Case Start Date: 12/31/3000

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U001258833 **DIST/DIR:** 0.297 SW **ELEVATION:** 2586 **MAP ID:** J34

NAME: WEST SIDE SERVICE **Rev:** 03/25/2021
ADDRESS: 702 W 3RD ST ID/Status: 92765
PECOS, TX 79772 ID/Status: 3 - MONITORING

SOURCE: TX Texas Commission on Environmental Quality

LPST:
Name: WEST SIDE GULF
Address: 702 W 3RD ST
City,State,Zip: PECOS, TX
Facility ID: Not reported
LPST Id: 92765
Facility Location: Not reported
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Not reported
Discovered Date: 03/17/1989
Entered Date: 03/31/1989
Reported Date: 03/17/1989
Closure Date: 12/31/3000
Priority: 2.3 - DOM H2O SUPPLY WELL/LINE/SW INTAKE IMPACT ADDITIONAL H2O AVAILABLE
Program: 3 - STATE LEAD
CA Status: 3 - MONITORING
Priority Description: Not reported
Status: Not reported
Coordinators Primary: Not reported
Coordinators RPR: Not reported
Responsible Party Name: Not reported
Responsible Party Contact: Not reported
Responsible Party Address: Not reported
Responsible Party City,St,Zip: Not reported
Responsible Party Telephone: Not reported
Reported Date: 03/17/1989
Case Start Date: 12/31/3000

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U001264403 **DIST/DIR:** 0.303 SW **ELEVATION:** 2586 **MAP ID:** J35

NAME: FINA STORE **Rev:** 03/25/2021
ADDRESS: 714 W 3RD ST ID/Status: 94301
PECOS, TX 79772 ID/Status: 6X - CROSS REF TO ANOTHER LPST

SOURCE: TX Texas Commission on Environmental Quality

LPST:
Name: FINA STORE
Address: 714 W 3RD ST
City,State,Zip: PECOS, TX
Facility ID: Not reported
LPST Id: 94301
Facility Location: Not reported
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Not reported
Discovered Date: 10/05/1989
Entered Date: 01/15/1990
Reported Date: 10/05/1989
Closure Date: 12/31/3000
Priority: 2.3 - DOM H2O SUPPLY WELL/LINE/SW INTAKE IMPACT ADDL H2O AVAILABLE
Program: 3 - STATE LEAD
CA Status: 6X - CROSS REF TO ANOTHER LPST
Priority Description: Not reported
Status: Not reported
Coordinators Primary: Not reported
Coordinators RPR: Not reported
Responsible Party Name: Not reported
Responsible Party Contact: Not reported
Responsible Party Address: Not reported
Responsible Party City,St,Zip: Not reported
Responsible Party Telephone: Not reported
Reported Date: 10/05/1989
Case Start Date: 12/31/3000

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S106256362 **DIST/DIR:** 0.312 NNE **ELEVATION:** 2580 **MAP ID:** 36

NAME: OCTAVIO MUNEZS PRIVATE RESIDENCE **Rev:** 03/25/2021
ADDRESS: 421 N CEDAR ID/Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
PECOS, TX 79722 ID/Status: 114624
REEVES ID/Status: 6A - FINAL CONCURRENCE ISSUED
SOURCE: TX Texas Commission on Environmental Quality

LPST:
Name: OCTAVIO MUNEZS PRIVATE RESIDENCE
Address: 421 N CEDAR
City,State,Zip: PECOS, TX 79722
Facility ID: Not reported
LPST Id: 114624
Facility Location: 421 N CEDAR
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Odessa
Discovered Date: 06/01/1999
Entered Date: 06/01/1999
Reported Date: 06/01/1999
Closure Date: 02/08/2013
Priority: 2.4 - NON-PUBLIC/NON-DOMESTIC WATER SUPPLY WELL IMPACT
Program: 3 - STATE LEAD
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: A non-public or non-domestic water supply well is affected or immediately threatened.
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED
Coordinators Primary: 3
Coordinators RPR: ZL
Responsible Party Name: Not reported
Responsible Party Contact: ROSEMARY WYMAN
Responsible Party Address: CORRECTIVE ACTION
Responsible Party City,St,Zip: TX
Responsible Party Telephone: /-
Reported Date: 06/01/1999
Case Start Date: 02/08/2013

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

SEMS-ARCHIVE

EDR ID: 1000311540 **DIST/DIR:** 0.334 WSW **ELEVATION:** 2585 **MAP ID:** 37

NAME: WAYNE FEEDS **Rev:** 07/29/2021

ADDRESS: 2ND AND OLEANDER STREET
PECOS, TX 79772

SOURCE: US EPA

SEMS Archive:

Site ID: 0603781
EPA ID: TXD987966348
Name: WAYNE FEEDS
Address: 2ND AND OLEANDER STREET
Address 2: Not reported
City,State,Zip: PECOS, TX 79772
Cong District: 16
FIPS Code: 48389
FF: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

SEMS Archive Detail:

Region: 06
Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: VS
Action Name: ARCH SITE
SEQ: 1
Start Date: Not reported
Finish Date: 2013-11-07 05:00:00
Qual: Not reported
Current Action Lead: EPA Perf In-Hse

Region: 06
Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: PA
Action Name: PA
SEQ: 1
Start Date: 1989-08-01 04:00:00
Finish Date: 1989-08-01 04:00:00
Qual: L
Current Action Lead: EPA Perf

Region: 06

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

SEMS-ARCHIVE

EDR ID: 1000311540 **DIST/DIR:** 0.334 WSW **ELEVATION:** 2585 **MAP ID:** 37

NAME: WAYNE FEEDS **Rev:** 07/29/2021
ADDRESS: 2ND AND OLEANDER STREET
PECOS, TX 79772

SOURCE: US EPA

Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: AR
Action Name: ADMIN REC
SEQ: 2
Start Date: 1992-03-04 05:00:00
Finish Date: Not reported
Qual: V
Current Action Lead: EPA Perf

Region: 06
Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 1
Start Date: 1990-07-30 04:00:00
Finish Date: 1990-08-02 04:00:00
Qual: S
Current Action Lead: EPA Perf

Region: 06
Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: SI
Action Name: SI
SEQ: 1
Start Date: 1991-05-16 04:00:00
Finish Date: 1991-05-16 04:00:00
Qual: N
Current Action Lead: EPA Perf

Region: 06

- Continued on next page -

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

SEMS-ARCHIVE

EDR ID: 1000311540 **DIST/DIR:** 0.334 WSW **ELEVATION:** 2585 **MAP ID:** 37

NAME: WAYNE FEEDS **Rev:** 07/29/2021
ADDRESS: 2ND AND OLEANDER STREET
PECOS, TX 79772

SOURCE: US EPA

Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: DS
Action Name: DISCVRY
SEQ: 1
Start Date: 1988-07-01 04:00:00
Finish Date: 1988-07-01 04:00:00
Qual: Not reported
Current Action Lead: EPA Perf

Region: 06
Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: AR
Action Name: ADMIN REC
SEQ: 1
Start Date: 1992-04-27 04:00:00
Finish Date: Not reported
Qual: V
Current Action Lead: EPA Ovrsght

Region: 06
Site ID: 0603781
EPA ID: TXD987966348
Site Name: WAYNE FEEDS
NPL: N
FF: N
OU: 00
Action Code: BB
Action Name: PRP RV
SEQ: 1
Start Date: 1992-03-16 05:00:00
Finish Date: 1992-06-10 04:00:00
Qual: C
Current Action Lead: EPA Ovrsght

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S116701818 **DIST/DIR:** 0.419 SW **ELEVATION:** 2588 **MAP ID:** 38

NAME: TOWN COUNTRY 29 **Rev:** 03/25/2021
ADDRESS: 915 W 3RD ST ID/Status: 91597
PECOS, TX ID/Status: 6A - FINAL CONCURRENCE ISSUED
REEVES
SOURCE: TX Texas Commission on Environmental Quality

LPST:
Name: TOWN COUNTRY 29
Address: 915 W 3RD ST
City,State,Zip: PECOS, TX
Facility ID: Not reported
LPST Id: 91597
Facility Location: Not reported
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Not reported
Discovered Date: 01/11/1988
Entered Date: 01/11/1988
Reported Date: 01/11/1988
Closure Date: 05/25/2011
Priority: 4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program: 1 - RPR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Not reported
Status: Not reported
Coordinators Primary: Not reported
Coordinators RPR: Not reported
Responsible Party Name: Not reported
Responsible Party Contact: Not reported
Responsible Party Address: Not reported
Responsible Party City,St,Zip: Not reported
Responsible Party Telephone: Not reported
Reported Date: 01/11/1988
Case Start Date: 05/25/2011

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

SEMS

EDR ID: 1016170761 **DIST/DIR:** 0.427 SE **ELEVATION:** 2582 **MAP ID:** 39

NAME: PECOS MERCURY SPILL

Rev: 07/29/2021

ADDRESS: 623 S. ASH STREETSEP2013
PECOS, TX 79772
REEVES

ID/Status: 0607544
ID/Status: TXN000607544

SOURCE: US EPA

SEMS:

Site ID: 0607544
EPA ID: TXN000607544
Name: PECOS MERCURY SPILL
Address: 623 S. ASH STREETSEP*2013
Address 2: Not reported
City,State,Zip: PECOS, TX 79772
Cong District: Not reported
FIPS Code: 48389
Latitude: Not reported
Longitude: Not reported
FF: N
NPL: Not on the NPL
Non NPL Status: Removal Only Site (No Site Assessment Work Needed)

SEMS Detail:

Region: 06
Site ID: 0607544
EPA ID: TXN000607544
Site Name: PECOS MERCURY SPILL
NPL: N
FF: N
OU: 00
Action Code: RV
Action Name: RMVL
SEQ: 1
Start Date: 2013-07-11 04:00:00
Finish Date: 7/20/2013 4:00:00 AM
Qual: C
Current Action Lead: EPA Perf

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: S116702412 **DIST/DIR:** 0.454 WSW **ELEVATION:** 2588 **MAP ID:** 40

NAME: MERCHANTS FAST MOTOR LINES

Rev: 03/25/2021

ADDRESS:

ID/Status: 93432

PECOS, TX
REEVES

ID/Status: 6A - FINAL CONCURRENCE ISSUED

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: MERCHANTS FAST MOTOR LINES

Address: Not reported

City,State,Zip: PECOS, TX

Facility ID: Not reported

LPST Id: 93432

Facility Location: Not reported

TCEQ Region# and City: REGION 07 - MIDLAND

Region City: Not reported

Discovered Date: 07/27/1989

Entered Date: 08/15/1989

Reported Date: 07/27/1989

Closure Date: 06/12/2009

Priority: 2.5 - GW IMPACT PUBLIC/DOMESTIC WATER SUPPLY WELL W/IN 0.25mi

Program: 3 - STATE LEAD

CA Status: 6A - FINAL CONCURRENCE ISSUED

Priority Description: Not reported

Status: Not reported

Coordinators Primary: Not reported

Coordinators RPR: Not reported

Responsible Party Name: Not reported

Responsible Party Contact: Not reported

Responsible Party Address: Not reported

Responsible Party City,St,Zip: Not reported

Responsible Party Telephone: Not reported

Reported Date: 07/27/1989

Case Start Date: 06/12/2009

Site Detail Report

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

LPST

EDR ID: U001244743 **DIST/DIR:** 0.456 SE **ELEVATION:** 2583 **MAP ID:** 41

NAME: ALLSUPS 102266
ADDRESS: 708 S CEDAR ST
PECOS, TX 79772

Rev: 03/25/2021
ID/Status: 91630
ID/Status: 6A - FINAL CONCURRENCE ISSUED

SOURCE: TX Texas Commission on Environmental Quality

LPST:

Name: ALLSUPS 266
Address: 708 S CEDAR ST
City,State,Zip: PECOS, TX
Facility ID: Not reported
LPST Id: 91630
Facility Location: Not reported
TCEQ Region# and City: REGION 07 - MIDLAND
Region City: Not reported
Discovered Date: 01/14/1988
Entered Date: 01/14/1988
Reported Date: 01/14/1988
Closure Date: 05/09/2006
Priority: 4.1 - GW IMPACTED NO APPARENT THREATS OR IMPACTS TO RECEPTORS
Program: 1 - RPR
CA Status: 6A - FINAL CONCURRENCE ISSUED
Priority Description: Not reported
Status: Not reported
Coordinators Primary: Not reported
Coordinators RPR: Not reported
Responsible Party Name: Not reported
Responsible Party Contact: Not reported
Responsible Party Address: Not reported
Responsible Party City,St,Zip: Not reported
Responsible Party Telephone: Not reported
Reported Date: 01/14/1988
Case Start Date: 05/09/2006

Database Descriptions

NPL: NPL National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices. NPL - National Priority List Proposed NPL - Proposed National Priority List Sites.

NPL Delisted: Delisted NPL The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Delisted NPL - National Priority List Deletions

CERCLIS: SEMS SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL. SEMS - Superfund Enterprise Management System

NFRAP: SEMS-ARCHIVE SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be potential NPL site. SEMS-ARCHIVE - Superfund Enterprise Management System Archive

RCRA COR ACT: CORRACTS CORRACTS identifies hazardous waste handlers with RCRA corrective action activity. CORRACTS - Corrective Action Report

RCRA TSD: RCRA-TSDF RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste. RCRA-TSDF - RCRA - Treatment, Storage and Disposal

RCRA GEN: RCRA-LQG RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. RCRA-LQG - RCRA - Large Quantity Generators RCRA-SQG - RCRA - Small Quantity Generators. RCRA-VSQG - RCRA - Very Small Quantity Generators (Formerly Conditionally Exempt Small Quantity Generators).

Federal IC / EC: US ENG CONTROLS A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. US ENG CONTROLS - Engineering Controls Sites List US INST CONTROLS - Institutional Controls Sites List.

Database Descriptions

ERNS: ERNS Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances. ERNS - Emergency Response Notification System

State/Tribal NPL: SHWS State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state. SHWS - State Superfund Registry

State/Tribal SWL: SWF/LF Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites. SWF/LF - Permitted Solid Waste Facilities

State/Tribal LTANKS: INDIAN LUST R8 INDIAN LUST R7 - Leaking Underground Storage Tanks on Indian Land. INDIAN LUST R5 - Leaking Underground Storage Tanks on Indian Land. INDIAN LUST R6 - Leaking Underground Storage Tanks on Indian Land. INDIAN LUST R1 - Leaking Underground Storage Tanks on Indian Land. INDIAN LUST R9 - Leaking Underground Storage Tanks on Indian Land. INDIAN LUST R10 - Leaking Underground Storage Tanks on Indian Land. INDIAN LUST R4 - Leaking Underground Storage Tanks on Indian Land. LUSTs on Indian land in Florida, Mississippi and North Carolina. INDIAN LUST R4 - Leaking Underground Storage Tanks on Indian Land LPST - Leaking Petroleum Storage Tank Database.

State/Tribal Tanks: UST Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program. UST - Petroleum Storage Tank Database AST - Petroleum Storage Tank Database. INDIAN UST R6 - Underground Storage Tanks on Indian Land. INDIAN UST R10 - Underground Storage Tanks on Indian Land. INDIAN UST R4 - Underground Storage Tanks on Indian Land. INDIAN UST R5 - Underground Storage Tanks on Indian Land. INDIAN UST R7 - Underground Storage Tanks on Indian Land. INDIAN UST R9 - Underground Storage Tanks on Indian Land. INDIAN UST R8 - Underground Storage Tanks on Indian Land. INDIAN UST R1 - Underground Storage Tanks on Indian Land.

State/Tribal IC / EC: AUL Activity and use limitations include both engineering controls and institutional controls. AUL - Sites with Controls

State/Tribal VCP: VCP RRC VCP TCEQ - Voluntary Cleanup Program Database. The Texas Voluntary Cleanup Program was established to provide administrative, technical, and legal incentives to encourage the cleanup of contaminated sites in Texas. VCP TCEQ - Voluntary Cleanup Program Database

ST/Tribal Brownfields: BROWNFIELDS Brownfield site assessments that are being cleaned under EPA grant monies. BROWNFIELDS - Brownfields Site Assessments

US Brownfields: US BROWNFIELDS Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs. US BROWNFIELDS - A Listing of Brownfields Sites

Other Haz Sites: PRIORITY CLEANERS A listing of dry cleaner related contaminated sites. PRIORITY CLEANERS - Dry Cleaner Remediation Program Prioritization List US CDL - Clandestine Drug Labs. CENTRAL REGISTRY - The Central Registry. PFAS - PFAS Contamination Site Location Listing.

Database Descriptions

Other Tanks: NON REGIST PST A listing of non-registered petroleum storage tank site locations. NON REGIST PST - Petroleum Storage Tank Non Registered

Spills: HMIRS Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT. HMIRS - Hazardous Materials Information Reporting System SPILLS - Spills Database. SPILLS 90 - SPILLS90 data from FirstSearch. SPILLS 80 - SPILLS80 data from FirstSearch.

Other: RCRA NonGen / NLR RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste. RCRA NonGen / NLR - RCRA - Non Generators / No Longer Regulated FEDLAND - Federal and Indian Lands. TSCA - Toxic Substances Control Act. TRIS - Toxic Chemical Release Inventory System. SSTS - Section 7 Tracking Systems. RAATS - RCRA Administrative Action Tracking System. PRP - Potentially Responsible Parties. PADS - PCB Activity Database System. ICIS - Integrated Compliance Information System. FTTS - FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act). FTTS INSP - FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act). MLTS - Material Licensing Tracking System. RADINFO - Radiation Information Database. BRS - Biennial Reporting System. INDIAN RESERV - Indian Reservations. US AIRS (AFS) - Aerometric Information Retrieval System Facility Subsystem (AFS). US AIRS MINOR - Air Facility System Data. FINDS - Facility Index System/Facility Registry System. DRYCLEANERS - Drycleaner Registration Database Listing. Ind. Haz Waste - Industrial & Hazardous Waste Database. PST STAGE 2 - PST Stage 2. COMP HIST - Compliance History Listing. PCS - Permit Compliance System. PCS INACTIVE - Listing of Inactive PCS Permits. MINES MRDS - Mineral Resources Data System. PCS ENF - Enforcement data.

Database Sources

NPL: EPA

Updated Quarterly

NPL Delisted: EPA

Updated Quarterly

CERCLIS: EPA

Updated Quarterly

NFRAP: EPA

Updated Quarterly

RCRA COR ACT: EPA

Updated Quarterly

RCRA TSD: Environmental Protection Agency

Updated Quarterly

RCRA GEN: Environmental Protection Agency

Updated Quarterly

Federal IC / EC: Environmental Protection Agency

Varies

ERNS: National Response Center, United States Coast Guard

Updated Quarterly

State/Tribal NPL: Texas Commission on Environmental Quality

Updated Semi-Annually

State/Tribal SWL: Texas Commission on Environmental Quality

Updated Quarterly

State/Tribal LTANKS: EPA Region 7

Varies

State/Tribal Tanks: Texas Commission on Environmental Quality

Updated Quarterly

Database Sources

State/Tribal IC / EC: Texas Commission on Environmental Quality

Varies

State/Tribal VCP: Texas Commission on Environmental Quality

Updated Quarterly

ST/Tribal Brownfields: TCEQ

Updated Semi-Annually

US Brownfields: Environmental Protection Agency

Updated Semi-Annually

Other Haz Sites: Texas Commission on Environmental Quality

Varies

Other Tanks: Texas Commission on Environmental Quality

Updated Quarterly

Spills: U.S. Department of Transportation

Updated Quarterly

Other: Environmental Protection Agency

Updated Quarterly


Street Name Report for Streets near the Target Property

Target Property: 100 S. ELM ST
PECOS, TX 79772

JOB: NA

Street Name	Dist/Dir	Street Name	Dist/Dir
1st St	0.24 ENE		
E 1st St	0.11 ENE		
E 2nd St	0.12 East		
E 4th St	0.22 SE		
E A St	0.14 NNE		
E B St	0.19 NNE		
I-20 Bus W	0.12 SSE		
N Cypress St	0.07 NNE		
N Elm St	0.05 NW		
N Oak St	0.14 NNE		
S Ash St	0.24 ENE		
S Cherry St	0.20 WSW		
S Cypress St	0.05 ENE		
S Elm St	0.02 WSW		
S Hickory St	0.08 WSW		
S Oak St	0.11 ENE		
S Willow St	0.14 WSW		
US-285 N	0.18 ENE		
US-285 S	0.17 ENE		
W 2nd St	0.05 SSE		
W 4th St	0.19 SSE		
W B St	0.15 North		
W C St	0.24 NNW		

100 S. ELM ST PECOS, TX 79772



Black Rings Represent Qtr. Mile Radius; Red Ring Represents 500 ft. Radius

- ★ Target Property (Latitude: 31.42658 Longitude: 103.497906)
- ▲ Identified Sites
- Indian Reservations BIA
- National Priority List Sites


Environmental FirstSearch

0.25 Mile Radius

ASTM MAP: RCRAGEN, ERNS, UST, FED IC/EC, METH LABS



100 S. ELM ST PECOS, TX 79772



Black Rings Represent Qtr. Mile Radius; Red Ring Represents 500 ft. Radius


-  Target Property (Latitude: 31.42658 Longitude: 103.497906)
-  Identified Sites
-  National Priority List Sites
-  Indian Reservations BIA

Environmental FirstSearch

0.25 Mile Radius
Non ASTM Map, Spills, FINDS



100 S. ELM ST PECOS, TX 79772



Black Rings Represent Qtr. Mile Radius; Red Ring Represents 500 ft. Radius


- ★ Target Property (Latitude: 31.42658 Longitude: 103.497906)
- ▲ Identified Sites
- ▭ Indian Reservations BIA
- ⚡ Sensitive Receptors
- ⚡ National Priority List Sites

Site location Map

Topo: 0.75 Mile Radius



100 S. ELM ST PECOS, TX 79772



Map Image Position: TP
Map Reference Code & Name: 5928916 Pecos East
Map State(s): TX
Version Date: 2012
Map Image Position: W
Map Reference Code & Name: 5928918 Pecos West
Map State(s): TX
Version Date: 2012