

State of Hawaii License No. 10743

## PATTISON LAND SURVEYING

P.O. Box 384569 Waikoloa, Hawaii 96738 Office Phone: 808.327.9439 E-mail: tom@surveyhawaii.com

## SURVEY REPORT

as shown on Map 8, filed in the Office of the Assistant Registrar of the Land Court of the State of Hawaii with Land Court Application No. 1318 of John George Medeiros situate as Hilo, County of Hawaii, State of Hawaii

TMK No. (3)2-2-021:045

Address: 1080 Kilauea Avenue, Hilo, HI 96720

I performed a survey of the subject property on August 14th, 2024 and found the existing improvements in the vicinity of the lot boundary lines and setback areas as shown on the accompanying map. For your added information, the County setback codes are as follows:

> Front or Rear Setback......Fifteen (15) feet Side Setbacks.....Zero (0) feet


According to County code, roof overhangs may protrude into the setback up to five [5.00] feet on the side yards.

Upon study of the survey. I found no County setback violations. As the accompanying map shows the Southeast corner of the building is 43.19 feet from the East (front) boundary line and 1.43 feet from the South (side) boundary line. All remaining building corners and building overhangs [eaves] are within code. Please see the accompanying map for more information, not mentioned in this report.

No boundary encroachments were found. Please see the accompanying map for more information, not mentioned in this report.

The features and distances shown between lot lines are based on selected found boundary monuments and acceptable tolerances for properties in this area and age of the original survey. Please note that four [4] of the five [5] recognized original boundary corners were found as noted on the accompanying map. The remaining one [1] boundary corner (SE) was set as noted on the accompanying map.

NOTE: Please refer to the accompanying map for all information pertaining to this report.



Thomas G. Pattison, LPLS #10743 August 20th, 2024