

Other Options

[Return to menu](#)
[Plot this site in State Library Digital Atlas](#)
[Plot this site in Google Maps](#)
[View scanned well log \(8/10/2009 1:42:46 PM\)](#)

Section 7: Well Test Data

Section 1: Well Owner(s)

Total Depth: 180
Static Water Level: 91
Water Temperature:

Section 2: Location

Air Test *

15 gpm with drill stem set at feet for 3 hours.
Time of recovery hours.
Recovery water level feet.
Pumping water level 160 feet.

FLATHEAD				
Latitude	Longitude	Geomethod	Datum	
48.363715	-114.208764	TRS-SEC	NAD83	
Ground Surface Altitude	Ground Surface Method	Datum	Date	

** During the well test the discharge rate shall be as uniform as possible. This rate may or may not be the sustainable yield of the well. Sustainable yield does not include the reservoir of the well casing.*

Addition	Block	Lot
		1

Section 8: Remarks

Section 3: Proposed Use of Water

UNKNOWN (1)

Section 4: Type of Work

Drilling Method: FORWARD ROTARY
Status: NEW WELL

Section 5: Well Completion Date

Date well completed: Wednesday, February 6, 1980

Section 6: Well Construction Details

There are no borehole dimensions assigned to this well.

Casing

From	To	Diameter	Wall Thickness	Pressure Rating	Joint	Type
0	180	6				STEEL

Completion (Perf/Screen)

From	To	Diameter	# of Openings	Size of Openings	Description
180	180	6			OPEN BOTTOM

Annular Space (Seal/Grout/Packer)

There are no annular space records assigned to this well.

Section 9: Well Log

Geologic Source

112ALVM - ALLUVIUM (PLEISTOCENE)

[illegible]

Driller Certification

All work performed and reported in this well log is in compliance with the Montana well construction standards. This report is true to the best of my knowledge.

Name:

Company: CHAMBERS DRILLING COMPANY

License No: WWC-321

Date Completed: 2/6/1980