Form No. GWS-32

PUMP INSTALLATION AND PRODUCTION EQUIPMENT TEST REPORT

State of Colorado, Office of the State Engineer
313 Sherman St., Room 821, Denver, CO 80203 303.866.3581

| For Office Use Only |
|---------------------|
| RECE. |
| CEIVED |
| A |

| 10/2016 | | t., Room 821, Denver, CO 80203 303.86 ate.co.us and dwrpermitsonline@state. | | A110 | LIVED | |
|---|------------------------|--|--|-------|-----------------|--|
| 1. Well Permit Number: 191058A Receipt Number: 3686306 | | | | 706 | 2 0 2018 | |
| 2. Owner's Well Designation: # 1 3. Well Owner Name: Zoka's Kurt Blackwell | | | | | | |
| 2. Owner's Well Designation: # 1 3. Well Owner Name: Zoka's Kurt Blackwell | | | | | | |
| 4. Well Location Street Address: 16940 Co Rd 126 Pine, Co 80471 | | | | | | |
| 5. GPS Well Location: Zone 12 Zone 13 Easting: 473020 Northing: 4362135 County: Jefferson | | | | | | |
| 6. Legal Well Location: <u>nw</u> 1/4, <u>sw</u> 1/4, Sec. <u>26</u> Twp. <u>7</u> Nor S , Range <u>71</u> E or W | | | | | | |
| Distances from Section Lines: ft. from N or S sec. line, and ft. from E or W sec. line | | | | | | |
| Subdivision:, Lot, Block, Filing (Unit) | | | | | | |
| 7. Check Installation Type: ✓ Initial Pump Installation Replacement Pump Change in Depth Only Repair | | | | | | |
| 8. Pump Data: Type: SubmersibleDate Installed(mm/dd/yyyy): 06/21/2018 | | | | | | |
| Pump Manufacturer: Sta-Rite Pump Model No. S5P4HS10221 | | | | | | |
| Design GPM: 5 at RPM 3450 HP 1 Volts 230 Full Load Amps 9.6 | | | | | | |
| Pump Intake Depth: 620 Feet, Drop/Column Pipe Size Inches, 1 Kind of Drop Pipe sch 80 pvc | | | | | | |
| Additional Information for Pumps Greater Than 50 GPM: Turbine Driver Type: 🗸 Electric 🔲 Engine 🔲 Other | | | | | | |
| Design Head: _ | feet | Number of Stages: | Shaft size: | | inches | |
| 9. Other Equip | ment: | | | | | |
| Airline Installed: Yes No, Orifice Depth ft Monitor Tube Installed: Yes No, Depth ft | | | | | | |
| Flow Meter Mfg. Meter Serial No. | | | | | | |
| Meter Readout: Gallons, Thousand Gallons, Acre feet Beginning Reading: | | | | | | |
| | | | - | | a i i r | |
| 10. Cistern Information: Material: Capacity: gallons Date Installed: | | | | | | |
| 11. Production Equipment Test Data: check box if data is submitted on Form Number GWS-39 Well Yield Test Report. | | | | | | |
| Date: <u>6/21/18</u> | | | | | | |
| Total Well Depth: 700 ft. Time: 10:00 | | | | | | |
| | | e (gpm):5 | | | | |
| Date Measured: Pumping Level (ft): | | | | | | |
| | | | | | | |
| 12. Disinfection: Type: HTH Amt. Used: 2.5 Cup | | | | | | |
| 13. Notification: Was Advanced Notification Required Prior to Installation? Yes No, Date Notification Given: 14. Water Quality analysis available: Yes No 15 yes, please submit with this report. | | | | | | |
| | | | The state of the s | | | |
| 15. Remarks: GPM is the pumping rate Not the actual recovery rate. Please refer the driller log for the actual GPM | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 16. I have read the statements made herein and know the contents thereof, and they are true to my knowledge. This | | | | | | |
| document is signed (or name entered if filing online) and certified in accordance with Rule 17.4 of the Water Well Construction | | | | | | |
| Rules, 2 CCR 402-2. The filing of a document that contains false statements is a violation of section 37-91-108(1)(e), C.R.S., | | | | | | |
| and is punishable by fines up to \$1,000 and/or revocation of the contracting license. If filing online, the State Engineer | | | | | | |
| considers the entry of the licensed contractor's name to be compliance with Rule 17.4. | | | | | | |
| Company Name | i ne an | Email: | Phone w/area co | de: | License Number: | |
| Living Wate | r Pump Service Co Inc. | LWPSCI@Qwestoffice.net | (303) 838-7 | 301 | #1138 | |
| Mailing Address: PO BOX 942 Conifer Co 80433 | | | | | | |
| Sign (or enter a | | | | | | |
| | | Print Name and Title | - | Date: | 3-18 | |
| Wan | enla | Wayne Wilson | | 8-1 | 5-18 | |