4-Point Inspection Form

Insured/Applicant Name:	Steve Daria	Application / Policy #:
Address Inspected: 17780	Caloosa Rd , Alva, FL 33920	
Actual Year Built: 1956		Date Inspected: <u>12/09/2024</u>
Minimum Photo Requirem	ents	
☑ Dwelling: Each side ☑	Roof: Each slope 🗹 Plumbing: Wa	ater heater, under cabinet plumbing/drains, exposed valves
☑ Main electrical service	panel with interior door label	
☑ Electrical box with pane	el off	
☑ All hazards or deficie	ncies noted in this report	
	A Florida-licensed insp	pector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring r	remediation must be provi	ded and certified by a lice	ensed electrician.	
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 100 Is amperage sufficient for current usage? ☑ Yes	□ No (explain)	Second Panel Type: Circuit breaker Total Amps: Is amperage sufficient	er □Fuse for current usage? □ Yes □No (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring ☐ Active knob and tube				
☐ Branch circuit aluminum wiring (If present, d			the second all according to the second dead	
* If single strand (aluminum branch) wiring, prov	nde details of all remediation	оп. Ѕерага!е иосигнепіа	uon or air work must be provided.	
☐ Connections repair via COPALUM crimp				
☐ Connections repair via AlumiConn				
Hazards Present		☐ Exposed wiring		
☐ Blowing fuses		☐ Over fusing		
☐ Empty sockets		☐ Unsafe wiring		
☐ Loose Wiring		☐ Improper breaker size		
☐ Tripping breakers		Scorching		
☐ Improper grounding		☐ Other (explain)		
☐ Corrosion				
☐ Double taps				
General condition of the electrical system: ☑	Satisfactory Unsatisfac	ctory (explain)		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 7 years	Panel age:		☑ Copper	
Year last updated: 2017	Year last updated:		☑ NM, BX or Conduit	
Brand/Model: Square D	Brand/Model:			

4-Point Inspection Form

HVAC System					
Central AC: ☑ Yes ☐ No					
Central heat: ☑ Yes ☐ No	Myes □Ns				
If not central heat, indicate primary heat source and fuel type:					
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)				
Date of last HVAC servicing/inspection: unknown					
Hazards Present					
Wood burning stove or central gas fireplace not professionally installed? □	lYes ☑No				
Space heater used as primary heat source? ☐ Yes ☑ No					
Is the source portable? ☐ Yes ☑ No					
Does the air handler/condensate line or drain pan show any signs of blocka ☐ Yes ☑ No	ge or leakage, including water damage to the surrounding area?				
Supplemental Information					
Age of system: 7 years					
Year last updated: 2017					
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	plate)				
Plumbing System					
Is there a temperature pressure relief valve on the water heater? $lacktriangle$ Yes $lacktriangle$] No				
Is there any indication of an active leak? ☐ Yes ☑ No					
Is there any indication of a prior leak? ☐ Yes ☑ No					
Water heater location: 2023 laundry room					
General condition of the following plumbing fixtures and connections	to applicances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A				
Dishwasher	Toilets 🗹 🗆				
Refrigerator □ □ Washing Machine □ □	Sinks ☑ □ □ Sump pump □ ☑ ☑				
Water Heater	Main shut off valve				
Showers/Tubs	All other visible ☑ □				
If unsatisfactory, please provide comments/details (leaks, wet/soft spo	ts, mold, corrosion, grout/caulk, etc.).				
Supplemental Information					
Age of Piping System:	Type of pipes (check all that apply)				
Original to home	☐ Copper				
Completely re-piped	☑ PVC/CPVC				
X Partially re-piped	☐ Galvanized				
(Provide year and extent of renovation in the comments below)	□PEX				
2024 remodel	☐ Polybutylene				
	☐ Other (specify)				

4-Point Inspection Form

Roof (With photos of each roof slope	, this section can take the pla	ace of the Roof Inspection Form.)			
Predominant Roof		Secondary Roof			
Covering material: Metal Panel		Covering material: $N/A - BLANK$	Covering material: N/A - BLANK SECTION		
Roof age (years): 25		Roof age (years):			
Remaining useful life (years): 15+	<u> </u>	Remaining useful life (years):	Remaining useful life (years):		
Date of last roofing permit: unknown	-		Date of last roofing permit:		
Date of last update:		Date of last update:			
If updated (check one):		If updated (check one):			
☑ Full Replacement		☐ Full Replacement	☐ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement		
% of replacement		% of replacement	<u> </u>		
Overall condition:		Overall condition:			
☑ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain belo	ow)		
Any visible signs of damage / deterior	ration?	Any visible signs of damage / de	terioration?		
(check all that apply and explain below)		(check all that apply and explain be	(check all that apply and explain below)		
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling	☐ Cupping/Curling		
☐ Excessive granule loss			☐ Excessive granule loss		
_		-			
☐ Exposed asphalt		☐ Exposed asphalt			
☐ Missing/loose/cracked tabs or tiles		☐ Exposed felt			
☐ Exposed felt		☐ Missing/loose/cracked tabs o	r tiles		
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks ☐ Yes ☑N	lo	Any visible signs of leaks ☐ Yes	s ☑ No		
Attic/underside of decking ☐ Yes ☑ No		Attic/underside of decking ☐ Yes	☑No		
Interior ceilings ☐ Yes ☑ No		Interior ceilings ☐ Yes ☑ No	Interior ceilings ☐ Yes ☑ No		
Additional Comments/Observa	•	-			
All systems were in good co	ndition at the time of	the inspection.			
All 4-Point Inspection Forms must be con	mpleted and signed by a verif	iable Florida-licensed inspector.			
I certify that the above statements are tru					
_/ D4					
Inspector Signature	Hernan Prieto Title	HI 8405 License Number	2024-12-09 Date		
mopeolor Signature	Huc	LICEUSE MUNIDEI	Dale		
Dream Protection Home Inspection	Home Inspector	239-233-1269	<u></u>		
Company Name	License Type	Work Phone			

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations


Exterior Photos



Electrical System

Panel Photos





HVAC System

HVAC Equipment



Plumbing System


Water Heater





Under cabinet plumbing & drains








Plumbing



RoofPhotos of Each Slope



4-Point Inspection Form

Insured/Applicant Name:	Steve Daria	Application / Policy #:	
Address Inspected: 1779	0 Caloosa Rd , Alva, FL 339	120	
Actual Year Built: 1957		Date Inspected: <u>12/09/2024</u>	
Minimum Photo Requirer ☑ Dwelling: Each side		ng: Water heater, under cabinet plumbing/drains, exposed valves	
☑ Main electrical service	panel with interior door label		
☑ Electrical box with par	nel off		
☑ All hazards or defici	encies noted in this report		
	A Florida-license	d inspector must complete, sign and date this form.	

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.				
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☑ Yes	□ No (explain)	Second Panel Type: Circuit breake Total Amps: Is amperage sufficient f	r □Fuse or current usage? □ Yes □No (explain)	
Indicate presence of any of the following:				
☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, do * If single strand (aluminum branch) wiring, provi ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumiConn	g .	σ,	tion of all work must be provided.	
Hazards Present		☐ Exposed wiring		
☐ Blowing fuses ☐ Empty sockets ☐ Loose Wiring ☐ Tripping breakers ☐ Improper grounding ☐ Corrosion ☐ Double taps		Over fusing Unsafe wiring Improper breaker Scorching Other (explain)	size	
General condition of the electrical system: ☑	Satisfactory 🗆 Unsatisfac	tory (explain)		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 24 years	Panel age:		☑ Copper ☑ NM, BX or Conduit	
Year last updated: 2000	Year last updated:			
Brand/Model: Square D	Brand/Model:			

4-Point Inspection Form

HVAC System			
Central AC: ☑ Yes ☐ No			
Central heat: ☑ Yes ☐ No			
If not central heat, indicate primary heat source and fuel type:			
Are the heating, ventilation and air conditioning systems in good working or	der? ☑ Yes ☐ No (explain)		
Date of last HVAC servicing/inspection: unknown			
Hazards Present			
Wood burning stove or central gas fireplace not professionally installed?]Yes ☑No		
Space heater used as primary heat source? ☐ Yes ☑ No			
Is the source portable? ☐ Yes ☑ No			
Does the air handler/condensate line or drain pan show any signs of blocka ☐ Yes ☑ No	ge or leakage, including water damage to the surrounding area?		
Supplemental Information			
Age of system: 1 year			
Year last updated: 2023			
(Please attach photo(s) of HVAC equipment, including dated manufacturer's	s plate)		
Plumbing System			
Is there a temperature pressure relief valve on the water heater? 🗹 Yes 🗆]No		
Is there any indication of an active leak? Yes No			
Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location: Exterior closet 2024			
General condition of the following plumbing fixtures and connections	to applicances:		
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets ☑ □ □		
Refrigerator	Sinks 🗹 🗆		
Washing Machine ☐ ☐	Sump pump □ □ ☑		
Water Heater	Main shut off valve		
Showers/Tubs	All other visible		
If unsatisfactory, please provide comments/details (leaks, wet/soft spo	ts, mold, corrosion, grout/caulk, etc.).		
Supplemental Information			
Ago of Diving Customs			
Type of pipes (check all that apply). ——— Original to home ☐ Copper			
Completely re-piped	☑ Copper ☑ PVC/CPVC		
X Partially re-piped	☐ Galvanized		
(Provide year and extent of renovation in the comments below)	□ PEX		
2024 remodel	☐ Polybutylene		
	☐ Other (specify)		

4-Point Inspection Form

Roof (With photos of each roof slope,	this section can take the place of	the Roof Inspection Form.)		
Covering material: Metal Panel Roof age (years): 25 Remaining useful life (years): 15 Date of last roofing permit: unknown Date of last update:		Secondary Roof Covering material: N/A - BLANK SECTION Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update: If updated (check one):		
☑ Full Replacement		☐ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement		
% of replacement		% of replacement		
Overall condition:		Overall condition:		
☑ Satisfactory		☐ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)		
Any visible signs of damage / deteriors (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Missing/loose/cracked tabs or tiles Exposed felt Soft spots in decking Visible hail damage Any visible signs of leaks Attic/underside of decking Yes No Interior ceilings Yes No		Any visible signs of damage / deterior (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tile Soft spots in decking Visible hail damage Any visible signs of leaks Attic/underside of decking Messing Yes Minterior ceilings Yes Mo	s No	
Additional Comments/Observa All systems were in good cor				
All 4-Point Inspection Forms must be con I certify that the above statements are tru	·	Florida-licensed inspector.		
4 Dt	Haman Drieta	111.0405	0004.40.00	
Inspector Signature	Hernan Prieto Title	HI 8405 License Number	2024-12-09 Date	
Dream Protection Home Inspection Company Name	Home Inspector License Type	239-233-1269 Work Phone		

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos



Electrical System

Panel Photos



HVAC System

HVAC Equipment







Plumbing System


Water Heater








Under cabinet plumbing & drains






Plumbing



Roof

Photos of Each Slope





4-Point Inspection Form

Insured/Applicant Name:	Steve Daria	Application / Policy #:
Address Inspected: 1780	00 Caloosa Rd , Alva, FL 33920	
Actual Year Built: 1970		Date Inspected: <u>12/09/2024</u>
Minimum Photo Require	ements	
☑ Dwelling: Each side	☑ Roof: Each slope ☑ Plumbing: Wa	ater heater, under cabinet plumbing/drains, exposed valves
☑ Main electrical servic	e panel with interior door label	
☑ Electrical box with pa	anel off	
☑ All hazards or defic	iencies noted in this report	
	A Florida-licensed insp	pector must complete, sign and date this form.

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring i	remediation must be provi	ded and certified by a lice	ensed electrician.	
Main Panel Type: ☑ Circuit breaker ☐ Fuse Total Amps: 150 Is amperage sufficient for current usage? ☑ Yes		Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)		
Indicate presence of any of the following:				
☐ Cloth wiring ☐ Active knob and tube ☐ Branch circuit aluminum wiring (If present, d * If single strand (aluminum branch) wiring, prov ☐ Connections repair via COPALUM crimp ☐ Connections repair via AlumiConn			tion of all work must be provided.	
Hazards Present Blowing fuses Empty sockets Loose Wiring Tripping breakers Improper grounding Corrosion Double taps		□ Exposed wiring □ Over fusing □ Unsafe wiring □ Improper breaker size □ Scorching □ Other (explain)		
General condition of the electrical system: ☑	Satisfactory Unsatisfac	ctory (explain)		
Supplemental information				
Main Panel	Second Panel		Wiring Type	
Panel age: 24 years	Panel age:		☑ Copper ☑ NM, BX or Conduit	
Year last updated: 2000	Year last updated:			
Brand/Model: Square D	Brand/Model:			

4-Point Inspection Form

HVAC System	HVAC System						
Central AC: ☑\	∕es □ No						
	′es □No						
If not central heat, ir	ndicate primary h	eat source and f	uel type:				
Are the heating, ver	itilation and air co	nditioning syster	ms in good working o	rder? ☑ Yes ☐ No (exp	olain)		
Date of last HVAC s							
Hazards Present							
Wood burning stove	or central gas fire	eplace not profes	ssionally installed?]Yes ☑No			
Space heater used	as primary heat so	ource? 🗆 Yes 🖪	☑ No				
Is the source portab	le? □Yes ☑No						
Does the air handle ☐ Yes ☑ No	r/condensate line	or drain pan sho	ow any signs of blocka	age or leakage, includin	g water damage t	o the surroundi	ng area?
Supplemental In	formation						
Age of system: 1 ye	ear						
Year last updated: 2							
(Please attach photo	(s) of HVAC equip	oment, including	dated manufacturer's	s plate)			
Plumbing Sys	stem						
			ter heater? ☑ Yes ☐] No			
Is there any indication			0				
Is there any indication	n.						
Water heater location	11. 2024 laundr	y room					
General condition	of the following p	lumbing fixture	es and connections	to applicances:			
	Satisfactory (Jnsatisfactory	N/A		Satisfactory U	nsatisfactory	N/A
Dishwasher	$\mathbf{\underline{\square}}$			Toilets	$\mathbf{\underline{\square}}$		
Refrigerator			lacksquare	Sinks	⊻		
Washing Machine Water Heater	⊻ ⊻			Sump pump Main shut off valve	□ ⊻		
Showers/Tubs	∑			All other visible	⊻		
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
Age of Piping System: Type of pipes (check all that apply)							
Original to home			☑ Copper				
Complete	ly re-piped			☑ PVC/CPVC			
X Partially r				☐ Galvanized			
(Provide year and ex	• •	in the comment	ts below)	□ PEX			
2024 remodel		0.0 00111110111		☐ Polybutylene			
				Other (specify)			
				Li Other (specify)			

4-Point Inspection Form

Roof (With photos of each roof slope	e, this section can take the place of	the Roof Inspection Form.)			
Covering material: Metal Panel Roof age (years): 25 Remaining useful life (years): 15 Date of last roofing permit: unknown		Secondary Roof Covering material: Roof age (years): Remaining useful life (years): Date of last roofing permit: Date of last update:			
If updated (check one):		If updated (check one):			
☑ Full Replacement		☐ Full Replacement	☐ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement			
% of replacement		% of replacement			
Overall condition:		Overall condition:			
☑ Satisfactory		☐ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss		Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss			
☐ Exposed asphalt		☐ Exposed asphalt			
☐ Missing/loose/cracked tabs or tiles		☐ Exposed felt			
☐ Exposed felt		☐ Missing/loose/cracked tabs or tile	S		
☐ Soft spots in decking		☐ Soft spots in decking			
☐ Visible hail damage		☐ Visible hail damage			
Any visible signs of leaks Yes Yes		Any visible signs of leaks Yes			
Attic/underside of decking ☐ Yes ☑ No Interior ceilings ☐ Yes ☑ No		Attic/underside of decking ☐ Yes ☐ No Interior ceilings ☐ Yes ☐ No			
Additional Comments/Observa All systems were in good co		•			
All 4-Point Inspection Forms must be con I certify that the above statements are true		Florida-licensed inspector.			
-f-Dt	Hernan Prieto	HI 8405	2024-12-09		
Inspector Signature	Title	License Number	Date		
Dream Protection Home Inspection	Home Inspector	239-233-1269			
Company Name	License Type	Work Phone			

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos




Electrical System

Panel Photos



Additional Photos






Plumbing System

Water Heater



Under cabinet plumbing & drains





Plumbing



Roof

