

2024 Property Records for Town of Lomira, Dodge Country

January 22, 2025

Tax key number: 030-1317-1443-000

Property address: W644 State Rd 67

Traffic / water / sanitary: Heavy / Well water / Septic



Summary of Assessment	
Land	\$42,000
Improvements	\$112,200
Total value	\$154,200

Land									
Qty	Land Use	Width	Depth	Square Feet	Acres	Water Frontage	Tax Class	Special Tax Program	Assess Value
1	1st grade tillable			566,280	13.000	None	1st grade tillable		\$4,100
1	2nd grade tillable			675,180	15.500	None	2nd grade tillable		\$4,200
1	Prime pasture			152,460	3.500	None	Pasture		\$300
1	Agri-homesite			123,972	2.846	None	Agri homesite		\$33,400

Residential Building			
Year built:	1930	Full basement:	1,054 SF
Year remodeled:		Crawl space:	
Stories:	1.5 story	Rec room (rating):	
Style:	Old style	Fin bsmt living area:	
Use:	Single family	First floor:	1,054 SF
Exterior wall:	Brick	Second floor:	520 SF
Masonry adjust:		Third floor:	
Roof type:	Asphalt shingles	Finished attic:	
Heating:	Gas, forced air	Unfinished attic:	
Cooling:	A/C, same ducts	Unfinished area:	
Bedrooms:	4	Enclosed porch	90 SF
Family rooms:			
Baths:	1 full, 0 half		
Other rooms:	3		
Whirl / hot tubs:			
Add'l plumb fixt:			
Masonry FPs:			
Metal FPs:			
Gas only FPs:		Grade:	C-
Bsmt garage:		Condition:	Average
Shed dormers:		Energy adjustment:	No
Gable/hip dorm:		Percent complete:	100%



Total living area is 1,574 SF; building assessed value is \$89,500



2024 Property Records for Town of Lomira, Dodge Country

January 22, 2025

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Barn, general purpose	Width: 40 LF	Grade: C		not available
Const type: Bank, wood	Depth: 72 LF	Condition: Average		
Year built: 1920	Floor area: 2,880 SF	% complete: 100%		
	Height: 24 LF	Assessed \$: \$4,000		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Granary	Width: 16 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 20 LF	Condition: Average		
Year built: 1930	Floor area: 320 SF	% complete: 100%		
	Height: 12 LF	Assessed \$: \$400		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Farm implement building, pole	Width: 14 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 20 LF	Condition: Average		
Year built: 1930	Floor area: 280 SF	% complete: 100%		
	Height: 10 LF	Assessed \$: \$500		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Farm implement building, pole	Width: 22 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 64 LF	Condition: Average		
Year built: 1930	Floor area: 1,408 SF	% complete: 100%		
	Height: 8 LF	Assessed \$: \$1,600		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Farm implement building, pole	Width: 18 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 22 LF	Condition: Average		
Year built: 1930	Floor area: 396 SF	% complete: 100%		
	Height: 8 LF	Assessed \$: \$600		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Lean-to	Width: 42 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 14 LF	Condition: Average		
Year built: 1930	Floor area: 588 SF	% complete: 100%		
	Height: 8 LF	Assessed \$: \$200		

2024 Property Records for Town of Lomira, Dodge Country

January 22, 2025

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Lean-to	Width: 20 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 40 LF	Condition: Average		
Year built: 1930	Floor area: 800 SF	% complete: 100%		
	Height: 14 LF	Assessed \$: \$300		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Lean-to	Width: 12 LF	Grade: C		not available
Const type: Pole frame, metal siding	Depth: 40 LF	Condition: Average		
Year built: 1970	Floor area: 480 SF	% complete: 100%		
	Height: 10 LF	Assessed \$: \$100		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Farm implement building, pole	Width: 16 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 18 LF	Condition: Average		
Year built: 1930	Floor area: 288 SF	% complete: 100%		
	Height: 8 LF	Assessed \$: \$200		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Farm implement building, pole	Width: 22 LF	Grade: C		not available
Const type: Wood frame, wood siding	Depth: 32 LF	Condition: Average		
Year built: 1930	Floor area: 704 SF	% complete: 100%		
	Height: 8 LF	Assessed \$: \$500		

# of identical OBIs: 1		Other Building Improvement (OBI)		
Main Structure		Modifications (Type, Size)		Photograph
OBI type: Garage	Width: 24 LF	Grade: C		not available
Const type: Detached, frame or cb	Depth: 54 LF	Condition: Average		
Year built: 1984	Floor area: 1,296 SF	% complete: 100%		
		Assessed \$: \$14,300		

Building Permits				
Issued	Permit #	Purpose	\$ Amount	Completed

Sales History		
Date	Price	Type
6/5/2023	\$165,000	Not a market sale