

210,000 SF OF CLASS A OFFICE SPACE WITH PARK VIEWS







501, 503 & 505 CARR ROAD WILMINGTON, DE 19809

SUITES AVAILABLE FROM 2,098 SF – 23,072 SF

THREE 70,000 RSF BUILDINGS ON 17.76 ACRES SURROUNDED BY PUBLIC PARKS





RECENT IMPROVEMENTS

- On-site fitness center
- Conference center
- Grab-and-go cafe
- Upgraded elevators

FEATURES

- Dynamic two and threestory atrium lobbies with glass curtain walls
- Building signage opportunities
- Adjacent to I-95
- Ample surface parking free of charge
- Adjacent to Northern
 Delaware Greenway Trail
- Located outside the city limits of Wilmington
- Heat pump HVAC system





BUILDING SPECIFICATIONS

YEAR BUILT 1986

RENOVATED 2020

PARKING

There are a total of 759 parking spaces on the site, including 15 handicapped accessible spaces representing 3.81 spaces per 1,000 rentable square feet.

VOICE AND DATA COMMUNICATIONS

Verizon, Comcast and Cavalier services available.

BACK-UP GENERATOR

501 Carr Road has a full building back-up generator.

ELECTRICITY

The building standard electrical capacity ranges from 6 watts/USF to 7 watts/ USF (2 watts/USF for lighting and 4 watts/USF to 5 watts/ USF for receptacles).

ELEVATORS

Newly upgraded. Each building is equipped with two 3,000 lb. 3-stop hydraulic passenger elevators.


ENERGY CONSERVATION

The buildings include a Building Automation System (BAS).






















AVAILABILITIES














For more information, please contact:

CBRE Inc., 3711 Kennett Pike, Suite 210, Wilmington, DE, 19807, T +1 302 661 6700 cbre.us/wilmington, Licensed Real Estate Broker

© 2024 CBRE, Inc. All rights reserved. This information has been obtained from sources believed reliable but has not been verified for accuracy or completeness. CBRE, Inc. makes no guarantee, representation or warranty and accepts no responsibility or liability as to the accuracy, completeness, or reliability of the information contained herein. You should conduct a careful, independent investigation of the property and verify all information. Any reliance on this information is solely at your own risk. CBRE and the CBRE logo are service marks of CBRE, Inc. All other marks displayed on this document are the property of their respective owners, and the use of such marks does not imply any affiliation with or endorsement of CBRE. Photos herein are the property of their respective owners. Use of these images without the express written consent of the owner is prohibited.

