PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

| | SECTION I – WATER SUPPLY |
|------------------|--------------------------------------------------------------------------------------------------------------|
| | SECTION I — WATER SUPPLY |
| TYPE OF SYST | TEM: Public Private Seasonal Unknown X Drilled Dug Other |
| MALFUNCTIO | NS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system? |
| | Pump (if any): N/A Yes X No Unknown |
| | Quantity: Yes X No Unknown |
| | Quality: Yes X No Unknown |
| | If Yes to any question, please explain in the comment section below or with attachment. |
| WATER TEST: | Have you had the water tested? |
| | If Yes, Date of most recent test: <u>u/k</u> Are test results available? Yes X No |
| | To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation? |
| | If Yes, are test results available? Yes X No |
| | What steps were taken to remedy the problem? satisfactory results |
| IF PRIVATE: (St | rike Section if Not Applicable): |
| INSTALLAT | ION: Location: downstairs bathroom |
| | Installed by: unknown/ 200 feet deep |
| | Date of Installation: unknown |
| USE: | Number of persons currently using system: 2 |
| | Does system supply water for more than one household? Yes X No Unknown |
| Comments: 7/13/2 | 2024 components in well completely replaced as well was not holding pressure |
| | I information: sellers |
| Buyer Initials | Page 1 of 8 Seller Initials VT ST |

| SECTION II — WASTE WATER DISPOSAL |
|--------------------------------------------------------------------------------------------------------------------------------------------------|
| TYPE OF SYSTEM: Public |
| IF PUBLIC OR QUASI PUBLIC (Strike Section if Not Applicable): |
| Have you had the sewer line inspected? |
| If Ves, what results: |
| Have you experienced any problems such as line or other malfunctions? |
| What steps were taken to remedy the problem? |
| IF PRIVATE (Strike Section if Not Applicable): Tank: X Septic Tank Holding Tank Cesspool Other: |
| |
| |
| |
| Location: <u>under outside seated bar area</u> Date installed: <u>unknown</u> Date last pumped: <u>2019</u> Name of pumping company: <u>Nest</u> |
| Have you experienced any malfunctions? |
| If Yes, give the date and describe the problem: none |
| |
| Date of last servicing of tank:Name of company servicing tank: n/a |
| Leach Field: X Yes No Unknow |
| If Yes, Location: to right of little barn |
| Date of installation of leach field: <u>u/k</u> Installed by: <u>u/k</u> |
| Date of last servicing of leach field:Company servicing leach field: n/a |
| Have you experienced any malfunctions? Yes X No |
| If Yes, give the date and describe the problem and what steps were taken to remedy: none |
| |
| Do you have records of the design indicating the # of bedrooms the system was designed for? X Yes No |
| If Yes, are they available? Yes X No |
| Is System located in a Shoreland Zone? |
| Comments: none |
| Source of Section II information: sellers |
| |
| |
| |
| |
| J = - |
| Buyer Initials Page 2 of 8 Seller Initials $\sqrt{7}$ |

| SECTION III — HEATING SYSTEM(S)/HEATING SOURCE(S) | | | | | | | |
|---------------------------------------------------------------------------------------------|--------------------------------------|-----------------------------------------|---------------------------|---------------------|--|--|--|
| Heating System(s) or Source(s) | SYSTEM 1 | SYSTEM 2 | SYSTEM 3 | SYSTEM 4 | | | |
| TYPE(S) of System | 2 propane stove fireplaces | Kerosene Monitors | Electric Baseboards | Geo Thermal | | | |
| Age of system(s) or source(s) | see below | u/k | 1994 | u/k | | | |
| TYPE(S) of Fuel | propane | K1 | Electric | n/a | | | |
| Annual consumption per system | _ | | | | | | |
| or source (i.e., gallons, kilowatt hours, cords) | u/k | 400 Gallons | n/a | 10' Basement filled | | | |
| Name of company that services | | | n/a | with stone | | | |
| system(s) or source(s) | Irving | Arrow Kerosene | n/a | n/a | | | |
| Date of most recent service call | none | none | n/a | n/a | | | |
| Malfunctions per system(s) or | | | | | | | |
| source(s) within past 2 years | none | none | n/a | n/a | | | |
| Other pertinent information | 2022 added 2nd stovee | 3 Monitor Heaters | Only use when temperature | n/a | | | |
| | 1st stove 5-10 yrs old | | below freezing | n/a | | | |
| Are there fuel supply lin | nes? | | X Yes | No Unknown | | | |
| Are any buried? | | | | | | | |
| Are all sleeved? | | | | | | | |
| | | | | | | | |
| Chimney(s): | | | | | | | |
| - | 1: | | | _ | | | |
| Is more than one heat | • | | | | | | |
| | Had a chimney fire: Yes X No Unknown | | | | | | |
| | inspected? | *************************************** | Yes X | No Unknown | | | |
| If Yes, date: n/a | | | | | | | |
| Date chimney(s) last c | | | | | | | |
| Direct/Power Vent(s): | ***************** | ******************************* | X Yes | No Unknown | | | |
| Has vent(s) been inspe | cted? | *************************************** | Yes X | No Unknown | | | |
| If Yes, date: n/a | | | | | | | |
| Comments: Electric Radi | ant Heat in Primary | Bathroom | | | | | |
| Source of Section III infor | mation: Sellers | | | | | | |
| THE RESERVE OF THE | SECTION IV - | - HAZARDOUS MA | TERIAL | | | | |
| The licensee is disclosing | | | | BUTTER OF STREET | | | |
| A. UNDERGROUND S | | | | any underground | | | |
| | | | | | | | |
| storage tanks on the property? | | | | | | | |
| If no longer in use, how long have they been out of service? n/a | | | | | | | |
| If tanks are no longer in use, have tanks been abandoned according to DEP? Yes No X Unknown | | | | | | | |
| Are tanks registered with DEP? Yes No X Unknown | | | | | | | |
| Age of tank(s): n/a Size of tank(s): n/a | | | | | | | |
| - | | | | | | | |
| | · | | | | | | |
| Buyer Initials | 1 | Page 3 of 8 Se | eller Initials <u>VT</u> | 7 | | | |

| What materials are, or were, stored in the tank(s)? n/a | | |
|---------------------------------------------------------------|----------------|--------------|
| Have you experienced any problems such as leakage: | Yes | No X Unknown |
| Comments: none | | |
| Source of information: sellers | | |
| B. ASBESTOS — Is there now or has there been asbestos: | | |
| As insulation on the heating system pipes or duct work? | Yes | X No Unknown |
| In the ceilings? | Yes | X No Unknown |
| In the siding? | Yes | X No Unknown |
| In the roofing shingles? | Yes | X No Unknown |
| In flooring tiles? | Yes | X No Unknown |
| Other: none | _ Yes | X No Unknown |
| Comments: n/a | | |
| Source of information: sellers | | |
| C. RADON/AIR - Current or previously existing: | | |
| Has the property been tested? | Yes | X No Unknown |
| If Yes: Date: n/a By: n/a | | |
| Results: n/a | | |
| If applicable, what remedial steps were taken? | | |
| Has the property been tested since remedial steps? | | X No Unknown |
| Are test results available? | Yes | X No |
| Results/Comments: n/a | | |
| Source of information: sellers | | |
| D. RADON/WATER - Current or previously existing: | | |
| Has the property been tested? | Yes | X No Unknown |
| If Yes: Date: <u>n/a</u> By: <u>n/a</u> | | |
| Results: n/a | | |
| If applicable, what remedial steps were taken? n/a | | |
| Has the property been tested since remedial steps? | Yes | X No Unknown |
| Are test results available? | Yes | X No |
| Results/Comments: n/a | | |
| Source of information: sellers | | |
| E. METHAMPHETAMINE - Current or previously existing: | Yes | X No Unknown |
| Comments: n/a | | |
| Source of information: n/a | | |
| | | |
| | :1 | |
| Buyer Initials Page 4 of 8 Seller Init | ials <u>VT</u> | 5/ |

PROPERTY LOCATED AT: 245 Arundel Road, Kennebunkport, ME 04046

| PROPERTY LOCATED AT: 245 Arundel Road, Kennebunkport, ME 04046 | _ |
|-----------------------------------------------------------------------------------------------------------------------|-----|
| F. LEAD-BASED PAINT/PAINT HAZARDS — (Note: Lead-based paint is most commonly found in home constructed prior to 1978) | 2S |
| Is there now or has there ever been lead-based paint and/or lead-based paint hazards on the property? | ••• |
| | e) |
| If Yes, describe location and basis for determination: <u>n/a</u> | |
| Do you know of any records/reports pertaining to such lead-based paint/lead-based paint hazards: Yes X N | 0 |
| If Yes, describe: | |
| Are you aware of any cracking, peeling or flaking paint? | 0 |
| Comments: small amount on exterior of barn | |
| Source of information: sellers | |
| G. OTHER HAZARDOUS MATERIALS - Current or previously existing: | |
| TOXIC MATERIAL: Yes X No Unknow | n |
| LAND FILL: Yes X No Unknow | n |
| RADIOACTIVE MATERIAL: Yes X No Unknow | n |
| Other: n/a | |
| Source of information: sellers | |
| Buyers are encouraged to seek information from professionals regarding any specific issue or concern. | |
| | |
| SECTION V — ACCESS TO THE PROPERTY | |
| Is the property subject to or have the benefit of any encroachments, easements, rights-of-way, leases, rights of | |
| first refusal, life estates, private ways, trails, homeowner associations (including condominium | S |
| and PUD's) or restrictive covenants? Yes X No Unknown | 1 |
| If Yes, explain: n/a | |
| Source of information: sellers | |
| Is access by means of a way owned and maintained by the State, a county, or a municipality | |
| over which the public has a right to pass? Yes X No Unknown | |
| If No, who is responsible for maintenance? n/a | |
| Road Association Name (if known): n/a | _ |
| Source of information: sellers | _ |
| | _ |
| | |
| | |
| | |
| | |
| | |
| ı | |
| Buyer Initials Page 5 of 8 Seller Initials VT ST | |

SECTION VI - FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

| During the time the seller has owned the property: | | |
|---------------------------------------------------------------------------------|----------------------------------------------|------------------------|
| Have any flood events affected the property? | Yes | X No Unknown |
| If Yes, explain: n/a | | |
| Have any flood events affected a structure on the property? | Yes | X No Unknown |
| If Yes, explain: n/a | | |
| Has any flood-related damage to a structure occurred on the property? | Yes | X No Unknown |
| If Yes, explain: n/a | | |
| Has there been any flood insurance claims filed for a structure on the | | |
| property? | Yes | X No Unknown |
| If Yes, indicate the dates of each claim: n/a | | |
| Has there been any past disaster-related aid provided related to the property | | |
| or a structure on the property from federal, state or local sources for | | |
| purposes of flood recovery? | Yes | X No Unknown |
| If Yes, indicate the date of each payment: n/a | <u>. </u> | |
| Is the property currently located wholly or partially within an area of special | | |
| flood hazard mapped on the effective flood insurance rate map issued by the | | |
| Federal Emergency Management Agency on or after March 4, 2002? | Yes | X No Unknown |
| If yes, what is the federally designated flood zone for the property indicated | d on that flo | od insurance rate map? |
| n/a | | |
| Relevant Panel Number: 23031C0463G Year: | 7/2024 | (Attach a copy) |
| Comments: Sellers have never had any flooding on the property in the | 30 years of | ownerships |
| | | |
| Source of Section VI information: sellers | | |
| Buyer Initials Page 6 of 8 Seller Init | ials // | ST |

| SECTION VII – GENER | | | | 0.4 (0.4 7) |
|--------------------------------------------------------------------------------|----------------------------------------------|--------------|------------------|-------------|
| Are there any tax exemptions or reductions for this proper | | | | |
| Tree Growth, Open Space and Farmland, Veteran's, Homes | tead Exemption, Bl | lind, Workii | ng Waterfront | ? |
| | | Yes | X No | Unknown |
| If Yes, explain: n/a | | | | |
| Is a Forest Management and Harvest Plan available? | ••••••••••• | Yes | x No [| Unknowr |
| Are there any actual or alleged violations of a shoreland zo | oning ordinance | | | |
| including those that are imposed by the state or municipality of Yes, explain: | ty? | Yes | X No | Unknown |
| Equipment leased or not owned (including but not limited | to, propane tank, ł | not water he | eater, satellite | dish, water |
| filtration system, photovoltaics, wind turbines): Type: | <u>n/a</u> Year Princip | al Structure | e Built: 1905 | |
| What year did Seller acquire property? 1994 | <u>. </u> | | | |
| Roof: Year Shingles/Other Installed: Metal Roof 199 | 15 | | | |
| Water, moisture or leakage: none | | | | |
| Comments: none | | | | |
| Foundation/Basement: | | | | |
| Is there a Sump Pump? | ************************** | Yes | X No | Unknown |
| Water, moisture or leakage since you owned the pr | | Yes | X No | Unknown |
| Prior water, moisture or leakage? | | Yes | X No | Unknown |
| Comments: | | | | 0111101111 |
| Mold: Has the property ever been tested for mold? | ••••• | Yes | X No | Unknown |
| If Yes, are test results available? | ************************ | Yes | X No | |
| Comments: | | | [23] | |
| Electrical: Fuses X Circuit Breaker Other: n/s | a | | | Unknown |
| Comments: 3 circuit breaker boxes and 2 sub par | nels | | | |
| Has all or a portion of the property been surveyed? | | X Yes | No 🗌 | Unknown |
| If Yes, is the survey available? | ******** | Yes | No | |
| Manufactured Housing – Is the residence a: | | | | |
| Mobile Home | ************************* | Yes | X No | Unknown |
| Modular | *************************************** | Yes | No 🗆 | Unknown |
| Known defects or hazardous materials caused by insect or a | nimal infestation i | nside or on | 4.5 | |
| | | Yes | | Unknown |
| Comments: none | | | 20 | O IMMIO WII |
| KNOWN MATERIAL DEFECTS about Physical Condition | on and/or value of | Property, i | ncluding thas | e that may |
| have an adverse impact on health/safety: none | | | | |
| Comments: none | | | | |
| Source of Section VII information: sellers | | | | |
| Buyer Initials Page 7 of 8 | Seller Init | tials (// | ST | |

SECTION VIII - ADDITIONAL INFORMATION Propane tank to the left of the house serves the downstairs kitchen oven. Propane tank to the right of the house serves 2 propane stove fireplaces and 2nd floor kitchen oven. ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN DISCLOSURE: ______ Yes 🔀 No Seller shall be responsible and liable for any failure to provide known information regarding known material defects to the Buyer. Neither Seller nor any Broker makes any representations as to the applicability of, or compliance with, any codes of any sort, whether state, municipal, federal or any other, including but not limited to fire, life safety, building. electrical or plumbing. As Sellers, we have provided the above information and represent that all information is correct. To the best of our knowledge, all systems and equipment, unless otherwise noted on this form, are in operational condition. SELLER DATE SELLER **DATE** I/We have read and received a copy of this disclosure, the arsenic in wood fact sheet, the arsenic in water brochure, and understand that I/we should seek information from qualified professionals if I/we have questions or concerns. BUYER DATE BUYER DATE



BUYER



DATE

BUYER

DATE

027628

Warranty Deed Maine Statutory Short Form

KNOW ALL MEN BY THESE PRESENTS.

That I, Pauline M. Doane of Kennebunkport, in the County of York and State of Maine,

for consideration paid,

grant to Vincent J. Thelin and Susan E. Thelin, both of Ogunquit, in the County of York and State of Maine,

with WARRANTY COVENANTS, as joint tenants, the land in Kennebunkport, County of York and State of Maine, described as follows:

A certain lot or parcel of land, located on the Southeasterly side of the Lester Wildes Road, in the Town of Kennebunkport, County of York and State of Maine, which certain lot or parcel of land is identified as LOT NO. 3 as the same is depicted on a plan entitled "Subdivision for ROBERT A. LAROCHELLE of Andover, Ma. in Kennebunkport, ME." dated October 1982, revised October 28, 1982 and further revised on November 23, 1982, the same being recorded in the York Registry of Deeds in Plan Book 122, Page 31.

The above described LOT NO. 3 on said recorded plan contains 10 acres and bears the notation "Lot not approved for residential use".

For Grantor's source of title, reference may be had to the following instruments:

- Quitclaim Deed from Ronald P. Doane and Karen L. Doane to Ronald P. Doane and Pauline M. Doane dated August 15, 1985 and recorded in said Registry in Book 3681, Page 145.
- Quitclaim Deed from Ronald P. Doane to Pauline M. Doane dated August 2, 1988 and recorded in said Registry in Book 4821, Page 197.

WITNESS my hand and seal this _______ day of June. 1994

Muy bolaus

Pauline M. Doane

State of Maine County of York, ss.


Then personally appeared the above named Pauline M. Doane and acknowledged the foregoing instrument to be her free act and deed,


Before me,

Notary Public Print name: WAYNE T. ADAMS

RECEIVED YORK S.S. 94 JUN 20 AH 8: 48

ATTEST: anney Stone REGISTER OF DEEDS





Have you tested your well water for arsenic?



Your water looks, smells and tastes fine. So why do you need to test it?

It is hard to believe that water that looks, smells and tastes fine may not be safe to drink. But the truth is that 1 in 10 wells in Maine has water that is high in arsenic. There are wells high in arsenic in all parts of Maine.

Protect your family.

Test your well for arsenic every 3 to 5 years.

How to Test Your Well Water

1. Call a lab.

- Call a certified lab and ask for an arsenic test kit for your well water. You can find a lab at this website: wellwater.maine.gov. Or call the Maine Lab Certification Officer at 207-287-1929.
- If you have never tested your well water for bacteria, nitrites and nitrates, or other chemicals like radon, uranium and flouride, ask your lab for a test kit for all of these.

2. Do the test.

- Your test kit will arrive in the mail. It will have empty bottles, directions and forms to fill out.
- Follow the directions and mail the bottles back to the lab with the forms.
- Watch a video on how to do a water test: youtube.com/user/MainePublicHealth

3. Get your results.

- Your test results will come to you in the mail.
- If you have too much arsenic in your water, or if you are not sure you understand your test results, call 866-292-3474 (toll-free in Maine) or 207-287-4311 to speak to an expert.

Why Arsenic is Bad

People who drink water with too much arsenic for many years are more likely to get cancer. Arsenic can cause skin, bladder and lung cancers.

It may cause low birthweight and affect brain development in babies if pregnant women drink water with too much arsenic in it. Arsenic can also affect brain development in young children. Other problems from drinking water with very high arsenic levels include: stomach pain, nausea, diarrhea, numbness or tingling in the hands and feet and changes in skin.

Your chance of having any of these health problems depends on:

- how much arsenic is in your water;
- · how much water you drink;
- how long you have been drinking the water.

Solving Arsenic Problems

There are actions you can take to protect your family if your water has too much arsenic. First, you can switch to bottled water for drinking and making drinks. This will allow you time to decide if you want to install a water treatment system.

Call us at 866-292-3474 (toll-free in Maine) or 207-287-4311 if you have high arsenic. We can help you decide how to solve the problem.

Protect your family. Test your well.

- For more information: wellwater.maine.gov
- Call for advice: 866-292-3474 TTY: Call Maine Relay 71





Fact Sheet: Arsenic Treated Wood

Department of Health and Human Services 11 State House Station Augusta, ME 04333 Maine CDC Environmental and Occupational Health Program Toll Free in Maine: 866-292-3474

> Fax: 207-287-3981 TTY: 207-287-8066 Email: ehu@maine.gov

IF YOU WORK WITH CCA WOOD

- NEVER burn CCA wood.
- Wear gloves when handling CCA wood
- Wear a dust mask when sanding or cutting CCA wood
- Don't work with CCA wood in an enclosed area (like a garage)

Apply a coating to seal the wood every 1-2 years

TO LEARN MORE

Eric Frohmberg
Environmental and
Occupational Health
Program
Maine CDC
Toll-free in Maine 866292-3474
TTY: 207-287-8066
www.maine.gov/dhhs/
eohp

Does Your New Home Have Arsenic (CCA) Treated Wood?

About half of all Maine homes have a deck, or playground or some other structure that is made of wood treated with arsenic. This wood is called "CCA pressure-treated wood" or just "pressure-treated" wood. The wood was treated with arsenic to protect against rot and insects.

Too much arsenic can cause cancer. So it is good to prevent arsenic getting into your body when you can. When you touch wood treated with arsenic, you can get arsenic on your hands. The arsenic on your hands can get into your mouth if you are not careful about washing before eating. Young children are most at risk because they are more likely to put their hands in their mouths. The good news is that there are simple things you can do to protect yourself and your family from arsenic treated wood. This fact sheet will tell you how.



Children touching unsealed treated wood, and then putting their hands in their mouths is the biggest concern

First: Does your house have arsenic treated (CCA) wood?

When arsenic treated wood is new, it tends to have a greenish tint. When CCA wood is older, it is harder to tell. Ask your realtor if the seller knows whether CCA wood was used. You can also test the wood to find out if it contains arsenic. Call us to find out how.

Second: If so, reduce contact with the arsenic.

You can lower the amount of arsenic on the surface of the wood by applying a coating on the wood every 1-2 years. Oil-based sealants, varnishes, or polyurethane work best for sealing arsenic in the wood. Be sure to wash your children's hands when they finish playing on or near CCA wood

Third: If you have any questions, call us toll-free in Maine: 866-292-3474

Common Questions

What is CCA wood?

CCA wood is made by dipping the wood in a mixture of chemicals. These chemicals include chromium, copper, and arsenic. This protects the wood against insects and rot. This wood is known as CCA wood or "pressure treated" wood. Most pressure treated wood in the U.S. is CCA wood. After December 31, 2003, no more CCA wood will be made for use around homes. CCA wood may still be sold for home use until April 1, 2004 in the state of Maine.

What is Arsenic?

Arsenic is found in soil and rocks. Most people get a little arsenic every day from the food they eat. Also, some people have arsenic in their private wells, which is why it is important that anyone with a well have it tested for arsenic. People who are exposed to too much arsenic over many years are more likely to get cancer.

National Flood Hazard Layer FIRMette

70°28'22"W 43°24'24"N



FLOOD HAZARD OTHER AREAS OF OTHER FEATURES OTHER AREAS MAP PANELS Zone 70°27'45"W 43°23'58"N eff. 7/17/2024 23031C0464G Zone A 1:6,000 TOWNOFIKENNEBUNKPORT Feet AREA OF MINIMAL FLOOD) HAZARD 1,500 1,000 23031004636 eff. 7/17/2024 200 250

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS

With BFE or Depth Zone AE AO, AH, VE, AR Without Base Flood Elevation (BFE) Regulatory Floodway

0.2% Annual Chance Flood Hazard, Areas depth less than one foot or with drainage areas of less than one square mile zone x of 1% annual chance flood with average

Future Conditions 1% Annual Chance Flood Hazard Zone X

Area with Reduced Flood Risk due to or the

Area with Flood Risk due to Levee Zone D Levee. See Notes. Zone X

NO SCREEN Area of Minimal Flood Hazard Zone X **Effective LOMRs**

Area of Undetermined Flood Hazard Zone D

- - - Channel, Culvert, or Storm Sewer STRUCTURES | 1111111 Levee, Dlke, or Floodwall

GENERAL

Cross Sections with 1% Annual Chance

Water Surface Elevation **Coastal Transect** 17.5

Base Flood Elevation Line (BFE) Limit of Study work \$13 work

Coastal Transect Baseline Jurisdiction Boundary

Hydrographic Feature Profile Baseline

Digital Data Available

No Digital Data Available

Unmapped

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map compiles with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown compiles with FEMA's basemap accuracy standards


was exported on 10/1/2024 at 2:15 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or authoritative NFHL web services provided by FEMA. This map The flood hazard information is derived directly from the become superseded by new data over time. This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers. FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

Basemap Imagery Source: USGS National Map 2023

| Street, and the street, and th | 1 | | | | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| err by CEO Garadia | Trent by code to | 4 3//Y | | Departm | nent of Human Service | Cos |
| SUBSURFACE | WASTEWATER DIS Y ADDRESS | POSAL SYS | TEM APPLICATION | Ulvision | of Health Engineer (207)269-3826 | ang . |
| | UNKPORT | | | | | |
| 1 | LIBEL ROAD | | Caution: Pi The Subsurface Wastewater to Installed until a Permit is attai Inspector. The Permit shall at | ermit Requir Disposal Syste ched here by I | m shall not be | |
| 1 / 1 TOT 1 12 | VINCENT & SUS | 1 11 4 | Inspector. The Permit shall au install the disposal system in the Maine Subsurface Waste | | | n and |
| Applicant | VINCERI | | and the second of the second o | | A Wallet | |
| Namo: Making Address of General anticate | | | | | | |
| Owner/Appleant (II Different) Certify that the information submitted and submitted and submitted and submitted from the submitted and submitted submi | licant Statement is correct to the best of my cation is reason for the Local | | Caution: Ins I have inspected the installabe in compliance with the Sub- | pection Req ation suihorized a surface Wastewar | uired bove and found it to ler Disposal Rules. | |
| The state of the s | | Date | Local Plumbing Inspector Si | gnature | | Date Approved |
| Signature of Owner/Ap. | plicant | PERMIT INF | ORMATION | | | H. |
| | | | TION REQUIRES: | INSTALLA | TION IS: | |
| THIS APPLICATION IS FOR | | THIS APPLICATION | | COMPLETE S | | |
| 1. O NEW SYSTEM | 1 1 4 | 7 OVETEN | AVARIANCE | 1. DE NON-E | ENGINEERED SY | STEM |
| A CT EVOANDED SYSTEM | | Attach New 5 | ystem variance i com | | TIVE SYSTEM les Alternative Toile | de la companya della companya della companya de la companya della |
| 1. EXPERIMENTAL SYSTEM | ON | Attach Replace | NT SYSTEM VARIANCE iment System Variance Form | a. D ENGII | NEERED (+2000 | gpd) |
| SEASONAL CONVERSION to be completed by the LPI | l a L | Requiring Loca | I Plumbing Inspector Approval | INDIVIDUALLY INSTALLED COMPONENTS: | | |
| | TH RULES b. T | Requires State Approval | and Local Plumbing Inspector | | TMENT TANK (C | |
| 6 CONNECTED TO SANT | P# 4. C | MINIMUM FO. | T SIZE VARIANCE | 1 | DING TANK | |
| I & CT GVOTEM DESIGN REUL | ORDED | | | 6. ALTERNATIVE TOILET (ONLY) 7. NON-ENGINEERED DISPOSAL AREA | | |
| AND ATTACHED | | ICDOCAL SV | STEM TO SERVE: | 7. LI NON | | ASPOSAL AREA |
| IF REPLACEMENT SYSTEM | | | | , | INEERED DISPO | OSAL AREA |
| YEAR FAILING SYSTEM INST. | | | NILY DWELLING | (ON | | |
| THE FAILING SYSTEM IS: | | | OR MOBILE HOME | 9. SEF | PARATED LAUNI | DRY SYSTEM |
| 1. D BED 3. D TRENCH 2. D CHAMBER 4. D OTHER. | 3, 🗆 | MULTIPLE F | AMILY DWELLING | TYPI | E OF WATER | SUPPLY |
| SIZE OF PROPERTY ZOI | NING 4. | OTHER | | | | |
| 10 AC. + FARM & | ENREST | - | SPECIFY | | ING WI | = |
| 18 AC. STARTIE | DESIGN DETAI | LS (SYSTEM L | AYOUT SHOWN ON PAGE | 3) | | (C) (E) (E) (F) (A) (E) |
| 46 C. S. | | azoka Milita (1977) | PUMPING | ĭ | | A USED FOR EDROOMS, SEATING, |
| EXIST HEATMENT TANK | WATER CONSE | ERVATION | 1. NOT REQUIRED | E | MPLOYEES, WA | TER RECORDS, ETC.) |
| 1. SEPTIC: A Regular | 1 NONE 2 D LOW VOLUME | | 2. MAY BE REQUIR (DEPENDING ON TREA | ED THENT TANK | SINGL | E |
| Low Profile | 3. SEPARATED LAU | NDRY SYSTEM | LOCATION AND ELEVA | (TION) | FAMIL | Y / |
| 2. AEROBIC | 4. ALTERNATIVE | TOILET | 3. REQUIRED | 041.6 | DWEL | |
| SIZE: 1000 GALS. | SPECIFY: | | DOSE: | GALS. | (3 8 | EDROOM) |
| SOIL CONDITIONS USED FOR | SIZE RATINGS U | SED FOR | DISPOSAL AREA TY | PE/SIZE | | |
| DESIGN PURPOSES | DESIGN PURI | | 1. BED | _ Sq. Ft. | | |
| PROFILE CONDITION | 1. SMALL 2. MEDIUM | | 2. CHAMBER 52 | 5 Sq. Ft. | | |
| 1 2 A | 3. MEDIUM-LARG | E | REGULAR 🗆 | | DESIGN | 0-1 |
| DEPTH TO | 4. 🗆 LARGE 💀 | | 3. TRENCH | _ Linear Ft. | FLOW: | <u> </u> |
| LIMITING 16-26. | 5. EXTRA LARGE | | 4. OTHER: | AMDEDA | | (GALLONS/DAY) |
| 100 100 100 100 100 100 100 100 100 100 | AND STATE OF THE PARTY OF THE STATE OF THE S | | | JUIDER | | anaga, was galabasi |
| SITE EVALUATOR STATEMENT | | | | | | |
| | | | THE STREET STATES | | ger x m | |
| On october 4, 1994 (date) | I conducted a site e | valuation for | this project and certify | that the da | ita reported is | accurate. The |
| system I propose is in accordance v | with the Subsurface | | | | 1-11- | |
| Albert thic | 1 | /1 | 63 | 10, | 13/194 | |
| Site Evaluator Signature | | | SE# | Francisco | Date | Page 1 of 3 |

(Local Plumbing Inspector's Signature if permit is for Seasonal Conversion.)

Page 1 of 3 HHE-200 Rev. 11/86



Site Evaluator Signalure

163

10/31/94 Date

Page 2 of 3 HHE-200 Rev. 1/84